

INS CASE OWNER:

VAL

CC 4/AXA1800

4344, R22639

LKK:

IDAC:

Surveyor:

Kash

DOI:

ASSIGNMENT

31/5/18

Date / Time:

Registered in Merimen:

21/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLP 4086

Name of Insured:

TEO POK MUI

Insured Tel No.:

HP: 96691157

Excess Sec II :SS

D.O.A: 12/5/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SGM00419 / 44070

Policy No.:

WPK (11936128)

Make / Model:

UXUS

Place of Accident:

LIANHIN RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLJ 1134H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Mun Wong



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

6.6.18 = 3.30

PHOTOS OF CONFIRMED ACCIDENT. OLD STAGE A SHARP LEFT TURN AND COLLISION INTO TP. PROCEED TO CLAIM AND VIDEO TESTED TO STATE AND ADVISE ABOUT NEXT STEP.

From WSP Liability Claim.

17/10 - TO SEEK mandate.

18/10 - Pending mandate approval. (Approved).

5/11 - offer a settle @ \$1831.08 as per TP proposed. File pass on 11/11/18.

26/11/19 - File pass to LSP to close.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KASHI

Repair Cost:

\$1485.12

(3 days)

Reduction: \$3134.08 = 68

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

5/11/19

Confirm with:

ACHIEVE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$1589.08

OO TURN IN TO CLOSE TO TP

Loss of Rental (LOR):

\$5

( days)

Loss of Use (LOU):

\$5

(5 days)

Loss of Income (LOI):

\$5

(5 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5

2.00

Medical:

\$5

Disbursement:

\$5

Legal Cost

\$5

Total:

\$1831.08

Global Sum \$5:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

\$1831.08

Name 1:

Hua Hong Private Limited

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

✓ ETD





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009399/R1eb3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 23-05-2018



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |          |                |            |
|--------------|----------|----------------|------------|
| Insured Veh. | SLP 408G | Veh. Inspected | SLJ 1139H  |
| Policy No.   |          | Coverage (\$)  | 0.00       |
| Claim No.    |          | Excess (\$)    | 0.00       |
| Assign From  |          | Assign Date    | 23/05/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |                                                                |                 |            |
|----------------|----------------------------------------------------------------|-----------------|------------|
| Accident Date  | 12/05/2018                                                     | Inspection Date | 31/05/2018 |
| Survey held at | HUA HONG PTE LTD<br>25D SUNGEI KADUT STREET 1 SINGAPORE 729332 |                 |            |

## 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|



# HUA HONG PRIVATE LIMITED

250 Sungai Kodat Street 1 Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

25 May 2018

HHTPClaims18-43

AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

### ACCIDENT INVOLVING SLJ 1139 H & SLP 408 G ON 12/05/2018 ALONG CAIRNHILL ROAD AT ABOUT 0915 HOURS

Insured : TAN KEOK INN  
Vehicle Registration No : SLJ 1139 H  
Vehicle Make : HONDA  
Vehicle Model : HRV 1.5 DX CVT  
Vehicle Chassis No : JHMRU1810GX201249  
Policy No : SD16V16307/VPC2/R00  
Date of Accident : 12/5/2018

Type of Claim: Third Party

| S/N      | Quantity | Description                     | Unit Price S\$ | Amount S\$     |
|----------|----------|---------------------------------|----------------|----------------|
| 1        | 1        | Front Bumper                    |                | \$ 801.70 DE   |
| 2        | 10       | Front Bumper Clip               | 3.90           | \$ 39.00       |
| 3        | 1        | Front Bumper Retainer (RH)      |                | \$ 14.70       |
| 4        | 1        | Front Bumper Lower Garnish      |                | \$ 351.00 X NN |
| 5        | 1        | Front Fog Lamp (RH)             |                | \$ 327.70      |
| 6        | 1        | Front Fog Lamp Cover (RH)       |                | \$ 29.50       |
| 7        | 1        | Head Lamp (RH)                  |                | \$ 1,784.50    |
| 8        | 1        | Head Lamp Bracket (RH)          |                | \$ 35.00       |
| 9        | 1        | Front Reinforcement             |                | \$ 321.00      |
| 10       | 1        | Front Fender Arch Garnish (RH)  |                | \$ 195.00 X    |
| 11       | 10       | Front Fender Inner Shield Clip  | 3.90           | \$ 39.00 X     |
| 12       | 1        | Front Bumper Lower Skirt        |                | \$ 351.00 DE   |
| 13       | 1        | Front Bumper Lower Skirt Rubber |                | \$ 84.90 X NN  |
|          |          |                                 |                | \$ 4,374.00    |
| Less 20% |          |                                 |                | \$ (874.80)    |
|          |          |                                 |                | \$ 3,499.20    |

To dismantle & change front bumper, front RH head lamp, front reinforcement, knocking & pull straight all area affected by accident.

\$ 600.00 300

To perform wire checking.

\$ 20.00

To spray front bumper, front reinforcement and touch up front RH fender.

\$ 500.00 200

\$ 4,619.20

7% GST

\$ 323.34

Total

\$ 4,942.54

Authorised by Claims Dept  
Mrs Tan @ 9639 9195





## Service Request Details

Claim

S8M00H19

Reference

None 

Loss Date

May 12, 2018

Request Date

May 14, 2018

Due Date

May 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21052018 @ 405pm  
Yvonne veh not in

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLJ1139H

Make

TPVD HONDA

## Service Address

...

## Primary Contact/Insured

TEO POH MUI  
BLK 406 SIN MING AVE, #10-259, 507406, Singapore

teopmfelicia@gmail.com

## Claim Handler

OH Vale  
6568804897  
vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

5/14/18 3:03 PM

FROM

OH Vale

SUBJECT

Re:NON REPORTING

BODY

TP reported come out from minor road. Pls proceed ...



TYPE



SENT

5/14/18 3:00 PM

FROM

OH Vale

BODY





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/2019

### Survey Details:

|                     |                          |
|---------------------|--------------------------|
| Date of loss        | 12-May-18                |
| Date of appointment | 23-May-18                |
| Date of survey      | 31-May-18                |
| Location of survey  | HUA HONG PRIVATE LIMITED |

### Vehicle Details:

|                      |             |
|----------------------|-------------|
| Claim Type:          | Third party |
| Vehicle number       | SLJ 1139H   |
| Make and Model       | HONDA HRV   |
| Date of registration | 29/11/2016  |
| Excess               |             |
| Market Value         | \$88,000    |
| Parf Rebate          | \$57,300    |
| Nett Loss            | \$30,700    |

### Repair details:

|                  |             |
|------------------|-------------|
| Initial Estimate | \$ 4,619.20 |
|------------------|-------------|

### Proposed/Revised repair cost:

|                         |                    |
|-------------------------|--------------------|
| Parts                   | \$ 965.12          |
| Check items (estimate)  | \$ -               |
| Labour                  | \$ 520.00          |
| <b>Total</b>            | <b>\$ 1,485.12</b> |
| Lump Sum(if applicable) | -                  |

|                           |   |
|---------------------------|---|
| Number of days for repair | 3 |
|---------------------------|---|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

03 RECOMMENDED REPAIR DAYS + 1PRS = 4 DAYS

**Mandate:**

| Liability(TP)                | 100%               |              |
|------------------------------|--------------------|--------------|
| Proposed repair cost (W/GST) | \$ 1,589.08        |              |
| Loss of use                  | \$ 240.00          | 4days x \$60 |
| Loss of rental               | \$ -               |              |
| Loss of income               | \$ -               |              |
| LTA search fees              | \$ 2.00            |              |
| Others                       | \$ -               |              |
| <b>Proposed Total</b>        | <b>\$ 1,831.08</b> |              |

 <MANDATE IA> - S8M00H19 {ACCIDENT INVOLVING  
SLP 408G(OI) & SLJ 1139H(TP) ON 12/05/2018}

Type

 Question

Message

LIABILITY: 100%, OI TURN LEFT TOO CLOSE TO TP - INFORMED OI ABOUT TP CLAIM AND NCD  
ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1,831.08 (CLAIMING LOU).  
MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR  
APPROVAL/INSTRUCTION. THANKS - CCL

[Reply](#)

## Cecilia Chong (LKK Auto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Thursday, 26 September 2019 6:00 PM  
**To:** Cecilia Chong (LKK Auto)  
**Subject:** FW: LOD for Vehicle No. SLJ1139H  
**Attachments:** TAX INVOICE.pdf; TP Search Fee.pdf

Hi Cecilia,

Kindly assist.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5408933

---

**From:** Ashley Tan <[ashley@huahong.com.sg](mailto:ashley@huahong.com.sg)>  
**Sent:** Wednesday, 4 September 2019 9:45 AM  
**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** LOD for Vehicle No. SLJ1139H

Dear all

Please refer to the LOD as attached.

We are claiming LOD as below:-

|               |                  |
|---------------|------------------|
| COR           | \$1589.08        |
| TP Search fee | \$2.00           |
| LOU           | \$400.00         |
| <b>Total</b>  | <b>\$1991.08</b> |

Thanks & Regards

*Ashley Tan*



**HUA HONG PRIVATE LIMITED**  
25D SUNGEI KADUT STREET 1 SINGAPORE 729332  
T. 6661 9690 | M. 9816 4151 | F. 6661 9699  
Follow us @ [huahong.com.sg](http://huahong.com.sg)



**HUA HONG PRIVATE LIMITED**

25D Sungai Kadul Street 1 Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

**TAX INVOICE**

30 August 2019

HHTPClaims18-43F

AXA Insurance Pte Ltd  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

Attn: Motor Claims Dept

**ACCIDENT INVOLVING SLJ 1139 H & SLP 408 G ON 12/05/2018 ALONG CAIRNHILL ROAD AT ABOUT 0915 HOURS**

Insured : TAN KEOK INN  
Vehicle Registration No : SLJ 1139 H  
Vehicle Make : HONDA  
Vehicle Model : HRV 1.5 DX CVT  
Vehicle Chassis No : JHMRU1810GX201249  
Policy No : SD16V16307/VPC2/R00  
Date of Accident : 12/05/2018

Type of Claim: Third Party

| S/N                                                                                                                                  | Quantity | Description                | Unit Price S\$ | Amount S\$         |
|--------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------------|----------------|--------------------|
| 1                                                                                                                                    | 1        | Front Bumper               |                | \$ 801.70          |
| 2                                                                                                                                    | 10       | Front Bumper Clip          | \$ 3.90        | \$ 39.00           |
| 3                                                                                                                                    | 1        | Front Bumper Retainer (RH) |                | \$ 14.70           |
| 4                                                                                                                                    | 1        | Front Bumper Lower Skirt   |                | \$ 351.00          |
|                                                                                                                                      |          |                            |                | \$ 1,206.40        |
|                                                                                                                                      |          |                            |                | Less 20%           |
|                                                                                                                                      |          |                            |                | \$ (241.28)        |
|                                                                                                                                      |          |                            |                | \$ 965.12          |
| To dismantle & change front bumper, front RH head lamp, front reinforcement, knocking & pull straight all area affected by accident. |          |                            |                | \$ 300.00          |
| To perform wire checking.                                                                                                            |          |                            |                | \$ 20.00           |
| To spray front bumper, front reinforcement and touch up front RH fender.                                                             |          |                            |                | \$ 200.00          |
|                                                                                                                                      |          |                            |                | \$ 1,485.12        |
|                                                                                                                                      |          |                            |                | 7% GST             |
|                                                                                                                                      |          |                            |                | \$ 103.96          |
|                                                                                                                                      |          |                            |                | \$ 1,589.08        |
| Third Party Insurer Enquiry Fee (receipt attached)                                                                                   |          |                            |                | \$ 2.00            |
| Loss of use @ 4 days x \$100 per day.                                                                                                |          |                            |                | \$ 400.00          |
| <b>Total</b>                                                                                                                         |          |                            |                | <b>\$ 1,991.08</b> |



Authorised by Claims Dept  
Mrs Tan @ 9639 9195



Re:<MANDATE IA> - S8M00H19 {ACCIDENT  
INVOLVING SLP 408G(OI) & SLJ 1139H(TP) ON  
12/05/2018}

Type

🔗 Question

Message

Hi Pls proceed, tks

Reply



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18009399/R1gb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:VALE OH

Date : 03-12-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | SLP 408G     | Veh. Inspected | SLJ 1139H  |
| Policy No.   | VPA/P1936128 | Coverage (\$)  | 0.00       |
| Claim No.    | S8M00H19     | Excess (\$)    | 0.00       |
| Assign From  |              | Assign Date    | 23/05/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | HONDA HRV 1.5 DX  | c.c          | 1496       |
| Engine No.   | HIDDEN            | Year of Reg. | 2016       |
| Chassis No.  | JHMRU1810GX201249 | Colour       | GREEN      |
| Odometer     | 19304             | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | FAIR              |              |            |

## 3. Conditions of Tyres

|                | Size       | Make   | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | DUNLOP | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                |                 |            |
|----------------|----------------------------------------------------------------|-----------------|------------|
| Accident Date  | 12/05/2018                                                     | Inspection Date | 31/05/2018 |
| Survey held at | HUA HONG PTE LTD<br>25D SUNGEI KADUT STREET 1 SINGAPORE 729332 |                 |            |

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1139H**

| Qty                                | Description of Parts                                                                                                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                                                                                       |               |                           |                   |
| 1                                  | FRONT BUMPER (CONSISTENT)                                                                                                             | DEFORMED      | 801.70                    | 801.70            |
| 10                                 | FRONT BUMPER CLIP @\$3.90 (CONSISTENT)                                                                                                | NECESSARY     | 39.00                     | 39.00             |
| 1                                  | FRONT BUMPER RETAINER (RH) (CONSISTENT)                                                                                               | NECESSARY     | 14.70                     | 14.70             |
| 1                                  | FRONT BUMPER LOWER GARNISH (CONSISTENT)                                                                                               | NOT NECESSARY | 351.00                    | -                 |
| 1                                  | FRONT FOG LAMP (RH) (CONSISTENT)                                                                                                      | NOT NECESSARY | 327.70                    | -                 |
| 1                                  | FRONT FOG LAMP COVER (RH) (CONSISTENT)                                                                                                | NOT NECESSARY | 29.50                     | -                 |
| 1                                  | HEAD LAMP (RH) (CONSISTENT)                                                                                                           | NOT NECESSARY | 1,784.50                  | -                 |
| 1                                  | HEAD LAMP BRACKET (RH) (CONSISTENT)                                                                                                   | NOT NECESSARY | 35.00                     | -                 |
| 1                                  | FRONT REINFORCEMENT (CONSISTENT)                                                                                                      | NOT NECESSARY | 321.00                    | -                 |
| 1                                  | FRONT FENDER ARCH GARNISH (RH) (CONSISTENT)                                                                                           | NOT NECESSARY | 195.00                    | -                 |
| 10                                 | FRONT FENDER INNER SHIELD CLIP @\$3.90 (CONSISTENT)                                                                                   | NOT NECESSARY | 39.00                     | -                 |
| 1                                  | FRONT BUMPER LOWER SKIRT (CONSISTENT)                                                                                                 | DEFORMED      | 351.00                    | 351.00            |
| 1                                  | FRONT BUMPER LOWER SKIRT RUBBER (CONSISTENT)                                                                                          | NOT NECESSARY | 84.90                     | -                 |
|                                    | LESS 20% DISCOUNT                                                                                                                     |               | -874.80                   | -241.28           |
|                                    |                                                                                                                                       |               | 3,499.20                  | 965.12            |
| <b>LABOUR</b>                      |                                                                                                                                       |               |                           |                   |
|                                    | TO DISMANTLE & CHARGE FRONT BUMPER ,FRONT RH HEAD LAMP ,FRONT REINFORCEMENT ,KNOCKING & PULL STRIAIGHT ALL AREA AFFECTED BY ACCIDENT. |               | 600.00                    | 300.00            |
|                                    | TO PERFORM WIRE CHECKING.                                                                                                             |               | 20.00                     | 20.00             |
|                                    | TO SPRAY FRONT BUMPER ,FRONT REINFORCEMENT AND TOUCH UP FRONT RH FENDER.                                                              |               | 500.00                    | 200.00            |
|                                    |                                                                                                                                       |               | 1,120.00                  | 520.00            |
| <b>GRAND TOTAL</b>                 |                                                                                                                                       |               | <b>4,619.20</b>           | <b>1,485.12</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                       |               |                           | <b>1,485.12</b>   |

Report Ref No. CC4/ASM18009399/R1gb3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

⏪ Service Request Details

|              |                                                                                                              |                                                                                          |                |
|--------------|--------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|----------------|
| Claim        | SLM00H19                                                                                                     | Vehicle Information                                                                      |                |
| Reference    | CCA/ASM1B007399/RT1gb3p2  | Incident Vehicle Registration #                                                          | SLJ1139H       |
| Loss Date    | 12 May 2018                                                                                                  | Make                                                                                     | TRVD HONDA     |
| Report Date  | 14 May 2018 2:37:20 PM                                                                                       | Model                                                                                    | HRV 1.5 DX CVT |
| Request Date | 23 September 2018                                                                                            | Service Address                                                                          |                |
| Due Date     |                                                                                                              | ...                                                                                      |                |
| Vendor Name  | LKK AUTO CONSULTANTS PTE LTD (TP)                                                                            | Primary Contact/Insured                                                                  |                |
| Type of Loss | Third Party Vehicle Damage                                                                                   | TEO POH MUJ<br>BLK 406 SIN MING AVE, #10-359, 507406, Singapore<br>leopmfelela@gmail.com |                |
| Services     | Pending verification - Direct Settlement                                                                     | Claim Handler                                                                            |                |
|              |                                                                                                              | OH Vale<br>6568804897<br>vale.oh@axa.com.sg                                              |                |

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Additional Instructions

Messages Invoies History Documents Assessment Metrics Notes

Document Type Document SubType

Upload Documents

| NAME                  | TYPE                | SUB-TYPE   | AUTHOR   | DATE UPLOADED |
|-----------------------|---------------------|------------|----------|---------------|
| OO Accident Statement | Reports & Statement | GIA Report | Merrimen |               |

| NAME                                                                                                                                  | TYPE                          | SUB-TYPE                         | AUTHOR                               | DATE<br>UPLOADED    |
|---------------------------------------------------------------------------------------------------------------------------------------|-------------------------------|----------------------------------|--------------------------------------|---------------------|
|  LKKInvoice1 (6).pdf                               | Invoice                       | Surveyor/ Assessor expense       | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  LKKInspection (4).pdf                             | Forms / Claim<br>Documents    | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  LKKAdjustment1a (3).pdf                           | Forms / Claim<br>Documents    | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  GIA SEARCH.pdf                                    | Forms / Claim<br>Documents    | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  PAYMENT BREAKDOWN, EXPRESS<br>SETTLEMENT FORM.pdf | Forms / Claim<br>Documents    | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  AUTHORISATION TO ACT FORM.pdf                     | Forms / Claim<br>Documents    | POA / Authority Letter           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  LETTER TO OI.pdf                                  | Letters and<br>Correspondence | Policy Holders / Insured         | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 December<br>2019 |
|  PARF CODE REBATE.pdf                              | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  LOO.pdf                                           | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  LTA SEARCH INVOICE.pdf                          | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  MANDATE IA DO 18102019.pdf                      | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  TP FINAL EST LIST.pdf                           | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  LKK RESURVEY PHOTO.pdf                          | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |
|  LKK SURVEY PHOTO.pdf                            | Reports &<br>Statement        | Others                           | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October<br>2019  |

| NAME                                                                                                                  | TYPE                    | SUB-TYPE                                               | AUTHOR                               | DATE<br>UPLOADED |
|-----------------------------------------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------|--------------------------------------|------------------|
|  FINAL REPAIR INVOICE.pdf          | Reports & Statement     | Others                                                 | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 18 October 2019  |
|  TP Immediate Advice.pdf           | Reports & Statement     | Estimate / Quotation                                   | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 11 June 2018     |
|  TP ESTIMATE- MARKED.pdf           | Reports & Statement     | Estimate / Quotation                                   | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 1 June 2018      |
|  TP VIDEO.mp4                      | Evidence                | Videos                                                 | LKK AUTO CONSULTANTS<br>PTE LTD (TP) | 22 May 2018      |
|  P1936128_NB_00001_1.pdf           | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of Insurance | OH Vale                              | 14 May 2018      |
|  P1936125_C1_00001_1.pdf           | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of Insurance | OH Vale                              | 14 May 2018      |
|  TP EMAIL WITH TP SLJ1139H GAA.png | Forms / Claim Documents | Others                                                 | KUMAR Shalendra                      | 14 May 2018      |