



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

25 May 2018

HHTPClaims18-43

AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ACCIDENT INVOLVING SLJ 1139 H & SLP 408 G ON 12/05/2018 ALONG CAIRNHILL ROAD AT ABOUT 0915 HOURS

Insured : TAN KEOK INN
Vehicle Registration No : SLJ 1139 H
Vehicle Make : HONDA
Vehicle Model : HRV 1.5 DX CVT
Vehicle Chassis No : JHMRU1810GX201249
Policy No : SD16V16307/VPC2/R00
Date of Accident : 12/5/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper		\$ 801.70 DE-
2	10	Front Bumper Clip		\$ 39.00 DE-
3	1	Front Bumper Retainer (RH)		\$ 14.70 DE-
4	1	Front Bumper Lower Garnish		\$ 351.00 X
5	1	Front Fog Lamp (RH)		\$ 327.70 ?
6	1	Front Fog Lamp Cover (RH)		\$ 29.50 ?
7	1	Head Lamp (RH)		\$ 1,784.50 ?
8	1	Head Lamp Bracket (RH)		\$ 35.00 ?
9	1	Front Reinforcement		\$ 321.00 ?
10	1	Front Fender Arch Garnish (RH)		\$ 195.00 X
11	10	Front Fender Inner Shield Clip		\$ 39.00 X
12	1	Front Bumper Lower Skirt		\$ 351.00 DE-
13	1	Front Bumper Lower Skirt Rubber		\$ 84.90 X
				\$ 4,374.00
				Less 20%
				\$ (874.80)
				\$ 3,499.20

To dismantle & change front bumper, front RH head lamp, front reinforcement, knocking & pull straight all area affected by accident.

\$ 600.00 300

To perform wire checking.

\$ 20.00

To spray front bumper, front reinforcement and touch up front RH fender.

\$ 500.00 200

\$ 4,619.20

7% GST \$ 323.34

Total \$ 4,942.54

Authorised by Claims Dept
Mrs Tan @ 9639 9195