

**Trans-cab Auto Services Pte Ltd**

**AAD1805-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHB 9926P**

*Not Authored  
 11 Sep @ 3450h*

*LHC*

Vehicle No.: **SHB 9926P**  
 Chassis No.: VF1ABL15AUC273379  
 Vehicle Make: RENAULT  
 Vehicle Model: LATITUDE  
 Date of Accident : 21.5.2018  
 Third Party Insurer : **AXA**

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buitem</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mgmt</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>mir</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61

**Trans-cab Auto Services Pte Ltd**

**AAD1805-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9926P**

1	BONNET HINGE LH	\$	R	348.31	}
1	BONNET HINGE RH	\$	R	348.31	
1	BONNET LOCK	\$	R	305.48	
1	BONNET CABLE	\$	Sn	119.19	
1	BONNET CABLE COVER	\$	Sn	161.03	
1	BONNET SEAL OUTER	\$	Sn	92.36	
1	BONNET SEAL INNER	\$	Sn	157.28	
1	SUBFRAME OUTER FRT	\$	Sn	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	Sn	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	Sn	92.36	
1	ENGINE UNDERTRAY	\$	Sn	564.98	
1	A/C CONDENSER	\$	Sn	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	
1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	
1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	
1	LOWER ARM RH	\$	Sn	685.76	
1	KUNCKLE ARM RH	\$	Sn	846.98	
1	ABSORBER FRT RH	\$	Sn	360.54	
1	STABILIZER BAR FRT	\$	Sn	604.65	
1	DRIVESHAFT RH	\$	R	1,747.45	
1	WIPER RESERVOIR	\$	Det	348.25 ✓	
1	WIPER RESERVOIR NECK	\$	Sn	136.11 X	
1	WIPER RESERVOIR MOTOR	\$	Sn	270.06 X	

<b>TOTAL</b>	<b>\$</b>	<b>35,626.53</b>
<b>10%</b>	<b>\$</b>	<b>3,562.65</b>
	<b>\$</b>	<b>32,063.87</b>

**Special Nett**

1SET	BUMPER CLIP FRT	\$	Acc	66.00	}
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	

**Trans-cab Auto Services Pte Ltd**

AAD1805-200

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9926P**

1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i>	30.50	} X
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i>	7.30	
2	BONNET STRUT L70Y	\$	<i>nn</i>	88.61	
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i>	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i>	10.85	

<b>TOTAL</b>	<b>\$</b>	<b>421.08</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>32,484.95</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>4001</i>
Putty and spray painting of the affected portion.	\$	4,000.00	<i>4401</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1805-200**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9926P**

To replace, refix and top up coolant for radiator \$ *nn* 170.00 *X*

To vacuum, replace, refix and recharge Air Intercooler \$ *nn* 170.00 *X*

**TOTAL \$ 11,090.00**

**Over All Total \$ 43,574.95**

**LUMP SUM (REPAIR DAY)**

**15-DAYS**

*2 1/2 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: