

INS. CASE OWNER

Sharon Chan

CC 6 / AIG1800 9408, Upa3

LKK

IDAC

ASSIGNMENT

DOI

23/5/18

Date / Time

23/5/18

Registered in Merimen

23/5/18

Pre-assign / CCU / FTE

SJQ 6209T



Insured Vehicle No.

Claim No.

Name of Insured

Policy No.

Insured Tel No.

HP:

Make / Model

Excess Sec II : \$5

D.O.A.

Place of Accident

Is driver the owner?

(YES/NO)

Nature of Accident

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

Insured Liability:

%

Final ? Yes / No

SJJ 3971G



INSRS:

WSP:

Tel:

Liability:

RMKS:

Lim Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

GIA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

26/5/2018

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost

\$5 1,700.00

(2 days)

Reduction: 70 %

Email

Call

FINAL SETTLEMENT

Date/Time: 31/11/18

Confirm with Sharon Chan

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

(\$651) \$5 1,819.00

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 120.00

(560.00 x 2 days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

\$5 7.49

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost

\$5 -

Total:

\$5 1946.49

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 1946.49

Name 1:

Tan Lim Motor Pte Ltd

Payee 2 (Strike if N/A)

\$5 -

Name 2:

Payee 3 (Strike if N/A)

\$5 -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

7520 + 420

CLAIM SETTLEMENT
15/11/18

अथवा उप

11/9 08

Call No. ST 39716 11 Ego

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck & Trailer (C) CA/

STJ 39716

7th um

51 Defu Lane 10

55 Q 62097

Date: Nov 3 Sp

15-98

FORM	(over)	A/C	Insured / Std / NI / NA
------	--------	-----	-------------------------

187A.7 TRAC: Insured / Std / NI / NA

CINO JM6BK106280429533

Grd: Good / Fair / Poor / Burnt

Steering Inoperable / Jammed / Leaked / Burnt / ...

Brake: ☐ Inoperable / Jammed / Leaked / Burnt ☐

Mod: Nil (S/Rim) / STD A/Rim of

Type Size F 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO 111

Front

R/Eat 6

(Signature)

Vehicle IN / OUT

L/Bal 6 mm L/Bal 6 mm

DOA 8/5/18 DOI 23/c-1.0

Survey held in

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop

The UIC / Chassis frame / Body Structure affected due to collision

Date	Time	Action	Instruction
23/5/18	4/5	#	1700 confirmed with did 7cr.

York.

$L/S: \$1,700.00$ $(\$2,884.00 / 70\%)$

☐ Prelim. Report

Days Of Repair

Resurvey No. of Trip:

Add Fee: Site Incg: \$

□ *Journal of Management Education* 35(10) 1155-1165

Figure 1	Figure 2
----------	----------

	$\chi^2_{\text{min}} = 18.3$	15
--	------------------------------	----



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18009408/Upa3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 23-05-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJQ 6209T	Veh. Inspected	SJJ 3971G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/05/2018	Inspection Date	23/05/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SJQ6209T

Date of Accident : 08 May 2018

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

confirmed
with Marcus
By Mr Tan
23.05.2018

Miss Azlita Binte Ibrahim

Date : 21 May 2018

not blue
L/S #1700
23/5/18
Take photo after repair

Estimate To Repair SJJ3971G - MAZDA 3 SP

Chassis No : JM6BK106280429556

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	bootlid mazda badge 11	\$ 28.00
02	1 pc	bootlid 3 badge 11	\$ 22.00
03	1 pc	bootlid sp badge 11	\$ 42.00
04	1 pc	bootlid centre emblem badge 11	\$ 59.00
05	1 pc	rear bumper 80/10.1	\$ 862.00
06	2 ps	rear bumper reflector @ \$67.00 11	\$ 134.00
07	1 pc	rear bumper reinforcement 11	\$ 404.00
08	2 ps	rear bumper side retainer @ \$41.00 11	\$ 82.00
09	2 ps	rear bumper side holder @ \$20.00 11	\$ 40.00
10	8 ps	rear bumper clip @ \$5.00 11	\$ 40.00
11	2 ps	rear licence lamp @ \$244.00 11	\$ 488.00
12	1 pc	rear end panel R	\$ 385.00
13	1 pc	rear end panel inner trim 11	\$ 187.00
Less 20 %			\$ 2,773.00
			\$ 554.60
			\$ 2,218.40
SPECIAL NETT ITEMS			
14	1 set	rear bumper parking sensor 11	\$ 450.00
15	1 set	rear bumper side lip 11	\$ 700.00
16	1 pc	rear licence plate 11	\$ 50.00
			\$ 1,200.00
LABOUR & MISC. CHARGES			
01		To rust-proofing of the affected areas.	\$ 11 120.00
02		To check electrical lighting concerned.	\$ 40.00
03		To reinstall of rear bumper parking sensor.	\$ 150.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same	\$ 800.00
06		Putty and spray painting of the affected portion	\$ 900.00
			\$ 2,130.00
Total			\$ 5,548.40

Acknowledged by Repairer

Signature:

Poh Kin (LKKAuto)

From: Wei Shong <wei.shong@tlmotor.com.sg>
Sent: Saturday, 3 November 2018 2:37 PM
To: Poh Kin (LKKAuto)
Cc: Admin A; 'Johnson Chua'
Subject: RE: URGENT - TLM Ref: TP025052018; LKK Ref: TBA; Accident involving SJJ3971G (TLM) & SJQ6209T (AIG) on 08.05.2018
Attachments: 03112018142024.pdf; CIMG4250.JPG; CIMG4251.JPG; CIMG4252.JPG; CIMG4253.JPG

Without prejudice

Dear Poh Kin,

Enclosed the duly signed DV and after repair photo for payment.

Thank you.

Regards,



Lam Wei Shong
William
wei.shong@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Johnson Chua [mailto:johnson.chua@tlmotor.com.sg]
Sent: Saturday, November 3, 2018 2:12 PM
To: 'Wei Shong' <wei.shong@tlmotor.com.sg>
Cc: Poh Kin (LKKAuto) <pohkin@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: URGENT - TLM Ref: TP025052018; LKK Ref: TBA; Accident involving SJJ3971G (TLM) & SJQ6209T (AIG) on 08.05.2018
Importance: High

Dear William,

Please forward the duly signed DV as well as the post repair photos to LKK as soon as possible.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Poh Kin (LKKAUTO)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Saturday, 3 November 2018 1:03 PM
To: Poh Kin (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A; 'Wei Shong'
Subject: URGENT - TLM Ref: TP025052018; LKK Ref: TBA; Accident involving SJJ3971G (TLM) & SJQ6209T (AIG) on 08.05.2018

Importance: High

Categories: clear

Dear Poh Kin,

We refer to your email below.

Please forward us the Discharge Voucher as soon as possible.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Motor Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Saturday, 3 November 2018 12:28 PM
To: Johnson Chua <johnson.chua@tlmotor.com.sg>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: URGENT - TLM Ref: TP025052018; LKK Ref: TBA; Accident involving SJJ3971G (TLM) & SJQ6209T (AIG) on 08.05.2018
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18009408/Upa3
Your Ref: TP025052018

Dear Johnson,

ROAD TRAFFIC ACCIDENT INVOLVING SJQ 6209T AND SJJ 3971G ON 08.05.2018

We refer to the above matter.

Thank you for patient waiting on this matter.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 3 November 2018 12:28 PM
To: 'Johnson Chua'
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: RE: URGENT - TLM Ref: TP025052018; LKK Ref: TBA; Accident involving SJJ3971G (TLM) & SJQ6209T (AIG) on 08.05.2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/AIG18009408/Upa3
Your Ref: TP025052018

Dear Johnson,

ROAD TRAFFIC ACCIDENT INVOLVING SJQ 6209T AND SJJ 3971G ON 08.05.2018

We refer to the above matter.

Thank you for patient waiting on this matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair (w/GST)	S\$ 1,819.00
2. Loss of Use (\$60.00 x 2 days)	S\$ 120.00
4. LTA search	<u>S\$ 7.49</u>
	<u>S\$ 1,946.49</u>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP025052018

Date : 27-07-2018

Your Ref : SJQ6209T

WITHOUT PREJUDICE

Claims Department - **Motor Claims**

c/o **ALL ASIA PACIFIC INSURANCE P/L**

Dear Sir/Madam,

ACCIDENT INVOLVING SJJ39716 & SJQ6209T ON 08-05-2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- | | |
|--|---|
| <input type="checkbox"/> Original survey report/ _____ copies of photographs _____ | <input type="checkbox"/> Original rental invoice number _____ |
| <input checked="" type="checkbox"/> Original Tax-invoice number TP05181039 | <input type="checkbox"/> police result _____ |
| <input checked="" type="checkbox"/> SAS / AS & IS / police report | <input checked="" type="checkbox"/> Vehicle search result _____ |
| <input type="checkbox"/> Certificate Of Insurance | <input type="checkbox"/> _____ |
| <input checked="" type="checkbox"/> Authorisation To Act | |

*Survey under insurance instruction - LKK

a)	Cost of repair (inclusive GST)	\$ 1,819.00
b)	Survey fees / Photographs as per request	\$
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ 7.49
d)	Loss of hire / use / rental / earnings / rental fees [\$100 x 2 days]	\$ 200.00
e)	Scene photographs	\$
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$
g)		\$
Total		\$ 2,026.49

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@timotor.com.sg

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 24 October 2018 2:24 PM
To: 'victor139@yahoo.com.sg'
Subject: Our Ref: CC6/AIG18009408/Upa3; Your Veh: SJQ 6209T
Attachments: Picture from OI GIA REPORT.pdf; P5230153.JPG; P5230155.JPG; P5230156.JPG; P5230157.JPG; P5230158.JPG; P5230164.JPG; P5230165.JPG; P5230166.JPG; P5230167.JPG; P5230168.JPG

Importance: High

Our Ref: CC6/AIG18009408/Upa3
Your Veh: SJQ 6209T

Dear Mr Lim Victor,

ROAD TRAFFIC ACCIDENT INVOLVING SJQ 6209T AND SJJ 3971G ON 08.05.2018

We refer to the above matter and our tele conversation.

Apologies for late reply on this matter. As spoken over the phone, We attached herewith a copy of some survey photo for your kind attention.

We also attached herewith a copy of the photo from your GIA report for your easy reference.

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this E-mail.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Poh Kin, Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, ^{binfe} Azli Ibrahim ("the third party claimant")
of BK 249 #04-370 Bishan St 22 (570249) (address),
owner of SJJ39714 (vehicle no.) hereby authorize
TAN UM MOTOR PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJJ39714 that was
damaged pursuant to the accident which occurred on 08-05-2018 (date) along
ANK AVE 3 NEAR BUS STOP (location)
involving vehicle no/s SJQ6209T ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 19-th day of MAY (month) 20 18 (year)

Azli Ibrahim
Signed by "the third party claimant"

[Signature]
Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Tan Lim Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,819.00 (Repair Cost), S\$120.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SJJ 3971G that was damaged pursuant to the accident which occurred on 08/05/2018 (date) along Ang Mo Kio Avenue 3 (location) involving vehicle no/s SJQ 6209T. This is pursuant to the inspection conducted on 23/05/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner Azlita Binte Ibrahim ("the third party claimant") of vehicle no. SJJ 3971G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJJ 3971G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 (day) of November (month) 2018 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

TAX-INVOICE
NUMBER: TP0518/059

(Please quote our reference number TP025052018 for payment)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Azlita Binte Ibrahim

Date: 30/05/2018

Vehicle No: **SJT3971G**
Model: **MAZDA 3**

Description	Amount
To lump sum repair as recommended by surveyor.	\$1,700.00

Sub Total	\$1,700.00
Add 7% GST	\$119.00
Total	\$1,819.00


Tan Lim Motor Pte Ltd

No. 51 Defu Lane 10 Singapore 639216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

Enquire Vehicle & Owner Information (Vehicle No. SJQ6209T As At 08 May 2018 / 11:05:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: TLM(CAYMENT)SJJ3971G

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7228439I
Owner Name: LIM HOCK HOON, JENNY (LIN FUYUN, JENNY)
Registered Address Type: HDB / HUDC
Registered Block/House No.: 771
Registered Street Name: YISHUN AVENUE 3
Registered Unit No.: # 03 - 243
Registered Building Name: -
Registered Postal Code: 760771

Current Vehicle Details

Vehicle No.: SJQ6209T
Make Description/Model: MITSUBISHI / LANCER 1.6 A
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018 Edit Reg		23 May 2018 00:00 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LIM HOCK HOON JENNY (LIM FUYUN JENNY) , ID: S72284391								
Main Claimant:	AZLITA BINTE IBRAHIM , ID: S7025562F								
Vehicle Reg. No.:	SJJ3971G	Date of Loss:	08/05/2018 00:00 ~ :59 [115 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2734728556SG	Policy/Cover Note No.:	2100137478 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJQ6209T	Policy No. (Claimant):	SD17V10268/VPA/R00(COMP)						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, S39216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-ID] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/06/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJJ3971G (2734728556SG)
[SJQ6209T]
TP
AZLITA BINTE IBRAHIM
May 8 2018 12:00AM
[LIM HOCK HOON JENNY (LIM FUYUN JENNY)]
Tan Lim Motor Pte Ltd

Upload Documents
Upload Photos
Compose New Letter
Upload Video
Upload Audio

View View in Browser

Letters/Correspondences

1 per page v ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Photos/Images

3 per page v ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 17:29	Chassis Number	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	23/05/18 17:29	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	23/05/18 17:29	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	15/11/18 09:03	Reinspection Photo- after repair	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	15/11/18 09:03	Reinspection Photo- after repair	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	15/11/18 09:03	Reinspection Photo- after repair	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	15/11/18 09:03	Reinspection Photo- after repair	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/05/18 15:20	TP ESTIMATE - MARKED		Load PDF
2	26/05/18 15:20	TP GIA REPORT		Load PDF
3	15/11/18 13:04	LETTER TO OI		Load PDF
4	28/11/18 10:05	WORKSHOP INVOICE		Load PDF
5	28/11/18 10:05	AUTHORISATION TO ACT FORM		Load PDF
6	28/11/18 10:05	Release Voucher		Load PDF
7	28/11/18 10:05	LTA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/05/18 11:41	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJQ6209T (Insd veh)	Model:	MAZDA 3 1.6 SP (A)
	SJJ3971G (TP veh)		
Date of Accident:	08/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,936.79
Final Repair Cost	:	\$	1,819.00
Loss of Use	:	\$	120.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,946.49

2.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 1,946.49
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

28 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18009408/UPA3Q2

Date: 28/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100137478
Claimant Vehicle No : SJJ3971G **Insured Vehicle No :** SJQ6209T
 Date of Loss: 08/05/2018 Nature of Claim: TP Claim No: 2734728556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ3971G**
 Make & Model: MAZDA 3, 1.6 SP (A) Engine No: Z6723649
 Reg. Date: 11/09/2008 (Man. Year: 2008) Chassis No: JM6BK106280429556
 Colour: Grey Odometer: 197857 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,418.40	1,367.20	2,051.20	60.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	780.00	1,350.00	63.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,548.40	2,147.20	3,401.20	61.30
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	5,548.40	1,700.00	3,848.40	69.36
+ GST 7.00/7.00% (S\$)	388.39	119.00	269.39	69.36
Nett Amount (S\$)	5,936.79	1,819.00	4,117.79	69.36
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,946.49		

INSPECTION

Date of Assignment: 23/05/2018
 Date Inspected: 23/05/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID MAZDA BADGE	Not Necessary	28.00 FL	*- FL
2	1		*BOOTLID 3 BADGE	Not Necessary	22.00 FL	*- FL
3	1		*BOOTLID SP BADGE	Not Necessary	42.00 FL	*- FL
4	1		*BOOTLID CENTRE EMBLEM BADGE	Not Necessary	59.00 FL	*- FL
5	1		*REAR BUMPER	Dented / Torn	862.00 FL	*862.00 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	134.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	404.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER	Necessary	82.00 FL	*82.00 FL
9	2		*REAR BUMPER SIDE HOLDER	Not Necessary	40.00 FL	*- FL
10	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
11	2		*REAR LICENCE LAMP	Not Necessary	488.00 FL	*- FL
12	1		*REAR END PANEL	Repair	385.00 FL	*- FL
13	1		*REAR END PANEL INNER TRIM	Not Necessary	187.00 FL	*- FL
14	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
15	1		*SET REAR BUMPER SIDE LIP	Torn	700.00 FS	*380.00 FS
16	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	3,973.00	1,564.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	554.60	196.80
Total Parts (\$\$)	3,418.40	1,367.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	20.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	60.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	250.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	400.00
Gross Labour Cost (S\$)			2,130.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >