



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SJQ6209T

Date of Accident : 08 May 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Azlita Binte Ibrahim

Date : 21 May 2018

Confirmed
with Maras
By Mr Tan
23.05.2018

not Akul
L/S #1700
23/5/18
Take photo after repair

Estimate To Repair SJJ3971G - MAZDA 3 SP

Chassis No : JM6BK106280429556

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid mazda badge 11	\$ 28.00
02	1 pc	bootlid 3 badge 11	\$ 22.00
03	1 pc	bootlid sp badge 11	\$ 42.00
04	1 pc	bootlid centre emblem badge 11	\$ 59.00
05	1 pc	rear bumper 10/10.1	\$ 862.00
06	2 ps	rear bumper reflector @ \$67.00 11	\$ 134.00
07	1 pc	rear bumper reinforcement 11	\$ 404.00
08	2 ps	rear bumper side retainer @ \$41.00 11	\$ 82.00
09	2 ps	rear bumper side holder @ \$20.00 11	\$ 40.00
10	8 ps	rear bumper clip @ \$5.00 11	\$ 40.00
11	2 ps	rear licence lamp @ \$244.00 11	\$ 488.00
12	1 pc	rear end panel R	\$ 385.00
13	1 pc	rear end panel inner trim 11	\$ 187.00
Less 20 %			\$ 2,773.00
			\$ 554.60
			\$ 2,218.40
<u>SPECIAL NETT ITEMS</u>			
14	1 set	rear bumper parking sensor 8 hub	\$ 450.00
15	1 set	rear bumper side lip 11	\$ 700.00
16	1 pc	rear licence plate 11	\$ 50.00
			\$ 1,200.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 11 120.00
02		To check electrical lighting concerned.	\$ 40.00
03		To reinstall of rear bumper parking sensor.	\$ 150.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 120.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same	\$ 800.00
06		Putty and spray painting of the affected portion	\$ 900.00
			\$ 2,130.00
Total			\$ 5,548.40

Acknowledged by Repairer

Signature: