

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHCILE NO: GZ 1200M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not followed
rule
4/5 \$4000
427.

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE	27/Bent \$1,645.10
1 PCS	TAILGATE 'TOYOTA' STICKER	ME \$215.00
2 PCS	TAILGATE LOCK LATCHES @\$119.30	MS Bent \$238.60 1PC
1 PCS	TAILGATE LOWER MEMBER	27/Bent \$545.10
1 PCS	TAILGATE 'DYNAL' STICKER	NF \$45.50 X
2 PCS	TAILGATE LOWER 'L' PANELS @\$90.50	MS Bent \$181.00 1PC
2 PCS	TAILGATE LOWER 'L' PANEL STOPPERS @\$62.30	17 \$124.60 X
2 PCS	TAILLAMPS @\$285.30	ONE \$570.60
2 PCS	TAILLAMP BRACKETS @\$119.20	Two/Bent \$238.40
1 PCS	REAR LICENCE PLATE BRACKET	Bent \$119.50
1 PCS	REAR SPARE TYRE BRACKET & CHAIN	17 \$392.40 X
1 PCS	REAR EXHAUST PIPE	17 \$585.20 X
1 PCS	REAR EXHAUST PIPE MOUNTING	17 \$112.00 X
1 PCS	REAR CENTRE CROSS MEMBER	17 \$845.20 X
1 PCS	REAR LICENCE PLATE INNER 'L' BRACKET	17 \$115.50 X
		\$5,973.70
	S.NETT	3543.8 2657.6
1 PCS	TAILGATE '70KM/H' STICKER	ME \$20.00 10
1 PCS	TAILGATE '13 PAX' STICKER	ME \$20.00 10
1 PCS	TAILGATE INNER ALUMINIUM PLATE	Bent \$680.00 600
1 SET	TAILGATE INNER ALUMINIUM PLATE RIVETS	ME \$50.00
1 PCS	REAR LICENCE PLATE	Bent \$20.00 14
1 SET	REAR REVERSE SENSOR	NF \$280.00 X
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 30
	TO DISMENTLE & REPLACING REVERSE SENSOR	17 \$80.00 X
	TO DISMENTLE & REPLACING REAR EXHAUST	17 \$100.00 X
	TO SPRAY RUST PROOFING	\$100.00 50
	TO STRAIGHTEN REAR CHASSIS FRAME	17 \$680.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,000.00 880
	TO PUTTY & SPRAY PAINTING	\$1,200.00 700
	TOTAL	\$10,283.70

(25%)

5021.62