

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **21.05.2018**

Accident Date : **13.05.2018**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Axio" Reg. No. SLB4603G Claiming Against Your Insured Reg. No. SGZ6051T		
1pc	Front Door RH	3.80	Repair 1,186.00
1pc	Front Door Sticker		new 76.00
12pcs	Front Door Inner Trim Board Clips		new 45.60
1pc	Front Fender RH		Repair 789.00
			2,096.60
	Less 25%		524.15
			1,572.45
1pc	Front Door Visor		X 180.00 SN
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		60 150.00
	To Dismantle / Repair Front O/S Wheel Rim		60 100.00
	To Conduct Computerize Wheel Alignment Test		60 80.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60 100.00
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, and Parts Replacement		300 450.00
	To Respray Affected Areas		400 500.00
	Total :		3,132.45

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
HP 96010068
4 days
P/P
22/05/18 @ 1525
Resurvey by paint