

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III18009416/GHA3S2**Date:** 12/07/2018REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SGY8883B	Insured Vehicle No :	SHC3362A
Date of Loss:	18/05/2018	Nature of Claim:	TP
		Claim No:	MCT18050498

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY8883B		
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Engine No:	27186030082767
Reg. Date:	29/10/2010 (Man. Year: 2010)	Chassis No:	WDD2120472A245702
Colour:	Silver	Odometer:	239728 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,260.60	3,410.10	850.50	19.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	1,060.00	380.00	26.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,700.60	4,470.10	1,230.50	21.59
+ GST 7.00/7.00% (S\$)	399.04	312.91	86.13	21.58
Nett Amount (S\$)	6,099.64	4,783.01	1,316.63	21.59

INSPECTION

Date of Assignment:	22/05/2018	
Date Inspected:	23/05/2018	Inspected At: 160 SIN MING DRIVE #04-01
Estimated Period of Repair:	5.0 days	Repairer: Lai Huat (Meng Kee) Motor Pte Ltd

Adjuster: XING GUO QIANG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/12/2018

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1050.50 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2018)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY8883B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR WING MIRROR LH	Cut	914.00 FN	*914.00 FN
2	1		*FRONT DOOR WING MIRROR COVER LH	Cracked	380.00 FN	*380.00 FN
3	1		*FRONT FENDER LH	Buckled	950.00 FN	*950.00 FN
4	1		*FRONT FENDER CHROME MOULDING LH	Necessary	55.00 FN	*55.00 FN
5	1		*FRONT FENDER BLUE EFFICIENCY EMBLEM	Necessary	60.00 FN	*60.00 FN
6	1		*FRONT SPORT RIM LH (ORIGINAL)	Cut	770.00 FN	*770.00 FN
7	1		*FRONT CONTROL ARM LH	*Check	480.00 FN	*- FN
8	1		*FRONT LOWER ARM LH	*Check	465.00 FN	*- FN
9	1		*FRONT WHEEL BEARING WITH HUP LH	Necessary	660.00 FN	*660.00 FN
					Sub Total (\$\$)	4,734.00 3,789.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	473.40 378.90
					Total Parts (\$\$)	4,260.60 3,410.10

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT (COMPUTERISED)	New	80.00	60.00
2	TO DISMANTLE AND RENEW FRONT LOWER ARM + CONTROL ARM RH. (*Check)	New	200.00	0.00
3	TO REMOVE AND REFIX SIDE SKIRT RH.	New	60.00	50.00
4	TO STRAIGHTEN BODY, TO REPAIR FRONT BUMPER AND RENEW OF PARTS.	New	450.00	350.00
5	TO SPRAY PAINT.	New	650.00	600.00
Gross Labour Cost (S\$)			1,440.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >