

来發 (明 记) 嘛 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No : EST0019365
Yeo Hsiu Shen Clement

Page : 1 of 2
Your ref. : TP-SHC 3362A India
Job No. : 69505
Our ref. : 18.05.31
Payment :
Date : 22/5/2018

Attn :

Vehicle No : SGY 8883B
Vehicle Model : Mercedes Benz E250
Accident on : 18/5/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front door wing mirror LH / <i>Cut</i>	914.00	10.00	822.60
1.00	Pc	Front door wing mirror cover LH / <i>CRA</i>	380.00	10.00	342.00
1.00	Pc	Front fender LH / <i>Buc</i>	950.00	10.00	855.00
1.00	Pc	Front fender chrome moulding LH / <i>MC</i>	55.00	10.00	49.50
1.00	Pc	Front fender Blue Efficiency emblem / <i>MC</i>	60.00	10.00	54.00
1.00	Pc	Front sport rim LH(Original) / <i>Cut</i>	770.00	10.00	693.00
1.00	Pc	Front control arm LH ?	480.00	10.00	432.00
1.00	Pc	Front lower arm LH ?	465.00	10.00	418.50
1.00	Pc	Front wheel bearing with hup LH / <i>MC</i>	660.00	10.00	594.00
Labour & Misc:					
1.00		To check wheel alignment (computerised)	80.00	<i>60</i>	80.00
1.00		To dismantle and renew front lower arm + control arm RH	200.00	<i>?</i>	200.00
1.00		To remove and refix side skirt RH	60.00	<i>50</i>	60.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No : EST0019365
Yeo Hsiu Shen Clement

Page : 2 of 2
Your ref. : TP-SHC 3362A India
Job No. : 69505
Our ref. : 18.05.31
Payment :
Date : 22/5/2018

Attn :

Vehicle No : SGY 8883B
Vehicle Model : Mercedes Benz E250
Accident on : 18/5/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To straighten body, to repair front bumper and renew of parts	450.00	350	450.00
1.00		To spray paint	650.00	600	650.00

GuoQiang - 8288 0282
part by part.
before paint photos.
5 Days.
22/5/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total 5,700.60
GST 7.00% 399.04
Total S\$ 6,099.64

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."