

AIGAsia Insured's Veh No : SLN2252K
Date of Accident : 26 April 2018

not Alvin
13/5/18
487.745.2
13/5/18
487.745.2



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Sam Lain Equipment Services Pte Ltd

Date : 11 May 2018

Estimate To Repair YK1902L - Mitsubishi Fuso FK617JJ

Chassis No : FK617JA00164

REQ: 13/05/18 C15186
LEA - M4C5

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front bumper <i>Real</i>	\$ 975.48
02	1 pc	left side lamp <i>cm</i>	\$ 140.62
03	1 pc	left headlamp garnish <i>cm</i>	\$ 85.00
04	1 pc	left front indication lamp <i>cm</i>	\$ 232.00
05	1 pc	left front corner panel <i>2x</i>	\$ 366.65
06	1 pc	left front door <i>20/Real</i>	\$ 2,646.37
07	1 pc	left front door marker lamp <i>3x</i>	\$ 81.22
08	1 pc	left front door hinge bottom <i>1x</i>	\$ 315.77
09	1 pc	left front door weatherstrip <i>1x</i>	\$ 361.11
10	1 pc	left front door step garnish <i>2x</i>	\$ 666.67
11	1 pc	left front door step plate <i>CRQ</i>	\$ 265.80
12	1 pc	left front door hinges top <i>1x</i>	\$ 315.77
13	1 pc	left front wheel mudguard <i>2x</i>	\$ 424.63
14	1 pc	left front wheel mudguard aluminium plate <i>1x</i>	\$ 359.80
			\$ 7,236.89
		Less 25 %	\$ 1,809.22
			\$ 5,427.67
		SPECIAL NETT ITEMS	
15	1 pc	left front door corporate logo sticker <i>Real 150</i>	\$ 250.00
			\$ 250.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
04		Putty and spray painting of the affected portion.	\$ 880.00
			\$ 1,920.00
		Total	\$ 7,597.67

Total

the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-3812.12
252
2-2889.09
S.N-637.74
4416.83
3833.40

5025.2

X

X

X

X

X

X

20

50

450

400