



22/6/2018

PAGE 1/2

(C)

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: TAULIKH (LKK)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 12 DAYS.

Customer: WZ1007 / INDIA INTERNATIONAL
Chassis No: JHMRU1810GX202899
License No: SLR7772Y
Mileage: 21627
Engine No: L15B4532899

Document No: SVO18030003
Printed By: JESHURUEBEN
Order Date: 24. May 2018
Order Time: 12:08:58 PM
Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70539) OWNER: EMILIA BTE ABU BAKAR OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 22/5/18 SURVEYED BY: TAULIKH DATE: 24/5/18 @11.20AM REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHC 3092D						
66100-T7A-300ZZ	PANEL COMPRR.	1	365.70	25	274.27	19.20	293.47
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1	662.20	25	496.65	34.77	531.42
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	60.20	25	45.15	3.16	48.31
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	144.70	25	108.52	7.60	116.12
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21
34150-T7A-J01	LIGHT ASSY,R.LID	1	264.60	25	198.45	13.89	212.34
74440-T7A-003	WEATHERSTRIPTAILGATE	1	96.80	25	72.60	5.08	77.68
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	34.51
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31
33502-T7A-J01	LAMP UNITR.	1	428.70	25	321.52	22.51	344.03
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
74800-T7A-J02	LOCK ASSYTAILGATE	1	76.60	25	57.45	4.02	61.47
74820-T7A-003	STAY ASSYR.TAILGATE OPEN	1	92.10	25	69.07	4.83	73.90
74870-T7A-003	STAY ASSYL.TAILGATE OPEN	1	92.10	25	69.07	4.83	73.90
	SUM PARTS:				2,903.17	203.21	3,106.38
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BOJSE	0672 BODY JOINT SEALANT.	1	100.00		200.00	14.00	214.00
BOBC	0672 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	0672 APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00		80.00	5.60	85.60



22/6/18

PAGE 2/2

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	WZI007 / INDIA INTERNATIONAL	Document No:	SVO18030003			
Chassis No:	JHMRU1810GX202899	Printed By:	JESHURUEBEN			
License No:	SLR7772Y	Order Date:	24. May 2018			
Mileage:	21627	Order Time:	12:08:58 PM			
Engine No:	L15B4532899	Service Advisor:	LIEW THYE WEI			
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	280.00	280.00	19.60	299.60
BMF00D	EXT-YJ RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	160.00	160.00	11.20	171.20
BMI02D	EXT-YJ REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	280.00	280.00	19.60	299.60
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00	120.00	8.40	128.40
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50
BOMISC1	EXT-YJ REMOVE, REPLACE AND INSTALL SMART ENTRY SENSOR. RESET MEMORY.	1	280.00	280.00	19.60	299.60
BKRP02B	EXT-YJ CUT OFF & RENEW RR FLOOR & RR PANEL. STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	3,975.00	3,975.00	278.25	4,253.25
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,700.00	2,700.00	189.00	2,889.00
			SUM LABOUR:	8,885.00	621.95	9,506.95
			TOTAL SGD	11,788.17	825.16	12,613.33
			Total Payable (SGD)	12,613.33		

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT18002560	Page	1
Registration No	: SLR7772Y	Date	: 22. Jun 2018		
Chassis No	: JHMRU1810GX202899	Customer No.	: WZI007		
Model	: HRV DX-SIN CVT YM 2016	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: EMILIA BINTE ABU BAKAR	Engine No	: L15B4532899		
Ins Policy No.	:	Date Time	: 22. Jun 2018 9:39:02 AM		
Date of Accident	: 22/5/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	SUPPLEMENTARY ITEM, PARTS & LABOUR						
	TP DIRECT SETTLEMENT (J/NO: 70539)						
	OWNER: EMILIA BTE ABU BAKAR						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 22/5/18						
	SURVEYED BY: TAULIKH						
	DATE: 24/5/18 @11.20AM						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHC 3092D						
74820-T7A-003	STAY ASSYR.TAILGATE OPEN	1	92.10	25	69.07	4.83	73.90
74870-T7A-003	STAY ASSYL.TAILGATE OPEN	1	92.10	25	69.07	4.83	73.90
					Sum Item	138.14	9.66
							147.80

Survey By	_____						
Date & Time	_____				Total Amount	138.14	9.66
Excess	_____				Total (Inclusive of GST)		147.80
Status	_____						
Signature	_____						

Printed on 22/6/2018 9:46:45 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)