

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLR7772Y

Chassis No : JHMRU1810GX202899

Model : HRV DX-SIN CVT YM 2016

Owner's Name : EMILIA BINTE ABU BAKAR

Ins Policy No. :

Date of Accident : 22/5/2018

Document No. : SQT18002078

Date : 22. May 2018

Customer No. : WZ1007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4532899

Date | Time : 22. May 2018 2:33:30 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: EMILIA BTE ABU BAKAR						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 22/5/18						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHC 3092D						
66100-T7A-300ZZ	PANEL COMPRR.	1 <i>bt</i>	365.70	25	274.27	19.20	293.47
04655-T7A-310ZZ	PANEL SETRR.FLOOR	1 <i>bt</i>	662.20	25	496.65	34.77	531.42
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1 <i>net</i>	60.20	25	45.15	3.16	48.31
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1 <i>net</i>	144.70	25	108.52	7.60	116.12
65540-T7A-310ZZ	STIFFENER COMPR.RR.FRAME UPP	1 <i>?</i>	103.20	25	77.40	5.42	82.82
65590-T7A-310ZZ	STIFFENER COMPL.RR.FRAME UPP	1 <i>?</i>	103.20	25	77.40	5.42	82.82
65590-T7A-310ZZ	STIFFENER COMPL.RR.FRAME UPP	1 <i>?</i>	103.20	25	77.40	5.42	82.82
65662-T7A-300ZZ	FRAME B,L,RR.	1 <i>?</i>	62.40	25	46.80	3.28	50.08
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1 <i>net</i>	19.30	25	14.47	1.01	15.48
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	1 <i>net</i>	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1 <i>net</i>	8.30	25	6.22	0.44	6.66
76711-T6A-003	CAPPIVOT	1 <i>net</i>	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD	4 <i>net</i>	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2 <i>net</i>	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2 <i>net</i>	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1 <i>net</i>	60.00		60.00	4.20	64.20
68100-T7A-J20ZZ	TAIL GATE COMP	1 <i>bt</i>	838.90	25	629.17	44.04	673.21
74440-T7A-003	WEATHERSTRIPTAILGATE	1 <i>de</i>	96.80	25	72.60	5.08	77.68
74800-T7A-J02	LOCK ASSYTAILGATE	1 <i>?</i>	76.60	25	57.45	4.02	61.47
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1 <i>x</i>	103.20	25	77.40	5.42	82.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLR7772Y

Chassis No : JHMRU1810GX202899

Model : HRV DX-SIN CVT YM 2016

Owner's Name : EMILIA BINTE ABU BAKAR

Ins Policy No. :

Date of Accident : 22/5/2018

Document No. : SQT18002078 Page 2

Date : 22. May 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4532899

Date | Time : 22. May 2018 2:33:30 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1 <i>del</i>	43.00	25	32.25	2.26	34.51
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING	1 <i>X</i>	144.20	25	108.15	7.57	115.72
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING	1 <i>X</i>	144.20	25	108.15	7.57	115.72
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1 <i>X</i>	186.00	25	139.50	9.77	149.27
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1 <i>X</i>	126.90	25	95.17	6.66	101.83
84431-T7A-J01ZA	LINING ASSYTAILGATE	1 <i>?</i>	133.40	25	100.05	7.00	107.05
84485-T7A-J01ZA	LINING ASSYL.TAILGATE SIDE	1 <i>X</i>	20.90	25	15.67	1.10	16.77
84435-T7A-J01ZA	LINING ASSYR.TAILGATE SIDE	1 <i>X</i>	20.90	25	15.67	1.10	16.77
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER	1 <i>X</i>	58.10	25	43.57	3.05	46.62
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH	1 <i>?</i>	172.10	25	129.07	9.03	138.10
74450-T7B-003	PROTECTOR,L,RR.WHEEL ARCH	1 <i>?</i>	172.10	25	129.07	9.03	138.10
75722-T7W-A01	EMBLEMRR.	1 <i>del</i>	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1 <i>del</i>	14.10	25	10.57	0.74	11.31
18307-T7A-901	SILENCER COMPEXHUAST	1 <i>X</i>	528.00	25	396.00	27.72	423.72
74605-T7A-000	PLATESILENCER BAFFLE	1 <i>X</i>	24.70	25	18.52	1.30	19.82
34100-T5A-003	LIGHT ASSYLICENSE	2 <i>del</i>	31.20	25	46.80	3.28	50.08
33502-T7A-J01	LAMP UNITR.	1 <i>del</i>	428.70	25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL.	1 <i>X</i>	428.70	25	321.52	22.51	344.03
34150-T7A-J01	LIGHT ASSY,R.LID	1 <i>del</i>	264.60	25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSYL.LID	1 <i>X</i>	264.60	25	198.45	13.89	212.34
75701-T5A-000	EMBLEMH	1 <i>del</i>	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2 <i>del</i>	1.90	25	2.85	0.20	3.05
38387-TZ5-A01	ANTENNA ASSYL.F.	1 <i>?</i>	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART	1 <i>?</i>	59.30	25	44.47	3.11	47.58
71501-T7B-000	FACE RR.BUMPER	1 <i>del</i>	762.60	25	571.95	40.04	611.99
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1 <i>X</i>	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1 <i>X</i>	92.30	25	69.22	4.85	74.07
33505-T7A-J01	REFLECTOR ASSYR.RR.	1 <i>X</i>	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR.	1 <i>X</i>	151.80	25	113.85	7.97	121.82
71593-T7A-000	SPACERR.RR.BUMPER SIDE	1 <i>del</i>	11.50	25	8.62	0.60	9.22

Printed on 22/5/2018 2:58:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLR7772Y

Chassis No : JHMRU1810GX202899

Model : HRV DX-SIN CVT YM 2016

Owner's Name : EMILIA BINTE ABU BAKAR

Ins Policy No. :

Date of Accident : 22/5/2018

Document No. : SQT18002078 Page 3

Date : 22. May 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4532899

Date | Time : 22. May 2018 2:33:30 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					5985.15	418.99	6,404.14
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	BODY JOINT SEALANT.	2	100.00		200.00	14.00	214.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00		280.00	19.60	299.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	180.00		180.00	12.60	192.60
BMU30R	RMOVE & REPLACE EXHAUST SYSTEM.(N)	1	160.00		160.00	11.20	171.20
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	360.00		360.00	25.20	385.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BOMISC1	REMOVE, REPLACE AND INSTALL SMART ENTRY SENSOR.	1	560.00		560.00	39.20	599.20
BKRP02B	CUT OFF & RENEW RR FLOOR & RR PANEL. STRAIGHTEN	1	5600.00		5600.00	392.00	5992.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3800.00		3800.00	266.00	4066.00
Sum Labor					12170.00	851.90	13,021.90

Survey By Tanjith 97495749 / 62563561

Date & Time 24/5/18 @ 1120

Excess 12 days.

Status WP

Signature [Signature]

Total Amount 18,155.15 1,270.89 19,426.04

Total (Inclusive of GST) **19,426.04**

Resurvey before paint
sup @ 1hr/amb.com

Printed on 22/5/2018 2:58:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLR7772Y

Chassis No : JHMRU1810GX202899

Model : HRV DX-SIN CVT YM 2016

Owner's Name : EMILIA BINTE ABU BAKAR

Ins Policy No. :

Date of Accident : 22/5/2018

Document No. : SQT18002078 **Page** 4

Date : 22. May 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4532899

Date | Time : 22. May 2018 2:33:30 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Printed on 22/5/2018 2:58:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)