



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co. Reg No : 199405410K

GST Reg No : NR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR ARSHID BIN ABDULLAH	Cust No/Name /MR ARSHID BIN ABDULLAH
BLK 756	Reg No/Reg Date SFZ2424P / 27/05/201
JURONG WEST STREET 74	Date In/Mileage / 0
SINGAPORE 640756	Chassis No KNAFX411MG5596563
Contact No Mobile: 96951204	Engine No G4FGGH612122
	Make/Model KIA/FORTE K3 1.6 A EX BF4
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	14/05/2018/ 09:10	QUE	261 / Edwin Caina	28493			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2200 3300.00
RENEW & RE-ALIGN RR ACCIDENT DAMAGED PORTION:								
RENEW RR FENDER RH & RR BUMPER								
REPAIR RR WHEELHOUSE PNL RH								
E PNT98000								1470 2520.00
RESPRAY RR BUMPER , RR BUMPER AIRDAM , RR FENDER RH , RR WHEELHOUSE RH								
& RR DOOR RH								
M SUNDRY								✓ 50.00
RENEW RHR SPORT RIM & TRANSFER TYRE								
M SUNDRY								ut 380.00
SUPPLY RHR SPORT RIM								
E PNT88000								200 250.00
REMOVE & REFIT SPARETYRE BOARD, TRIM, CARPET & SEAT TO FACILITATE REPAIR								
A 54900099								30 50.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								200 300.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								120 150.00
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment								100 200.00
M SUNDRY								
APPLY ANTI CORROSION & BODY SEALEANT ON AFFECTED AREAS								
E PNT88000								✓ 250.00
REMOVE & REFIT RR WINDSCREEN GLASS								
E PNT88000								80 100.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								✓ 80.00
SUPPLY WINDSCREEN SEALANT								
M SUNDRY								20 50.00
Sundries								
M PANEL ASSY-QUARTER OUTER, RH					1.00	1133.00	00.00	bt 1133.00
M GUARD ASSY-REAR WHEEL, RH					1.00	75.00	00.00	75.00
M COVER-RR BUMPER, LWR					1.00	234.00	00.00	R 234.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR ARSHID BIN ABDULLAH BLK 756 JURONG WEST STREET 74 SINGAPORE 640756 Contact No Mobile: 96951204	Cust No/Name /MR ARSHID BIN ABDULLAH Reg No/Reg Date SFZ2424P / 27/05/201 Date In/Mileage / 0 Chassis No KNAFX411MG5596563 Engine No 64FGGH612122 Make/Model KIA/FORTE K3 1.6 A EX BF4 Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	14/05/2018/ 09:10	QUE	261 / Edwin Caina	28493
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GUARD-BUMPER REAR, RH		1.00	17.00	00.00	17.00
M BRACKET-RR BUMPER SIDE MTG, RH		1.00	33.00	00.00	33.00
M LAMP ASSY-REAR COMBINATION, RH		1.00	788.00	00.00	788.00
M MOULDING-REAR WINDOW GLASS		1.00	27.00	00.00	27.00
M STOPPER-RR WINDOW GLASS		2.00	4.00	00.00	8.00
M PAD-WINDSHIELD GLASS		8.00	2.00	00.00	16.00
P COVER-RR BUMPER		1.00	768.00	00.00	768.00

# Estimate

SURVEYOR NAME:

Taufik 97495749

SURVEYOR SIGNATURE:

DATE:

25/5/18

01140 WP

REMARKS:

Resurvey before paint  
sur @ khentokam

7 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

7% GST on	Nett 10,779.00	10,779.00
		754.53
	<b>Total Payable</b>	<b>11,533.53</b>

Authorized signatory and company stamp

Acknowledged by Repairer

Validity of this estimate is 14 days from date of quote. This is a computer generated document; no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.