

ISS. REC. BY:

REF

CS/A1618009125/RI-td3

Special Instruction:

Surveyor:

Mullin

ASSIGNMENT (Office)

From (Person):

Chan Yoke Shi

of

AIG

Date/Time:

04/5/2018 @ 9:29am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCY 40S

Insured:

SDR 96185

at Workshop m/i:

King's Auto

Tel:

6457 8629

of

Blk 176 Sin Ming Drive # 02-10

Policy No:

0100483168

Claim No:

488404785754.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/05/2018

CA / REV / REP. / REV 24 HRS

Lup

H.O.D. Endorsement:

Date/Time:

9:39am 02/5/18

Person Contacted:

Ms. Ng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SCY 40S - X

SDR 96185 - X

lump sum \$4300+ (Red: 2759.40, 397.0)

ASSIGNMENT

From: Date: 21/5/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SCY 40S
at Workshop m/s King's Auto
of BIK 176 Bin Ming Drive # 02-10

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / up

Date: Person Contacted

Vehicle: IN / OUT

Veh No: SCY 40S Yr Regn: 2014 / PG3

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: LAMBORGHINI 3.0 c.c. 2593

Colour: BROWN A/C: Insured / Std / NI / NA

Sp Reading: 08 2241 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SALLAAAG5DA680768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55 R 19

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/05/18 D.O.I. 30/05/18

Survey held at KING'S AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 OCT 2018

Date/Time. File Pass to?

☐ : Prel. Report

11/10 Typist

☒ : Final Report

Date/Time. File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1 S - RS 1 S

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$ 4300/-)

TOTAL

- Pre repair inspection request - SCY40S VS SDR9618S (OI) DOA: 22/05/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKAUTO.COM, admin-a@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Supramaniam, Darshene; Lim, Sheng Yang
Sent: 24/5/2018 9:29:10 AM
Attachments:  [img-573154651.pdf](#)

Hi,

Please refer to the enclosed request from **Kuru & Co.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign MA CHIN FOOK as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Thursday, May 24, 2018 9:25 AM
To: Lim, Sheng Yang
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDR9618S AND SCY40S ON 22/05/2018

We refer to your email of 23.05.18.

Our client is agreeable to the following surveyor as the SJE: **MA CHIN FOOK/LKK AUTO CONSULTANTS PTE LTD**

Please arrange for your surveyor to survey our client's vehicle at the following address:

KING'S AUTO AIR-CONDITIONING SERVICE
Blk 176 Sin Ming Drive
#02-10 Sin Ming Autocare
Singapore 575721
Contact: 64578629

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Wednesday, 23 May 2018, 4:39:31 PM SGT, Lim, Sheng Yang <ShengYang.Lim@aig.com> wrote:

Without Prejudice

Your Reference : L18.0836.AT

Our Reference : SDR9618S

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd

Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Wednesday, May 23, 2018 3:52 PM
To: Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran
Subject: Our Ref: L18.0836.AT// Your Ref: SDR 9618S //PRS

Dear Sirs

ACCIDENT INVOLVING SCY 40S & SDR 9618S ON 22.05.2018

ALONG RIVER VALLEY ROAD TOWARDS KIM YAM ROAD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Tan Kok Kheng Galen**, whose vehicle registration number **SCY 40S** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 14:23
Date Of Accident	22/05/2018 19:45
Exact Location Of Accident	RIVER VALLEY RD TO KIM YUAN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCY40S
Insured/Policyholder	
Name Of Registered Owner	TAN KOK KHENG GALEN
NRIC No	S1521894J
Email Address	GALEN.TAN@EFGBANK.COM
Mobile Phone No	(LOCAL) +65-90882626
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	LAND ROVER
Model	DISCOVERY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA298587
Cover Note Number	

Driver

Name of Driver	CHER POH YOKE
NRIC No	S7512505D
Date Of Birth	14/04/1975
Occupation	INDOOR
Date Of Driving Pass	12/02/2000
Driving Experience	18 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97999922
Fax Number	
Contact Number	
Email Address	ANNIECHER@YAHOO.COM.SG

Injuries Sustain

HEAD & NECK

Injured person in which vehicle?

SCY40S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO


Address

Postcode

Sketch Plan Pg. 2

SKETCH PLAN

Date of Accident: 22/5/18 Time: 1955L Location: Petioir Valley Rd & Kim Yew Rd
 My Vehicle A: OCY 403 Vehicle B: SDR 9618S Vehicle C/Others: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) Front vehicle did not turn on "right indicator signal", but suddenly slowed down to turn right.
- 2) I reacted accordingly to avoid a collision and slowed down.
- 3) Spit second later, I was hit on the rear by vehicle SDR 9618S.

() Claim OD/TP at Ah Lim Motor (X) Claim OD/TP at other workshop () Reporting Only

Remarks : Please forward a copy of my efile accident report to:

My workshop : King's Auto
 email address : yanlin13@kstar-1.com
 & myself :
 email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

© All rights reserved. V8

Address	69 ONE TREE HILL #13-71
Postcode	248706
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDR9618S
Vehicle Make/Model/Colour	JAGUAR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM COL LIN BERNADE HE
NRIC/Passport Number	S1548730E
Contact Number	86889119
Address	9 HOLLAND RD
Postcode	249499
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHER POH YOKE
Approximate Age	

KING'S AUTO AIR-CONDITIONING SERVICE

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721

TEL: 6457-8629 FAX: 451-7651

Reg No: 001956/00W

Attn: Denise (Mrs)

Fax: 62564315 (18/7/2018)

62563561

DATE 17th July 2018

OUR REF SCY 40 S

Tan Kok Kheng Galen

TO 69 One Tree Hill

#13-71

Singapore 248706

RE QUOTATION FOR VEHICLE SCY 40 S

Quantity	Item	Unit Price (S\$)	Amount (S\$)
1	Rear Bumper		2,155.89 DE
1	Rear Bumper Centre Garnish		88.00 DE
1	Rear Bumper Top Garnish		199.65 DG
(1pc) /	Rear Bumper Reflector	98.34 CH	196.68 RH X
set	Rear Parking Sensor (set of 4)		334.40 AM
4	Rear Parking Sensor Holder	20.02	80.08 AM
1	Rear Door Lower Garnish		418.00 DG
set	Rear Door Lower Garnish Clips		8.80 AM
1	Rear LH Lamp		1,133.00 X CRA
2	Rear Bumper Bracket	117.15 LH AM	234.30 RH X
2	Rear Bumper Side Holder	152.70 AM	305.58 RH X
1	Rear Bumper Sponge		75.24 X CRA
1	Rear LH Fender Garnish (outer)		181.83 X CRA
set	Rear LH Fender Garnish Clips		22.00 X AM
1	Rear LH Fender inner Shield		188.10 X
SUB-TOTAL			5,621.55
LESS 10% DISCOUNT			562.16
TOTAL			5,059.40

5065.17
10%
4558.65

FOR LABOUR CHARGES

Quantity	Item	Unit Price (S\$)	Amount (S\$)
	Panel Beating		900.00 500
	Spray Painting		900.00 600
	Rustproof		120.00 30
	To check wiring and and installation of parking sensors and lamp		80.00 40
TOTAL			2,000.00

1170

Rashid
Hp 90010068

GRAND TOTAL FOR THIS QUOTATION 7,059.40

4 days
45
25/05/18 @ 1350
Resary after repair

4558.65
1170.00
5728.65
252
4296.48
415 - 4,300

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018 Edit Reg		04 May 2018 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Foo Soo Liang, ID: S1438809E		
Main Claimant:	TAN KOK KHENG GALEN, ID: S1521894J		
Vehicle Reg. No.:	SCY40S	Date of Loss:	22/05/2018 19:00 - :59 [50 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4884047857SG	Policy/Cover Note No.:	0100483168
Vehicle Reg. No. (Insured):	SDR961BS	Policy No. (Claimant):	
		Excess:	
Repairer:	King's Auto Air-conditioning (HQ) Blk 176 Sin Ming Dr #02-10 Singapore 575721, 575721 Sin Ming - Tel: 64578629		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/06/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (05/06/2018): No OI GIA Report
- AIG_SG (05/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCY40S (4884047857SG)
[SDR96185]




































TP
































TAN KOK KHENG GALEN

May 22 2018 7:00PM

[Foo Soo Liang]

King's Auto Air-conditioning

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
2	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
3	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
4	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
5	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
6	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
7	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
8	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
9	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
10	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
11	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
12	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
13	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
14	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
15	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
16	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
17	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
18	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
19	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
20	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
21	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
22	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
23	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
24	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
25	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
26	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
27	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
28	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
29	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
30	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
31	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
32	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
33	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
34	12/10/18 09:55	General View													 Load JPG	<input checked="" type="checkbox"/>		
35	12/10/18 09:55	Reinspection Photo													 Load JPG	<input checked="" type="checkbox"/>		
36	12/10/18 09:55	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
37	12/10/18 09:55	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
39	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
40	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
41	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
42	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
43	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
44	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
45	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
46	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
47	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
48	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
49	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
50	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
51	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
52	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
53	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
54	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
55	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
56	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
57	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
58	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
59	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
60	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
61	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
62	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
63	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
64	12/10/18 09:55	Reinspection Photo		<input checked="" type="checkbox"/>
65	12/10/18 09:56	Reinspection Photo		<input checked="" type="checkbox"/>
66	12/10/18 09:56	Reinspection Photo		<input checked="" type="checkbox"/>
67	12/10/18 09:56	Reinspection Photo		<input checked="" type="checkbox"/>
68	12/10/18 09:56	Reinspection Photo		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18009425/R1TD3Q2

Date: 23/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100483168
 Claimant Vehicle No: SCY40S Insured Vehicle No: SDR9618S
 Date of Loss: 22/05/2018 Nature of Claim: TP Claim No: 4884047857SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCY40S
 Make & Model: LAND ROVER DISCOVERY, 3.0 D TSS SR (A) Engine No: 0731519306DT
 Reg. Date: 26/02/2014 (Man. Year: 2013) Chassis No: SALLAAAG5DA680768
 Colour: Brown Odometer: 82241 km
 Engine Capacity: 2993 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,059.39	4,558.65	500.74	9.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,170.00	830.00	41.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,059.39	5,728.65	1,330.74	18.85
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	7,059.39	4,300.00	2,759.39	39.09

INSPECTION

Date of Assignment: 04/05/2018
 Date Inspected: 30/05/2018 Inspected At: King's Auto Air-conditioning (HQ)
 Blk 176 Sin Ming Dr #02-10 Singapore
 575721
 Singapore 575721
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,155.89 FL	*2,155.89 FL
2	1		*REAR BUMPER CENTRE GARNISH	Deformed	88.00 FL	*88.00 FL
3	1		*REAR BUMPER TOP GARNISH	Deformed	199.65 FL	*199.65 FL
4	1		*REAR BUMPER REFLECTOR	O/S Cracked	196.68 FL	*98.34 FL
5	1		*SET REAR PARKING SENSOR (SET OF 4)	Not Working	334.40 FL	*334.40 FL
6	4		*REAR PARKING SENSOR HOLDER	Necessary	80.08 FL	*80.08 FL
7	1		*REAR DOOR LOWER GARNISH	Deformed	418.00 FL	*418.00 FL
8	1		*SET REAR DOOR LOWER GARNISH CLIPS	Necessary	8.80 FL	*8.80 FL
9	1		*REAR LH LAMP	Cracked	1,133.00 FL	*1,133.00 FL
10	1		*REAR BUMPER BRACKET	N/S Necessary	234.30 FL	*117.15 FL
11	1		*REAR BUMPER SIDE HOLDER	N/S Necessary	305.58 FL	*152.79 FL
12	1		*REAR BUMPER SPONGE	Cracked	75.24 FL	*75.24 FL
13	1		*REAR LH FENDER GARNISH (OUTER)	Cracked	181.83 FL	*181.83 FL
14	1		*SET REAR LH FENDER GARNISH CLIPS	Necessary	22.00 FL	*22.00 FL
15	1		*REAR LH FENDER INNER SHIELD	Serviceable	188.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,621.55	5,065.17
- List Item Discount on L Items 10.00/10.00% (\$\$)	562.16	506.52
Total Parts (\$\$)	5,059.39	4,558.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	500.00
2	SPRAY PAINTING	New	900.00	600.00
3	RUSTPROOF	New	120.00	30.00
4	TO CHECK WIRING AND INSTALLATION OF PARKING SENSORS AND LAMP	New	80.00	40.00
Gross Labour Cost (\$\$)			2,000.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >