

\* SURVEY BY LKK. JUNE 8, 2018 @ 11 AM.



TRANS EUROKARS PTE LTD  
NO:5 UBI CLOSE, SINGAPORE 408605  
ESTIMATE COST OF REPAIRS



not done  
3/6/18  
Tel: 6395 7874

|                                                                                                               |                   |                                                                                                                  |           |                                          |                   |
|---------------------------------------------------------------------------------------------------------------|-------------------|------------------------------------------------------------------------------------------------------------------|-----------|------------------------------------------|-------------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY<br>#24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN.: MOTOR CLAIMS<br>FAX: |                   | NAME: Mr Sun Ziming, Benjamin<br>ADDRESS: 101a Lorong 2 Toa Payoh<br>#02-05<br>Singapore 310101<br>TEL: 96320128 |           | WIP: 18540<br>EXCESS:<br>DATE: 23-May-18 |                   |
| VEH NO:                                                                                                       | SLV5001G          | DATE IN:                                                                                                         |           | CONTACT PERSON:                          | JESS 6395 7874    |
| CHASSIS NO:                                                                                                   | JM6CW1071H0127281 | MILEAGE:                                                                                                         |           | TYPE OF CLAIM:                           | THIRD PARTY CLAIM |
| MODEL:                                                                                                        | MAZDA5            | DATE REG.:                                                                                                       | 29-Dec-17 | POLICY NO.:                              |                   |

NATURE OF WORKS

Parts Description

| NO | QTY                        |    | REVISED         | PRICES      |
|----|----------------------------|----|-----------------|-------------|
| 1  | FRT BUMPER                 | 1  | MC513-50-031BBB | \$ 1,055.40 |
| 2  | MASCOT,FRT BUMPER          | 1  | MC291-51-731    | \$ 43.40    |
| 3  | BRACKET(LH),FRT BUMPER     | 1  | MC513-50-161B   | \$ 39.90    |
| 4  | BRACKET(RH),FRT BUMPER     | 1  | MC513-50-151A   | \$ 40.20    |
| 5  | RETAINER (LH),FRT BUMPER   | 1  | MC513-50-0U1B   | \$ 20.50    |
| 6  | RETAINER (RH),FRT BUMPER   | 1  | MC513-50-0T1B   | \$ 20.50    |
| 7  | GRILLE,FRONT BUMPER        | 1  | MC514-50-1T0E   | \$ 668.80   |
| 8  | COVER,TOWING               | 1  | MC513-50-A10B   | \$ 52.10    |
| 9  | PLATE(LH),SEAL, FRT BUMPER | 1  | MC513-50-1V1    | \$ 32.50    |
| 10 | PLATE(RH),SEAL, FRT BUMPER | 1  | MC513-50-1U1    | \$ 32.50    |
| 11 | GUIDE(LH),AIR, FRT BUMPER  | 1  | MC597-50-A23A   | \$ 31.50    |
| 12 | GUIDE(RH),AIR, FRT BUMPER  | 1  | MC597-50-A22    | \$ 31.50    |
| 13 | INTAKE,AIR, FRT BUMPER     | 1  | MC513-50-7M1E   | \$ 154.00   |
| 14 | FOAM,FRT BUMPER            | 1  | MC513-50-111    | \$ 75.40    |
| 15 | FASTENER, FOAM             | 2  | MFD01-68-AC3    | \$ 11.80    |
| 16 | FRONT REINFORCEMENT        | 1  | MC513-50-070A   | \$ 506.20   |
| 17 | COVER(LH), FOGLAMP         | 1  | MC513-50-C21    | \$ 74.40    |
| 18 | COVER(RH), FOGLAMP         | 1  | MC513-50-C11    | \$ 74.40    |
| 19 | RIVET, FRT BUMPER          | 4  | MBN8F-50-355    | \$ 21.60    |
| 20 | RIVET, FRT BUMPER          | 4  | MEA01-50-037    | \$ 30.40    |
| 21 | RIVET, FRT BUMPER          | 3  | MS51S-51-833    | \$ 11.40    |
| 22 | GROMMET, FRT BUMPER        | 1  | MC513-50-0U5A   | \$ 15.40    |
| 23 | GROMMET, FRT BUMPER        | 1  | MC513-50-0T5A   | \$ 15.40    |
| 24 | CLIP, FRT BUMPER           | 10 | MC274-50-133    | \$ 35.00    |
| 25 | FASTENER, FRT BUMPER       | 4  | MGD7A-50-EA1    | \$ 12.00    |
| 26 | SEAL, FRT BUMPER           | 1  | MC513-50-0G8    | \$ 10.30    |
| 27 | FRT SUPPORT PANEL          | 1  | MC513-53-110G   | \$ 429.70   |
| 28 | STAY,LOCK, FRT             | 1  | MC513-52-15Y    | \$ 38.10    |
| 29 | LABEL,CAUTION              | 1  | MYF47-15-031    | \$ 3.20     |
| 30 | BONNET                     | 1  | MC5Y3-52-31X    | \$ 1,033.90 |

|                  |                      |   |              |           |             |
|------------------|----------------------|---|--------------|-----------|-------------|
| 31               | WEATHERSTRIP, BONNET | 1 | MC513-56-770 | <i>me</i> | \$ 70.20    |
|                  |                      |   |              |           |             |
| TOTAL PARTS      |                      |   |              |           | \$ 4,691.60 |
| LESS 10%         |                      |   |              |           | \$ 469.16   |
| TOTAL PARTS COST |                      |   |              |           | \$ 4,222.44 |

| Labour Description |              |                                                                                                                   |               |             |             |
|--------------------|--------------|-------------------------------------------------------------------------------------------------------------------|---------------|-------------|-------------|
|                    |              |                                                                                                                   |               | <i>1980</i> |             |
| 1                  |              | TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND BONNET. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.            | <i>660</i>    | <i>2370</i> | \$ 2,640.00 |
| 2                  |              | TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND BONNET.                                                          | <i>630</i>    | <i>1260</i> | \$ 2,520.00 |
| 3                  | MZ-BR-PANEL1 | TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST. |               | <i>✓</i>    | \$ 660.00   |
| 4                  | MZ-BR-TOP-UP | TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.                                       |               | <i>✓</i>    | \$ 660.00   |
| 5                  | MZ-BR-PLATE1 | TO SUPPLY NUMBER PLATE.                                                                                           | <i>70</i>     | NETT        | \$ 70.00    |
| 6                  | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                                |               | <i>120</i>  | \$ 250.00   |
| 7                  | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                                   |               | <i>150</i>  | \$ 350.00   |
| 8                  | MZ-BR-SUNDRI | SUNDRIES.                                                                                                         | <i>net 30</i> | NETT        | \$ 100.00   |

|                    |      |              |
|--------------------|------|--------------|
| TOTAL LABOUR       | \$ - | \$ 7,250.00  |
| TOTAL PARTS        | \$ - | \$ 4,222.44  |
| TOTAL              | \$ - | \$ 11,472.44 |
| LESS EXCESS        | \$ - | \$ -         |
| TOTAL AFTER EXCESS | \$ - |              |
| GST 7%             | \$ - | \$ -         |
| GRAND TOTAL        | \$ - | \$ -         |

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature \_\_\_\_\_

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_