222	- /
ASS. REG. BY:	7m1/ CC3/TMIL8009442/KHom
Kenneth	ASSIGNMENT
From: Date:	Veh No: S1+0 9181K YERROR 10, 11
OD TP WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
	Make: Chevrolet Girs c.c 19.81
at Workshop m/s Trans	Cob Colour White I Red AC: Insured / Std / NI / NA
Insured: SJC 1277 M	Sp.Reading 255568 T/Radio: Insured / Std / NI / NA
	Eng/No:
Policy No.	CNO: KUILA 69R JBB 05 8782
Claims No.	Gen. Cond: Geod / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorger/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/Rim / STD A/Rim or
-	Tyre Size: F: 195/65 R 15
(Policy Condition)	R:
Remark: The veh had commenced its	N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	- I II TOYO / YOYO
Bal. or Market Value:	Front
IDAC Accident Rport: Consistent? : Yes or I	No Rear
GIA / PR Seen: Consistent? : Yes or h	No L/Bal. 9 mm
Est. Repairs: ///2 days Res.: Yes or	No D.O.A. 22/5/18 DOI 22/5/10
Lum Sum: 20 % 3 Val.: Yes or I	
CA / REV / REP. / 24 HRS	
- Vohi	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
, orson contacted,	The U/C / Chassis frame / Body Structure affected due to collision.
76/2	
-413 19h poss to Corner	ч
SHO GISIK - CC3/ FCT LUCIDE	509/KHD13 VA - 2500 2011
SICTETO X	5U1/KHDK3 UA: 25012CH4
25 5-@1:04pm revert via	email estimate, FIA is police report.
	crient estimate I film to poulle report.
11 Sy 8 16502 (1	Red. 19167.43; 92%)
Date/Time, File Pass to? : Prell. Report	EIVED 0-5 JUN 2018
1156 Typlet : Final Report	Days Of Repair: 1.5
Oate/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
7)	Add Fee: Site Insp. (\$
)_s.Rssi 10
Report Format :	: Interview (\$) Photos
Lump Sum / I.B.I: (S	Tech Invs (\$): Others
)	Weekend (\$
	10TAL 260

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 25 May 2018 1:04 PM

To:

Motor Claims

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE

LTD, DOA: 22/5/2018, SHD 9181K (TP VEHICLE), SJC 7277M (OI VEHICLE)

Attachments:

SHD 9181K ESTIMATE.pdf; SHD 9181K GIA.pdf; SHD 9181K POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9181K M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9181K
Vehicle to be Exported:	Yes
Intended De-registration Date:	22 May 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z2051443783K
Chassis No.:	KL1LA69RJBB058782
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,052.00
Original Registration Date:	14 Oct 2011
First Registration Date:	14 Oct 2011
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$14,052.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2019
PARF Rebate Amount: Intended COE Rebate Details	\$9,133.00
COE Expiry Date:	13 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$35,200.00
COE Rebate Amount:	\$6,118.00
Total Rebate Amount: Message	\$15,251.00
Please note that the 8-year COF for this vehicle cannot	be further renewed. The vehicle must be de-registered upon COE expiry or when the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 May 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	22/05/2018 15:15
Date Of Accident	22/05/2018 11:05
Exact Location Of Accident	GAMBAS AVENUE X SEMBAWANG ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD9181K
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	TAN BOON HAI
NRIC No	S1686387D
Date Of Birth	12/07/1965
Occupation	OUTDOOR
Date Of Driving Pass	27/05/1992
Driving Experience	25 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93884677
ACCORD WYSTE ACCORD	

NOEMAIL

Address

BLK 333 SEMBAWANG CLOSE

#08-421

Postcode

750333

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

*

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO 2

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

0.912/34

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: UKNOWN

GENDER:

: FEMALE

Passenger 2

NAME:

: UKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,

POSTCODE: 319194, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2519999 - FAX NO: 63548749

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT T/20180522/2071

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJC7277M

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE HIRE

Vehicle Category Name of Driver

KHAIRUL ANUAR BIN BIAMIN

NRIC/Passport Number

S6939000E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN BOON HAI

Approximate Age

Were seat belts worn?

Injuries Sustain

Injured person in which vehicle?

SHD9181K

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time:


De Shuan

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pleas	see	attached	Po//18	report			
					1.11-1-5-2		
			ST				
	33150					5340000-1000-	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Name: NRIC/FIN No.:


De Shuen

Reporting Centre Personnel's Signature

GIARMO SkutchPlanForm_V3

2

POLICE REPORT Pg. 1



T/20180522/2071

4 of 4

Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT Tel No: 1800-2519999

Report No. T/20180522/2071

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Record E / Sgt 2 SITI NADIA BINTE RO	//	Signature Of Informa	nt:
Signature Of Interpreter: Not applicable	10	Date/Time: 22/05/2018 14:02	
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI	/	Classification Of Cas	e:
Contact No : 85476151	SINGAPORE POLICE FORCE	SN 168	
Authentication Stamp NP168		ATURE	*

POLICE REPORT Pg. 1





3 of 4

Report No. T/20180522/2071

Police Station Of Origin:

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

I am making this report for record and insurance purposes.

POLICE REPORT Pa. 1



T/20180522/2071

2 of 4

Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT

Report No. T/20180522/2071

Tel No: 1800-2519999

Details of Person Involved Any Pedestrian Involved: No Use of Pedestrian Crossing: NA No. of Pedestrians Injured: NIL Driver S1686387D ID No. TAN BOON HAI Name 93884677 Contact No. SHD9181K (Car) Related Vehicle Class: 2B.2A.2,3 Class of DOCTORS INC. MEDICAL GROUP Hospital/Clinic Date of Expiry: NIL Drivina Licence & Expiry Date Date Discharge 22/05/2018 Date Treatment | 22/05/2018 Degree of Injury | Slight 03 No. of Days granted Medical Leave Driver S6939000E KHAIRUL ANUAR BIN BIAMIN ID No Name Contact No. 98583526 Related Vehicle SJC7277M (Car) Class of Class: 2B.2A.2.3 Hospital/Clinic NIL Driving Date of Expiry: NIL Licence & Expiry Date Date Discharge NIL Date Treatment NIL

On the 22/05/2018 at about 1105hrs, the taxi I was driving, 'SHD9181K' was stationary at the traffic light at the straight road of Gambas Avenue. I was on the second lane, and the second car, while waiting for the traffic light to turn green. However, I suddenly heard a bang from behind, and my taxi jerked forward. I then realised that a vehicle that was changing from the 3rd to the 2nd lane of the road, namely 'SJC7277M' had bumped into the left rear of my vehicle.

NIL

Degree of Injury NIL

There were 2 passengers alongside me in my car:

1. Nurul Jannah (96322670)

No. of Days granted Medical Leave

2. Nurul Amairah (91724752)

After the collision, I asked my passengers if they were ok and if they needed an ambulance. However, they declined as they were on their way to the hospital as well, so they would get the doctor to assess their condition anyway. I then got down from my taxi to take photos of the scene and to exchange contact details with the other driver. No ambulance, traffic police or tow truck was called to the scene. There was also 1 passenger inside the other vehicle.

I had sustained the following injuries due to the impact of the collision: Stiff neck and lower back pain. I then went to seek medical attention at Doctors Inc. Medical Group. I was granted 3 days of medical leave from 22/05/2018-24/05/2018, no hospitalisation required.

POLICE REPORT Pg. 1





Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 Tel No: 1800-2519999

1 of 4 Report No. T/20180522/2071

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2018 14:02	Vide Report No.:	Station Diary No.: 82
C C D D D D D D	AUTORIO COMPTONI ANTONI STATUMBILISTA	

22/05/2010 14.02					
Informa	nt's Partici	ulars		ALEXANDER MANAGEMENT	
Name of TAN BO	Informant: ON HAI		Address: APT BLK 333 SEMBAWANG CLOSE #08-421 SINGAPORE 750333		
ID Type / ID No.; NRIC NO / S1686387D			Contact No.: Home/Office:	Mobile: 93884677	
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 12/07/1965	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Informat Class: 2B,2A,2,3	tion: Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/05/2018 11:0	Type of Location Straight Road
Location: GAMBAS AV at the cross in	ENUE unction of Sembawa	ang Road		Pand Spand Limits
Weather: Clear		Road Surface: Dry		Road Speed Limit: 70 Km/h
Traffic Flow:		Traffic Control: Traffic Light - Wo	rking	Traffic Volume: Moderate
One Way			12	Anyone conveyed by

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHD9181K	Car	CHEVROLET	EPICA 2.0DSL AT ABS D/AB 2WD 4DR	Red	Seriously Damaged	
SJC7277M	Car	TOYOTA	WISH 1.8X A	Blue	Slightly Damaged	1

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Vehicle No.:

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9181K

Not Norhanker

SHD 9181K

AAD1805-204

CI. N	LK1LA69RJBB058782
Chassis No.:	LK I LAGSKIBBU30/02
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	22.5.2018
Third Party Insurer:	TOKIO MARINE
PART	LIST
	P

1	1	Rear Bumper	\$ B 1,202.00 —
2	1	Rear Bumper Beam	\$ A 239.94 ⊀
3	1	Rear Bumper Centre Absorber	\$ 1 260.00 x
4	1	Rear Bumper Side Retainer RH	\$ 5h 68.76 x
5	1	Rear Bumper Side Retainer LH	\$ °m 68.76 —
6	1	Rear Bumper Reflectors RH	\$ 1 119.74 X
7	1	Rear Bumper Reflectors LH	\$ CN+ 119.74
8	1	Rear Bumper Tow Hook Cover	\$ مر 93.00 ک
9	1	Rear End Panel Outer	\$ A 623.76
10	1	Rear End Panel Inner Trim	\$ Su 263.84
11	1	Rear Luggage Floor Panel	\$ N 973.00
12	1	Rear Luggage Floor Panel Insulator	\$ 5h 63.50
13	1	Rear Luggage Floor Panel Trim Board	\$ 5 378.00 d
14	1	Bootlid	\$ A 973.00
15	1	Bootlid inner trim board	\$ Su 400.00 X
16	1	Bootlid Weatherstrip	\$ Sm 344.28
17	1	Bootlid Lock - Top	\$ A 466.56
18	1	Bootlid 'CHEVROLET' Badge	\$ 120.62
19	1	Bootlid Logo	\$ 138.84
20	1	Bootlid 'EPICA LT' Badge	\$ 119.84
21	1	Bootlid Reflector Centre	\$ 5 ≥ 217.97
22	1	Bootlid Reflector RH	\$ Sm 128.40
23	1	Bootlid Reflector LH	\$ Sa 128.40
24	1	Rear Tail Lamp RH	\$ Sn 479.30
25	1	Rear Tail Lamp LH	\$ 5n 479.30
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ 7 1,110.00
27	1	Rear Fender RH	\$ n 1,145.00
28	1	Rear Fender Inner Trim RH	\$ Sm 418.44
29	1	Rear Fender LH	\$ N 1,145.00
	1		

Trans-cab Auto Services Pte Ltd

AAD1805-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G

SHD 9181K

30	1	Rear Fender Inner Trim LH	\$	5 418.44 X
		TOTAL	\$	12,707.43
		10%	\$	1,270.74
			\$	11,436.69
		Specical Nett		
1	1Set	Bootlid inner trim board Clip	\$	Na 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	nd 300.00 -
3	1Set	Rear Bumper Fastener Clip	\$	Ma 44.00 -
4	1Set	Rear Fender Inner Trim Clip LH	\$	~~ 30.00 \
5	1Set	Rear Bumper End Dust Cover Clip	\$	~~ 30.00 /
6	1	Rear Exhaust Mounting	\$	July 300.00
7	2	Rear Windscreen Sealant	\$	12 80.00 X
8	1	Rear Windscreen Inner Sponge Seal	\$	~ 100.00
9	1	Spare Tyre	\$	Pm 180.00
10	1	Spare Wheel Rim	\$	Sa 126.74)
		TOTAL	\$	1,230.74
		TOTAL PARTS	\$	12,667.43
		Devel Besting Vacabing And Straightoning The		
		Panel Beating, Knocking And Straightening The		
		Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,500.00 2001
		·	0.78	VII/20000000
		To Check Electrical Lighting Concerned.	\$	170.00 154
		To Rust-Proofing Of The Affected Areas.	\$	~~ 170.00 X
		Putty And Spray Painting Of The Affected		
		Portion.	\$	3,200.00 2001
		To reinstall rear bumper parking sensor.	\$	170.00 601

Trans-cab Auto Services Pte Ltd

AAD1805-204

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9181K

Repair Days (LUMP SUM) 10 Days		
TOTAL	\$	20,817.43
	\$	8,150.00
To check steering geometry and computer wheel alignment	\$	~~ _{220.00} X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	22 380.00 X
To transfer of boot fittings and conduct water seepage test.	\$	170.00 X
To transfer of end panel fittings and conduct water seepage test.	\$	170.00 X

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI18009442/KTBN2

Date:

06/06/2018

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MJ000426

Claimant Vehicle No:

SHD9181K

Insured Vehicle No:

SJC7277M

Date of Loss:

22/05/2018

Nature of Claim:

TP

Claim No: M1802654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD9181K

Make & Model:

CHEVROLET EPICA, 2.0 (A) 14/10/2011 (Man. Year: 2011) Engine No: Chassis No: Z20S1443783K

Reg. Date: Colour:

White/Red

Odometer:

KL1LA69RJBB058782 255568 km

Engine Capacity:

1991 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

No Pre-accident Condition:

Front Tyre Size: Front Left Side:

195/65R15

Rear Tyre Size:

195/65R15

Giti 9 mm

Rear Left Side: Rear Right Side:

Giti 9 mm Giti 9 mm

Giti 9 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIM	s	Repairer's	Adjuster's	Difference	Diff %
Parts		12,667.43	1,595.45	11,071.98	87.41
Miscellaneous Iten	ns	0.00	0.00	0.00	
Labour		8,150.00	475.00	7,675.00	94.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	20,817.43	2,070.45	18,746.98	90.05
10	Approved Total (Overridden) (S\$)		1,650.00		
	(S\$)	20,817.43	1,650.00	19,167.43	92.07
	+ GST 7.00/7.00% (S\$)	1,457.22	115.50	1,341.72	92.07
	Nett Amount (S\$)	22.274.65	1,765.50	20,509.15	92.07

INSPECTION

Date of Assignment:

25/05/2018

Date Inspected:

23/05/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

1.5 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2018)

Parts: 143 CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD9181K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

			ed Parts Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,202.00 FL	*1,202.00 FL
2	1		*REAR BUMPER BEAM	Repair	239.94 FL	*- FL
3	1		*REAR BUMPER CENTRE ABSORBER	Serviceable	260.00 FL	*-FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	68.76 FL	*-FL
5	1		*REAR BUMPER SIDE RETAINER LH	Cracked	68.76 FL	*68.76 FL
6	1		*REAR BUMPER REFLECTORS RH	Serviceable	119.74 FL	*-FL
7	1		*REAR BUMPER REFLECTORS LH	Cracked	119.74 FL	*119.74 FL
В	1		*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*-FL
9	1		*REAR END PANEL OUTER	Repair	623.76 FL	*-FL
10	1		*REAR END PANEL INNER TRIM	Serviceable	263.84 FL	*-FL
11	1		*REAR LUGGAGE FLOOR PANEL	Repair	973.00 FL	*-FL
12	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Serviceable	63.50 FL	*-FL
13	1		*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	378.00 FL	*-FL
14	1		*BOOTLID	Repair	973.00 FL	*- FL
15	1		*BOOTLID INNER TRIM BOARD	Serviceable	400.00 FL	*- FL
16	1		*BOOTLID WEATHERSTRIP	Serviceable	344.28 FL	*-FL
17	1		*BOOTLID LOCK-TOP	Repair	466.56 FL	*-FL
18	1		*BOOTLID CHEVROLET BADGE	Not Necessary	120.62 FL	*- FL
19	1		*BOOTLID LOGO	Not Necessary	138.84 FL	*-FL
20	1		*BOOTLID EPICA LT BADGE	Not Necessary	119.84 FL	*- FL
21	1		*BOOTLID REFLECTOR CENTRE	Serviceable	217.97 FL	*- FL
22	1		*BOOTLID REFLECTOR RH	Serviceable	128.40 FL	*-FL
23	1		*BOOTLID REFLECTOR LH	Serviceable	128.40 FL	*-FL
24	1		*REAR TAIL LAMP RH	Serviceable	479.30 FL	*- FL
	1		*REAR TAIL LAMP LH	Serviceable	479.30 FL	*- FL
25 26	1		*REAR EXHAUST BOX (MUFFLER A-EXH,RR)	Repair	1,110.00 FL	*-FL
	-9:		*REAR FENDER RH	Repair	1,145.00 FL	*- FL
27 28	1		*REAR FENDER INNER TRIM RH	Serviceable	418.44 FL	
29	1		*REAR FENDER LH	Repair	1,145.00 FL	*-FL
30	1		*REAR FENDER INNER TRIM LH	Serviceable	418.44 FL	*-FL
31	1		*SET BOOTLID INNER TRIM BOARD CLIP	Not Necessary	40.00 FS	*-F8
32	1		*SET REAR BUMPER PARKING SENSOR	Dented	300.00 FS	*300.00 FS
33	1		*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
34	1		*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*-F
	4		*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*-F8
35	1		*REAR EXHAUST MOUNTING	Serviceable	300.00 FS	
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	
37	2		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	66 men 1225
38	1			Serviceable	180.00 FS	
39	1		*SPARE TYRE	Serviceable	126.74 FS	
40	1		*SPARE WHEEL RIM	Octatocable		
F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)				1,734.50 139.05		

No. Qty		Part No. Particulars	Condition		Amount	
			Total Parts (S\$)	12,667.43	1,595.45	
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
1 CCCOIIIIICIIGCG	LUDUUI

Particulars	Lab.Type	Repairer's	Amount
ur Items			
NECESSARY PORTION, REMOVE AND RENEWAL OF	New	3,500.00	200.00
TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	14
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,200.00	200.00
TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	
TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	
TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	19 2
TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	5
Gross Labou	r Cost (S\$)	8,150.00	475.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME TO CHECK ELECTRICAL LIGHTING CONCERNED TO RUST-PROOFING OF THE AFFECTED AREAS PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION TO REINSTALL REAR BUMPER PARKING SENSOR TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME TO CHECK ELECTRICAL LIGHTING CONCERNED New TO RUST-PROOFING OF THE AFFECTED AREAS New PUTTY AND SPRAY PAINTING OF THE AFFECTED New PORTION TO REINSTALL REAR BUMPER PARKING SENSOR New TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST TO TRANSFER OF BOOT FITTINGS AND CONDUCT New WATER SEEPAGE TEST TO REMOVE AND REFIT INTERIOR New FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR TO CHECK STEERING GEOMETRY AND COMPUTER New	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME TO CHECK ELECTRICAL LIGHTING CONCERNED New 170.00 TO RUST-PROOFING OF THE AFFECTED AREAS New 170.00 PUTTY AND SPRAY PAINTING OF THE AFFECTED New 3,200.00 PORTION TO REINSTALL REAR BUMPER PARKING SENSOR New 170.00 TO TRANSFER OF END PANEL FITTINGS AND CONDUCT New 170.00 WATER SEEPAGE TEST TO TRANSFER OF BOOT FITTINGS AND CONDUCT New 170.00 WATER SEEPAGE TEST TO REMOVE AND REFIT INTERIOR New 380.00 FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR TO CHECK STEERING GEOMETRY AND COMPUTER New 220.00

< END OF ESTIMATES >