

INS. CASE OWNER:

CC 4/III1800

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: ☒ Email ☐ Call ☐

Repair Cost:

SS1,000

() days

Reduction:

40 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 14 DEC 18

Confirm with: KJ

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

N/A

Repair Cost:

SS1,000.00

Loss of Rental (LOR):

SS -

() days

Loss of Use (LOU):

SS300.00

(\$100 x 3 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS145

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

+350

Total:

SS1,301.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 14.12.18

Confirm with: KJ

Email ☒ Call ☐

Payee 1:

SS1,301.45

Name 1:

KHEK JOO MOTOR WORKSHOP

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18009445/Nha3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 24-05-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6535J	Veh. Inspected	SKB 1343M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/04/2018	Inspection Date	24/05/2018	
Survey held at	KHEK JOO MOTOR WORKSHOP BLK 9004 TAMPINES IND. PARK 1 #01-94 SINGAPORE 528836			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838

Tel/Fax: 67854258 Mobile: 96766658

Date: 22 May 2018

The Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Tel: 63476100 Fax: 62244174/62257743

REPAIR QUOTATION FOR SKB1343M MAZDA 3

	Qty	(\$)	Discount	(\$)	
Rear bumper	1	974.80	20%	779.84	den
Rear bumper reflector LH	1	54.90	20%	43.92	sm
Rear bumper side retainer	2	68.60	20%	54.88	crack
Rear bumper retaining clip	10 x 6	27 45.00	20%	321.6 36.00	acc
Total Cost of parts				878.64	

LABOUR

To check wiring.	30.00	x n
To reinstall reverse sensors and check sensing distance.	120.00	x
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	400.00	2.00
Spray painting charges to putty and spray all affected parts/areas.	300.00	2.00

Total Cost of labour 850.00

Total Repair Cost 1,728.64

Yours faithfully

Wee Kiang

NA2 LKK
2 days
L/S
98804220

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 23 May 2018 9:12 AM
To: Ng Wee Khiang; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: RE: ACCIDENT INVOLVING SKB1343M AND YOUR INSURED SHA6535J ON 17 APRIL 2018
Attachments: SKS1343M-India.pdf; SKS1343M-India-PRI notice.pdf; 1343-AXA (1).pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKB1343M and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

9.55am @ 23/5/2018
vehicle not in
Mr. Ng

From: Ng Wee Khiang [mailto:kj.motor@yahoo.com.sg]

Sent: 22 May, 2018 6:50 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: RE: ACCIDENT INVOLVING SKS1343M AND YOUR INSURED SHA6535J ON 17 APRIL 2018

Dear Sir / Mdm,

LKK Auto Consultants Pte Ltd may do.

Best Regards,

wee khiang

On Tuesday, 22 May 2018, 5:21:25 PM GMT+8, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: Ng Wee Khiang [<mailto:kj.motor@yahoo.com.sg>]

Sent: 22 May, 2018 4:08 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: ACCIDENT INVOLVING SKS1343M AND YOUR INSURED SHA6535J ON 17 APRIL 2018

To Motor Claims Department

We have been entrusted by the owner of vehicle SKS1343M to carry out repairs to his accident damaged vehicle and claim against your insured for the damage/loss caused as a result of the accident which occurred on . A copy of our customer's accident report and repair estimate are enclosed.

Before we proceed to repair the damaged vehicle, please let us know within the next 2 working days of the receipt of this notice whether you would like to carry out a Pre-Repair Inspection of the vehicle.

If you do not hear from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

By the way we are looking forward to an amicable direct settlement with you.

Yours faithfully

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	24 May 2018 11:59	Clim Veh Model Changed	(204893) MAZDA 3 2.0 (A).		[A] HOW MEI KWAN
2	24 May 2018 11:59	Clim Created	Reg No: SKB1343M, Acct Date: 2018/04/17, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Khek Joo Motor Workshop (HQ)		[A] HOW MEI KWAN
3	24 May 2018 11:59	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] HOW MEI KWAN
4	24 May 2018 11:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/05		[A] HOW MEI KWAN
5	24 May 2018 11:59	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] HOW MEI KWAN
6	24 May 2018 12:00	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.		[A] HOW MEI KWAN
7	24 May 2018 12:00	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] HOW MEI KWAN
8	25 May 2018 10:55	Label Removed	(30651):Vehicle Not In.		[A] HOW MEI KWAN
9	25 May 2018 10:55	Adj Adjuster Assigned	ADRIAN LING -> Muhammad Nazril Bin Abdullah		[A] HOW MEI KWAN
10	07 Jun 2018 10:01	Adj Mandate Request	Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA NIL (OID reversed)		[A] VIC ALPEH
11	07 Jun 2018 11:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/05, Mandate Remarks: Agree to do direct settlement. Please seek mandate through merimen		[I] Sundari Nagarajan
12	07 Jun 2018 11:42	Adj Mandate Set	Approved:0.00:Agree to do direct settlement. Please seek mandate through merimen		[I] Sundari Nagarajan
13	10 Dec 2019 17:26	Adj Rpt Initiated			[A] Asher Sng Rong Yi
14	10 Dec 2019 17:26	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821 R.		[A] Asher Sng Rong Yi
15	10 Dec 2019 17:26	Clim Dtl Modified	3P) Reg. Date: -> 2011/04/29.		[A] Asher Sng Rong Yi
16	10 Dec 2019 17:26	Clim Details Notified			[A] Asher Sng Rong Yi
17	11 Dec 2019 11:31	Adj Mandate Request	Cur.Reg:1307.45:PODS LIABILITY: 100% QUANTUM: (a) COR : \$1,000.00 + (b) LOU : \$300.00 (3days x \$100) + (c) LTA Search:\$ 7.45 Total: a+b+c = \$1,307.45 VEH MO DEL: MAZDA 3 1999cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.		[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[27/06/2018 15:32] VIC ALPEH:

PENDING COR FINALIZATION

[27/06/2018 15:32] VIC ALPEH:

Alert - Adj Mandate Approved (\$0.00) - SKB1343M - Claim Handler: Priya

Approved:0.00:Agree to do direct settlement. Please seek mandate through merimen

[07/06/2018 10:01] VIC ALPEH:

Adj Mandate Request Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA NIL (OID reversed)

[07/06/2018 10:00] VIC ALPEH:

FILE REVIEWED. QID Mr Rodger Lim reported that he was reversing when hit TP vehicle. Seek liability mandate to III by merimen

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2373003	10 Dec 2019 17:26:58	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKB1343M	SHA6535J	11.77

12/12/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SKB1343M (MCT18040479)**
[SHA6535J]

TP

KAELYN GOH

Apr 17 2018 1:00PM

[COMFORT TRANSPORTATION PTE LTD]

Khek Joo Motor Workshop

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/12/2019 12:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1307.45) - SKB1343M - Claim Handler: Priya

Approved:1307.45:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018 Edit Reg		23 May 2018 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	KAELYN GOH, ID: S9020799G		
Vehicle Reg. No.:	SKB1343M	Date of Loss:	17/04/2018 13:00 - :59 [83 Months and 19 Days From LTA Reg. Date (Man Yr)]
Claim Type:	TP / MCT18040479	Policy/Cover Note No.:	MC0M0015
Vehicle Reg. No. (Insured):	SHA6535J	Policy No. (Claimant):	GA313120/1
		Excess:	
Repairer:	Khek Joo Motor Workshop (HQ) BLK 9004 TAMPINES STREET 93 #01-94, 528838 Tampines - Tel: 67854258		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 05/06/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (11/12/2019): Alert - Adj Mandate Approved (S\$1307.45) - SKB1343M - Claim Handler: Priya
- III_SG (07/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SKB1343M - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB1343M (MCT18040479)
[SHA6535J]
TP
KAELYN GOH
Apr 17 2018 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
Khek Joo Motor Workshop

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
2	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
3	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
12	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
13	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
14	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
15	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
16	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
17	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
18	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
19	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
20	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
21	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
22	12/06/19 10:16	General View		Load JPG	<input checked="" type="checkbox"/>
23	12/06/19 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	12/06/19 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	12/06/19 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	12/06/19 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	12/06/19 10:16	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/05/18 12:00	ACKNOWLEDGEMENT EMAIL TO III DO 23.05.2018		Load PDF	
2	24/05/18 12:00	TP ESTIMATE		Load PDF	
3	24/05/18 12:00	TP GIA REPORT		Load PDF	
4	24/05/18 12:00	NOTIFICATION FROM WORKSHOP		Load PDF	
5	25/05/18 10:56	TP ESTIMATE - MARKED		Load PDF	
6	10/12/19 17:45	LOD		Load PDF	
7	11/12/19 11:28	LTA SEARCH		Load PDF	
8	13/01/20 08:23	WORKSHOP INVOICE		Load PDF	
9	13/01/20 08:23	AUTHORISATION TO ACT FORM		Load PDF	
10	13/01/20 08:23	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	25/05/18 09:02	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009445/NEA3Q2

Date: 13/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant
Vehicle No : SKB1343M **Insured Vehicle No :** SHA6535J
Date of Loss: 17/04/2018 **Nature of Claim:** TP **Claim No:** MCT18040479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB1343M**
 Make & Model: MAZDA 3, 2.0 (A) Engine No: LF10898252
 Reg. Date: 29/04/2011 (Man. Year: 2011) Chassis No: JM6BL10F1A0136952
 Colour: White Odometer: 80074 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	914.64	856.32	58.32	6.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	400.00	450.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,764.64	1,256.32	508.32	28.81
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	1,764.64	1,000.00	764.64	43.33
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,307.45		

INSPECTION

Date of Assignment: 23/05/2018
 Date Inspected: 24/05/2018 Inspected At: Khek Joo Motor Workshop (HQ)
 BLK 9004 TAMPINES STREET 93
 #01-94
 Singapore 528838
 Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2020)
Parts:	144	MAZDA 3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB1343M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	974.80 FL	*974.80 FL
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	54.90 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Cracked	68.60 FL	*68.60 FL
4	10		*REAR BUMPER RETAINING CLIP	Necessary (6pcs Only)	45.00 FL	*27.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,143.30	1,070.40
- List Item Discount on L Items 20.00/20.00% (S\$)	228.66	214.08
Total Parts (S\$)	914.64	856.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	30.00	0.00
2	TO REINSTALL REVERSE SENSORS AND CHECK SENSING DISTANCE	New	120.00	0.00
3	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS/AREAS	New	400.00	200.00
4	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS/AREA	New	300.00	200.00
Gross Labour Cost (S\$)			850.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >