

Khek Joo Motor Workshop

Blk 9004 Tampines St 93, #01-94, Singapore 528838

Tel/Fax: 67854258 Mobile: 96766658

Date: 22 May 2018

The Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street

#04/#05 IOB Building

Singapore 049711

Tel: 63476100

Fax: 62244174/62257743

REPAIR QUOTATION FOR SKB1343M MAZDA 3

	<u>Qty</u>	<u>(\$)</u>	<u>Discount</u>	<u>(\$)</u>
Rear bumper	1	974.80	20%	779.84
Rear bumper reflector LH	1	54.90	20%	43.92
Rear bumper side retainer	2	68.60	20%	54.88
Rear bumper retaining clip	10	45.00	20%	36.00
Total Cost of parts				<u>878.64</u>

LABOUR

To check wiring. 30.00

To reinstall reverse sensors and check sensing distance. 120.00

Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas. 400.00

Spray painting charges to putty and spray all affected parts/areas. 300.00

Total Cost of labour **850.00**

Total Repair Cost **1,728.64**

Yours faithfully

Wee Kiang