

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0749/2018
DATE : 27-APR-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : LIN HUAZHONG, JENTSON
ADDRESS : APT BLK 988C BUANGKOK GREEN
#12-75
S(533988)
TELEPHONE NO : 9776 0558

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100499674
VEHICLE NO : SLK1221Y
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20B871680
CHASSIS NO : JF1SJGK85GG081021
MILEAGE : 1 KM
DATE IN : 27/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 26/04/2018

Print Date : 27/04/2018
Print Time : 13:46:54

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLK1221Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:KJE TWD PIE(TUAS) DATE:26/04/2018 TIME:0840HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND PANEL	1120.00	2801
4	ZZ/003	RESPRAY REAR BUMPER AND PANEL	840.00	4201
5	ZZ/004	TO CONDUCT REAR PROTECTANT COATING	500.00	2501
6	ZZ/005	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	X
7	ZZ/006	SUNDRIES	100.00	201
TOTAL LABOUR CHARGES			2860.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK1221Y

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 SKIRT COMPL R END PANEL	52401SG0109P	288.00	X		
2 BUMPER FACE R	57704SG012	540.00			
3 BRKT CORNER R RH	57707SG060	18.00	X		
4 BRKT CORNER R LH	57707SG070	18.00	X		
5 BRKT SD R RH	57707SG080	14.40			
6 BRKT SD R LH	57707SG090	14.40			
7 BEAM COMPL R EU	(SUPP) 57711SG0219P	288.00			
8 COVER HOOK R	57731SG010NN	12.60	X		
9 REFLEC AY RH	84281SC000	20.40	X		
10 REFLEX AY LH	84281SC010	20.40	X		
11 CARGO STEP PANEL S/S	E7710SG000	460.00			
SUB TOTAL		1694.20	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		338.84	0.00	0.00	0.00
GRAND TOTAL		1355.36	0.00	0.00	0.00
OVERALL TOTAL		1355.36			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLK1221Y

TOTAL LABOUR CHARGES	2860.00
TOTAL SPARE PARTS CHARGES	1355.36

GRAND TOTAL	4215.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Notified
1-B.1
Pullover B4 paint
2 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: