

ASS. REC. BY:

REF: es/msg18009454/Tlv34 Special Instruction:

Surveyor

Menimen

ASSIGNMENT (Office)From (Person): Christine Warey of MSG Date/Time: 24/5/2018 @ 10:26am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: EK 1328G Insured: SKK 9377Rat Workshop m/s: Performance Motors Tel: 03190174of 303 Alexandra RoadPolicy No: 28927838MCY Claim No: 559170

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/05/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement: _____

Date/Time: 12:23pm @ 24/5/18 Person Contacted: Caroline Vehicle IN/OUT OUT

Date/Time	Action/Instruction	Estimate
		<u>EK 1328G - CC3/A1913014629/Rha3y2</u>
		<u>SKK 9377R - X</u>
<u>5/6/18</u>	<u>Send preli revised by menimen</u>	
<u>25/6/18</u>	<u>Final fig \$3433 confirmed by email (Ref 1060:55, 27/6)</u>	

Signature

Tanphu

REF: MSIG

ASSIGNMENT

From: Date: 04/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: EK 1328G

at Workshop m/s

of: Performance 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: chuan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: EK 1328G Yr Regn: 2015 Feb

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 428i Gran Coupé c.c. 1997

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 249.01 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 JUN 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2) 25/6- typst

Report Format : merimen

Lump Sum / I.B.t: (\$) 3433 1/2

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee

Transportation

1 \$ + RE \$

Photos

Others

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		24 May 2018 10:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAM HWA ENGINEERING & TRADING PTE LTD, Co. Reg. No.: 200006689D		
Main Claimant:	BENHARD MICHAEL STEINER, ID: S2754222J		
Vehicle Reg. No.:	EK1328G	Date of Loss:	20/05/2018 00:00 - :59 [38 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559170	Policy/Cover Note No.:	28927838MCY Coverage: 20/03/2018 - 19/03/2019
Vehicle Reg. No. (Insured):	SKK9377R	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/05/2018]		
Driver/Custodian (Insured):	OH MIN KYOO (), NRIC: S2709636J		
Adj Asg. Remarks:	ON WP.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 05 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKK9377R		
TP Vehicle No	: EK1328G	Accident Date	: 20/05/2018
Make	: BMW 428i	Assignment Date	: 24/05/2018
Date of Inspection	: 04/06/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,652.55
Revised Amount	:S\$	3,040.90
Check Items (Estimated)	:S\$	779.60
Total	:S\$	3,820.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 12:32
Date Of Accident	20/05/2018 18:00
Exact Location Of Accident	SENTOSA GOLF CLUB PARKING (UNDERGROUND)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EK1328G
Insured/Policyholder	
Name Of Registered Owner	BENHARD MICHAEL STEINER
NRIC No	S2754222J
Email Address	BERNHARDSTEINERUK@YAHOO.COM.UK
Mobile Phone No	(LOCAL) +65-90231465
Alternative Phone No	OFFICE-90231465

Vehicle Particulars

Manufacturer	BMW
Model	428
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	10117375

Driver

Name of Driver	BENHARD MICHAEL STEINER
NRIC No	S2754222J
Date Of Birth	23/06/1965
Occupation	INDOOR
Date Of Driving Pass	27/06/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90231465
Fax Number	
Contact Number	OFFICE-90231465
EMail Address	BERNHARDSTEINERUK@YAHOO.COM.UK

Address	276 OCEAN DR SENTOSA #05-33
Postcode	098449
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	ZULKEFRY (MARSHALL SENTOSA GOLF CLUB)
Phone Number	92750022
Email Address	SGC_GOLF@SENTOSA.COM.SG

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK9377R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR OH MIN KYOO
NRIC/Passport Number	S2709636J
Contact Number	9438200/ASSISTANT AUDRY 97502832
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	LEFT

No. Of Passenger (Including Driver)

15 May, 2018 10:22 AM

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any (regulations, laws or court) orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reportee/Case Personnel's Signature
 Name:
 S(R)/FIN No.:

15 May, 2018 10:22 AM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, Bernhard Steiner, parked my car EK12286 in the underground parking of Fortuna Golf Club.

On my return the golf marshall Zulketay informed me that Mr. Oh with car number SKK 9377R damaged my car front/side when he left the club. The plastic front parts were lying on the car park.

Mr. Oh returned to the club and signed a damage report taking full responsibility for damage and costs.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

B. Steiner

Policyholder's Signature

Date & time:

21/5/2018/10.15am

B. Oh

Driver's Signature

(If driver is not the policyholder)

Date & time:

4/4

[Signature]

Reporting Centre Personnel's Signature

Name:

SRIC/RY No.:

Parking Damage

On May 20, 2018, Mr. Bernhard Michael Steiner (IC S2754222) parked his BMW number EK1328G in the underground parking.

Mr. Oh Min Kyoo (IC S27096361) was parked next to Mr. Steiner. When Mr. Oh left, he damaged the BMW front section.

Mr. Oh Min Kyoo hereby confirms his full responsibility for the damage and will pay costs of repair in full.

Signed:  Bernhard Michael Steiner

Mr. Oh Min Kyoo 

Witness:

ZULKEFLY-
(MARSHAL)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 MAY 2018

Estimate No. : b1 47010
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Bernhard Michael Steiner
278 Ocean Drive
#03-23
Sentosa
Singapore 098450

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EK1328G	D571749	26/02/2015	428IA GC	0

DESCRIPTION

Replace front bumper and remove attachment etc include knock on accident dent

Spray painting front bumper

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

Sundries.

VALUE

✓ 850 1,275.00

✓ 934 1,038.00

✓ 150 177.00

80 ? 40.00

Total Labour 1: 2,530.00

DESCRIPTION

FRT LH BOTTOM MOUNTING SIDE PANEL
SUPPORT FOG LAMP RH
FRT LH TOP MOUNTING SIDE PANEL
FRT RH TOP MOUNTING SIDE PANEL
FRT RH TOP MOUNTING SIDE PANEL
RH OPEN GRID (SPORT LINE)
PARTIALLY OPEN GRID LH (SPORTLINE)
FINISHER ROD CENTRE (SPORTLINE)
RH FINISHER (SPORTLINE)
COVER LOWER PART CENTRE
COVER LOWER PART CENTRE
FRT BUMPER PANEL PRIMED (SRA)
SET MOUNTING PDC/PMA SENSOR FRT
SET MOUNTING PDC/PMA SENSOR FRT
BUMPER RIVET (10PCS)
GROMMET
FRT RH COVER WHEEL ARCH
COVER BOTTOM RH
DEFLECTOR LIP RH
PLAQUE 82MM
(DG/SL) ADHESIVE SET K6

QTY	PRICE	VALUE
1	18.00	18.00
1	37.60	37.60
1	18.00	18.00
1	18.00	18.00
1	18.00	18.00
1	80.10	80.10
1	66.35	66.35
1	55.65	55.65
1	119.80	119.80
1	40.10	40.10
1	40.10	40.10
1	1,031.90	1,031.90
1	84.10	84.10
1	84.10	84.10
8	0.50	4.00
2	0.75	1.50
1	115.60	115.60
1	115.60	115.60
1	51.50	51.50
1	69.50	69.50
1	53.05	53.05

Total Parts : 2,122.55

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64796770

286, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47010
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
EK1328G	D571749	26/02/2015	428IA GC	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time 4/6/18 16:50 Excess \$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 92445444 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail Ev Tan Jiah @ Performance

No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

4693.55

Labour 1	:	2,530.00
Parts	:	2,122.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	325.68
Grand Total	:	4,978.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401589W, GST Reg. No. M2-0000881-X



FINAL REPORT

Estimate No. : b1 47010
Date Estimated : 21/05/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Bernhard Michael Steiner
278 Ocean Drive
#03-23
Sentosa
Singapore 098450

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
EK1328G	D571749	26/02/2015	428IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FINISHER ROD CENTRE (SPORTLINE)	55.65	1.00		55.65
RH FINISHER (SPORTLINE)	119.80	1.00		119.80
FRT BUMPER PANEL PRIMED (SRA)	1,031.90	1.00		1,031.90
SET MOUNTING PDC/PMA SENSOR FRT	84.10	1.00		84.10
BUMPER RIVET	0.50	10.00		5.00
PLAQUE 82MM	69.50	1.00		69.50
(DG/SL) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,419.00
Total Labour & Parts :	3,433.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,433.00
GST @7%:	240.31
Grand Total :	3,673.31

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 June 2018 11:58 AM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / EK1328G

Dear Caroline,

WITHOUT PREJUDICE

Confirmed amount \$3433 before GST

Repair days: 3 days

Final invoice and all supporting documents sent over to MSIG INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 June 2018 8:44 AM
To: PBSP <pml-pbsp@simedarby.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: FINAL REPORT / EK1328G

Dear Caroline,

Please provides us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Friday, 22 June 2018 7:28 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / EK1328G

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,419.00

Total Labour & Parts : 3,433.00

Repair days: 3

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		24 May 2018 10:26 Edit Adj Rpt	S\$3,433.00 Edit Estimates	S\$3,433.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LAM HWA ENGINEERING & TRADING PTE LTD. Co. Reg. No.: 200006689D								
Main Claimant:	BENHARD MICHAEL STEINER , ID: S27542223								
Vehicle Reg. No.:	EK1328G	Date of Loss:	20/05/2018 00:00 - :59 [38 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559170	Policy/Cover Note No.:	28927838MCY Coverage: 20/03/2018 - 19/03/2019						
Vehicle Reg. No. (Insured):	SKK9377R	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/06/2018]								
Driver/Custodian (Insured):	OH MIN KYOO (), NRIC: S27096363								
Adj Asg. Remarks:	ON WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EK1328G (559170)
[SKK9377R]
TP
BENHARD MICHAEL STEINER
May 20 2018 12:00AM
[LAM HWA ENGINEERING & TRADING PTE LTD]
Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 13:46	Adjuster Immediate Advice	Load HTML	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/06/18 10:48	General View	Load JPG	☒
2	05/06/18 10:48	General View	Load JPG	☒
3	05/06/18 10:48	General View	Load JPG	☒
4	05/06/18 10:48	General View	Load JPG	☒
5	05/06/18 10:48	General View	Load JPG	☒
6	05/06/18 10:48	General View	Load JPG	☒
7	05/06/18 10:48	General View	Load JPG	☒
8	05/06/18 10:48	General View	Load JPG	☒
9	05/06/18 10:48	General View	Load JPG	☒
10	05/06/18 10:48	General View	Load JPG	☒
11	05/06/18 10:48	General View	Load JPG	☒
12	05/06/18 10:48	General View	Load JPG	☒
13	05/06/18 10:48	General View	Load JPG	☒
14	05/06/18 10:48	General View	Load JPG	☒
15	05/06/18 10:48	General View	Load JPG	☒
16	05/06/18 10:48	General View	Load JPG	☒
17	25/06/18 11:53	Reinspection Photo	Load JPG	☒
18	25/06/18 11:53	Reinspection Photo	Load JPG	☒
19	25/06/18 11:53	Reinspection Photo	Load JPG	☒
20	25/06/18 11:53	Reinspection Photo	Load JPG	☒
21	25/06/18 11:53	Reinspection Photo	Load JPG	☒
22	25/06/18 11:53	Reinspection Photo	Load JPG	☒
23	25/06/18 11:53	Reinspection Photo	Load JPG	☒
24	25/06/18 11:53	Reinspection Photo	Load JPG	☒
25	25/06/18 11:53	Reinspection Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/18 10:10	Email frm TP - PR1	Load PDF	☒
2	24/05/18 10:11	Estimate	Load PDF	☒
3	24/05/18 10:13	EK1328G GIA Rpt	Load PDF	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009454/T1VD3E2

Date: 02/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28927838MCY

Claimant Vehicle No: EK1328G

Insured Vehicle No: SKK9377R

Date of Loss: 20/05/2018

Nature of Claim: TP

Claim No: 559170

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: EK1328G

Make & Model: BMW 428i, 2.0 Coupe (A)

Engine No: B3810832N20B20A

Reg. Date: 26/02/2015 (Man. Year: 2014)

Chassis No: WBA4A52080D571749

Colour: Silver

Odometer: 24901 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size:

225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,203.55	1,499.00	704.55	31.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,693.55	3,433.00	1,260.55	26.86
+ GST 7.00/7.00% (S\$)	328.55	240.31	88.24	26.86
Nett Amount (S\$)	5,022.10	3,673.31	1,348.79	26.86

INSPECTION

Date of Assignment: 24/05/2018

Date Inspected: 04/06/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)	
Parts: M1-COUPE	BMW 428i 2.0 Coupe (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for EK1328G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT LH BOTTOM MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
3	1		*SUPPORT FOG LAMP RH	Not Necessary	37.60 FS	*- FS
4	1		*FRT LH TOP MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
5	1		*FRT RH TOP MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
6	1		*FRT RH TOP MOUNTING SIDE PANEL	Not Necessary	18.00 FS	*- FS
7	1		*RH OPEN GRID (SPORT LINE)	Not Necessary	80.10 FS	*- FS
8	1		*PARTIALLY OPEN GRID LH (SPORTLINE)	Not Necessary	66.35 FS	*- FS
9	1		*FINISHER ROD CENTRE (SPORTLINE)	Distorted	55.65 FS	*55.65 FS
10	1		*RH FINISHER (SPORTLINE)	Distorted	119.80 FS	*119.80 FS
11	1		*COVER LOWER PART CENTRE	Not Necessary	40.10 FS	*- FS
12	1		*COVER LOWER PART CENTRE	Not Necessary	40.10 FS	*- FS
13	1		*FRT BUMPER PANEL PRIMED (SRA)	Deformed	1,031.90 FS	*1,031.90 FS
14	1		*SET MOUNTING PDC / PMA SENSOR FRT	Not Necessary	84.10 FS	*- FS
15	10		*BUMPER RIVET	Necessary	5.00 FS	*5.00 FS
16	2		*GROMMET	Not Necessary	1.50 FS	*- FS
17	1		*FRT RH COVER WHEEL ARCH	Not Necessary	115.60 FS	*- FS
18	1		*COVER BOTTOM RH	Not Necessary	115.60 FS	*- FS
19	1		*DEFLECTOR LIP RH	Not Necessary	51.50 FS	*- FS
20	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
21	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
22	1		*SET MOUNTING PDC / PMA SENSOR FRT	Necessary	84.10 FS	*84.10 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,203.55	1,499.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,275.00	850.00
2	SPRAY PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >