

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBQ5512T Yr Regn: 2017 / Feb.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Mit Attrage C.C. 1193
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 40467 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MMB5TA13AHL003942
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R15
 R: 185/55R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 23/05/18
 Survey held at M4 Solution
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP A16</u>
	<u>L/S \$5,800</u>
	<u>MV: 60K</u>
	<u>PV: 436K</u>
	<u>NPH: 164K</u>
	<u>R (\$10,293.07/64%)</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18009457/Aja3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 24-05-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 5726C	Veh. Inspected	SBQ 5512T
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	24/05/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	21/05/2018	Inspection Date	23/05/2018
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG INSURANCE	DATE	: 22/05/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SBQ5512T	MMBSTA13A	
MODEL	: MITSUBISHI ATTRAGE 1.2	Joy	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 21-May-18
		TIME	: 14:50HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Broken d</i>	1	\$ 899.30	\$ 899.30
2	BOOTLID LOGO <i>new</i>	1	\$ 62.20	\$ 62.20
3	BOOTLID EMBLEM"ATTRAGE" <i>new</i>	1	\$ 63.00	\$ 63.00
4	BOOTLID EMBLEM"MIVEC TECHNOLOGY" <i>new</i>	1	\$ 63.00	\$ 63.00
5	BOOTLID EMBLEM"C&C" <i>new</i>	1	\$ 63.00	\$ 63.00
6	BOOTLID TOP LOCK <i>Changed</i>	1	\$ 228.40	\$ 228.40
7	BOOTLID CATCH <i>new</i>	1	\$ 103.00	\$ 103.00
8	BOOTLID HINGE <i>new</i>	2	\$ 123.20	\$ 246.40
9	BOOTLID KEYLESS ANTENNA <i>Combined</i>	1	\$ 233.20	\$ 233.20
10	BOOTLID BUZZER <i>Combined</i>	1	\$ 203.40	\$ 203.40
11	BOOTLID WEATHERSTRIP <i>int</i>	1	\$ 192.00	\$ 192.00
12	BOOTLID SENSOR LOCK <i>new</i>	1	\$ 203.40	\$ 203.40
13	BOOTLID OUTER GARNISH <i>new</i>	1	\$ 220.00	\$ 220.00
14	REAR BUMPER <i>Distorted</i>	1	\$ 822.30	\$ 822.30
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 72.50	\$ 145.00
16	REAR BUMPER AIR VENT <i>new</i>	1	\$ 89.00	\$ 89.00
17	REAR BUMPER AIR VENT COVER <i>Combined</i>	1	\$ 133.00	\$ 133.00
18	REAR BUMPER REFLECTOR <i>combined</i>	2	\$ 63.00	\$ 126.00

19	REAR NUMBER PLATE LAMP(SET) <i>New</i>	1	\$	133.80	\$	133.80	X
20	TAILLAMP <i>cracked</i>	2	\$	463.20	\$	926.40	552
21	TAILLAMP PANEL <i>Repair</i>	2	\$	174.00	\$	348.00	+
22	REAR FENDER <i>Repair</i>	2	\$	680.00	\$	1,360.00	+
23	REAR FENDER INNER TRIM <i>New</i>	2	\$	310.20	\$	620.40	+
24	REAR END PANEL <i>Distorted</i>	1	\$	566.30	\$	566.30	385
25	REAR END PANEL TOP GARNISH <i>Replaced</i>	1	\$	174.00	\$	174.00	-
26	REAR FLOOR PANEL <i>Repair</i>	1	\$	960.80	\$	960.80	+
27	REAR FLOOR PANEL TOP BOARD <i>Cracked</i>	1	\$	233.90	\$	233.90	-
28	EXHAUST PIPE <i>Seal</i>	1	\$	810.00	\$	810.00	576
29	EXHAUST PIPE MOUNTING <i>New</i>	4	\$	62.30	\$	249.20	+
30	EXHAUST PIPE INSULATOR <i>New</i>	1	\$	233.90	\$	233.90	+

4673.50

4206.15

TOTAL PRICE \$ 10,712.30

LESS 10% \$ 1,071.23

SUB TOTAL PRICE \$ 9,641.07

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00
2	BOOTLID OUTER GARNISH CLIP (SET) <i>New</i>	1	\$ 25.00	\$ 25.00
3	BOOTLID STICKER <i>New</i>	1	\$ 125.00	\$ 125.00
4	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 22.00	\$ 22.00
5	TAILLAMP CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
6	TAILLAMP PANEL SEALANT <i>New</i>	1	\$ 20.00	\$ 20.00
7	REAR WINDSCREEN SEALANT <i>2 part New</i>	1	\$ 120.00	\$ 120.00
8	REAR WINDSCREEN INNER SEAL	1	\$ 100.00	\$ 100.00
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
10	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 120.00	\$ 120.00
11	REAR FLOOR PANEL INSULATION SEAL <i>New</i>	1	\$ 120.00	\$ 120.00
12	REVERSE CAMERA <i>New</i>	1	\$ 380.00	\$ 380.00
13	REVERSE SENSOR <i>Replaced</i>	1	\$ 220.00	\$ 220.00

322

TOTAL \$ 1,342.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	120.	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	130.	
3	TUFF COAT	\$ 150.00	50	
4	WIRING CHECK	\$ 150.00	30.	

5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	50	
7	TO REMOVE AND REFIX EXHAUSE PIPE	\$ 320.00	80	
8	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 100.00	X	
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X	
TOTAL		\$5,110.00	2760	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,983.07

TOTAL LABOUR COST : \$ 5,110.00

TOTAL REPAIR COST : \$ 16,093.07

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian King : total: 7288.13
 L/S 23/05/18 L/S 58K
 08 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



EAE Parents' Talk 1 June

Republic Polytechnic

Help your child get into a dream course based on aptitudes and interests. Learn how!



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years COE Renewal Toyota Vios 1.5A

\$2300 Downpayment! Monthly \$580 Onwards! Lowest 3.68% P.A. @ GV Cars Financing! GV Credit Pte Ltd StarAd

HIN LUNG AUTO
No Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category Sort by Date Posted 20 results/page

10 vehicles **Search**

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Attrage	Any	Any	2017	Any	Any	Any	Available



☐ **Mitsubishi Attrage 1.2A** \$58,800 \$6,530 /yr 03-Jan-2017 1,193 cc 40,000 km Sedan Available

COE At \$51507! Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! We Are sgCarMart Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost!...

88 Motor Trading

☆ Posted: 22-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



☐ **Mitsubishi Attrage 1.2A** \$53,888 \$5,950 /yr 12-Jan-2017 1,193 cc 63,600 km Sedan Available

Latest Arrival! Cheapest In Town! Drive Away With No Repairs Needed. Well Maintained By Previous Owner. Hop On With Great Boot Space And Sporty Original Look For Whichever Occasion Needed! Ex Bankrupt...

☆ Posted: 15-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



☐ **Mitsubishi Attrage 1.2A** \$60,800 \$6,740 /yr 13-Jan-2017 1,193 cc 18,000 km Sedan Available

Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! We Are sgCarMart Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost! 100% Accident ...

88 Motor Trading

☆ Posted: 21-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi




☐ **Mitsubishi Attrage 1.2A** \$58,800 \$6,510 /yr 13-Jan-2017 1,193 cc 35,000 km Sedan Available

Viewing And Test Drive! Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! Buy With Confidence! No Hidden Cost! 100% Accident Free! In House Loan...

88 Motor Trading

☆ Posted: 21-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle

Buying a pre-owned car, but unsure of its Condition?
Get a Car Audit Report



☐ **Mitsubishi Attrage 1.2A** \$59,800 \$6,630 /yr 13-Jan-2017 1,193 cc 33,000 km Sedan Available

Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! Buy With Confidence! No Hidden Cost! Low Mileage! 100% Accident Free! In House Loan Or Bank Ld...

88 Motor Trading

☆ Posted: 23-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



☐ **Mitsubishi Attrage 1.2A** \$60,800 \$6,670 /yr 17-Feb-2017 1,193 cc 31,000 km Sedan Available

Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! We Are sgCarMart Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost! 100% Accident ...

88 Motor Trading

☆ Posted: 18-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



☐ **Mitsubishi Attrage 1.2A** \$60,800 \$6,630 /yr 07-Mar-2017 1,193 cc 35,000 km Sedan Available

Fully Serviced By Agent And Under Agent Warranty! \$0 Down Payment Available! Fast And Easy Loan Approval! We Are sgCarMart Premium Dealer 2015-2017! Buy With Confidence! No Hidden Cost! 100% Accident ...

88 Motor Trading

☆ Posted: 13-May-2018 Tags: 2017 Mitsubishi Attrage, Mitsubishi Attrage, Mitsubishi, Attrage, Used Mitsubishi



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6737C
Vehicle Details	
Vehicle No.:	SBQ5512T
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 May 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	3A92UDP3563
Chassis No.:	MMBSTA13AHH003942
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,671.00
Original Registration Date:	21 Feb 2017
First Registration Date:	21 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	20 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$39,800.00
Total Rebate Amount:	\$43,550.00

The information contained herein is correct as at 23 May 2018

OK



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 21/08/2018

Your Ref : SLG5726C

To : AIG ASIA PACIFIC INSURANCE PTE LTD

Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SBQ5512T & SLG5726C ON 21/05/2018 AT
ALONG PASIR RIS DRIVE 1 BEFORE JUNCTION OF LOYANG AVENUE.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.188260 @ S\$6,206.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$540.00 (9 Days x S\$60)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You.

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

PROFORMA BILL

Bill To:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-12 AIG BUILDING

SINGAPORE 079120

Bill No : 188260

Date : 21-August-2018

Vehicle Number : **SBQ 5512T**

ATTN : MOTOR CLAIMS DEPARTMENT

QTY	CLAIM	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 5,800.00
BEFORE GST		5,800.00
7% GST		406.00
TOTAL		\$ 6,206.00

Tax Invoice will be issue upon amount finalised.

Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis with sole intention of resolving the matter amicably without parties resorting to legal proceeding. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.



Co's stamp & Authorised Signature

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No.: 201427344N

MOTOR CLAIM DISCHARGE

INSURED: UGENESIS SERVICES
CAR/LORRY/CYCLE: REG NO: SBQ 55127 POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. SBQ 55127from the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 21 day of 05 2018 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature:



Co's Stamp: NRIC No:

23/5/2018 PRI

Vehicle In. 23/5/2018

27/5/2018 - Sunday

Vehicle Out. 31/5/2018

Loan - 9 days x \$60
= \$540

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Friday, 1 June 2018 5:59 PM
To: Eileen, May Hwee Yap; 'Insurance LCR SG'
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLG 5726C (LCR) & SBQ 5512T & OTHERS ON 21/05/2018 (14:00) ALONG PASIR RIS DR 1

01 June 2018

LION CITY RENTALS PTE LTD

Policy Holder

Your Ref: SLG 5726C
Our Ref: CC6/LCR18009457/Aja3

Dear Sir/Madam,

ACCIDENT INVOLVING SLG 5726C (LCR) & SBQ 5512T & OTHERS ON 21/05/2018 (14:00) ALONG PASIR RIS DR 1

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SBQ 5512T** against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, UGENESIS SERVICES ("the third party claimant")
of 106 PASIR RIS STREET 12 #05-119 SINGAPORE 510106 (address),
owner of SBR 5512T (vehicle no.) hereby authorize
MG SOLUTION PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SBR 5512T that was
damaged pursuant to the accident which occurred on 21/05/2018 (date) along
PASIR RIS DRIVE 1 BEFORE JUNCTION OF LOTANG AVENUE (location)
involving vehicle no/s SLG 5726C ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 23 day of 05 (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"

LETTER OF AUTHORITY

Name : UGENESIS SERVICES
Address : 106 PASIR RIS STREET 12
#05-119 SINGAPORE 510106

Contact No : _____

TO: AIH ASIA PACIFIC INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SBQ5512T AND SLG5726C ON 21/03/2018
AT/ALONG PASIR RIS DRIVE 1 BEFORE JUNCTION OF LOYANG AVENUE

I/We, UGENESIS SERVICES, am/are the registered owner of
motor car no. SBQ5512T

Please note that I have assigned all compensations monies due to me/us in the above said accident
to M/S MG SOLUTION PTE LTD.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to M/S MG SOLUTION PTE LTD and forward your settlement cheque to M/S MG SOLUTION
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant

Witness By

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MG SOLUTION PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,750.00 (Global Sum) for vehicle no. SBO 5512T that was damaged pursuant to the accident which occurred on 21/05/2018 (date) along PASIR RIS DRIVE 1 BEFORE TURNING TO LOYANG AVE (location) involving vehicle no/s SLG 5726C. This is pursuant to the inspection conducted on 23/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner UGENESIS SERVICES ("the third party claimant") of vehicle no. SBO 5512T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SBO 5512T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of 05 (month) **2018** (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-12 AIG BUILDING

SINGAPORE 079120

INVOICE No : TI 189211

PB No : 188260

Date : 21-August-2018

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : *SBQ 5512T*

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 5,800.00
BEFORE GST		5,800.00
7% GST		406.00
TOTAL		\$ 6,206.00

Cheque should be made payable to **MG Solution Pte Ltd**



Co's stamp & Authorised Signature

[» Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SLG5726C	21 May 2018 / 14:50:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.



OK

Save as PDF

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No.: M4-0006529-2

Print Date/Time : 21 May 2018 / 15:47:24

Receipt Date/Time : 21 May 2018 / 15:47:24

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180521-001735

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
-----	--	--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SLG5726C

As at 21 May 2018/14:50:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1	Insurance Enquiry - SLG5726C Enquiry Fee 20180521154625563511	7.00	0.49	7.49
---	---	------	------	------

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

20180521154633785	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018 Edit Reg		23 May 2018 00:00 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K		
Main Claimant:	UGENESIS SERVICES, Co. Reg. No.: 53346737C		
Vehicle Reg. No.:	SBQ5512T	Date of Loss:	21/05/2018 14:00 - :59 [15 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1333435024SG	Policy/Cover Note No.:	0999994801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLG5726C	Policy No. (Claimant):	5097697674
		Excess:	
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/06/2018]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
AIG_SG (25/05/2018): Request To Upload TP GIA Report			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SBQ5512T (1333435024SG)
[SLG5726C]
TP
UGENESIS SERVICES
May 21 2018 2:00PM
[LCRF Pte Ltd]
MG Solution Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser		
Letters/Correspondences										1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown									Edit	
Photos/Images										3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	31/07/18 17:22	General View									Load JPG	☒
2	31/07/18 17:22	General View									Load JPG	☒
3	31/07/18 17:22	General View									Load JPG	☒
4	31/07/18 17:22	General View									Load JPG	☒
5	31/07/18 17:22	General View									Load JPG	☒
6	31/07/18 17:22	General View									Load JPG	☒
7	31/07/18 17:22	General View									Load JPG	☒
8	31/07/18 17:22	General View									Load JPG	☒
9	31/07/18 17:22	General View									Load JPG	☒
10	31/07/18 17:22	General View									Load JPG	☒
11	31/07/18 17:22	General View									Load JPG	☒
12	31/07/18 17:22	General View									Load JPG	☒
13	31/07/18 17:22	General View									Load JPG	☒
14	31/07/18 17:22	General View									Load JPG	☒
15	31/07/18 17:22	General View									Load JPG	☒
16	31/07/18 17:22	General View									Load JPG	☒
17	31/07/18 17:22	General View									Load JPG	☒
18	31/07/18 17:22	General View									Load JPG	☒
19	31/07/18 17:22	General View									Load JPG	☒
20	31/07/18 17:22	General View									Load JPG	☒
21	31/07/18 17:22	General View									Load JPG	☒
22	31/07/18 17:22	General View									Load JPG	☒
23	31/07/18 17:22	General View									Load JPG	☒
24	31/07/18 17:22	General View									Load JPG	☒
25	31/07/18 17:22	General View									Load JPG	☒
26	31/07/18 17:22	General View									Load JPG	☒
27	31/07/18 17:22	General View									Load JPG	☒
28	31/07/18 17:22	General View									Load JPG	☒
29	31/07/18 17:22	General View									Load JPG	☒
30	31/07/18 17:22	General View									Load JPG	☒
31	31/07/18 17:22	General View									Load JPG	☒
32	31/07/18 17:22	General View									Load JPG	☒
33	31/07/18 17:22	General View									Load JPG	☒
34	31/07/18 17:22	General View									Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	31/07/18 17:22	General View	 Load JPG	☒
36	31/07/18 17:22	General View	 Load JPG	☒
37	31/07/18 17:22	General View	 Load JPG	☒
38	31/07/18 17:22	General View	 Load JPG	☒
39	31/07/18 17:22	General View	 Load JPG	☒
40	31/07/18 17:22	General View	 Load JPG	☒
41	31/07/18 17:22	General View	 Load JPG	☒
42	31/07/18 17:22	General View	 Load JPG	☒
43	31/07/18 17:22	General View	 Load JPG	☒
44	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
45	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
46	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
47	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
48	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
49	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
50	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
51	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
52	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
53	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
54	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
55	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
56	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
57	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
58	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
59	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
60	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
61	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
62	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
63	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
64	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
65	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
66	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
67	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
68	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
69	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
70	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
71	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
72	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
73	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
74	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
75	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
76	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
77	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
78	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
79	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
80	31/07/18 17:22	Reinspection Photo	Load JPG	☒
81	31/07/18 17:22	Reinspection Photo	Load JPG	☒
82	31/07/18 17:22	Reinspection Photo	Load JPG	☒
83	31/07/18 17:22	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
85	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
86	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
87	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
88	31/07/18 17:22	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/05/18 15:25	TP GIA REPORT	 Load PDF	
2	21/08/18 14:55	LETTER TO LCRF	 Load PDF	
3	30/08/18 11:04	WORKSHOP INVOICE	 Load PDF	
4	30/08/18 11:04	AUTHORISATION TO ACT FORM	 Load PDF	
5	30/08/18 11:04	Release Voucher	 Load PDF	
6	30/08/18 11:04	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/05/18 15:27	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLG5726C (Insd veh)	Model:	MITSUBISHI ATTRAGE 1.2
	SBQ5512T (TP veh)		CVT (A)
Date of Accident:	21/05/2018		

Global Sum Settlement	: [X]	Yes	[]	No	
Repair Estimate	:	\$	17,219.58		
Final Repair Cost	:	\$	6,750.00		
Loss of Use	:	\$			9.00 days at \$60.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$	6,750.00		

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	MG Solution Pte Ltd	: \$	6,750.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

30 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18009457/AJA3Q2

Date: 30/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994801

Claimant Vehicle No: SBQ5512T Insured Vehicle No: SLG5726C

Date of Loss: 21/05/2018 Nature of Claim: TP Claim No: 1333435024SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBQ5512T**
 Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UDP3563
 Reg. Date: 21/02/2017 (Man. Year: 2016) Chassis No: MMBSTA13AHH003942
 Colour: Silver Odometer: 40467 km
 Engine Capacity: 1193 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,983.07	4,528.15	6,454.92	58.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	2,760.00	2,350.00	45.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,093.07	7,288.15	8,804.92	54.71
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	16,093.07	5,800.00	10,293.07	63.96
+ GST 7.00/7.00% (S\$)	1,126.51	406.00	720.51	63.96
Nett Amount (S\$)	17,219.58	6,206.00	11,013.58	63.96
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,753.45		
Global Sum Settlement (S\$)		6,750.00		

INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 23/05/2018 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	899.30 FL	*798.00 FL
2	1		*BOOTLID LOGO	Necessary	62.20 FL	*62.20 FL
3	1		*BOOTLID EMBLEM ATTRAGE	Necessary	63.00 FL	*63.00 FL
4	1		*BOOTLID EMBLEM MIVEC TECNOLOGY	Necessary	63.00 FL	*63.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	63.00 FL	*63.00 FL
6	1		*BOOTLID TOP LOCK	Damaged	228.40 FL	*228.40 FL
7	1		*BOOTLID CATCH	Not Necessary	103.00 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	246.40 FL	*- FL
9	1		*BOOTLID KEYLESS ANTENNA	Cracked	233.20 FL	*84.00 FL
10	1		*BOOTLID BUZZER	Cracked	203.40 FL	*87.00 FL
11	1		*BOOTLID WEATHERSTRIP	Cut	192.00 FL	*192.00 FL
12	1		*BOOTLID SENSOR LOCK	Not Necessary	203.40 FL	*- FL
13	1		*BOOTLID OUTER GARNISH	Not Necessary	220.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	822.30 FL	*708.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	145.00 FL	*145.00 FL
16	1		*REAR BUMPER AIR VENT	Not Necessary	89.00 FL	*- FL
17	1		*REAR BUMPER AIR VENT COVER	Cracked	133.00 FL	*133.00 FL
18	2		*REAR BUMPER REFLECTOR	Cracked	126.00 FL	*126.00 FL
19	1		*SET REAR NUMBER PLATE LAMP	Not Necessary	133.80 FL	*- FL
20	2		*TAILLAMP	Cracked	926.40 FL	*552.00 FL
21	2		*TAILLAMP PANEL	Repair	348.00 FL	*- FL
22	2		*REAR FENDER	Repair	1,360.00 FL	*- FL
23	1		*REAR FENDER INNER TRIM	Not Necessary	620.40 FL	*- FL
24	1		*REAR END PANEL	Distorted	566.30 FL	*385.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	174.00 FL	*174.00 FL
26	1		*REAR FLOOR PANEL	Repair	960.80 FL	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Cracked	233.90 FL	*233.90 FL
28	1		*EXHAUST PIPE	Bent	810.00 FL	*576.00 FL
29	2		*EXHAUST PIPE MOUNTING	Not Necessary	249.20 FL	*- FL
30	1		*EXHAUST PIPE INSULATOR	Not Necessary	233.90 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	1		*SET BOOTLID OUTER GARNISH CLIP	Not Necessary	25.00 FS	*- FS
33	1		*BOOTLID STICKER	Necessary	125.00 FS	*10.00 FS
34	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
35	1		*SET TAILLAMP CLIP	Necessary	20.00 FS	*20.00 FS
36	1		*TAILLAMP PANEL SEALANT	Not Necessary	20.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	100.00 FS	*- FS
39	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
41	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
42	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
43	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part, S=SpecNett, L=ListItemDisc.

Sub Total (\$\$)	12,054.30	4,995.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,071.23	467.35
Total Parts (\$\$)	10,983.07	4,528.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,300.00
3	TUFF COAT	New	150.00	50.00
4	WIRING CHECK	New	150.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND DIATANCE SETTING	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	50.00
7	TO REMOVE AND REFIX EXHAUST PIPE	New	320.00	80.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	100.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
Gross Labour Cost (\$\$)			5,110.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >