

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8892 J

1 pc	Boot lid — <i>Repl</i>	\$	1,119.00
1 pc	Boot lid lock <i>X sue</i>	\$	99.00
1 pc	Bootlid striker <i>X sue</i>	\$	21.00
1 pc	Bootlid emblem — <i>re</i>	\$	27.00
1 pc	Bootlid CRDi — <i>re</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X sue</i>	\$	96.00
1 pc	Boot lid lower garnish <i>X repair</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 — <i>Repl</i>	\$	132.00
2 pcs	n/s & o/s tail lamp @\$421.00 — <i>re</i>	\$	842.00
2 pcs	n/s & o/s reflector @\$350.00 — <i>re</i>	\$	700.00
2 pcs	Licence lamp @\$30.00 <i>n/s re o/s X sue</i>	\$	60.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	End panel garnish <i>X sue</i>	\$	74.00
1 pc	Spare tyre clamp <i>X sue</i>	\$	6.00
1 pc	Rear bumper — <i>Repl</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X sue</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X sue</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X sue</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X sue</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X sue</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X sue</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X sue</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X sue</i>	\$	92.00
	<i>o/s tail lamp panel — Repl \$218</i>	\$	5,698.00
	Less 10%	\$	569.80
		\$	5,128.20

S/NETT

1 set	Rear bumper clips — <i>re</i>	\$	48.00
1 set	End panel inner garnish clips <i>X re</i>	\$	30.00
1 set	Bootlid lower garnish clips <i>X re</i>	\$	60.00
1 set	Bootlid stickers — <i>re</i>	\$	100.00
1 set	Reverse sensor — <i>skid</i>	\$	280.00 200
1 pc	Rear no. plate with casing — <i>Repl</i>	\$	50.00 35
1 pc	Rear floorboard insulator paddings <i>X re</i>	\$	120.00

24-May-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8892 J

Sundry	\$ 50.00 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard etc	\$ 1,300.00 800
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, <i>tail lamp panel</i>	\$ 1,000.00 900
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 50
	<u>\$ 8,666.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalini Clerk

24/5/18 1400hrs.

4 Days

4/5

After Repair photo

*31/5/18
total 415\$ 4500 / 4 Days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: