

ASS. REC. BY:

REP

CS/ASM18009467/8rd307

Special Instruction

Surveyor

Subashian

ASSIGNMENT (Office)

From Person

Yvonne Ang

of

ASM(CAXA)

Date/Time

24/05/2018

Estimated Cost

Bill to

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SLX 54B

Insured

at Workshop info

Trans Eurokars

Tel:

6360 2846

of

12 Sungai Kendut Ave

443

Policy No.

Claim No.

S8M00175

Sum Insured

Excess:

\$ 1000.00

Make of Veh.

D.O.A. 22/05/2018

(Client's Record)

CA / (REV)

REP. / REV 24 HRS

EVA

H.O.D. Endorsement

Date/Time

3.55pm @ 24/5/18

Person Contacted

Jobi

Vehicle

(IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SLX 54B - X
	Revert thru smart claim; Pending investigation.
4/6/18	Authorize repair; Inform Eun to proceed for repair.
12/6/18	Seek approval for supplementary estimate
21/8/18	Seek approval for supplementary
6/9/18	Supplementary approve
6/9/18	Confirm \$92,571.20 @ 28 down with Trscl24

REF: OD Rev Excess: \$4000

ASSIGNMENT

Frigh

Date:

Veh No: S1 X54B

Vt Regn: 15/4/15

Estimated Cost

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

Make: Porsche 911 GT3

CC: 3399

at Workshop m/s

Colour: Black

A/C: Insured / Std / NI / NA

of

Sp Reading: 12126

T/Radio: Insured / Std / NI / NA

Insured

Eng No:

Policy No:

C/No: WP0222 99255/80498

Claims No:

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Mod: ☒ M / ☐ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Tyre Size: F: 245/35 ZR20

R: 305/30 ZR20

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ M/S / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

696k.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal: 7 mm

R/Bal: 7 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal: 7 mm

L/Bal: 7 mm

Est. Repairs:

days

Res: Yes or No

D.O.A: 22/5/18

D.O.I: 24/5/18

Lump Sum:

%

3 Val: Yes or No

Survey held at: Trans Europe

CA / REV / REP. / 24 HRS

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Confirm \$92371.20 @ 28 days
 Rd: \$19,070.55, 17/.

RECEIVED 30 OCT 2018

17/8/2018

Draw/Time: File Pass to?

typist



Prelim. Report

Final Report

Call/Time: File Return to?

Days Of Repair: 28

Resurvey No. of Trip: 1

Survey Fee

Transportation

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10.

Report Format:

00

Lump Sum / I.B.I: \$92371.20

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Assn (\$



Workshop (\$

300

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18009467/Srd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 24-05-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLX 54B
Policy No.	Coverage (\$)	0.00
Claim No. S8M00175	Excess (\$)	0.00
Assign From SMARTCLAIM (YVONNE ANG)	Assign Date	24/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 22/05/2018	Inspection Date 24/05/2018
Survey held at TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--



Service Request Details

Claim

S8M00I75

LKK AUTO CONSULTANTS PTE LTD (OD) ▾

Reference

None

Loss Date

May 22, 2018

Request Date

May 25, 2018

Due Date

June 4, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SLX54B

Make

PORSCHE 911 GT3

Service Address

NO:12 SUNGEI KADUT AVE, . . 729648

Primary Contact/Insured

WONG SIEW LIN
28 SIGLAP HILL, 456083, Singapore
81770107
dianag@singnet.com.sg

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 4000 PENDING INVESTIGATION

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28.05.2018

Survey Details:

Date of loss	22.05.2018
Date of appointment	24.05.2018
Date of survey	24.05.2018
Location of survey	Eurokars Group

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLX 54B
Make and Model	PORSCHE 911 GT3
Date of registration	15-Apr-15
Excess	4000
Market Value	\$696,000.00
Part Rebate	\$273,301.00
Nett Loss	\$422,699.00

Repair details:

Initial Estimate	\$91,324.44
------------------	-------------

Proposed/Revised repair cost:

Parts	\$33,078.24
Check items (estimate)	\$12,836.24
Labour	\$34,375.00
Total	\$80,289.48
Lump Sum(if applicable)	\$

Number of days for repair	22
---------------------------	----



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Vehicle sustained damages at front portion. Damages consistent. Repair cost economical. We have not authorise repair.

Mandate:

Liability(TP)	%
Proposed repair cost	\$
Loss of use	\$ no. of days
Loss of rental	\$ no. of days
Loss of income	\$ no. of days
LTA search fees	\$
Others	\$
Proposed Total	#VALUE!



EXTENSIVE DAMAge

Type

🔗 Question

Message

Please comment mechanical issue of the vehicle

Reply



RE: EXTENSIVE DAMAge

Type

 Question

Message

Dear Yvonne, According to our surveyor at the time of the inspection, the braking system of the insured vehicle appears to be in good working condition. All the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately of 6mm. Thanks. Jannice

Reply



Re:SLX 54B IA UPLOADED

Type

🔗 Question

Message

Hi Jannice, Please authorise at \$80,289.48 before excess of \$4000.

Reply

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, June 04, 2018 11:20 AM
To: 'eva.kok@eurokars.com.sg'
Cc: 'janice.syn@porsche.com.sg'; 'rickteo@eurokars.com.sg'; 'jobithomas@eurokars.com.sg';
Subject: SUR
RE: OD CLAIMS- SLX54B DOA 22/05/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLX 54B (excess \$4,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Monday, May 28, 2018 4:37 PM
To: eva.kok@eurokars.com.sg; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg
Subject: RE: OD CLAIMS- SLX54B DOA 22/05/2018

Hi Eva,

The case is under investigation. We are still pending approval for insurance.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]

Sent: Monday, May 28, 2018 4:17 PM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>

Cc: janice.syn@porsche.com.sg; rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg

Subject: OD CLAIMS- SLX54B DOA 22/05/2018

Hi,

Please refer to the attached for your perusal.

Please let us have your authorization repair for the vehicle above.

Thank you

Eva Kok

Insurance Claims Officer

Trans Eurokars Pte Ltd

12 Sungei Kadut Avenue

Singapore 729648

Dir: +65 6360 2846 | Fax: +65 63602899 | Email: eva.kok@eurokars.com.sg

Website: www.eurokarsgroup.com



DISCLAIMER

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62863861 FAX : (665) 62864315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12.06.2018

Survey Details:

Date of loss	22.05.2018
Date of appointment	24.05.2018
Date of survey	24.05.2018
Location of survey	Eurokars Group

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLX 548
Make and Model	PORSCHE 911 GT3
Date of registration	15-Apr-15
Excess	4000
Market Value	\$696,000.00
Part Rebate	\$273,301.00
Nett Loss	\$422,699.00


Repair details:

Initial Estimate	\$111,441.75	Include Supplementary \$20,117.31
------------------	--------------	-----------------------------------

Proposed/Revised repair cost:

Parts	\$54,749.63	Include Supplementary \$20,117.31
Check items (estimate)	\$300.00	
Labour	\$40,615.00	
Total	\$95,664.63	
Lump Sum(if applicable)	\$	

Number of days for repair	24
---------------------------	----



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408935 TEL : (065) 62564861 FAX : (065) 62564318

Remarks:

Vehicle sustained damages at front portion. Damages consistent. Repair cost economical. Repair cost include supplementary \$20,117.31

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$ no. of days	
Loss of rental	\$ no. of days	
Loss of income	\$ no. of days	
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, June 13, 2018 3:33 PM
To: 'ANG Yvonne'
Subject: SLX 54B SUPPLEMENTARY
Attachments: SLX 54B SUP + REVISED ESTIMATE.pdf; SLX 54B IA 2nd.pdf; SLX 54B REINSPECTION PHOTO.pdf

Hi Yvonne,

Please refer the attachment. Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, August 20, 2018 6:30 PM
To: ANG Yvonne
Subject: RE: SLX 54B SUPPLEMENTARY S8M00I75 URGENT

Dear Yvonne,

The repairer not agree on the labour. They propose 2 day at \$3,120.00.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANG Yvonne [mailto:yvonne.ang@axa.com.sg]
Sent: Thursday, June 14, 2018 4:56 PM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Subject: FW: SLX 54B SUPPLEMENTARY S8M00I75 URGENT

Hi Janice

For the supplementary labour charge, can we recommend at 1.5 days at \$2340 instead of \$3120.

	Labour Description	
1	TO REPLACE LH / RH FRONT COMPARTMENT SIDE MEMBER AREAS AFFECTED BY THE ACCIDENT.	1560/day

Best Regards,

Yvonne Ang
Assistant Manager
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: yvonne.ang@axa.com.sg



redefining / insurance

AXA's Values at Work:



**Customer
First**



Integrity



Courage



**ONE
AXA**

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Janice Lee (LKKAuto) [<mailto:JaniceLee@lkkauto.com>]

Sent: Wednesday, June 13, 2018 3:33 PM

To: ANG Yvonne <yvonne.ang@axa.com.sg>

Subject: SLX 54B SUPPLEMENTARY

Hi Yvonne,

Please refer the attachment. Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, August 21, 2018 10:26 AM
To: 'ANG Yvonne'
Subject: SLX 54B S8M00I75 DOA : 22.05.2018
Attachments: SLX 54B IA.pdf; SLX 54B FINALISE EST + SUPP 3.pdf; SLX 54B REINSPECTION PHOTO.pdf

Hi Yvonne,

As spoken yesterday, enclosed IA for your reference.

Initial estimate \$112,863.87 (Include supplementary \$21,539.43).
Revised cost : \$92,371.20 (Include check + supplementary)
check : \$0
Total : \$92,371.20

*Initial approved amount is \$80,289.48

Our surveyor had since check and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28.05.2018

Survey Details:

Date of loss	22.05.2018
Date of appointment	24.05.2018
Date of survey	24.05.2018
Location of survey	Eurokars Group

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLX 54B
Make and Model	PORSCHE 911 GT3
Date of registration	15-Apr-15
Excess	4000
Market Value	\$696,000.00
Part Rebate	\$273,301.00
Nett Loss	\$422,699.00

Repair details:

Initial Estimate	\$112,863.87	(Include Supplementary \$9,465 + \$10,652.31 + \$1,422.12 = \$21,539.43)
------------------	--------------	---

Proposed/Revised repair cost:

Parts	\$51,506.20	(Inc Supplementary \$21,539.43)
Check items (estimate)		
Labour	\$40,865.00	
Total	\$92,371.20	
Lump Sum(if applicable)	\$	

Number of days for repair	28
---------------------------	----



Auto
Consultants
Pte Ltd

81 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (665) 62563561 FAX : (665) 62564315

Remarks:

Vehicle sustained damages at front portion. Damages consistent. Repair cost economical.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

Janice Lee (LKKAUTO)

From: ANG Yvonne <yvonne.ang@axa.com.sg>
Sent: Thursday, September 06, 2018 2:22 PM
To: Janice Lee (LKKAUTO)
Subject: RE: SLX 54B S8M00I75 DOA : 22.05.2018

Hi Janice

As spoken, please proceed to authorize the supplementary parts below

Regards

Yvonne Ang
Assistant Manager
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: yvonne.ang@axa.com.sg
DID: 1800 880 4888



redefining / insurance

AXA's Values at Work:



**Customer
First**



Integrity



Courage



**ONE
AXA**

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, August 21, 2018 10:26 AM
To: ANG Yvonne <yvonne.ang@axa.com.sg>
Subject: SLX 54B S8M00I75 DOA : 22.05.2018

Hi Yvonne,

As spoken yesterday, enclosed IA for your reference.

Initial estimate \$112,863.87 (Include supplementary \$21,539.43).
Revised cost : \$92,371.20 (Include check + supplementary)

check : \$0
Total : \$92,371.20

*Initial approved amount is \$80,289.48

Our surveyor had since check and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7221A
Vehicle Details	
Vehicle No.:	SLX54B
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	PORSCHE
Vehicle Model:	911 GT3
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	MA175E10343
Chassis No.:	WP0ZZZ99ZE5180498
Maximum Power Output:	320.0 kW (429 bhp)
Open Market Value:	\$181,872.00
Original Registration Date:	15 Apr 2015
First Registration Date:	15 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$299,370.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2025
PARF Rebate Amount:	\$224,527.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$48,774.00
Total Rebate Amount:	\$273,301.00


The information contained herein is correct as at 28 May 2018

OK





**DRIVE-AWAY
LEASING PROGRAMME**
LEARN MORE
WIDE VARIETY OF VEHICLES


incapepreowned.com.sg

6303 6303

porsche 911

Price Range

Depreciation

2015

Vehicle Type



Advanced Search

Used Car Comparison

— Comparing 2 Vehicles —

Porsche 911 GT3 RS PDK

Porsche 911 GT3 RS PDK



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

Price	\$799,000	\$728,800	-	-
Instalment	\$6,898	\$6,292	-	-
Registration Date	03-Aug-2015	15-Sep-2015	-	-
Manufactured	2015	2015	-	-
Mileage	9,800 km	21,000 km	-	-
Transmission	Auto	Auto	-	-
Engine Cap	3,996 cc	3,996 cc	-	-
Road Tax	\$3,944 /yr	\$3,944 /yr	-	-
Power	368.0 kW (493 bhp)	368.0 kW (493 bhp)	-	-
Curb Weight	1,420 kg	1,420 kg	-	-
Features	4L Flat-Six Producing 500hp And 460nm, 0-100 KM/H In 3.3 Sec And A Top Speed Of 310KM/Hr.	3996cc Flat 6 Naturally Aspirated Engine With 7 Speed PDK Transmission Producing 512 Bhp And 470Nm, 0 To 100 Km/H 3.2secs. Top Speed 312Km/H.	-	-
Accessories	20/21" RS Wheel, Black / Lava Orange Leather / Alcantara Interior, Full Carbon Interior, Carbon Door Sills, Porsche Sport Pedal Set, Clubsport Packag	Bi-Xenon Headlights In Black Inclu.Porsche Dynamic Light System (PDLs), Deletion Of ClubSport Package, Lava Orange Seat Belts.	-	-
Description	Sound Package, Lifter, PASM, Smoker Package, Track App, LED Headlight With Dynamic Cornering Light, Sports Pedals, Dynamic Engine Mount, Acoustic Package, Options Middle Radiator, Roll Cage In Lava Orange, 918 Spyder CF Bucket Seats, CF Door Sills, (PTV+), TPMS Etc (Too Long To List). One Of The Very Few Highly Spec GT3RS. 5 Years Stuggart Warranty/ Maintenance. Owner Selling Due To Upgrading.	Front Axle Lifting System, Light Design Package, Mobile Phone Preparation,Smoking Package, Sound Package Plus, Sports Chrono Package Included. Porsche Track Precision And Preparation For Laptrigger, Sports Bucket Seats, White Instrument Dial. Beautiful Lava Orange GT3 RS No Need Further Introduction! There Are No Old Porsches, Only New Owners.	-	-
COE	\$58,109	\$62,101	-	-
OMV	\$211,937	\$194,624	-	-
ARF	\$353,487	\$322,324	-	-
Depreciation	\$86,490 /yr	\$77,630 /yr	-	-
No. of Owners	2	2	-	-
Type of Vehicle	Sports	Sports	-	-
Category	PARF Car, Direct Owner Sale, Rare & Exotic, Low Mileage Car	PARF Car, Rare & Exotic, Low Mileage Car	-	-

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/05/2018 15:09
Date Of Accident	22/05/2018 08:35
Exact Location Of Accident	ALONG CTE BEFORE MOULMEIN RD EXIT AFT KAMPONG JAVA
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLX54B
Insured/Policyholder	
Name Of Registered Owner	WONG SIEW LIN
NRIC No	S0137221A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91770107
Alternative Phone No	OTHERS-91770107
Vehicle Particulars	
Manufacturer	PORSCHE
Model	911 GT3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken:	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPX/P1962454
Cover Note Number	
Driver	
Name of Driver	GOH PEI MIN, JOLENE
NRIC No	S8225750J
Date Of Birth	12/08/1982
Occupation	INDOOR
Date Of Driving Pass	30/03/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91770107
Fax Number	
Contact Number	
EMail Address	JOLENEGOH@GMAIL.COM

Address	28 SIGLAP HILL
Postcode	456083
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG1099S
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANDREW ONG
NRIC/Passport Number	
Contact Number	97921924
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



$$\left| \frac{\Delta}{c} \right| - \text{Unterwasser}$$

$\begin{bmatrix} \Delta \\ B \end{bmatrix}$ - SkG 10995

$\begin{bmatrix} \Delta \\ B \end{bmatrix} - \text{SLX } 54B -$

On 22/05/2018 around 0835 hrs, I was driving along CTE Northbound, just before Moulmein Rd exit, after Kampung Jawa. Vehicle C applied sudden brakes. Vehicle B followed too, but I could not stop in time and rear ended onto the rear portion of Vehicle B.

I/We declare the foregoing particulars are true in every respect.

Fuller

Trully,

Janice Sy  

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel: (65)63387288 Fax: (65)63382522
 Website: www.axa.com.sg
 GST Registration Number: 199903512M
Customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

• Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) • Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 • Road Transport Act, 1987 (Malaysia) • Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.	: VPX/P1962454	Account No. :	10960
Coverage	: Comprehensive		
Sum Insured	: SGD 595,000.00		
Name of Policy Holder	: WONG SIEW LIN		
Vehicle Registration No.	: SLX54B		
Period of Insurance	: From 31/01/2018 To 14/10/2018 (Both Dates Inclusive)		

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
 The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
- (b) Any Named Driver as stated in the Policy
- (c) 1. WONG SIEW LIN
 2. GOH YONG SIANG
 3. GOH PEI MIN JOLENE
 4. PINKSTON MATTHEW HEATH
- (d) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes. (01)

EXCESS :

Sect I - Used In S'pore Only	: SGD 4,000.00
Sect I - Used Outside S'pore	: SGD 4,000.00
Fire&Theft - Outside Singapore	: SGD 4,000.00
Windscreen Excess	: SGD 500.00

Policy is extended to cover geographical area up to Thailand

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia); are not to be included under these headings.

I/We hereby certify that the policy to which this Certification relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Authorized Workshop



Stuttgart Auto Pte Ltd
 Eurokars Group of Companies

AXA INSURANCE PTE LTD

Authorized Signature

Issued by -SGOTCAS2 on 07/02/2018

IMPORTANT:

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with the obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act, (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period falling which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIM DEPT FAX: 68804838 / 68804739		NAME: Ms Wong Siew Lin ADDRESS: 28 Siglap Hill Singapore 456083 TEL:	WIP: 34262 EXCESS: DATE: 24.05.2018
VEH NO:	SLX54B	DATE IN:	CONTACT PERSON: RICK 63602445
CHASSIS NO:	WPOZZZ99ZES18049B	MILEAGE:	TYPE OF CLAIM: OD
MODEL:	911 GT3	DATE REG.: 15.04.2015	POLICY NO.:

NATURE OF WORKS

S/NO	Parts Description	QTY		REVISED	PRICES
1	FRONT FENDER LH ✓ CAR	1	P991-503-031-00-GRV	107.80	\$ 1,017.80
2	FRONT FENDER RH ✓ CAR	1	P991-503-032-00-GRV	107.80	\$ 1,017.80
3	FRONT BUMPER ✓ CAR	1	P991-505-191-90-	10143.70	\$ 10,143.70
4	TOW COVER ✓ MS	1	P991-505-703-91-	65.50	\$ 65.50
5	FRONT BUMPER LOWER SPOILER ✓ CRF	1	P991-505-525-90-1E0	694.10	\$ 694.00
6	FRONT BUMPER RETAINING FRAME LH ✓ CRF	1	P991-505-563-90-1E0	232.70	\$ 232.70
7	FRONT BUMPER RETAINING FRAME RH ✓ CRF	1	P991-505-564-90-1E0	232.70	\$ 232.70
8	RETAINING FRAME VENTILATION GRILLE LH ✓ Defon	1	P991-505-713-91-	205.40	\$ 205.40
9	RETAINING FRAME VENTILATION GRILLE RH ✓ Defon	1	P991-505-714-91-	205.40	\$ 205.40
10	VENTILATION GRILLE TRIM LH ✓ NEC	1	P991-505-715-90-1E0	89.90	\$ 89.90
11	VENTILATION GRILLE TRIM RH ✓ NEC	1	P991-505-716-90-1E0	89.90	\$ 89.90
12	FRONT BUMPER SIDE SPOILER LH ✓ NEC	1	P991-505-527-90-1E0	56.10	\$ 56.10
13	FRONT BUMPER SIDE SPOILER RH ✓ NEC	1	P991-505-528-90-1E0	56.10	\$ 56.10
14	FRONT BUMPER SIDE RETAINER LH ✓ NEC	1	P991-505-535-00-	40.90	\$ 40.90
15	FRONT BUMPER SIDE RETAINER RH ✓ NEC	1	P991-505-536-00-	40.90	\$ 40.90
16	NUMBER PLATE BRACKET (GT3-3) ✓ CRK	1	P991-701-051-90-1E0	45.90	\$ 45.90
18	FRONT BUMPER SPEED NUT ✓ NEC	6	P999-507-104-01-	3.60	\$ 3.60
19	RETAINING FRAME NUT ✓ NEC	4	P999-084-638-01-	20.40	\$ 20.40
20	FRONT BUMPER RETAINER PLATE LH ✓ NEC	1	P991-505-317-00-	18.30	\$ 18.30
21	FRONT BUMPER RETAINER PLATE RH ✓ NEC	1	P991-505-318-00-	18.30	\$ 18.30
22	RETAINER PLATE BLIND RIVET ✓ NEC	4	P999-190-191-30-	20.80	\$ 20.80
23	RETAINER PLATE CLIP ✓ NEC	2	P997-505-719-00-	64.80	\$ 64.80
24	FRONT BUMPER CABLE CLAMP X AN	7	P999-507-164-01-	X	\$ 43.40
25	FRONT BUMPER CENTER VENTILATION GRILLE ? X NN	1	P991-505-711-91-	X	\$ 406.30
26	FRONT BUMPER CENTER RETAINING FRAME ? ✓ CRF	1	P991-505-569-90-1E0	220.10	\$ 220.10
27	FRONT BUMPER CENTER AIR DUCT ? X NN	1	P991-575-141-90-1E0	X	\$ 187.10
28	RADITOR FRAME ? ✓ CRF	1	P991-504-487-91-1E0	136.40	\$ 136.40
29	RADITOR FRAME BEARING PIN ? ✓ CRF	2	P991-504-587-90-	22.00	\$ 22.00
30	BEARING PIN BOLT ? ✓ CRF	2	P999-919-133-09-	3.40	\$ 3.40
31	RADITOR AIR DUCT TOP ✓ Defon	1	P991-504-489-90-1E0	132.80	\$ 132.80
32	FRONT BUMPER TOP VENTILATION GRILLE ✓ TV	1	P991-505-717-92-	345.80	\$ 345.80
33	FRONT BUMPER TOP VENTILATION GRILLE FRAME ✓ CRF	1	P991-505-567-90-1E0	201.40	\$ 201.40
34	TOP VENTILATION GRILLE FRAME SCREW ✓ NEC	5	P999-919-268-01-	45.50	\$ 45.50
35	FRONT BUMPER REINFORCEMENT ✓ OT	1	P991-505-121-90-	1507.30	\$ 1,507.30
36	REINFORCEMENT SEAL ✓ NEC	2	P991-505-771-00-	13.60	\$ 13.60
37	REINFORCEMENT SCREW ✓ NEC	6	P900-378-351-01-	25.20	\$ 25.20

38	BONNET	✓ BT	1	P991-511-011-04-GRV	2085.40	\$	2,085.40
39	FRONT PANEL TOP SUPPORT	✓ BT	1	P9P1-806-620- -GRV	102.10	\$	102.10
40	BONNET LOCK LOWER PART	✓ IM	1	P991-511-033-05-	446.80	\$	446.80
41	LOCK LOWER PART SCREW	✓ NEC	2	P999-919-717-01-	3.00	\$	3.00
42	LOCK LOWER PART ACTUATOR	2044 NN	1	P991-504-117-80-	X	\$	144.30
43	BONNET DAMPER	✓ DMG	2	P991-511-551-00-	133.40	\$	133.40
44	BONNET GASKET	✓ NEC	1	P991-511-611-03-	166.50	\$	166.50
45	BONNET LOCK UPPER PART	✓ BT	1	P991-511-051-00-	31.50	\$	31.50
46	LOCK UPPER PART SCREW	✓ NEC	2	P999-073-378-02-	4.00	\$	4.00
47	LOCK UPPER PART PROTECTION CAP	X NN	1	P991-511-649-00-	X	\$	3.20
48	BONNET RUBBER STOPPER	✓ NEC 1pc	2	P999-703-140-41-	5.10	\$ 5.10	10.20
49	BONNET HINGE LH	✓ BT	1	P991-511-151-03-	134.10	\$	134.10
50	BONNET HINGE RH	✓ BT	1	P991-511-152-03-	134.10	\$	134.10
51	BONNET HINGE NUT	✓ NEC	4	P999-076-066-09-	4.40	\$	4.40
52	BONNET HINGE SCREW	✓ NEC	4	PN -911-883-02-	6.00	\$	6.00
53	DOOR LH	R	1	P991-531-911-01-GRV		\$	1,841.70
54	DOOR RH	R	1	P991-531-912-01-GRV		\$	1,841.70
55	DOOR CAP BIG	X	2	P9P1-837-111-B-		\$	34.20
56	DOOR CAP SMALL	X	2	P9P1-837-111-A-1E0	X	\$	23.60
57	DOOR INSULATION	X	2	P997-556-531-01-		\$	74.00
58	DOOR PROTECTIVE FILM	X	4	P996-537-337-00-		\$	154.80
59	DOOR GASKET OUTER LH	X	1	P991-537-377-02-		\$	429.40
60	DOOR GASKET OUTER RH	X	1	P991-537-378-02-		\$	429.40
61	FRONTY LUGGAGE COMPARTMENT FASTENER	✓ NEC	2	P999-507-294-40-	2.00	\$	2.00
62	FRONTY LUGGAGE COMPARTMENT LINING	? X NN	1	P991-551-051-01-A31	X	\$	433.50
63	FRONT COMPARTMENT TOP COVER LH	✓ Defau	1	P991-555-465-03-1E0	183.00	\$	183.00
64	FRONT COMPARTMENT TOP COVER LH RH	✓ MS	1	P991-555-466-03-1E0	183.00	\$	183.00
65	TOP COVER SPACER	✓ NEC	5	P999-209-084-40-	8.50	\$	13.50
66	TOP COVER CLAMP	✓ NEC	5	P999-507-047-01-	5.50	\$	5.50
67	FRONT COMPARTMENT CENTER LOCK COVER	✓ CRK	1	P991-555-411-00-1E0	114.60	\$	114.60
68	CENTER LOCK COVER CLIP	✓ NEC	2	P999-507-839-01-	2.20	\$	2.20
69	BATTERY COVER UPPER	✓ Defau	1	P991-555-367-07-1E0	320.70	\$	320.70
70	DASHBOARD TRIM	BR	1	P991-552-102-05-DRK	6663.50	\$	6,663.50
71	REAR VIEW MIRROR	✓ DMG	1	P991-731-511-01-1E0	249.80	\$	249.80
72	REAR VIEW MIRROR COVER RH	✓ CRK	1	P991-731-812-01-1E0	12.00	\$	12.00
73	REAR VIEW MIRROR COVER LH	✓ CRK	1	P991-731-811-01-1E0	12.00	\$	12.00
74	BONNET EMBLEM	✓ NEC	1	P991-559-211-00-	236.90	\$	236.90
75	EMBLEM GASKET	✓ NEC	1	P991-559-215-02-	11.70	\$	11.70
76	EMBLEM NUT	✓ NEC	2	P999-591-423-03-	10.20	\$	10.20
77	EMBLEM ADHESIVE FILM	✓ NEC	1	P999-911-756-41-	2.20	\$	2.20
78	SEAT BELT	✓ JM	2	P991-803-033-04-N13	1690.00	\$	1,690.00
79	SEAT BELT SCREW LOWER	✓ NEC NN	2	P999-510-048-01-	X	\$	17.80
80	SEAT BELT SCREW UPPER	✓ NEC	2	PN -989-261-02-	7.40	\$	7.40
81	SEAT-BELT BUCKLE PASSENGER	X NN	1	P991-803-183-05-	X	\$	244.10
82	SEAT-BELT BUCKLE DRIVER'S	X JM	1	P991-803-184-02-	244.10	\$	244.10
83	AIRBAG UNIT PASSENGER'S SIDE	✓ Activated	1	P991-803-071-00-	2806.60	\$	2,806.60
84	STEERING AIRBAG UNIT	✓ Activated	1	P991-803-089-09-A34	2981.00	\$	2,981.00
85	CONDENSER	X NN	2	P991-573-111-04-	X	\$	1,425.80
86	CONDENSER O-RING	✓ NEC	3	P999-707-557-41-	15.30	\$	15.30
87	CONDENSER SCREW	✓ NEC	1	P900-075-340-01-	6.40	\$	6.40
88	CONDENSER PRESSURE LINE UPPER	✓ BT	1	P991-573-105-80-	694.60	\$	694.60
89	CONDENSER PRESSURE LINE LOWER	✓ BT	1	P991-573-103-80-	694.60	\$	694.60
90	PRESSURE LINE SCREW	✓ NEC	5	PN -104-144-02-	14.00	\$	14.00

91	CONDENSER AIR DUCT RH	1	P991-575-322-90-1E0	232.60	\$	232.60	
92	CONDENSER AIR DUCT LH	1	P991-575-321-90-1E0	232.60	\$	232.60	
93	FRONT SENSOR AIRBAG	2	P991-618-223-01-	440.40	\$	440.40	
94	FRONT BUMPER WIRING HARNESS	1	P991-612-938-01-	923.30	\$	923.30	
95	FRONT BUMPER WASHER NOZZLE	2	P997-628-163-01-	328.40	\$	328.40	
96	HEADLAMP LH - BLACK	1	P991-631-995-52-	3884.40	\$	3,884.40	
97	HEADLAMP RH - BLACK	1	P991-631-996-52-	3884.40	\$	3,884.40	
98	HEADLAMP SUPPORT LH	1	P991-631-201-02-	204.30	\$	204.30	
99	HEADLAMP SUPPORT RH	1	P991-631-202-03-	227.80	\$	227.80	
100	SIDE INDICATOR LIGHT (LH)	1	P991-631-255-06-	124.40	\$	124.40	
101	SIDE INDICATOR LIGHT (RH)	1	P991-631-256-06-	124.40	\$	124.40	
102	FRONT ADDITIONAL HEADLAMP LH	1	P991-631-151-81-	1177.60	\$	1,177.60	
103	FRONT ADDITIONAL HEADLAMP RH	1	P991-631-152-81-	1177.60	\$	1,177.60	
104	FRONT END PANEL	1	P991-501-431-01-GRV	468.60	\$	468.60	
105	FRONT END PANEL TOP FRAME	1	P991-501-231-02-GRV	435.90	\$	435.90	
106	BLIND RIVET	100	P999-190-228-01-	460.00	\$	460.00	
107	ADHESIVE	2	P000-043-305-41-	816.20	\$	816.20	
108	ACTIVATOR	2	P000-043-305-31-	343.20	\$	343.20	
109	MIXING TUBE	2	P000-043-206-32-	51.40	\$	51.40	
110	WINDSCREEN	1	P991-541-911-06-	1579.30	\$	1,579.30	
111	ADHESIVE FILM FOR RAIN SEN	1	P9A7-955-609-00-	63.00	\$	63.00	
TOTAL PARTS					\$	62,386.80	64993
LESS 20%					\$	12,477.36	
TOTAL PARTS COST					\$	49,909.44	50303.2
Labour Description							
1	TO REPLACE FRONT BUMPER, BONNET, LH/RH FRT FENDER, LH/RH DOOR & FRONT COMPARTMENT PANELS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			1560/day	\$	18,720.00	15600
2	TO RESPRAY FRONT BUMPER, BONNET, LH/RH FRONT FENDERS, LH/RH DOORS, FRONT COMPARTMENT PANELS.			1300/bumper 1100/others	\$	8,100.00	7900
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.			200	\$	350.00	200
4	TO CARRY-OUT BODY CAVITY PRESERVATION.			200	\$	350.00	200
6	TO REMOVE & REPLACE RADIATOR, CONDENSER AND RADIATOR FAN ASSY.			1560	\$	3,120.00	1560
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			NETT 500	\$	500.00	✓
8	TO REMOVE & REPLACE THE DASH BOARD ASSY.			NETT 3120	\$	3,120.00	✓
9	TO REMOVE & REPLACE THE AIR BAGS, AIR BAG ECU AND SEAT BELTS.			NETT 3120	\$	3,120.00	✓
10	TO TRANSFER THE LH/RH DOOR MECHANISM.			NETT X	\$	1,560.00	X
11	TO REMOVE & REFIT THE FRONT WINDSCREEN GLASS.			NETT 560	\$	560.00	✓
12	TO SUPPLY SEALER ON THE FRONT WINDSCREEN GLASS.			NETT 195	\$	195.00	✓

13	TO SUPPLY SOLAR FILM ON THE FRONT WINDSCREEN GLASS.	NETT 300	\$ 300.00	✓
14	TO SUPPLY 1 PC CHASSIS STICKER. NEL	NETT 150	\$ 150.00	✓
15	TO SUPPLY 1 PC NUMBER PLATE NEL	NETT 70	\$ 70.00	✓
16	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT 250	\$ 250.00	✓
17	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT 600	\$ 600.00	✓
18	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. Receipt	NETT X	\$ 300.00	236
19	SUNDRIES.	NETT 50	\$ 50.00	✓

TOTAL LABOUR	\$ -	\$ 41,415.00
TOTAL PARTS	\$ -	\$ 49,909.44
TOTAL	\$ -	\$ 91,324.44
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

91,324.44
5: \$21,539.43
112,863.87

Sebastian.
24/5/18

- Part by part repair.
- Question mark I am Photo.
- Photo Before Paint.
- Excess : \$4000
- Revert

22/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

113008.64



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD		NAME : Ms Wong Siew Lin		WIP : 34262	
8 SHENTON WAY		ADDRESS : 28 Siglap Hill		EXCESS :	
#24-01 AXA TOWER		Singapore 456083		DATE : 25.05.2018	
SINGAPORE 068811		TEL :			
ATTN. : MOTOR CLAIM DEPT					
FAX : 68804838 / 68804739					
VEH NO :	SLX54B	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ99ZES180498	MILEAGE :		TYPE OF CLAIM :	00
MODEL :	911 GT3	DATE REG.:	15.04.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT COMPARTMENT LINER BIG ✓ TN	1	406.00	\$ 406.00
2	FOAM SUPPORT ✓ Rk	1	29.30	\$ 29.30
3	FRONT COMPARTMENT SIDE MEMBER LH ✓ DT	1	439.40	\$ 439.40
4	FRONT COMPARTMENT SIDE MEMBER RH ✓ DT	1	439.40	\$ 439.40
5	SIDE MEMBER BLIND RIVET A ✓ N5C	25	132.50	\$ 132.50
6	SIDE MEMBER BLIND RIVET B ✓ N5C	15	69.00	\$ 69.00
7	FRONT BUMPER ANTENNA ✓ M3	1	192.20	\$ 192.20
8	FRONT BUMPER ANTENNA WIRE HARNESS ✓ DMG	1	142.20	\$ 142.20
TOTAL PARTS				\$ 1,850.00
LESS 10% - 2011				\$ 185.00
TOTAL PARTS COST				\$ 1,665.00
Labour Description				
1	TO REPLACE LH / RH FRONT COMPARTMENT SIDE MEMBER 1560/day			\$ 7,800.00
AREAS AFFECTED BY THE ACCIDENT.				3120
TOTAL LABOUR				\$ - \$ 7,800.00
TOTAL PARTS				\$ - \$ 1,665.00
TOTAL				\$ - \$ 9,465.00
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ - \$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "With" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be subject to final approval

Acknowledged by Repairer:

Signature:

Date:



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
2ND SUPPLEMENTARY

EUROKARS GROUP

AXA INSURANCE PTE LTD		NAME : Ms Wong Siew Lin		WIP : 34262	
8 SHENTON WAY		ADDRESS : 28 Siglap Hill		EXCESS :	
#24-01 AXA TOWER		Singapore 456083		DATE: 11.06.2018	
SINGAPORE 068811		TEL :			
ATTN. : MOTOR CLAIM DEPT					
FAX : 68804838 / 68804739					
VEH NO :	SLX54B	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ99ZES180498	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	911 GT3	DATE REG.:	15.04.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	LH SIDE SECTION PRIME COATED	1 ✓ OT	P991-501-911-01-GRV	3152.10 \$ 3,152.10
2	RH SIDE SECTION PRIME COATED	1 ✓ DT	P991-501-912-01-GRV	3152.10 \$ 3,152.10
3	BLIND RIVET	40 ✓ NEL	P999-190-228-01-	486.10 \$ 324.00
4	RADIATOR SUPPORT	1 ✓ CRK	P991-106-255-02-	13.50 \$ 7.70
TOTAL PARTS				\$ 6,635.90
LESS 10% 20%				\$ 663.59
TOTAL PARTS COST				\$ 5,972.31
Labour Description				
1	TO REMOVE / REPLACE LH / RH SIDE SECTION.			\$ 4,680.00
TOTAL LABOUR				\$ - \$ 4,680.00
TOTAL PARTS				\$ - \$ 5,972.31
TOTAL				\$ - \$ 10,652.31
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ - \$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

Auto Consultants hence notify the Repairer of the following:

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDING TO THE MAN-HOURS INVOLVED.

IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES. The party survey is on a "Without Prejudice" basis. No illegal modification(s) is allowed. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

2 days

Sankhya Sai
11/6/2018

LKK

9086-72

10/22-96



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIM DEPT FAX : 68804838 / 68804739		NAME : Ms Wong Siew Lin ADDRESS : 28 Siglap Hill Singapore 456083 TEL :		WIP : 34262 EXCESS : DATE: 24.05.2018	
VEH NO :	SLX54B	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WPOZZZ99ZE5180498	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	911 GT3	DATE REG.:	15.04.2015	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	ADHESIVE	2	P000-043-305-41	\$ 816.20	
2	ACTIVATOR	1	P000-043-305-31	\$ 173.00	
3	ANTIFREEZE FOR COOLANT	6	PSAL-043-301-48	\$ 113.40	
4	RETAINER PLATE	1	P991-505-761-00	\$ 92.10	
5	FIXING PLATE HEADLAMP WASHER	1	P991-505-762-00	\$ 92.10	
6	SCREW	18	P999-919-268-01	\$ 289.80	
7	CORNER PANEL	1	P991-505-573-00	\$ 97.65	
8	BLIND RIVET	4	P999-190-191-30	\$ 20.80	
9	REPAIR KIT	1	P991-505-313-90	\$ 77.30	
10	WINDSCREEN	1	P991-541-911-06	\$ 1,592.80	Repair
11	ADHENSIVE FILM FOR RAIN SENSOR	1	P9A7-955-609-00	\$ 63.60	Repair
12	PAN HEAD SCREW	1	P9A7-007-755-00	\$ 5.30	
TOTAL PARTS				\$ 3,434.05	\$ 1777.65
LESS 20%				\$ 686.81	\$
TOTAL PARTS COST				\$ 2,747.24	\$ 1422.12



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE PTE LTD		NAME : Ms Wong Siew Lin		WIP : 34262	
8 SHENTON WAY		ADDRESS : 28 Siglap Hill		EXCESS :	
#24-01 AXA TOWER		Singapore 456083		DATE: 24.05.2018	
SINGAPORE 068811		TEL :			
ATTN. : MOTOR CLAIM DEPT					
FAX : 68804838 / 68804739					
VEH NO :	SLX54B	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WPOZZZ99ZES180498	MILEAGE :		TYPE OF CLAIM :	OD
MODEL :	911 GT3	DATE REG.:	15.04.2015	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	FRONT FENDER LH ✓ CRK	1		\$ 1,017.80
2	FRONT FENDER RH ✓ CRK	1		\$ 1,017.80
3	FRONT BUMPER ✓ CRK	1		\$ 10,143.70
4	TOW COVER VMS	1		\$ 65.50
5	FRONT BUMPER LOWER SPOILER ✓ CRK	1		\$ 694.00
6	FRONT BUMPER RETAINING FRAME LH ✓ CRK	1		\$ 232.70
7	FRONT BUMPER RETAINING FRAME RH ✓ CRK	1		\$ 232.70
8	RETAINING FRAME VENTILATION GRILLE LH ✓ Defan	1		\$ 205.40
9	RETAINING FRAME VENTILATION GRILLE RH ✓ Defan	1		\$ 205.40
10	VENTILATION GRILLE TRIM LH ✓ NEC	1		\$ 89.90
11	VENTILATION GRILLE TRIM RH ✓ NEC	1		\$ 89.90
12	FRONT BUMPER SIDE SPOILER LH ✓ NEC	1		\$ 56.10
13	FRONT BUMPER SIDE SPOILER RH ✓ NEC	1		\$ 56.10
14	FRONT BUMPER SIDE RETAINER LH ✓ NEC	1		\$ 40.90
15	FRONT BUMPER SIDE RETAINER RH ✓ NEC	1		\$ 40.90
16	NUMBER PLATE BRACKET (GT3-3) ✓ CRK	1		\$ 45.90
18	FRONT BUMPER SPEED NUT ✓ NEC	6		\$ 3.60
19	RETAINING FRAME NUT ✓ NEC	4		\$ 20.40
20	FRONT BUMPER RETAINER PLATE LH ✓ NEC	1		\$ 18.30
21	FRONT BUMPER RETAINER PLATE RH ✓ NEC	1		\$ 18.30
22	RETAINER PLATE BLIND RIVET ✓ NEC	4		\$ 20.80
23	RETAINER PLATE CLIP ✓ NEC	2		\$ 64.80
24	FRONT BUMPER CABLE CLAMP X	7		\$ 43.40
25	FRONT BUMPER CENTER VENTILATION GRILLE ? X	1		\$ 406.30
26	FRONT BUMPER CENTER RETAINING FRAME ? ✓ CRK	1		\$ 220.10
27	FRONT BUMPER CENTER AIR DUCT ? X	1		\$ 187.10
28	RADITOR FRAME ? ✓ CRK	1		\$ 136.40
29	RADITOR FRAME BEARING PIN ? ✓ NEC	2		\$ 22.00
30	BEARING PIN BOLT ? ✓ NEC	2		\$ 3.40
31	RADITOR AIR DUCT TOP ✓ Defan	1		\$ 132.80
32	FRONT BUMPER TOP VENTILATION GRILLE ✓ TN	1		\$ 345.80
33	FRONT BUMPER TOP VENTILATION GRILLE FRAME ✓ CRK	1		\$ 201.40
34	TOP VENTILATION GRILLE FRAME SCREW	5		\$ 45.50
35	FRONT BUMPER REINFORCEMENT ✓ OF	1		\$ 1,507.30
36	REINFORCEMENT SEAL ✓ NEC	2		\$ 13.60
37	REINFORCEMENT SCREW ✓ NEC	6		\$ 25.20

38	BONNET	✓ BT	1	✓	P991-511-011-04-GRV	\$	2,085.40
39	FRONT PANEL TOP SUPPORT	✓ BT	1	✓	P9P1-806-620- -GRV	\$	102.10
40	BONNET LOCK LOWER PART	✓ IM	1	✓	P991-511-033-05-	\$	446.80
41	LOCK LOWER PART SCREW	✓ NEC	2	✓	P999-919-717-01-	\$	3.00
42	LOCK LOWER PART ACTUATOR	✓ DMG	1	✓	P991-504-117-80-	\$	144.30
43	BONNET DAMPER	✓ DMG	2	✓	P991-511-551-00-	\$	133.40
44	BONNET GASKET	✓ NEC	1	✓	P991-511-611-03-	\$	166.50
45	BONNET LOCK UPPER PART	✓ BT	1	✓	P991-511-051-00-	\$	31.50
46	LOCK UPPER PART SCREW	✓ NEC	2	✓	P999-073-378-02-	\$	4.00
47	LOCK UPPER PART PROTECTION CAP	X	1	✓	P991-511-649-00-	\$	3.20
48	BONNET RUBBER STOPPER	✓ NEC	1 pc	✓	P999-703-140-41-	\$	10.20
49	BONNET HINGE LH	✓ BT	1	✓	P991-511-151-03-	\$	134.10
50	BONNET HINGE RH	✓ BT	1	✓	P991-511-152-03-	\$	134.10
51	BONNET HINGE NUT	✓ NEC	4	✓	P999-076-066-09-	\$	4.40
52	BONNET HINGE SCREW	✓ NEC	4	✓	PN -911-883-02-	\$	6.00
53	DOOR LH	R	1	✓	P991-531-911-01-GRV	\$	1,841.70
54	DOOR RH	R	1	✓	P991-531-912-01-GRV	\$	1,841.70
55	DOOR CAP BIG	X	2	✓	P9P1-837-111-B -	\$	34.20
56	DOOR CAP SMALL	X	2	✓	P9P1-837-111-A -1E0	\$	23.60
57	DOOR INSULATION	X	2	✓	P997-556-531-01-	\$	74.00
58	DOOR PROTECTIVE FILM	X	4	✓	P996-537-337-00-	\$	154.80
59	DOOR GASKET OUTER LH	✓	1	✓	P991-537-377-02-	\$	429.40
60	DOOR GASKET OUTER RH	X	1	✓	P991-537-378-02-	\$	429.40
61	FRONTY LUGGAGE COMPARTMENT FASTENER	✓ NEC	2	✓	P999-507-294-40-	\$	2.00
62	FRONTY LUGGAGE COMPARTMENT LINING	? X	1	✓	P991-551-051-01-A31	\$	433.50
63	FRONT COMPARTMENT TOP COVER LH	✓ Defan	1	✓	P991-555-465-03-1E0	\$	183.00
64	FRONT COMPARTMENT TOP COVER RH	✓ MS	1	✓	P991-555-466-03-1E0	\$	183.00
65	TOP COVER SPACER	✓ NEC	5	✓	P999-209-084-40-	\$	13.50
66	TOP COVER CLAMP	✓ NEC	5	✓	P999-507-047-01-	\$	5.50
67	FRONT COMPARTMENT CENTER LOCK COVER	✓ CLK	1	✓	P991-555-411-00-1E0	\$	114.60
68	CENTER LOCK COVER CLIP	✓ NEC	2	✓	P999-507-839-01-	\$	2.20
69	BATTERY COVER UPPER	✓ Defan	1	✓	P991-555-367-07-1E0	\$	320.70
70	DASHBOARD TRIM		1	✓	P991-552-102-05-DRK	\$	6,663.50
71	REAR VIEW MIRROR	✓ DMG	1	✓	P991-731-511-01-1E0	\$	249.80
72	REAR VIEW MIRROR COVER RH	✓ CLK	1	✓	P991-731-812-01-1E0	\$	12.00
73	REAR VIEW MIRROR COVER LH	✓ CLK	1	✓	P991-731-811-01-1E0	\$	12.00
74	BONNET EMBLEM	✓ NEC	1	✓	P991-559-211-00-	\$	236.90
75	EMBLEM GASKET	✓ NEC	1	✓	P991-559-215-02-	\$	11.70
76	EMBLEM NUT	✓ NEC	2	✓	P999-591-423-03-	\$	10.20
77	EMBLEM ADHESIVE FILM	✓ NEC	1	✓	P999-911-756-41-	\$	2.20
78	SEAT BELT	✓ JM	2	✓	P991-803-033-04-N13	\$	1,690.00
79	SEAT BELT SCREW LOWER	✓ NEC	2	✓	P999-510-048-01-	\$	17.80
80	SEAT BELT SCREW UPPER	✓ NEC	2	✓	PN -989-261-02-	\$	7.40
81	SEAT-BELT BUCKLE PASSENGER	X	1	✓	P991-803-183-05-	\$	244.10
82	SEAT-BELT BUCKLE DRIVER'S	X ✓ Activated	1 pc	✓	P991-803-184-02-	\$	244.10
83	AIRBAG UNIT PASSENGER'S SIDE	✓ Activated	1	✓	P991-803-071-00-	\$	2,806.60
84	STEERING AIRBAG UNIT	✓ Activated	1	✓	P991-803-089-09-A34	\$	2,981.00
85	CONDENSER	X	2	✓	P991-573-111-04-	\$	1,425.80
86	CONDENSER O-RING		3	✓	P999-707-557-41-	\$	15.30
87	CONDENSER SCREW	7 } NEC	1	✓	P900-075-340-01-	\$	6.40
88	CONDENSER PRESSURE LINE UPPER		1	✓	P991-573-105-80-	\$	694.60
89	CONDENSER PRESSURE LINE LOWER		1	✓	P991-573-103-80-	\$	694.60
90	PRESSURE LINE SCREW		5	✓	PN -104-144-02-	\$	14.00

91	CONDENSER AIR DUCT RH ? ✓ CRK	1	✓	P991-575-322-90-1E0	\$	232.60
92	CONDENSER AIR DUCT LH ? ✓ CRK	1	✓	P991-575-321-90-1E0	\$	232.60
93	FRONT SENSOR AIRBAG ✓ NRC	2	✓	P991-618-223-01-	\$	440.40
94	FRONT BUMPER WIRING HARNESS ✓ NRC X	1	✓	P991-612-938-01-	\$	923.30
95	FRONT BUMPER WASHER NOZZLE ✓ NRC	2	✓	P997-628-163-01-	\$	328.40
96	HEADLAMP LH - BLACK ✓ CRK	1	✓	P991-631-995-52-	\$	3,884.40
97	HEADLAMP RH - BLACK ? ✓ CRK	1	✓	P991-631-996-52-	\$	3,884.40
98	HEADLAMP SUPPORT LH ✓ NRC	1	✓	P991-631-201-02-	\$	204.30
99	HEADLAMP SUPPORT RH ? X	1	✓	P991-631-202-03-	\$	227.80
100	SIDE INDICATOR LIGHT (LH) ✓ ? X	1	✓	P991-631-255-06-	\$	124.40
101	SIDE INDICATOR LIGHT (RH) ✓ CRK	1	✓	P991-631-256-06-	\$	124.40
102	FRONT ADDITIONAL HEADLAMP LH ✓ SCR	1	✓	P991-631-151-81-	\$	1,177.60
103	FRONT ADDITIONAL HEADLAMP RH ✓ SCR	1	✓	P991-631-152-81-	\$	1,177.60
104	FRONT END PANEL ✓ BT	1	✓	P991-501-431-01-GRV	\$	468.60
105	FRONT END PANEL TOP FRAME ✓ Defan.	1	✓	P991-501-231-02-GRV	\$	435.90
106	BLIND RIVET NRC	100	✓	P999-190-228-01-	\$	460.00
107	ADHESIVE ✓ NRC	2	✓	P000-043-305-41-	\$	816.20
108	ACTIVATOR ✓ NRC	2	✓	P000-043-305-31-	\$	343.20
109	MIXING TUBE ✓ NRC	2	✓	P000-043-206-32-	\$	51.40
110	WINDSCREEN ✓ CRK	1	✓	P991-541-911-06-	\$	1,579.30
111	ADHESIVE FILM FOR RAIN SEN ✓ NRC	1	✓	P9A7-955-609-00-	\$	63.00
TOTAL PARTS					\$	62,386.80
LESS 20%					\$	12,477.36
TOTAL PARTS COST					\$	49,909.44
Labour Description						
1	TO REPLACE FRONT BUMPER, BONNET, LH/RH FRT FENDER, 1560/day				\$	18,720.00
	LH/RH DOOR & FRONT COMPARTMENT PANELS & TO REPAIR ALL					15600
	AREAS AFFECTED BY THE ACCIDENT.					
2	TO RESPRAY FRONT BUMPER, BONNET, LH/RH FRONT FENDERS, 1300/bumper				\$	8,100.00
	LH/RH DOORS, FRONT COMPARTMENT PANELS. 1100/others.					7900.
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.				\$	350.00
						200
4	TO CARRY-OUT BODY CAVITY PRESERVATION.				\$	350.00
						200
6	TO REMOVE & REPLACE RADIATOR, CONDENSER AND RADIATOR FAN ASSY.				\$	3,120.00
						1560
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			NETT	\$	500.00 ✓
8	TO REMOVE & REPLACE THE DASH BOARD ASSY.			NETT	\$	3,120.00 ✓
9	TO REMOVE & REPLACE THE AIR BAGS, AIR BAG ECU AND SEAT BELTS.			NETT	\$	3,120.00 ✓
10	TO TRANSFER THE LH/RH DOOR MECHANISM.			NETT	\$	1,560.00 X
11	TO REMOVE & REFIT THE FRONT WINDSCREEN GLASS.			NETT	\$	560.00 ✓
12	TO SUPPLY SEALER ON THE FRONT WINDSCREEN GLASS.			NETT	\$	195.00 ✓

13	TO SUPPLY SOLAR FILM ON THE FRONT WINDSCREEN GLASS.	NETT	\$	300.00	✓
14	TO SUPPLY 1 PC CHASSIS STICKER.	NETT	\$	150.00	✓
15	TO SUPPLY 1 PC NUMBER PLATE	NETT	\$	70.00	✓
16	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	\$	250.00	✓
17	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$	600.00	✓
18	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>Receipt</i>	NETT	\$	300.00	?
19	SUNDRIES.	NETT	\$	50.00	✓
		TOTAL LABOUR	\$	-	\$ 41,415.00
		TOTAL PARTS	\$	-	\$ 49,909.44
		TOTAL	\$	-	\$ 91,324.44
		LESS EXCESS	\$	-	\$ -
		TOTAL AFTER EXCESS	\$	-	
		GST 7%	\$	-	\$ -
		GRAND TOTAL	\$	-	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian
24/5/18
 - Part by part repair.
 - Question Mark Item Photo
 - Photo Before Paint.
 - Excess: \$4000
 - Revert
 Resurvey
 25/5/18
 1635

24 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIM DEPT FAX : 68804838 / 68804739		NAME : Ms Wong Siew Lin ADDRESS : 28 Siglap Hill Singapore 456083 TEL :		WIP : 34262 EXCESS : DATE: 24.05.2018	
VEH NO :	SLX54B	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WPOZZZ99ZE5180498	MILEAGE :		TYPE OF CLAIM :	□□
MODEL :	911 GT3	DATE REG.:	15.04.2015	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	FRONT FENDER LH	1	P991-503-031-00-GRV	\$ 1,017.80	\$ 1,017.80
2	FRONT FENDER RH	1	P991-503-032-00-GRV	\$ 1,017.80	\$ 1,017.80
3	FRONT BUMPER	1	P991-505-191-90-	\$ 10,143.70	\$ 10,143.70
4	TOW COVER	1	P991-505-703-91-	\$ 65.50	\$ 65.50
5	FRONT BUMPER LOWER SPOILER	1	P991-505-525-90-1E0	\$ 694.00	\$ 694.00
6	FRONT BUMPER RETAINING FRAME LH	1	P991-505-563-90-1E0	\$ 232.70	\$ 232.70
7	FRONT BUMPER RETAINING FRAME RH	1	P991-505-564-90-1E0	\$ 232.70	\$ 232.70
8	RETAINING FRAME VENTILATION GRILLE LH	1	P991-505-713-91-	\$ 205.40	\$ 205.40
9	RETAINING FRAME VENTILATION GRILLE RH	1	P991-505-714-91-	\$ 205.40	\$ 205.40
10	VENTILATION GRILLE TRIM LH	1	P991-505-715-90-1E0	\$ 89.90	\$ 89.90
11	VENTILATION GRILLE TRIM RH	1	P991-505-716-90-1E0	\$ 89.90	\$ 89.90
12	FRONT BUMPER SIDE SPOILER LH	1	P991-505-527-90-1E0	\$ 56.10	\$ 56.10
13	FRONT BUMPER SIDE SPOILER RH	1	P991-505-528-90-1E0	\$ 56.10	\$ 56.10
14	FRONT BUMPER SIDE RETAINER LH	1	P991-505-535-00-	\$ 40.90	\$ 40.90
15	FRONT BUMPER SIDE RETAINER RH	1	P991-505-536-00-	\$ 40.90	\$ 40.90
16	NUMBER PLATE BRACKET (GT3-3)	1	P991-701-051-90-1E0	\$ 45.90	\$ 45.90
18	FRONT BUMPER SPEED NUT	6	P999-507-104-01-	\$ 3.60	\$ 3.60
19	RETAINING FRAME NUT	4	P999-084-638-01-	\$ 20.40	\$ 20.40
20	FRONT BUMPER RETAINER PLATE LH	1	P991-505-317-00-	\$ 18.30	\$ 18.30
21	FRONT BUMPER RETAINER PLATE RH	1	P991-505-318-00-	\$ 18.30	\$ 18.30
22	RETAINER PLATE BLIND RIVET	4	P999-190-191-30-	\$ 20.80	\$ 20.80
23	RETAINER PLATE CLIP	2	P997-505-719-00-	\$ 64.80	\$ 64.80
24	FRONT BUMPER CABLE CLAMP	7	P999-507-164-01-	\$ -	\$ 43.40
25	FRONT BUMPER CENTER VENTILATION GRILLE	1	P991-505-711-91-	\$ -	\$ 406.30
26	FRONT BUMPER CENTER RETAINING FRAME	1	P991-505-569-90-1E0	\$ 220.10	\$ 220.10
27	FRONT BUMPER CENTER AIR DUCT	1	P991-575-141-90-1E0	\$ -	\$ 187.10
28	RADITOR FRAME	1	P991-504-487-91-1E0	\$ 136.40	\$ 136.40
29	RADITOR FRAME BEARING PIN	2	P991-504-587-90-	\$ 22.00	\$ 22.00
30	BEARING PIN BOLT	2	P999-919-133-09-	\$ 3.40	\$ 3.40
31	RADITOR AIR DUCT TOP	1	P991-504-489-90-1E0	\$ 132.80	\$ 132.80
32	FRONT BUMPER TOP VENTILATION GRILLE	1	P991-505-717-92-	\$ 345.80	\$ 345.80
33	FRONT BUMPER TOP VENTILATION GRILLE FRAME	1	P991-505-567-90-1E0	\$ 201.40	\$ 201.40
34	TOP VENTILATION GRILLE FRAME SCREW	5	P999-919-268-01-	\$ 45.50	\$ 45.50
35	FRONT BUMPER REINFORCEMENT	1	P991-505-121-90-	\$ 1,507.30	\$ 1,507.30
36	REINFORCEMENT SEAL	2	P991-505-771-00-	\$ 13.60	\$ 13.60
37	REINFORCEMENT SCREW	6	P900-378-351-01-	\$ 25.20	\$ 25.20
38	BONNET	1	P991-511-011-04-GRV	\$ 2,085.40	\$ 2,085.40
39	FRONT PANEL TOP SUPPORT	1	P991-806-620- -GRV	\$ 102.10	\$ 102.10
40	BONNET LOCK LOWER PART	1	P991-511-033-05-	\$ 446.80	\$ 446.80

41	LOCK LOWER PART SCREW	2	P999-919-717-01-	\$ 3.00	\$ 3.00
42	LOCK LOWER PART ACTUATOR	1	P991-504-117-80-	\$ -	\$ 144.30
43	BONNET DAMPER	2	P991-511-551-00-	\$ 133.40	\$ 133.40
44	BONNET GASKET	1	P991-511-611-03-	\$ 166.50	\$ 166.50
45	BONNET LOCK UPPER PART	1	P991-511-051-00-	\$ 31.50	\$ 31.50
46	LOCK UPPER PART SCREW	2	P999-073-378-02-	\$ 4.00	\$ 4.00
47	LOCK UPPER PART PROTECTION CAP	1	P991-511-649-00-	\$ -	\$ 3.20
48	BONNET RUBBER STOPPER	1	P999-703-140-41-	\$ 5.10	\$ 10.20
49	BONNET HINGE LH	1	P991-511-151-03-	\$ 134.10	\$ 134.10
50	BONNET HINGE RH	1	P991-511-152-03-	\$ 134.10	\$ 134.10
51	BONNET HINGE NUT	4	P999-076-066-09-	\$ 4.40	\$ 4.40
52	BONNET HINGE SCREW	4	PN -911-883-02-	\$ 6.00	\$ 6.00
53	DOOR LH	1	P991-531-911-01-GRV	\$ -	\$ 1,841.70
54	DOOR RH	1	P991-531-912-01-GRV	\$ -	\$ 1,841.70
55	DOOR CAP BIG	2	P991-837-111-8 -	\$ -	\$ 34.20
56	DOOR CAP SMALL	2	P991-837-111-A -1E0	\$ -	\$ 23.60
57	DOOR INSULATION	2	P997-556-531-01-	\$ -	\$ 74.00
58	DOOR PROTECTIVE FILM	4	P996-537-337-00-	\$ -	\$ 154.80
59	DOOR GASKET OUTER LH	1	P991-537-377-02-	\$ -	\$ 429.40
60	DOOR GASKET OUTER RH	1	P991-537-378-02-	\$ -	\$ 429.40
61	FRONTY LUGGAGE COMPARTMENT FASTENER	2	P999-507-294-40-	\$ 2.00	\$ 2.00
62	FRONTY LUGGAGE COMPARTMENT LINING	1	P991-551-051-01-A31	\$ -	\$ 433.50
63	FRONT COMPARTMENT TOP COVER LH	1	P991-555-465-03-1E0	\$ 183.00	\$ 183.00
64	FRONT COMPARTMENT TOP COVER RH	1	P991-555-466-03-1E0	\$ 183.00	\$ 183.00
65	TOP COVER SPACER	5	P999-209-084-40-	\$ 13.50	\$ 13.50
66	TOP COVER CLAMP	5	P999-507-047-01-	\$ 5.50	\$ 5.50
67	FRONT COMPARTMENT CENTER LOCK COVER	1	P991-555-411-00-1E0	\$ 114.60	\$ 114.60
68	CENTER LOCK COVER CLIP	2	P999-507-839-01-	\$ 2.20	\$ 2.20
69	BATTERY COVER UPPER	1	P991-555-367-07-1E0	\$ 320.70	\$ 320.70
70	DASHBOARD TRIM	1	P991-552-102-05-DRK	\$ 6,855.40	\$ 6,663.50
71	REAR VIEW MIRROR	1	P991-731-511-01-1E0	\$ 249.80	\$ 249.80
72	REAR VIEW MIRROR COVER RH	1	P991-731-812-01-1E0	\$ 12.00	\$ 12.00
73	REAR VIEW MIRROR COVER LH	1	P991-731-811-01-1E0	\$ 12.00	\$ 12.00
74	BONNET EMBLEM	1	P991-559-211-00-	\$ 236.90	\$ 236.90
75	EMBLEM GASKET	1	P991-559-215-02-	\$ 11.70	\$ 11.70
76	EMBLEM NUT	2	P999-591-423-03-	\$ 10.20	\$ 10.20
77	EMBLEM ADHESIVE FILM	1	P999-911-756-41-	\$ 2.20	\$ 2.20
78	SEAT BELT	2	P991-803-033-04-N13	\$ 1,690.00	\$ 1,690.00
79	SEAT BELT SCREW LOWER	2	P999-510-048-01-	\$ -	\$ 17.80
80	SEAT BELT SCREW UPPER	2	PN -989-261-02-	\$ 7.40	\$ 7.40
81	SEAT-BELT BUCKLE PASSENGER	1	P991-803-183-05-	\$ -	\$ 244.10
82	SEAT-BELT BUCKLE DRIVER'S	1	P991-803-184-02-	\$ 244.10	\$ 244.10
83	AIRBAG UNIT PASSENGER'S SIDE	1	P991-803-071-00-	\$ 2,806.60	\$ 2,806.60
84	STEERING AIRBAG UNIT	1	P991-803-089-09-A34	\$ 2,981.00	\$ 2,981.00
85	CONDENSER	2	P991-573-111-04-	\$ -	\$ 1,425.80
86	CONDENSER O-RING	3	P999-707-557-41-	\$ 15.30	\$ 15.30

87	CONDENSER SCREW	1	P900-075-340-01-	\$ 6.40	\$ 6.40
88	CONDENSER PRESSURE LINE UPPER	1	P991-573-105-80-	\$ 694.60	\$ 694.60
89	CONDENSER PRESSURE LINE LOWER	1	P991-573-103-80-	\$ 694.60	\$ 694.60
90	PRESSURE LINE SCREW	5	PN -104-144-02-	\$ 14.00	\$ 14.00
91	CONDENSER AIR DUCT RH	1	P991-575-322-90-1E0	\$ 232.60	\$ 232.60
92	CONDENSER AIR DUCT LH	1	P991-575-321-90-1E0	\$ 232.60	\$ 232.60
93	FRONT SENSOR AIRBAG	2	P991-618-223-01-	\$ 440.40	\$ 440.40
94	FRONT BUMPER WIRING HARNESS	1	P991-612-938-01-	\$ -	\$ 923.30
95	FRONT BUMPER WASHER NOZZLE	2	P997-628-163-01-	\$ 328.40	\$ 328.40
96	HEADLAMP LH - BLACK	1	P991-631-995-52-	\$ 3,884.40	\$ 3,884.40
97	HEADLAMP RH - BLACK	1	P991-631-996-52-	\$ 3,884.40	\$ 3,884.40
98	HEADLAMP SUPPORT LH	1	P991-631-201-02-	\$ -	\$ 204.30
99	HEADLAMP SUPPORT RH	1	P991-631-202-03-	\$ 227.80	\$ 227.80
100	SIDE INDICATOR LIGHT (LH)	1	P991-631-255-06-	\$ 124.40	\$ 124.40
101	SIDE INDICATOR LIGHT (RH)	1	P991-631-256-06-	\$ -	\$ 124.40
102	FRONT ADDITIONAL HEADLAMP LH	1	P991-631-151-81-	\$ 1,177.60	\$ 1,177.60
103	FRONT ADDITIONAL HEADLAMP RH	1	P991-631-152-81-	\$ 1,177.60	\$ 1,177.60
104	FRONT END PANEL	1	P991-501-431-01-GRV	\$ 468.60	\$ 468.60
105	FRONT END PANEL TOP FRAME	1	P991-501-231-02-GRV	\$ 435.90	\$ 435.90
106	BLIND RIVET	100	P999-190-228-01-	\$ 810.00	\$ 460.00
107	ADHESIVE	2	P000-043-305-41-	\$ 816.20	\$ 816.20
108	ACTIVATOR	2	P000-043-305-31-	\$ 343.20	\$ 343.20
109	MIXING TUBE	2	P000-043-206-32-	\$ 51.40	\$ 51.40
110	WINDSCREEN	1	P991-541-911-06-	\$ -	\$ 1,579.30
111	ADHESIVE FILM FOR RAIN SEN	1	P9A7-955-609-00-	\$ -	\$ 63.00
SUPPLEMENTARY					
1	FRONT COMPARTMENT LINER BIG	1	P991-551-045-15-A31	\$ 406.00	\$ 406.00
2	FOAM SUPPORT	1	P991-551-465-00-	\$ 29.30	\$ 29.30
3	FRONT COMPARTMENT SIDE MEMBER LH	1	P991-501-535-01-GRV	\$ 439.40	\$ 439.40
4	FRONT COMPARTMENT SIDE MEMBER RH	1	P991-501-536-01-GRV	\$ 439.40	\$ 439.40
5	SIDE MEMBER BLIND RIVET A	25	P999-190-230-01-	\$ 132.50	\$ 132.50
6	SIDE MEMBER BLIND RIVET B	15	P999-190-229-01-	\$ 69.00	\$ 69.00
7	FRONT BUMPER ANTENNA	1	P971-035-510-C -	\$ 192.20	\$ 192.20
8	FRONT BUMPER ANTENNA WIRE HARNESS	1	P9P1-979-020- -	\$ 142.20	\$ 142.20
9	LH SIDE SECTION PRIME COATED	1	P991-501-911-01-GRV	\$ 3,152.10	\$ 3,152.10
10	RH SIDE SECTION PRIME COATED	1	P991-501-912-01-GRV	\$ 3,152.10	\$ 3,152.10
11	BLIND RIVET	40	P999-190-228-01-	\$ 324.00	\$ 324.00
12	RADIATOR SUPPORT	1	P991-106-255-02-	\$ 13.50	\$ 7.70
13	BLIND RIVET	20	P999-190-228-01-	\$ 162.00	\$ 162.00
14	ADHESIVE	2	P000-043-305-41	\$ 816.20	
15	ACTIVATOR	1	P000-043-305-31	\$ 173.00	
16	ANTIFREEZE FOR COOLANT	6	PSAL-043-301-48	\$ 113.40	
17	RETAINER PLATE	1	P991-505-761-00	\$ 92.10	
18	FIXING PLATE HEADLAMP WASHER	1	P991-505-762-00	\$ 92.10	
19	SCREW	18	P999-919-268-01	\$ 289.80	
20	CORNER PANEL	1	P991-505-573-00	\$ 97.65	
21	BLIND RIVET	4	P999-190-191-30	\$ 20.80	
22	REPAIR KIT	1	P991-505-313-90	\$ 77.30	
23	WINDSCREEN	1	P991-541-911-06	\$ 1,592.80	
24	ADHESIVE FILM FOR RAIN SENSOR	1	P9A7-955-609-00	\$ 63.60	
25	PAN HEAD SCREW	1	P9A7-007-755-00	\$ 5.30	
TOTAL PARTS				\$ 64,382.75	\$ 71,034.70
LESS 20%				\$ 12,876.55	\$ 14,206.94
TOTAL PARTS COST				\$ 51,506.20	\$ 56,827.76

	Labour Description		
1	TO REPLACE FRONT BUMPER, BONNET, LH/RH FRT FENDER, LH/RH DOOR & FRONT COMPARTMENT PANELS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 15,600.00	\$ 18,720.00
2	TO RESPRAY FRONT BUMPER, BONNET, LH/RH FRONT FENDERS, LH/RH DOORS, FRONT COMPARTMENT PANELS.	\$ 7,900.00	\$ 8,100.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	\$ 200.00	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 200.00	\$ 350.00
6	TO REMOVE & REPLACE RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	\$ 1,560.00	\$ 3,120.00
7	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	\$ 500.00	\$ 500.00
8	TO REMOVE & REPLACE THE DASH BOARD ASSY.	\$ 3,120.00	\$ 3,120.00
9	TO REMOVE & REPLACE THE AIR BAGS, AIR BAG ECU AND SEAT BELTS.	\$ 3,120.00	\$ 3,120.00
10	TO TRANSFER THE LH/RH DOOR MECHANISM.	\$ -	\$ 1,560.00
11	TO REMOVE & REFIT THE FRONT WINDSCREEN GLASS.	\$ 560.00	\$ 560.00
12	TO SUPPLY SEALER ON THE FRONT WINDSCREEN GLASS.	\$ 195.00	\$ 195.00
13	TO SUPPLY SOLAR FILM ON THE FRONT WINDSCREEN GLASS.	\$ 300.00	\$ 300.00
14	TO SUPPLY 1 PC CHASSIS STICKER.	\$ 150.00	\$ 150.00
15	TO SUPPLY 1 PC NUMBER PLATE	\$ 70.00	\$ 70.00
16	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 250.00	\$ 250.00
17	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
18	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	\$ 250.00	\$ 250.00
19	SUNDRIES.	\$ 50.00	\$ 50.00
SUPPLEMENTARY LABOUR			
1	TO REMOVE/REPLACE LH/RH SIDE SECTION	\$ 3,120.00	\$ 4,680.00
2	TO REPLACE LH/RH FRONT COMPARTMENT SIDE MEMBER AREA AFFECTED BY THE ACCIDENT	\$ 3,120.00	\$ 7,800.00
TOTAL LABOUR		\$ 40,865.00	\$ 46,045.00
TOTAL PARTS		\$ 51,506.20	\$ 56,827.76
TOTAL		\$ 92,371.20	\$ 102,872.76
LESS EXCESS		\$ 4,000.00	\$ -
TOTAL AFTER EXCESS		\$ 88,371.20	
GST 7%		\$ 6,185.98	\$ -
GRAND TOTAL		\$ 94,557.18	\$ -

NUMBER OF DAYS: 28 DAYS(EXCLUDE WAITING FOR ESTIMATE,SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

Janice Lee (LKKAUTO)

From: jessicahs@eurokars.com.sg
Sent: Monday, August 13, 2018 10:06 AM
To: Sebastian Yeang (LKK Auto); Admin A; CS A Team
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg
Subject: Finalization SLX54B
Attachments: FINALIZATION AXA OD - SLX54B.xlsx

Dear Sebastian,

Please find our computation attached for your agreement.

COR: \$88,371.20 before GST

28 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

10295.77

Janice Lee (LKKAUTO)

From: ANG Yvonne <yvonne.ang@axa.com.sg>
Sent: Thursday, September 06, 2018 2:22 PM
To: Janice Lee (LKKAUTO)
Subject: RE: SLX 54B S8M00I75 DOA : 22.05.2018

Hi Janice

As spoken, please proceed to authorize the supplementary parts below

Regards

Yvonne Ang
Assistant Manager
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: yvonne.ang@axa.com.sg
DID: 1800 880 4888



redefining / insurance

AXA's Values at Work:



Customer
First



Integrity



Courage



ONE
AXA

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Janice Lee (LKKAUTO) [<mailto:JaniceLee@lkkauto.com>]
Sent: Tuesday, August 21, 2018 10:26 AM
To: ANG Yvonne <yvonne.ang@axa.com.sg>
Subject: SLX 54B S8M00I75 DOA : 22.05.2018

Hi Yvonne,

As spoken yesterday, enclosed IA for your reference.

Initial estimate \$112,863.87 (Include supplementary \$21,539.43).
Revised cost : \$92,371.20 (Include check + supplementary)

check : \$0
Total : \$92,371.20

*Initial approved amount is \$80,289.48

Our surveyor had since check and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



PORSCHE

AXA INSURANCE PTE LTD

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ATTN : MOTOR CLAIMS DEPARTMENT

DATE: 18/09/2018

Car Regn No : **SLX54B**

Accident involving SLX54B & SKG1099S on 22/05/2018

Own Damage Claim

Dear Sirs

The repairs have been completed for **SLX54B**. We submit the following documents for
your perusal :

1) Invoice No: 13204585	\$ 94,557.18
2) Discharge voucher signed by client	
TOTAL	<u>\$ 94,557.18</u>

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$94,557.18** as soon as possible and mail
your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stanley Ngu
Manager - Body & Paint Division
DID: 63602845
FAX: 63602899
e-mail: stanley@eurokars.com.sg

Eurokars Centre

12 Sungei Kadut Avenue
Singapore 729648
Telephone: (65) 6363 0911
Fax: (65) 6363 3911



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WPOZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 1
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020

REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
CST	OD CLAIM UNDER AXA			0.00		0.00
EXC	Insurance Excess			0.00		-4000.00
SUB	TO REPLACE FRONT BUMPER, BONNET, LH/RH FRT FENDER, LH/RH DOOR & FRONT COMPARTMENT PANELS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			0.00		15600.00
SUB	TO RESPRAY FRONT BUMPER, BONNET, LH/RH FRONT FENDERS, LH/RH DOORS, FRONT COMPARTMENT PANELS.			0.00		7900.00
SUB	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.			0.00		200.00
SUB	TO CARRY-OUT BODY CAVITY PRESERVATION.			0.00		200.00
SUB	TO REMOVE & REPLACE RADIATOR, CONDENSER AND RADIATOR FAN ASSY.			0.00		1560.00
SUB	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			0.00		500.00
SUB	TO REMOVE & REPLACE THE DASH BOARD ASSY.			0.00		3120.00
SUB	TO REMOVE & REPLACE THE AIR BAGS,			0.00		3120.00

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

AfterSales Centre
 27A Tanjong Penjuru Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WP0ZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 2
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Cont	Amount
	AIR BAG ECU AND SEAT BELTS.					
SUB	TO REMOVE & REFIT THE FRONT WINDSCREEN GLA			0.00		560.00
SUB	TO SUPPLY SEALANT ON THE FRONT WINDSCREEN GLASS.			0.00		195.00
SUB	TO SUPPLY SOLAR FLIM ON THE FRONT WINDSCREEN GLASS.			0.00		300.00
SUB	TO SUPPLY 1 PC CHASSIS STICKER.			0.00		150.00
SUB	TO SUPPLY 1 PC NUMBER PLATE			0.00		70.00
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			0.00		250.00
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			0.00		600.00
SUB	SUNDRIES.			0.00		50.00
SUB	TO REMOVE/REPLACE LH/RH SIDE SECTION			0.00		3120.00
SUB	TO REPLACE LH/RH FRONT COMPARTMENT SIDE MEMBER AREA AFFECTED BY THE ACCIDENT			0.00		3120.00
SUN	TOWING CHARGES			0.00		250.00
000-043-206-32-	MIXING TUBE	2	25.70	20.00		41.12

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handlings. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

Aftersales Centre
 27A Tanjong Penjur Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No: M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WP0ZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 3
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
000-043-305-31-	ACTIVATOR	2	171.60	20.00		274.56
000-043-305-31-	ACTIVATOR	1	173.00	20.00		138.40
000-043-305-41-	ADHESIVE	2	408.10	20.00		652.96
000-043-305-41-	ADHESIVE	2	408.10	20.00		652.96
900-075-340-01-	HEX-HD BOLT	1	6.40	20.00		5.12
900-378-351-01-	SCREW	6	4.20	20.00		20.16
971-035-510-C -	ANTENNA	1	192.20	20.00		153.76
991-106-255-02-	CAP	1	13.50	20.00		10.80
991-501-231-02-GRV	SEALING FRAME	1	435.90	20.00		348.72
991-501-431-01-GRV	TERMINAL PIECE	1	468.60	20.00		374.88
991-501-535-01-GRV	WHEEL HOUSING	1	439.40	20.00		351.52
991-501-536-01-GRV	WHEEL HOUSING	1	439.40	20.00		351.52
991-501-911-01-GRV	Side section Prime coated	1	3152.10	20.00		2521.68
991-501-912-01-GRV	Side section Prime coated	1	3152.10	20.00		2521.68
991-503-031-00-GRV	WING LH FRONT	1	1017.80	20.00		814.24
991-503-032-00-GRV	WING RH FRONT RH	1	1017.80	20.00		814.24
991-504-487-91-1E0	FRAME	1	136.40	20.00		109.12
991-504-489-90-1E0	AIR DUCT	1	132.80	20.00		106.24

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which, STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

Aftersales Centre
 27A Tanjong Penjuru Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WP0ZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 4
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
991-504-587-90-	Bearing pin	2	11.00	20.00		17.60
991-505-121-90-	BUMPER REINFORCEMENT	1	1507.30	20.00		1205.84
991-505-191-90-	LINING	1	10143.70	20.00		8114.96
991-505-313-90-	REPAIR KIT	1	77.30	20.00		61.84
991-505-317-00-	RETAINER PLATE	1	18.30	20.00		14.64
991-505-318-00-	RETAINER PLATE	1	18.30	20.00		14.64
991-505-525-90-1E0	SPOILER	1	694.00	20.00		555.20
991-505-527-90-1E0	SPOILER	1	56.10	20.00		44.88
991-505-528-90-1E0	SPOILER	1	56.10	20.00		44.88
991-505-535-00-	RETAINING STRIP LATERAL LE	1	40.90	20.00		32.72
991-505-536-00-	RETAINING STRIP LATERAL RI	1	40.90	20.00		32.72
991-505-563-90-1E0	RETAINING FRAME	1	232.70	20.00		186.16
991-505-564-90-1E0	RETAINING FRAME	1	232.70	20.00		186.16
991-505-567-90-1E0	RETAINING FRAME	1	201.40	20.00		161.12
991-505-569-90-1E0	RETAINING FRAME	1	220.10	20.00		176.08
991-505-573-00-	Corner panel	1	97.65	20.00		78.12
991-505-703-91-	COVER	1	65.50	20.00		52.40
991-505-713-91-	VENTILATION GRILLE	1	205.40	20.00		164.32

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which, STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

Aftersales Centre
 27A Tanjong Penjuru Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurocars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WPOZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 5
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
991-505-714-91-	VENTILATIION GRILLE	1	205.40	20.00		164.32
991-505-715-90-1E0	COVER	1	89.90	20.00		71.92
991-505-716-90-1E0	COVER	1	89.90	20.00		71.92
991-505-717-92-	GRILLE	1	345.80	20.00		276.64
991-505-761-00-	RETAINER PLATE	1	92.10	20.00		73.68
991-505-762-00-	FIXING PLATE HEADLAMP WASH	1	92.10	20.00		73.68
991-505-771-00-	SEAL IMPACT ABSORBER	2	6.80	20.00		10.88
991-511-011-04-GRV	LID	1	2085.40	20.00		1668.32
991-511-033-05-	LOCK LOWER PART	1	446.80	20.00		357.44
991-511-151-03-	HINGE	1	134.10	20.00		107.28
991-511-152-03-	HINGE	1	134.10	20.00		107.28
991-511-551-00-	GAS-PRESSURE SPRING	2	66.70	20.00		106.72
991-511-611-03-	GASKET	1	166.50	20.00		133.20
991-541-911-06-	WINDSCREEN	1	1592.80	20.00		1274.24
991-551-045-15-A31	Lining Black	1	406.00	20.00		324.80
991-551-465-00-	Support	1	29.30	20.00		23.44
991-552-102-11-DRK	DASHBOARD TRIM	1	6855.40	20.00		5484.32
991-555-367-07-1E0	COVER UPPER	1	320.70	20.00		256.56

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handlings. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

Aftersales Centre
 27A Tanjong Penjur Tel : (65) 6331 0700
 Singapore 609042

STUTTGART AUTO PTE LTD

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No: M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WP0ZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 6
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
991-555-411-00-1E0	COVER	1	114.60	20.00		91.68
991-555-465-03-1E0	COVER	1	183.00	20.00		146.40
991-555-466-03-1E0	COVER WING STRUT RH	1	183.00	20.00		146.40
991-559-211-00-	LID EMBLEM	1	236.90	20.00		189.52
991-559-215-02-	DESK PAD CREST	1	11.70	20.00		9.36
991-573-103-80-	PRESSURE LINE	1	694.60	20.00		555.68
991-573-105-80-	PRESSURE LINE	1	694.60	20.00		555.68
991-575-321-90-1E0	AIR DUCT	1	232.60	20.00		186.08
991-575-322-90-1E0	AIR DUCT	1	232.60	20.00		186.08
991-618-223-01-	FRONT SENSOR AIRBAG	2	220.20	20.00		352.32
991-631-151-81-	ADDITIONAL HEADLAMP	1	1177.60	20.00		942.08
991-631-152-81-	ADDITIONAL HEADLAMP	1	1177.60	20.00		942.08
991-631-201-03-	MOUNTING HEADLAMP LEFT	1	227.80	20.00		182.24
991-631-256-06-	INDICATOR LIGHT (RH)	1	124.40	20.00		99.52
991-631-995-52-	HEADLAMP LH - BLACK	1	3884.40	20.00		3107.52
991-631-996-52-	HEADLAMP RH - BLACK	1	3884.40	20.00		3107.52
991-701-051-90-1E0	NUMBER PLATE BRACKET (GT3-	1	45.90	20.00		36.72
991-731-511-01-1E0	Interior mirror Black	1	249.80	20.00		199.84

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel: (65) 6472 4433
 Singapore 159099

Aftersales Centre
 27A Tanjong Penjuru Tel: (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WPOZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 7
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
991-731-811-01-1E0	COVER INTERIOR MIRROR MIRR	1	12.00	20.00		9.60
991-731-812-01-1E0	COVER INTERIOR MIRROR MIRR	1	12.00	20.00		9.60
991-803-033-04-N13	SEAT BELT FRONT	2	845.00	20.00		1352.00
991-803-071-00-	AIRBAG UNIT PASSENGER'S SI	1	2806.60	20.00		2245.28
991-803-089-09-A34	AIRBAG UNIT	1	2981.00	20.00		2384.80
991-803-184-02-	SEAT-BELT BUCKLE DRIVER'S	1	244.10	20.00		195.28
997-505-719-00-	FIXING DEVICE	2	32.40	20.00		51.84
997-628-163-01-	NOZZLE	2	164.20	20.00		262.72
999-073-378-02-	(AE04) ROUND SCREW	2	2.00	20.00		3.20
999-076-066-09-	NUT	4	1.10	20.00		3.52
999-084-638-01-	NUT	4	5.10	20.00		16.32
999-190-191-30-	BLIND RIVET	4	5.20	20.00		16.64
999-190-191-30-	BLIND RIVET	2	5.20	20.00		8.32
999-190-191-30-	BLIND RIVET	2	5.20	20.00		8.32
999-190-228-01-	BLIND RIVET	100	8.10	20.00		648.00
999-190-228-01-	BLIND RIVET	40	8.10	20.00		259.20
999-190-228-01-	BLIND RIVET	20	8.10	20.00		129.60
999-190-229-01-	BLIND RIVET	15	4.60	20.00		55.20

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

AfterSales Centre
 27A Tanjong Penjuru Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurokars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No: M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WP0ZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 8
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
999-190-230-01-	BLIND RIVET	25	5.30	20.00		106.00
999-209-084-40-	SPACER	5	2.70	20.00		10.80
999-507-047-01-	CLAMP	5	1.10	20.00		4.40
999-507-104-01-	SPEED NUT	6	0.60	20.00		2.88
999-507-294-40-	Fastening screw	2	1.00	20.00		1.60
999-507-839-01-	CLIP	2	1.10	20.00		1.76
999-591-423-03-	HOOD BADGE NUT	2	5.10	20.00		8.16
999-703-140-41-	RUBBER BUFFER	1	5.10	20.00		4.08
999-707-557-41-	O-RING	3	5.10	20.00		12.24
999-911-756-41-	ADHESIVE FILM	1	2.20	20.00		1.76
999-919-133-09-	HEXAGON-HEAD BOLT	2	1.70	20.00		2.72
999-919-268-01-	SCREW	5	9.10	20.00		36.40
999-919-268-01-	SCREW	18	16.10	20.00		231.84
999-919-717-01-	OVAL-HEAD SCREW	2	1.50	20.00		2.40
9A7-007-755-00-	PAN-HEAD SCREW	1	5.30	20.00		4.24
9A7-955-609-00-	ADHESIVE FILM FOR RAIN SEN	1	63.60	20.00		50.88
9P1-806-620- -GRV	SUPPORT	1	102.10	20.00		81.68
9P1-823-085- -	LOCK UPPER PART	1	31.50	20.00		25.20

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel: (65) 6472 4433
 Singapore 159099

AfterSales Centre
 27A Tanjong Penjuru Tel: (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 Eurskars Group
 Company Reg. No. 198403740N

www.porsche.com.sg



-P

PORSCHE**INSURANCE INVOICE**

GST Reg No:M90364005A

CODE: A0031 AXA
 CUSTOMER: AXA INSURANCE PTE LTD
 ADDRESS: 8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

MODEL: 911 GT3
 CHASSIS NO: WPOZZZ99ZES180498
 ENGINE NO: MA175E10343
 DESCRIPTION: Own Damaged Claim

PAGE NO: 9
 DOCUMENT NO: 13204585
 JOB NO: 34262
 DATE IN: 22/05/2018
 DATE PRINTED: 10/09/2018
 CSO/OP CODE: Janice Syn
 SVC MNT EXP: 13/04/2020
 EXT. WTY: 14/04/2019
 REGN NO: SLX54B
 REGN DATE: 15/04/2015
 MILEAGE: 22126

Item	Description	Unit	U/Price	Disc%	Con%	Amount
9P1-979-020- -	Single line	1	142.20	20.00		113.76
N -104-144-02-	PAN-HEAD SCREW	5	2.80	20.00		11.20
N -911-883-02-	Oval-head screw	4	1.50	20.00		4.80
N -989-261-02-	FASTENING SCREW	2	3.70	20.00		5.92
SAL-043-301-48-	ANTIFREEZE FOR COOLANT	6	18.90	20.00		90.72

Parts 51,506.20
 Sundries 250.00
 Labour 40,615.00
 Menus 0.00

Net 88371.20
 G.S.T. 7% 6185.98
 Total 94557.18
 Paid 0.00
 Amount Due 94557.18

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which ITUTTIGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped 'PAID' & signed by us. Any dispute to this invoice must be made within 5 calendar days.

STUTTGART AUTO PTE LTD

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Porsche Centre Singapore
 29 Leng Kee Road Tel : (65) 6472 4433
 Singapore 159099

AfterSales Centre
 27A Tanjong Penjuru Tel : (65) 6331 0700
 Singapore 609042

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
 15-03-2018
 company Reg. No. 198403740N

www.porsche.com.sg



PORSCHE

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
Repairers my / our vehicle No: 81X 54B which has been
repaired to my satisfaction and I/we admit that the payment for such repairs
by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under
policy number: YFX1P1962454 in respect of damage
caused to the said vehicle as a result of an accident that occurred on
20/05/2018 at CTE before Moulmein Road exit after Kampong Jam

Janice Syn



Witnessed by Repairers

20/07/2018

Date:

[Signature]

Signature by Insured

20/07/2018

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18009467/Nrd3e2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : YVONNE ANG

Date : 13-11-2018

Code : ASM



1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLX 54B
Policy No.	VPX/P1962454	Coverage (\$)	0.00
Claim No.	S8M00175	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	24/05/2018

2. Vehicle Particulars & Condition

Make & Model	PORSCHE 911 GT3	c.c	3799
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WP0ZZZ99ZES180498	Colour	BLACK
Odometer	22126	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35Z R20	MICHELIN	7 mm
L/H Front Tyre	245/35Z R20	MICHELIN	7 mm
R/H Rear Tyre	305/30Z R20	MICHELIN	7 mm
L/H Rear Tyre	305/30Z R20	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/05/2018	Inspection Date	24/05/2018
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A)THE MARKET VALUE IS S\$696,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	28 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 54B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH (CONSISTENT)	CRACKED	1,017.80	1,017.80
1	FRONT FENDER RH (CONSISTENT)	CRACKED	1,017.80	1,017.80
1	FRONT BUMPER (CONSISTENT)	CRACKED	10,143.70	10,143.70
1	TOW COVER (CONSISTENT)	MISSING	65.50	65.50
1	FRONT BUMPER LOWER SPOILER (CONSISTENT)	CUT	694.00	694.00
1	FRONT BUMPER RETAINING FRAME LH (CONSISTENT)	CRACKED	232.70	232.70
1	FRONT BUMPER RETAINING FRAME RH (CONSISTENT)	CRACKED	232.70	232.70
1	RETAINING FRAME VENTILATION GRILLE LH (CONSISTENT)	DEFORMED	205.40	205.40
1	RETAINING FRAME VENTILATION GRILLE RH (CONSISTENT)	DEFORMED	205.40	205.40
1	VENTILATION GRILLE TRIM LH (CONSISTENT)	NECESSARY	89.90	89.90
1	VENTILATION GRILLE TRIM RH (CONSISTENT)	NECESSARY	89.90	89.90
1	FRONT BUMPER SIDE SPOILER LH (CONSISTENT)	NECESSARY	56.10	56.10
1	FRONT BUMPER SIDE SPOILER RH (CONSISTENT)	NECESSARY	56.10	56.10
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	NECESSARY	40.90	40.90
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	40.90	40.90
1	NUMBER PLATE BRACKET (GT3-3) (CONSISTENT)	CRACKED	45.90	45.90
6	FRONT BUMPER SPEED NUT (CONSISTENT)	NECESSARY	3.60	3.60
4	RETAINING FRAME NUT (CONSISTENT)	NECESSARY	20.40	20.40
1	FRONT BUMPER RETAINER PLATE LH (CONSISTENT)	NECESSARY	18.30	18.30
1	FRONT BUMPER RETAINER PLATE RH (CONSISTENT)	NECESSARY	18.30	18.30
4	RETAINER PLATE BLIND RIVET (CONSISTENT)	NECESSARY	20.80	20.80
2	RETAINER PLATE CLIP (CONSISTENT)	NECESSARY	64.80	64.80
7	FRONT BUMPER CABLE CLAMP (CONSISTENT)	NOT NECESSARY	43.40	-
1	FRONT BUMPER CENTER VENTILATION GRILLE (CONSISTENT)	NOT NECESSARY	406.30	-
1	FRONT BUMPER CENTER RETAINING FRAME (CONSISTENT)	CRACKED	220.10	220.10
1	FRONT BUMPER CENTER AIR DUCT (CONSISTENT)	NOT NECESSARY	187.10	-
1	RADITOR FRAME (CONSISTENT)	CRACKED	136.40	136.40
2	RADITOR FRAME BEARING PIN (CONSISTENT)	NECESSARY	22.00	22.00

Report Ref No. CS/ASM18009467/Nrd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BEADING PIN BOLT (CONSISTENT)	NECESSARY	3.40	3.40
1	RADITOR AIR DUCT TOP (CONSISTENT)	DEFORMED	132.80	132.80
1	FRONT BUMPER TOP VENTILATION GRILLE (CONSISTENT)	TORN	345.80	345.80
1	FRONT BUMPER TOP VENTILATION GRILLE FRAME (CONSISTENT)	CRACKED	201.40	201.40
5	TOP VENTILATION GRILLE FRAME SCREW (CONSISTENT)	NECESSARY	45.50	45.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	DENTED	1,507.30	1,507.30
2	REINFORCEMENT SEAL (CONSISTENT)	NECESSARY	13.60	13.60
6	REINFORCEMENT SCREW (CONSISTENT)	NECESSARY	25.20	25.20
1	BONNET (CONSISTENT)	BENT	2,085.40	2,085.40
1	FRONT PANEL TOP SUPPORT (CONSISTENT)	BENT	102.10	102.10
1	BONNET LOCK LOWER PART (CONSISTENT)	JAMMED	446.80	446.80
2	LOCK LOWER PART SCREW (CONSISTENT)	NECESSARY	3.00	3.00
1	LOCK LOWER PART ACTUATOR (CONSISTENT)	NOT NECESSARY	144.30	-
2	BONNET DAMPER (CONSISTENT)	DAMAGED	133.40	133.40
1	BONNET GASKET (CONSISTENT)	NECESSARY	166.50	166.50
1	BONNET LOCK UPPER PART (CONSISTENT)	BENT	31.50	31.50
2	LOCK UPPER PART SCREW (CONSISTENT)	NECESSARY	4.00	4.00
1	LOCK UPPER PART PROTECTION CAP (CONSISTENT)	NOT NECESSARY	3.20	-
2	BONNET RUBBER STOPPER (CONSISTENT)	NECESSARY-1PC ONLY	10.20	5.10
1	BONNET HINGE LH (CONSISTENT)	BENT	134.10	134.10
1	BONNET HINGE RH (CONSISTENT)	BENT	134.10	134.10
4	BONNET HINGE NUT (CONSISTENT)	NECESSARY	4.40	4.40
4	BONNET HINGE SCREW (CONSISTENT)	NECESSARY	6.00	6.00
1	DOOR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,841.70	-
1	DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,841.70	-
2	DOOR CAP BIG (CONSISTENT)	NOT NECESSARY	34.20	-
2	DOOR CAP SMALL (CONSISTENT)	NOT NECESSARY	23.60	-
2	DOOR INSULATION (CONSISTENT)	NOT NECESSARY	74.00	-
4	DOOR PROTECTIVE FILM (CONSISTENT)	NOT NECESSARY	154.80	-

Report Ref No. CS/ASM18009467/Nrd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR GASKET OUTER LH (CONSISTENT)	NOT NECESSARY	429.40	-
1	DOOR GASKET OUTER RH (CONSISTENT)	NOT NECESSARY	429.40	-
2	FRONTY LUGGAGE COMPARTMENT FASTENER (CONSISTENT)	NECESSARY	2.00	2.00
1	FRONTY LUGGAGE COMPARTMENT LINING (CONSISTENT)	NOT NECESSARY	433.50	-
1	FRONT COMPARTMENT TOP COVER LH (CONSISTENT)	DEFORMED	183.00	183.00
1	FRONT COMPARTMENT TOP COVER RH (CONSISTENT)	MISSING	183.00	183.00
5	TOP COVER SPACER (CONSISTENT)	NECESSARY	13.50	13.50
5	TOP COVER CLAMP (CONSISTENT)	NECESSARY	5.50	5.50
1	FRONT COMPARTMENT CENTER LOCK COVER (CONSISTENT)	CRACKED	114.60	114.60
2	CENTER LOCK COVER CLIP (CONSISTENT)	NECESSARY	2.20	2.20
1	BATTERY COVER UPPER (CONSISTENT)	DEFORMED	320.70	320.70
1	DASHBOARD TRIM (CONSISTENT)	BROKEN	6,855.40	6,855.40
1	REAR VIEW MIRROR (CONSISTENT)	DAMAGED	249.80	249.80
1	REAR VIEW MIRROR COVER RH (CONSISTENT)	CRACKED	12.00	12.00
1	REAR VIEW MIRROR COVER LH (CONSISTENT)	CRACKED	12.00	12.00
1	BONNET EMBLEM (CONSISTENT)	NECESSARY	236.90	236.90
1	EMBLEM GASKET (CONSISTENT)	NECESSARY	11.70	11.70
2	EMBLEM NUT (CONSISTENT)	NECESSARY	10.20	10.20
1	EMBLEM ADHESIVE FILM (CONSISTENT)	NECESSARY	2.20	2.20
2	SEAT BELT (CONSISTENT)	JAMMED	1,690.00	1,690.00
2	SEAT BELT SCREW LOWER (CONSISTENT)	NOT NECESSARY	17.80	-
2	SEAT BELT SCREW UPPER (CONSISTENT)	NECESSARY	7.40	7.40
1	SEAT-BELT BUCKLE PASSENGER (CONSISTENT)	NOT NECESSARY	244.10	-
1	SEAT-BELT BUCKLE DRIVER'S (CONSISTENT)	JAMMED	244.10	244.10
1	AIRBAG UNIT PASSENGER'S SIDE (CONSISTENT)	ACTIVATED	2,806.60	2,806.60
1	STEERING AIRBAG UNIT (CONSISTENT)	ACTIVATED	2,981.00	2,981.00
2	CONDENSER (CONSISTENT)	NOT NECESSARY	1,425.80	-
3	CONDENSER O-RING (CONSISTENT)	NECESSARY	15.30	15.30
1	CONDENSER SCREW (CONSISTENT)	NECESSARY	6.40	6.40
1	CONDENSER PRESSURE LINE UPPER (CONSISTENT)	BENT	694.60	694.60
1	CONDENSER PRESSURE LINE LOWER (CONSISTENT)	BENT	694.60	694.60

Report Ref No. CS/ASM18009467/Nrd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	PRESSURE LINE SCREW (CONSISTENT)	NECESSARY	14.00	14.00
1	CONDENSER AIR DUCT RH (CONSISTENT)	CRACKED	232.60	232.60
1	CONDENSER AIR DUCT LH (CONSISTENT)	CRACKED	232.60	232.60
2	FRONT SENSOR AIRBAG (CONSISTENT)	NECESSARY	440.40	440.40
1	FRONT BUMPER WIRING HARNESS (CONSISTENT)	NOT NECESSARY	923.30	-
2	FRONT BUMPER WASHER NOZZLE (CONSISTENT)	DAMAGED / CRACKED	328.40	328.40
1	HEADLAMP LH - BLACK (CONSISTENT)	CRACKED	3,884.40	3,884.40
1	HEADLAMP RH - BLACK (CONSISTENT)	CRACKED	3,884.40	3,884.40
1	HEADLAMP SUPPORT LH (CONSISTENT)	NOT NECESSARY	204.30	-
1	HEADLAMP SUPPORT RH (CONSISTENT)	CRACKED	227.80	227.80
1	SIDE INDICATOR LIGHT (LH) (CONSISTENT)	CRACKED	124.40	124.40
1	SIDE INDICATOR LIGHT (RH) (CONSISTENT)	NOT NECESSARY	124.40	-
1	FRONT ADDITIONAL HEADLAMP LH (CONSISTENT)	SCRATCHED	1,177.60	1,177.60
1	FRONT ADDITIONAL HEADLAMP RH (CONSISTENT)	SCRATCHED	1,177.60	1,177.60
1	FRONT END PANEL (CONSISTENT)	BENT	468.60	468.60
1	FRONT END PANEL TOP FRAME (CONSISTENT)	DEFORMED	435.90	435.90
100	BLIND RIVET (CONSISTENT)	NECESSARY	810.00	810.00
2	ADHESIVE (CONSISTENT)	NECESSARY	816.20	816.20
2	ACTIVATOR (CONSISTENT)	NECESSARY	343.20	343.20
2	MIXING TUBE (CONSISTENT)	NECESSARY	51.40	51.40
1	WINDSCREEN (CONSISTENT)	CRACKED	1,579.30	1,592.80
1	ADHESIVE FILM FOR RAIN SEN (CONSISTENT)	NECESSARY	63.60	63.60
1	FRONT COMPARTMENT LINER BIG (CONSISTENT) (ADDITIONAL)	TORN	406.00	406.00
1	FOAM SUPPORT (CONSISTENT) (ADDITIONAL)	CRACKED	29.30	29.30
1	FRONT COMPARTMENT SIDE MEMBER LH (CONSISTENT) (ADDITIONAL)	DENTED	439.40	439.40
1	FRONT COMPARTMENT SIDE MEMBER RH (CONSISTENT) (ADDITIONAL)	DENTED	439.40	439.40
25	SIDE MEMBER BLIND RIVET A (CONSISTENT) (ADDITIONAL)	NECESSARY	132.50	132.50
15	SIDE MEMBER BLIND RIVET B (CONSISTENT) (ADDITIONAL)	NECESSARY	69.00	69.00
1	FRONT BUMPER ANTENNA (CONSISTENT) (ADDITIONAL)	MISSING	192.20	192.20

Report Ref No. CS/ASM18009467/Nrd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER ANTENNA WIRE HARNESS (CONSISTENT) (ADDITIONAL)	DAMAGED	142.20	142.20
1	LH SIDE SECTION PRIME COATED (CONSISTENT) (ADDITIONAL)	DENTED	3,152.10	3,152.10
1	RH SIDE SECTION PRIME COATED (CONSISTENT) (ADDITIONAL)	DENTED	3,152.10	3,152.10
60	BLIND RIVET (CONSISTENT) (ADDITIONAL)	NECESSARY	486.00	486.00
1	RADIATOR SUPPORT (CONSISTENT) (ADDITIONAL)	CRACKED	13.50	13.50
2	ADHESIVE (CONSISTENT) (ADDITIONAL)	NECESSARY	816.20	816.20
1	ACTIVATOR (CONSISTENT) (ADDITIONAL)	NECESSARY	173.00	173.00
6	ANTIFREEZE FOR COOLANT (CONSISTENT) (ADDITIONAL)	NECESSARY	113.40	113.40
1	RETAINER PLATE (CONSISTENT) (ADDITIONAL)	CRACKED	92.10	92.10
1	FIXING PLATE HEADLAMP WASHER (CONSISTENT) (ADDITIONAL)	NECESSARY	92.10	92.10
18	SCREW (CONSISTENT) (ADDITIONAL)	NECESSARY	289.80	289.80
1	CORNER PANEL (CONSISTENT) (ADDITIONAL)	DENTED	97.65	97.65
4	BLIND RIVET (CONSISTENT) (ADDITIONAL)	NECESSARY	20.80	20.80
1	REPAIR KIT (CONSISTENT) (ADDITIONAL)	NECESSARY	77.30	77.30
1	WINDSCREEN (CONSISTENT) (ADDITIONAL)	REPEATED	1,592.80	-
1	ADHENSIVE FILM FOR RAIN SENSOR (CONSISTENT) (ADDITIONAL)	REPEATED	63.60	-
1	PAD HEAD SCREW (CONSISTENT) (ADDITIONAL)	NECESSARY	5.30	5.30
	LESS 20% DISCOUNT		-15,003.41	-12,876.55
			60,013.64	51,506.20
	<u>SPECIAL NETT ITEMS</u>			
1	CHASSIS STICKER (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	70.00	70.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			270.00	270.00
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER, BONNET, LH/RH FRT FENDER, LH/RH DOOR & FRONT COMPARTMENT PANELS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF DOOR LH AND DOOR RH.		18,720.00	15,600.00

Report Ref No. CS/ASM18009467/Nrd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY FRONT BUMPER, BONNET, LH/RH FRONT FENDERS, LH/RH DOORS, FRONT COMPARTMENT PANELS		8,100.00	7,900.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		350.00	200.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		350.00	200.00
	TO REMOVE & REPLACE RADIATOR, CONDENSER AND RADIATOR FAN ASSY.		3,120.00	1,560.00
	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.		500.00	500.00
	TO REMOVE & REPLACE THE DASH BOARD ASSY.		3,120.00	3,120.00
	TO REMOVE & REPLACE THE AIR BAGS, AIR BAG ECU AND SEAT BELTS.		3,120.00	3,120.00
	TO TRANSFER THE LH/RH DOOR MECHANISM.	NOT NECESSARY	1,560.00	-
	TO REMOVE & REFIT THE FRONT WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE FRONT WINDSCREEN GLASS.		195.00	195.00
	TO SUPPLY SOLAR FILM ON THE FRONT WINDSCREEN GLASS.		300.00	300.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	250.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		300.00	250.00
	TO REPLACE LH/RH FRONT COMPARTMENT SIDE MEMBER AREAS AFFECTED BY THE ACCIDENT. (ADDITIONAL)		7,800.00	3,120.00
	TO REMOVE / REPLACE LH/RH SIDE SECTION. (ADDITIONAL)		4,680.00	3,120.00
			-	-
			-	-
			53,625.00	40,595.00
GRAND TOTAL			113,908.64	92,371.20
RECOMMENDED COST OF REPAIRS				92,371.20
LESS EXCESS				-4,000.00
NETT LIABILITY				88,371.20

Report Ref No. CS/ASM18009467/Nrd3e2



Report Ref No. CS/ASM18009467/Nrd3e2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.