



PORSCHE

STUTTGART AUTO PTE LTD  
NO:12 SUNGEI KADUT, SINGAPORE 729648  
ESTIMATE COST OF REPAIRS



|                              |                     |                                 |                         |
|------------------------------|---------------------|---------------------------------|-------------------------|
| <b>AXA INSURANCE PTE LTD</b> |                     | <b>NAME :</b> Ms Wong Siew Lin  | <b>WIP :</b> 34262      |
| 8 SHENTON WAY                |                     | <b>ADDRESS :</b> 28 Siglap Hill | <b>EXCESS :</b>         |
| #24-01 AXA TOWER             |                     | Singapore 456083                | <b>DATE:</b> 25.05.2018 |
| SINGAPORE 068811             |                     |                                 |                         |
| <b>ATTN. :</b>               | MOTOR CLAIM DEPT    | <b>TEL :</b>                    |                         |
| <b>FAX :</b>                 | 68804838 / 68804739 |                                 |                         |
| <b>VEH NO :</b>              | SLX54B              | <b>DATE IN :</b>                |                         |
| <b>CHASSIS NO :</b>          | WPOZZZ99ZES180498   | <b>CONTACT PERSON :</b>         | RICK 63602445           |
| <b>MODEL :</b>               | 911 GT3             | <b>MILEAGE :</b>                |                         |
|                              |                     | <b>TYPE OF CLAIM :</b>          | OD                      |
|                              |                     | <b>DATE REG.:</b>               | 15.04.2015              |
|                              |                     | <b>POLICY NO. :</b>             |                         |

**NATURE OF WORKS**

| S/NO                            | Parts Description                                | QTY      |                     | REVISED | PRICES           |
|---------------------------------|--------------------------------------------------|----------|---------------------|---------|------------------|
| 1                               | FRONT COMPARTMENT LINER BIG ✓ TN                 | 1        | P991-551-045-15-A31 | 406.00  | \$ 406.00        |
| 2                               | FOAM SUPPORT ✓ Rk                                | 1        | P991-551-465-00-    | 29.30   | \$ 29.30         |
| 3                               | FRONT COMPARTMENT SIDE MEMBER LH ✓ DT            | 1        | P991-501-535-01-GRV | 439.40  | \$ 439.40        |
| 4                               | FRONT COMPARTMENT SIDE MEMBER RH ✓ DT            | 1        | P991-501-536-01-GRV | 439.40  | \$ 439.40        |
| 5                               | SIDE MEMBER BLIND RIVET A ✓ NEC                  | 25       | P999-190-230-01-    | 132.50  | \$ 132.50        |
| 6                               | SIDE MEMBER BLIND RIVET B ✓ NEC                  | 15       | P999-190-229-01-    | 69.00   | \$ 69.00         |
| 7                               | FRONT BUMPER ANTENNA ✓ MS                        | 1        | P971-035-510-C -    | 192.20  | \$ 192.20        |
| 8                               | FRONT BUMPER ANTENNA WIRE HARNESS ✓ DMG          | 1        | P9P1-979-020- -     | 142.20  | \$ 142.20        |
| <b>TOTAL PARTS</b>              |                                                  |          |                     |         | \$ 1,850.00      |
| <b>LESS 10% 20%</b>             |                                                  |          |                     |         | \$ 185.00        |
| <b>TOTAL PARTS COST</b>         |                                                  |          |                     |         | \$ 1,665.00      |
| Labour Description              |                                                  |          |                     |         |                  |
| 1                               | TO REPLACE LH / RH FRONT COMPARTMENT SIDE MEMBER | 1560/day |                     |         | \$ 7,800.00      |
| AREAS AFFECTED BY THE ACCIDENT. |                                                  |          |                     |         | 3/20             |
| <b>TOTAL LABOUR</b>             |                                                  |          |                     |         | \$ - \$ 7,800.00 |
| <b>TOTAL PARTS</b>              |                                                  |          |                     |         | \$ - \$ 1,665.00 |
| <b>TOTAL</b>                    |                                                  |          |                     |         | \$ - \$ 9,465.00 |
| <b>LESS EXCESS</b>              |                                                  |          |                     |         | \$ - \$ -        |
| <b>TOTAL AFTER EXCESS</b>       |                                                  |          |                     |         | \$ - \$ -        |
| <b>GST 7%</b>                   |                                                  |          |                     |         | \$ - \$ -        |
| <b>GRAND TOTAL</b>              |                                                  |          |                     |         | \$ - \$ -        |

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "With Justice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted and is subject to final approval from insurance company

Acknowledged by Repairer  
Signature:  
Date:



**STUTTGART AUTO PTE LTD**  
**NO:12 SUNGEI KADUT, SINGAPORE 729648**  
**2ND SUPPLEMENTARY**



**PORSCHE**

|                                                                                                                                                              |                   |                                                                                                       |            |                                                                  |      |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------|------------|------------------------------------------------------------------|------|
| <b>AXA INSURANCE PTE LTD</b><br>8 SHENTON WAY<br>#24-01 AXA TOWER<br>SINGAPORE 068811<br><b>ATTN. :</b> MOTOR CLAIM DEPT<br><b>FAX :</b> 68804838 / 68804739 |                   | <b>NAME :</b> Ms Wong Siew Lin<br><b>ADDRESS :</b> 28 Siglap Hill<br>Singapore 456083<br><b>TEL :</b> |            | <b>WIP :</b> 34262<br><b>EXCESS :</b><br><b>DATE:</b> 11.06.2018 |      |
| <b>VEH NO :</b>                                                                                                                                              | SLX54B            | <b>DATE IN :</b>                                                                                      |            | <b>CONTACT PERSON :</b>                                          | RICK |
| <b>CHASSIS NO :</b>                                                                                                                                          | WPOZZZ99ZES180498 | <b>MILEAGE :</b>                                                                                      |            | <b>TYPE OF CLAIM :</b>                                           | OD   |
| <b>MODEL :</b>                                                                                                                                               | 911 GT3           | <b>DATE REG.:</b>                                                                                     | 15.04.2015 | <b>POLICY NO. :</b>                                              |      |

**NATURE OF WORKS**

| S/NO                      | Parts Description                         | QTY          | REVISED             | PRICES              |
|---------------------------|-------------------------------------------|--------------|---------------------|---------------------|
| 1                         | LH SIDE SECTION PRIME COATED              | 1 ✓ OT       | P991-501-911-01-GRV | 3152.10 \$ 3,152.10 |
| 2                         | RH SIDE SECTION PRIME COATED              | 1 ✓ DT       | P991-501-912-01-GRV | 3152.10 \$ 3,152.10 |
| 3                         | BLIND RIVET                               | 20+ 40 ✓ NEL | P999-190-228-01-    | 486.00 \$ 324.00    |
| 4                         | RADIATOR SUPPORT                          | 1 ✓ CRK      | P991-106-255-02-    | 13.50 \$ 7.70       |
| <b>TOTAL PARTS</b>        |                                           |              |                     | \$ 6,635.90         |
| <b>LESS 10% 20%</b>       |                                           |              |                     | \$ 663.59           |
| <b>TOTAL PARTS COST</b>   |                                           |              |                     | <b>\$ 5,972.31</b>  |
| <b>Labour Description</b> |                                           |              |                     |                     |
| 1                         | TO REMOVE / REPLACE LH / RH SIDE SECTION. |              |                     | \$ 4,680.00         |
| <b>TOTAL LABOUR</b>       |                                           |              |                     | \$ - \$ 4,680.00    |
| <b>TOTAL PARTS</b>        |                                           |              |                     | \$ - \$ 5,972.31    |
| <b>TOTAL</b>              |                                           |              |                     | \$ - \$ 10,652.31   |
| <b>LESS EXCESS</b>        |                                           |              |                     | \$ - \$ -           |
| <b>TOTAL AFTER EXCESS</b> |                                           |              |                     | \$ - \$ -           |
| <b>GST 7%</b>             |                                           |              |                     | \$ - \$ -           |
| <b>GRAND TOTAL</b>        |                                           |              |                     | \$ - \$ -           |

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A

QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED

IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • This party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

2 days

Sankhya Sain  
11/6/2018

LKK



PORSCHE

STUTTGART AUTO PTE LTD  
NO:12 SUNGEI KADUT, SINGAPORE 729648  
FINALIZATION COST OF REPAIRS



|                                                                                                                                                |                                |                                                                                                       |                 |                                                                  |               |
|------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------------------------------------------------------------|-----------------|------------------------------------------------------------------|---------------|
| <b>AXA INSURANCE PTE LTD</b><br>8 SHENTON WAY<br>#24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN. : MOTOR CLAIM DEPT<br>FAX : 68804838 / 68804739 |                                | <b>NAME :</b> Ms Wong Siew Lin<br><b>ADDRESS :</b> 28 Siglap Hill<br>Singapore 456083<br><b>TEL :</b> |                 | <b>WIP :</b> 34262<br><b>EXCESS :</b><br><b>DATE:</b> 24.05.2018 |               |
| <b>VEH NO :</b>                                                                                                                                | <b>SLX54B</b>                  | <b>DATE IN :</b>                                                                                      |                 | <b>CONTACT PERSON :</b>                                          | RICK 63602445 |
| <b>CHASSIS NO :</b>                                                                                                                            | WP0ZZZ99ZES180498              | <b>MILEAGE :</b>                                                                                      |                 | <b>TYPE OF CLAIM :</b>                                           | OD            |
| <b>MODEL :</b>                                                                                                                                 | 911 GT3                        | <b>DATE REG.:</b>                                                                                     | 15.04.2015      | <b>POLICY NO. :</b>                                              |               |
| <b>NATURE OF WORKS</b>                                                                                                                         |                                |                                                                                                       |                 |                                                                  |               |
| <b>S/NO</b>                                                                                                                                    | <b>Parts Description</b>       |                                                                                                       |                 | <b>REVISED</b>                                                   | <b>PRICES</b> |
|                                                                                                                                                | <b>QTY</b>                     |                                                                                                       |                 |                                                                  |               |
| 1                                                                                                                                              | ADHESIVE                       | 2                                                                                                     | P000-043-305-41 | \$ 816.20                                                        |               |
| 2                                                                                                                                              | ACTIVATOR                      | 1                                                                                                     | P000-043-305-31 | \$ 173.00                                                        |               |
| 3                                                                                                                                              | ANTIFREEZE FOR COOLANT         | 6                                                                                                     | PSAL-043-301-48 | \$ 113.40                                                        |               |
| 4                                                                                                                                              | RETAINER PLATE                 | 1                                                                                                     | P991-505-761-00 | \$ 92.10                                                         |               |
| 5                                                                                                                                              | FIXING PLATE HEADLAMP WASHER   | 1                                                                                                     | P991-505-762-00 | \$ 92.10                                                         |               |
| 6                                                                                                                                              | SCREW                          | 18                                                                                                    | P999-919-268-01 | \$ 289.80                                                        |               |
| 7                                                                                                                                              | CORNER PANEL                   | 1                                                                                                     | P991-505-573-00 | \$ 97.65                                                         |               |
| 8                                                                                                                                              | BLIND RIVET                    | 4                                                                                                     | P999-190-191-30 | \$ 20.80                                                         |               |
| 9                                                                                                                                              | REPAIR KIT                     | 1                                                                                                     | P991-505-313-90 | \$ 77.30                                                         |               |
| 10                                                                                                                                             | WINDSCREEN                     | 1                                                                                                     | P991-541-911-06 | \$ 1,592.80                                                      | Repeat        |
| 11                                                                                                                                             | ADHENSIVE FILM FOR RAIN SENSOR | 1                                                                                                     | P9A7-955-609-00 | \$ 63.60                                                         | Repeat        |
| 12                                                                                                                                             | PAN HEAD SCREW                 | 1                                                                                                     | P9A7-007-755-00 | \$ 5.30                                                          |               |
| <b>TOTAL PARTS</b>                                                                                                                             |                                |                                                                                                       |                 | \$ 3,434.05                                                      | \$ 1777.65    |
| <b>LESS 20%</b>                                                                                                                                |                                |                                                                                                       |                 | \$ 686.81                                                        | \$ -          |
| <b>TOTAL PARTS COST</b>                                                                                                                        |                                |                                                                                                       |                 | \$ 2,747.24                                                      | \$ 1422.12    |