

ASS. REC. BY:

REF:

CS3/ICS18009469/A24d302

Special Instruction:

Surveyor

Action

Muhmen

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time:

24/5/18 @ 3:32pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 14211

Insured:

GBE 949M

at Workshop m/s

N-51 Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 #01-18

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/05/2018

CA / REV / REP. / REV 24 HRS

'wp'

25/05/2018

H.O.D. Endorsement:

Date/Time:

3:45pm @ 24/5/18

Person Contacted:

Melody

Vehicle IN OUT

Date/Time

Action/Instruction (x) Estimate

SLB 14211 - X

GBE 949M - CS/EGII6018300/M/vbs2

DOA: 21/9/16

28/5/18

Dismantled

31/5/18

After Repair

ASS. REC. BY: Adrian Ling

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes** or **No**GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or **No**Est. Repairs: 06 days Res.: **Yes** or **No**Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or **No****CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLB 1421 J Yr Regn: 2016, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda Vezel c.c. 1496Colour: Black A/C: **Insured / Std / NI / NA**Sp. Reading: 121228 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: Ru11113025Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Inorder** / Jammed / Leaked / Burnt orBrake: **Inorder** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / **STD A/Rim** orTyre Size: F: 215/60R16R: 215/60R16**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** orHabilead**Front****Rear**R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 25/05/18Survey held at N51Des. of Damages: **Frt** / **Rear** / **O/S** / **N/S** / **U/C** / **Rooftop** orThe **U/C** / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ECICS PRSEstimated Repair Cost: 6k - 7k.7/6/18Submit PRS Report**RECEIVED 11 JUN 2018**

Date/Time, File Pass to?

☐ : **Preli. Report**☐ : **Final Report**

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 100Transportation: 100+100

\_\_\_\_ \$ + RS. \_\_\_\_ SI

Photos

Others

TOTAL

10310

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**Nivitha (LKK Auto)**

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Thursday, 24 May 2018 3:32 PM  
**To:** Chin Hui Xin; assignments  
**Cc:** ECICS Claims  
**Subject:** RE: SLB1421J & GBE949M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS  
**Attachments:** 24052018122047-0001.pdf

Without Prejudice

Dear Melody

Thank you for your email.  
We are not agreeable with your surveyor list and we will appoint LKK for the PRI.

Aside to LKK

Please assist to arrange for the TP PRI.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** Chin Hui Xin [mailto:huixin@n51.com.sg]  
**Sent:** Thursday, 24 May, 2018 2:54 PM  
**To:** ECICS Claims  
**Subject:** Re: SLB1421J & GBE949M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,  
Melody Chin  
N-51 Automotive Pte Ltd  
Office : 6842 0051  
Fax : 6741 0510  
**www.n51.com.sg**



On Thu, May 24, 2018 at 1:39 PM, ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)> wrote:

**Without prejudice**

Dear Melody

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,

Janice Goh

**Claims Division**

DID: +65 6303 0182

FAX: +65 6338 9267

**ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)

directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** Chin Hui Xin [mailto:[huixin@n51.com.sg](mailto:huixin@n51.com.sg)]

**Sent:** Thursday, 24 May, 2018 12:22 PM

**To:** ECICS Claims

**Subject:** SLB1421J & GBE949M - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,  
2 Kaki Bukit Ave 2, #01-18  
Singapore 417921  
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

Our Ref: SLB 1421 J  
Your ref: GBE 949 M

24 May 2018

**ECICS LIMITED**  
7 TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
SINGAPORE 038987  
Attn: Motor Claims Department

BY EMAIL [claims@ecics.com.sg](mailto:claims@ecics.com.sg) ONLY

Dear Sir/Madam,

**NAME OF CLAIMANT : TWINCAR LEASING**  
**VEHICLE NUMBER : SLB 1421 J**  
**YOUR INSURED VEHICLE NUMBER : GBE 949 M**  
**ACCIDENT ON 23 May 2018 ALONG SERANGOON NORTH AVE 4 TWD**  
**SERANGOON NORTH AVE 3 JUNCTION AT ABOUT 21:37 HOURS**

We refer to your email/fax dated **24 May 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

## **N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub  
2 Kaki Bukit Avenue 2  
#01-18  
Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



**N-51 AUTOMOTIVE PTE LTD**

### **FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/05/2018 11:55
Date Of Accident	23/05/2018 21:35
Exact Location Of Accident	SERANGOON NORTH AVE 4->SERANGOON NORTH AVE 3 JCT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB1421J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TWINCAR LEASING PTE LTD
Co Reg No	201533046C
Email Address	SALES@N51.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68420051

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 CVT ABS D/AIRBAG 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V11639/VPZ/R02
Cover Note Number	

### Driver

Name of Driver	TANG HUI YI, LORRAINE
NRIC No	S8806721E
Date Of Birth	05/03/1988
Occupation	OUTDOOR
Date Of Driving Pass	05/08/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92302716
Fax Number	
Contact Number	
EEmail Address	RAINEISLOVED@GMAIL.COM



Address	BLK 439C SENGKANG WEST AVENUE #17-301
Postcode	793439
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE949M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	SHTRADHAR SHREE TANJIT CHANDRA
NRIC/Passport Number	
Contact Number	86689952
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


## Sketch Plan #2

### SKETCH PLAN

A-SLB1421J

B-GBE949M

SERANGAP NORTH AVE 4 TOWARDS SERANGAP NORTH AVE 3 T-JUNCTION.



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Serangap North Ave 4 towards Serangap North Ave 3 on the right lane of dual-carriageway. Upon T-Junction at Serangap North Ave 3, I signal left as I am making a left turn into Serangap North Ave 3 towards Serangap North Ave 1. After I made a left turn, I realized Veh(B) GBE 949 M filtering towards my lane encroaching my path without any signal. As a result, Veh(B) Right portion collided onto my veh left front portion. Therefore, we alighted and exchanged particulars.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2018 08:22 <a href="#">Edit Reg</a>		24 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  












































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>TWINCAR LEASING PTE LTD</b> , Co. Reg. No.: 201533046C									
Vehicle Reg. No.: <b>SLB1421J</b>		Date of Loss: 23/05/2018 21:00 - :59 [25 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>GBE949M</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 06/06/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLB1421J**  
**[GBE949M]**  
**TP**  
**TWINCAR LEASING PTE LTD**  
**May 23 2018 9:00PM**  
**[-]**  
**N-51 Automotive Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/05/18 12:28	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	04/06/18 12:02	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	04/06/18 12:03	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18009469/AZ4D3E2

Date: 12/06/2018

## REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLB1421J

Insured Vehicle No :

GBE949M

Date of Loss: 23/05/2018

Nature of Claim:

TP

Claim No:

N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLB1421J

Make &amp; Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4033031

Reg. Date: 29/03/2016 (Man. Year: 2016)

Chassis No: RU11113025

Colour: Black

Odometer: 121228 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Habilead 6 mm

Rear Left Side:

Habilead 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side:

Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 24/05/2018

Date Inspected: 25/05/2018 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2018)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLB1421J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >