

SMRT Accident Vehicle Repair Estimates

C-11A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6488X
 Ref. No : TAX/05/18/2087
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : NG CHEE KIONG
 Type of Accident : OTHERS
 Date / Time of Accident : 19/05/2018 04:30:00 PM
 Accident Reported Date / Time : 21/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 19/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096181
 Special Instruction to ARC, if any :
 TOWED \$60 / SLL5295C
 Prepared Date : 21/05/2018 10:44:30 AM



Sebastian.
22/5/18.

- Part by part repair.
- Question mark Item Photo
- Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU103578539

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,183.00	0.00
Total Spray Painting Charges :	3,168.00	0.00
Total Material Charges :	10,935.02	10,935.02
Other Charges :	2,212.76	0.00
TOTAL :	17,498.78	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		5 days
Arc / Surveyor Sign Off Date :	21/05/2018 04:49:24 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/05/2018 04:49:09 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/21/2018 4:49:30 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	0.00 600
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 X
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY APRON PANEL LH	180.00	0.00 ?
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 50
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	360.00	0.00 50
Total Spray Painting & Panel Beating	3,168.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	0.00 30
TO TRANSFER DOOR MECHANISM	240.00	0.00 X
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	375.00	0.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	2,212.76	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace <i>R</i>	No
52116470 50			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace <i>?</i>	No
53301471 10			HOOD SUB-ASSY	1	938.40	25.00	703.80	Replace	Replace <i>X</i>	No
53802471 00			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace <i>✓ DJ</i>	No
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace <i>✓ NEC</i>	No
53828470 70			PROTECTOR, FR FENDER LH	1	90.40	25.00	67.80	Replace	Replace <i>X</i>	No
53876471 10			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace <i>X</i>	No
53732470 20			MEMBER, FR APRON TO COWL SIDE UPPER FRONT LH	1	106.30	25.00	79.72	Replace	Replace <i>?</i>	No
53738470 40			PLATE, FR APRON TO COWL SIDE MEMBER, LH	1	21.40	25.00	16.05	Replace	Replace <i>?</i>	No
60118470 20			COVER SUB-ASSY, FRONT PILLAR, UPR LH	1	96.90	25.00	72.67	Replace	Replace	No
67002471 62			PANEL SUB-ASSY, FRONT DOOR LH	1	1,249.60	25.00	937.20	Replace	Replace <i>R</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>✓ NEC</i>	No
75720470 40			MOULDING ASSY, FRONT DOOR BELT, LH	1	88.60	25.00	66.45	Replace	Replace <i>✓ NEC</i>	No
75752470 10			MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH	1	37.40	25.00	28.05	Replace	Replace <i>✓ SCL</i>	No
75756470 40			MOULDING, FRONT DOOR WINDOW FRAME, REAR LH	1	54.70	25.00	41.02	Replace	Replace <i>✓ Cuf</i>	No
69210470 51A1			DOOR OUTER HANDLE FRONT, LH	1	378.90	25.00	284.17	Replace	Replace <i>✓ Cuf</i>	No
69217470 20			DOOR FRONT, COVER OUTER HANDLE, LH	1	17.30	25.00	12.97	Replace	Replace <i>R</i>	No
68126470 30			GLASS, FRONT DOOR FIX WINDOW, LH	1	309.90	25.00	232.42	Replace	Replace <i>X</i>	No
68216470 10			WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	1	74.30	25.00	55.72	Replace	Replace <i>✓ TN</i>	No
67402470 10			FRAME SUB-ASSY, FRONT DOOR, FRONT LOWER LH	1	140.50	25.00	105.37	Replace	Replace <i>X</i>	No
38102472 30			GLASS SUB-ASSY, FRONT DOOR, LH	1	796.70	25.00	597.52	Replace	Replace <i>✓ SCL</i>	No
37940474 40			MIRROR ASSY, OUTER REAR VIEW, LH	1	1,283.90	10.00	1,155.51	Replace	Replace <i>✓ DMG</i>	No
37945470 30A1			COVER, OUTER MIRROR, LH	1	89.50	25.00	67.12	Replace	Replace <i>✓ MS</i>	No
75860479 10			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	25.00	432.00	Replace	Replace <i>X</i>	No

Number	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	25.00	932.92	Replace	Replace R	No
692114-7021A1	DOOR OUTER HANDLE REAR, LH	1	93.90	25.00	70.42	Replace	Replace R	No
6789647010	WEATHERSTRIP, REAR DOOR, NO.2, LH	1	33.20	25.00	24.90	Replace	Replace ?	No
6922747020	DOOR REAR, COVER OUTER HANDLE, RH & LH	1	17.30	25.00	12.97	Replace	Replace R	No
	PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace ✓	No
7574047040	MOULDING ASSY, REAR DOOR BELT, LH	1	109.80	25.00	82.35	Replace	Replace X	No
7576247050	MOULDING, REAR DOOR WINDOW FRAME, FRONT LH	1	54.70	25.00	41.02	Replace	Replace ✓	No SCR
6811447100	GLASS SUB-ASSY, REAR DOOR, LH	1	397.80	25.00	298.35	Replace	Replace ✓	No SCR
6160247160	PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace R	No
42611-47450	WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace R	No
4261147450	WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace X	No
	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
TOTAL MATERIALS						10,935.13	10,935.02	
TOTAL MATERIALS(Discounted)						10,935.02	10,935.02	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									