

Trans-cab Auto Services Pte Ltd

AAD1805-196

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5087R

*Not Authorised
Propose L1 Sing \$18,000+*

Vehicle No.:	SHC 5087R
Chassis No.:	VF1ABL15AUC275903
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	22.5.2018
Third Party Insurer :	

PART		LIST		
1	1 BUMPER COVER REAR	\$	<i>R₁</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Diy</i> 135.97	✓
5	1 BUMEP R RETAINER RH REAR	\$	<i>Diy</i> 44.99	✓
6	1 BUMPER REFLECTOR RH	\$	<i>R₂</i> 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Diy</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>Diy</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R₁</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R₁</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R₁</i> 225.95	✓
13	1 BOOT REAR	\$	<i>R₁</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>S₁</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>W₁</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>R₁</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>R₁</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>S₁</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>S₁</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>S₁</i> 586.45	} X
25	1 BOOT SWITCH	\$	<i>S₁</i> 168.13	
26	1 BOOT LOCK	\$	<i>R₁</i> 202.67	✓
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>S₁</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>S₁</i> 221.81	✓

Trans-cab Auto Services Pte Ltd

AAD1805-196

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5087R

30	1 DOOR PANEL REAR LH	\$	<i>A</i>	2,844.66	<i>X</i>
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i>	671.45	<i>X</i>
32	1 FENDER PANEL REAR LH	\$	<i>Ar</i>	3,299.13	—
33	1 WHEELARCH REAR LH	\$	<i>Sm</i>	543.47	<i>X</i>
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Deform</i>	671.45	—
35	1 FENDER PANEL REAR RH	\$	<i>Ar</i>	3,299.13	—
36	1 WHEELARCH REAR RH	\$	<i>Sm</i>	543.47	<i>X</i>
37	1 TAILLAMP RH	\$	<i>CM</i>	552.55	—
38	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	—
39	1 TAILLAMP LH	\$	<i>CM</i>	552.55	—
40	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	—
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	—
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i>	404.56	—
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>B-1 Ar</i>	2,189.88	—
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sm</i>	612.21	<i>X</i>
45	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	—
46	1 EXHAUST CAP REAR	\$	<i>ml</i>	230.49	—
47	1 FUEL FLAP L70Y	\$	<i>Sm</i>	343.57	<i>X</i>
TOTAL		\$		39,057.17	
10%		\$		3,905.72	
		\$		35,151.45	

Special Nett

1	1SET PARKING AID	\$	<i>Shor</i>	700.00	<i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	} <i>X</i>
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	—
10	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	<i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	<i>X</i>
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	—
14	1 BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	<i>X</i>
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-196

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5087R

16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nw</i>	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	<i>mc</i>	28.00	—
18	1 FENDER INNER TRIM CLIP LH	\$	<i>mc</i>	28.00	—
19	1 TAILLAMP CLIP RH	\$	<i>mc</i>	5.00	—
20	1 TAILLAMP CLIP LH	\$	<i>mc</i>	5.00	—
21	2 REAR WINDSCREEN SELANT	\$	<i>mc</i>	80.00	<i>40sn</i>
22	1 WINDSCREEN MOULDING	\$	<i>mc</i>	100.00	—
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>mc</i>	100.00	<i>30sn</i>
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i>	385.00	X
25	1 SPARE TYRE	\$	<i>sn</i>	330.00	X

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,376.47

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	<i>15401</i> 6,000.00 <i>27001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>22001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>1501</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	170.00 <i>801</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 <i>801</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nw</i> 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-196

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5087R

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	<i>100/</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	<i>80/</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>120/</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>60/</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>

TOTAL \$ 12,540.00

Over All Total \$ 49,916.47

(LUMP SUM)

Repair Days

20 DAYS

18 days