



GST / ROC Company No : 201101753C

Third Party Insurer : INDIA

Insured's Veh No : SH7691S

Date of accident : 21/05/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/05-1025

Quotation Date : 23/05/2018

Estimate To Repair HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No : SLT2836U

Chassis No : RU3-1252244

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
		SPARE PARTS	
1	1PC	REAR BUMPER <i>no/ee</i>	\$810.00
2	10PC	REAR BUMPER CLIPS <i>ee</i>	\$55.00
		LESS 20%	\$865.00
			\$173.00
			\$692.00
		MISC ITEMS	
13	1PC	REVERSE SENSOR <i>ee</i>	\$250.00
		Total	\$250.00
		LABOUR & MISC. CHARGES	
1		WIRE CHECKING	\$30.00
2		LABOUR CHARGE	\$250.00
3		SPRAY PAINTING	\$250.00
		Total	\$530.00
		Sub Total	\$1,472.00
		GST (7.00%)	\$103.04
		Total	\$1,575.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418

*not Afford
make
Take photo before painting
2 dy.
18/6/18*