

CARL MOTOR & ENTERPRISE CENTRE PTE LTD
 No. 38 Woodlands Ind. Park E 1 #05-10
 Singapore 757700
 Tel: 63666171 Fax: 63666805
 Co. Reg. No: 199901512 Z

22 May 2018

AXA Insurance Singapore Pte Ltd
 8 Shenton Way #24-01 AXA Tower
 Singapore 068811
 Tel: 68804888 Fax: 68804838

Attention: Motor Claim (3 Party Claim)

Dear Sir/Mdm

TRAFFIC ACCIDENT INVOLVING YOUR INSURED VEHICLE SHC 5115 J & OUR CLIENT VEHICLE SKV 6048 C ON 18.04.2018 ALONG NASSIM ROAD OUTSIDE PHILLIPINE EMBASSY

Toyota Harrier 2.0 A – Veh No: SKV 6048 C
 (Accident Involving SKV 6048 C and SHC 5115 J on 18.04. 2018 along Nassim Road)

1.	1 pc	Rear bumper. R		\$ 1,395.00
2.	1 pc	Rear bumper lower cover. ✓ CAR		408.00
3.	1 pc	Rear bumper sponge. ?		142.00
4.	2 pcs	Rear bumper side retainer – L & R. ✗	\$ 72.00	144.00
				<u>\$ 2,089.00</u>
			Less 20%	- 417.80
				<u>\$1,671.20</u>

S/nett:

5.	1 set	Reversr sensor. ✓ OMS.		350.00
----	-------	------------------------	--	--------

Labour Charges:

6.	Workmanship for knocking & welding.	300 · 450.00
7.	Respray painting.	300 · 400.00
		<u>\$ 2,871.20</u>



Sebastian.
 25/5/18.
 - Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint.
 90036121
 sebastianyang@lkkauto.com

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: