

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 47037**
Date Estimated : **22/05/2018**
Prepared By : **Gary Poh Chai Hoon**

Page No. :

REPAIR FOR -
Kemral Durgadas Shetty
Blk 305 Bukit Batok Street 31
#08-89

- ACCOUNT - 148376
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Singapore 650305

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident		2550.00		2,550.00
To spray paint rear bumper, boot lid and tail end panel		2399.00		2,399.00
To carry out body cavity preservation. (Per panel).		100.00		100.00
# To remove and install boot compartment carpet and garnish to facilitate repairs		231.00		231.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,204.80	1.00		1,204.80
REAR BUMPER CENTRE GUIDE	32.10	1.00		32.10
REAR BUMPER CARRIER (ECE)	432.90	1.00		432.90
REAR BUMPER PANEL PRIMED BASIS	1,100.25	1.00		1,100.25
# REAR PDC HOLDER SET *	23.10	1.00		23.10
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	69.50	1.00		69.50
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	5,510.00
Total Parts :	2,917.20
Total Labour & Parts :	8,427.20
Deduction for Excess :	
Total Repair Costs less Excess:	8,427.20
GST @7%:	589.90
Grand Total :	9,017.10