

22/03/2002

ASS. REC. BY:

REF: CS/CIA18009486/R1v672

Special Instruction:

Supervisor:

Ragui

ASSIGNMENT (Office)

From (Person):

Rachel Tim

of

GAL

Date/Time: 20052018 11:37am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFm 7739S

Insured:

YL 2472Z

at Workshop in/s

Performance

Tel:

63190174

of

303 Alexandra Rd

Policy No:

Claim No:

CLMOMVC000003257

Sum Insured:

Excess:

D.O.A.

20052018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

24052018 @ 5:30pm

H.O.D. Endorsement:

Date/Time:

20052018 - 1:40pm

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	OCA: 281040
	SFm 7739S - C4 / AXA 10021798 / R4H2	
	YL 2472Z - X	
25/5/18	Email preli revised to Rachel	
10/6/18	Final fig \$ 8427.20 confirmed by email (Reel	8170.80, 4979

DATE:

Signature

*Rame*

REF:

51173

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SFM 77395*

at Workshop m/s: *PERFORMANCE*

of

Insured:

*GA1/MP*

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No.

*SFM 77395*

Yr Regn: *2014 / July*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

*B.M.W 316I 1.6*

C.C. *1598*

Colour

*WHITE*

A/C: Insured / Std / NI / NA

Sp Reading

*68671*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*WBA3A16040N537629*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

*205/60R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

*CONTINENTAL*

Front

R/Bal.

*6*

mm

Rear

R/Bal.

*6*

mm

L/Bal.

*6*

mm

L/Bal.

*6*

mm

D.O.A.

*22/05/18*

D.O.I.

*24/05/18*

Survey held at

*PERFORMANCE*

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 10 SEP 2018

Date/Time: File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time: File Return to?

2)

*109- typist*

Report Format :

*TP*

Lump Sum / I.B.I: (\$

*8427.20*)

Days Of Repair: *6*

Resurvey No. of Trip: *1*

Add Fee:

☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

*450*



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED  
Our ref: CS/GAI18009486/R1vb

Date: 25/5/2018

The Motor Claims Department  
M/s GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SFM 7739S**


We thank you for your instruction on 23/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/5/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$16,290.85
Revised Estimate Amount	: S\$7,794.00
"Check" Items Amount	: S\$2,671.60
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

**MOHAMMED RASUL**  
Automotive Assessor

## Veron Chen (LKKAuto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Friday, 25 May 2018 2:32 PM  
**To:** Veron Chen (LKKAuto)  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018  
**Attachments:** SFM 7739S PRELI REVISED.PDF

CLMOMVC000003257

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Friday, May 25, 2018 2:02 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** [External] RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018

Dear Rachel,

Enclosed preliminary revised of vehicle SFM 7739S  
Date of survey: 24/5/2018  
Number of days: 6 days

**Please provides us the claim number.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 23 May, 2018 1:41 PM  
**To:** 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'PBSP' <pml-pbsp@simedarby.com.sg>  
**Cc:** 'LKK Assignments' <assignments@lkkauto.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018

Dear Rachel,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

**Sent:** Wednesday, 23 May, 2018 11:37 AM

**To:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>

**Cc:** LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018

Without Prejudice

Dear Caroline

Based on description of accident, liability is not in our (YL2472Z) favor.  
As requested, we will appoint LKK to conduct TP survey.

Dear LKK, please assist. Attached estimates (1pg) and TP GIA report.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Ngian, Kelvyna

**Sent:** Wednesday, May 23, 2018 11:16 AM

**To:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>; Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>

**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND insd YL2472Z ON 22/05/2018

Hi Rachel

Kindly assist

Thanks

Kelvyna

---

**From:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>

**Sent:** Wednesday, May 23, 2018 9:18 AM

**To:** Ng, Sharon <[Sharon.Ng@sg.gaig.com](mailto:Sharon.Ng@sg.gaig.com)>; Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>

**Subject:** [External] REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z ON 22/05/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,  
Caroline

C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 25 May 2018 2:01 PM  
**To:** 'Tan, Rachel'  
**Cc:** SUR  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018  
**Attachments:** SFM 7739S PRELI REVISED.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SFM 7739S  
Date of survey: 24/5/2018  
Number of days: 6 days

**Please provides us the claim number.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 23 May, 2018 1:41 PM  
**To:** 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; 'PBSP' <pml-pbsp@simedarby.com.sg>  
**Cc:** 'LKK Assignments' <assignments@lkkauto.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018

Dear Rachel,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]  
**Sent:** Wednesday, 23 May, 2018 11:37 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** LKK Assignments <assignments@lkkauto.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018

Without Prejudice

Dear Caroline

Based on description of accident, liability is not in our (YL2472Z) favor.  
As requested, we will appoint LKK to conduct TP survey.

Dear LKK, please assist. Attached estimates (1pg) and TP GIA report.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Ngian, Kelvyna  
**Sent:** Wednesday, May 23, 2018 11:16 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND insd YL2472Z ON 22/05/2018

Hi Rachel

Kindly assist

Thanks  
Kelvyna

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, May 23, 2018 9:18 AM  
**To:** Ng, Sharon <Sharon.Ng@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Subject:** [External] REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z ON 22/05/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601



**Catherine Chong (LKK Auto)**

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Wednesday, 23 May, 2018 11:37 AM  
**To:** PBSP  
**Cc:** LKK Assignments  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z (GA) ON 22/05/2018  
**Attachments:** SFM7739S.PDF; SKM\_558e18052309140.tif

Without Prejudice

Dear Caroline

Based on description of accident, liability is not in our (YL2472Z) favor.  
As requested, we will appoint LKK to conduct TP survey.

Dear LKK, please assist. Attached estimates (1pg) and TP GIA report.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Ngian, Kelvyna  
**Sent:** Wednesday, May 23, 2018 11:16 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>; Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT- SFM7739S AND insd YL2472Z ON 22/05/2018

Hi Rachel

Kindly assist

Thanks  
Kelvyna

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, May 23, 2018 9:18 AM  
**To:** Ng, Sharon <Sharon.Ng@sg.gaig.com>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>  
**Subject:** [External] REQ FOR DIRECT SETTLEMENT- SFM7739S AND YL2472Z ON 22/05/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 10 September 2018 10:37 AM  
**To:** PBSP; Rasul (LKKAUTO)  
**Cc:** SUR; Keith Leo Chi Yung  
**Subject:** RE: FINAL REPORT / SFM7739S

Dear Caroline,

WITHOUT PREJUDICE

Confirm \$8,427.20 before GST @ 6 working days.

**Kindly send Final invoice and all supporting documents to GREAT AMERICAN INSURANCE**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Keith Leo Chi Yung <keith.leo.chiyung@sime-darby.com.sg>

**Sent:** Thursday, 6 September 2018 12:24 PM

**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; PBSP <pml-pbsp@sime-darby.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>

**Cc:** SUR <sur@lkkauto.com>

**Subject:** RE: FINAL REPORT / SFM7739S

As requested

Warm Regards

Keith Leo

Body & Paint

DDI: 6319 0172

FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Thursday, 06 September, 2018 10:46 AM  
**To:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>; Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Keith Leo Chi Yung <[keith.leo.chiyung@simedarby.com.sg](mailto:keith.leo.chiyung@simedarby.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: FINAL REPORT / SFM7739S

Dear Keith,

Kindly forward us photos:

- 1) REAR BUMPER CENTRE GUIDE
- 2) REAR BUMPER CARRIER (ECE)

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 4 September 2018 4:51 PM  
**To:** 'PBSP' <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>; Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Keith Leo Chi Yung <[keith.leo.chiyung@simedarby.com.sg](mailto:keith.leo.chiyung@simedarby.com.sg)>  
**Subject:** RE: FINAL REPORT / SFM7739S

Dear Keith,

Kindly forward us check items and supplementary photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)>  
**Sent:** Tuesday, 4 September 2018 4:23 PM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Veron Chen (LKKAuto) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>  
**Subject:** FINAL REPORT / SFM7739S

Dear Rasul and Veron

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 5,510.00

Total Parts : 2,917.20

Total Labour & Parts : 8,427.20

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

23 MAY 2018

Estimate No. : b1 47037  
Date Estimated : 22/05/2018  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Kemral Durgadas Shetty  
Blk 305 Bukit Batok Street 31  
#08-89

Singapore 650305

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0

## DESCRIPTION

To Replace rear bumper, bootlid, tail panel and attachment  
knocking cause by the accident

Painting rear bumper, bootlid, tail panel, trunk floor,  
left rear fender, right rear fender

To carry out body cavity preservation.  
(Per panel).

To carry out body cavity preservation.  
(For cut panel).

To check electrical wiring systems and lightings at the  
rear section for proper function.

Sundries.

VALUE

2550 5,100.00

2399 4,987.00

100 118.00

11 x 451 531.00

150 177.00

rec 80 150.00

Total Labour 1: 11,043.00

## DESCRIPTION

BOOTLID  
TAIL PANEL  
RR BUMPER BOTTOM REINFORCEMENT  
REAR BUMPER CENTRE GUIDE  
REAR BUMPER CARRIER (ECE)  
REAR BUMPER PANEL PRIMED BASIS  
REAR BUMPER LH SIDE GUIDE  
REAR BUMPER RH SIDE GUIDE  
MODEL LETTERING 316i  
GROMMET  
PLAQUE 74MM  
TRUNK LID GASKET  
DECOUPLING RING PDC TORQUE CONVERTE  
PDC SENSOR MINERALWEISS (A96)

QTY PRIC

1 1,204.80  
1 592.25  
1 66.10  
1 32.10  
1 432.90  
1 1,100.25  
1 57.05  
1 57.05  
1 62.55  
2 0.75  
1 69.50  
1 76.40  
4 5.05  
4 368.80

VALUE

74 1,204.80  
Repair 592.25  
X 66.10  
(RA) 32.10  
M 432.90  
DE 1,100.25  
57.05  
57.05  
max 62.55  
rec 1.50  
rec 69.50  
max 76.40  
M 20.20  
M 1,475.20

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 47037  
Date Estimated : 22/05/2018  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0

Total Parts : 5,247.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim No. C  
Reg. No. 24/05/18 01720  
Description RASUL  
Surveyor's name 96010068  
Surveyor's Tel. 6 days

*[Signature]*  
28/5/18

16,598

Labour 1	:	11,043.00
Parts	:	5,247.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,140.36
Grand Total	:	17,431.21

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 1974015599, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47037  
Date Estimated : 22/05/2018  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Kemral Durgadas Shetty  
Blk 305 Bukit Batok Street 31  
#08-89

- ACCOUNT - 148376  
Great American Insurance Company  
3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

Singapore 650305

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE	
SFM7739S	NS37629	30/07/2014	316iA/4	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachments, boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00		
To spray paint rear bumper, boot lid and tail end panel	2399.00		2,399.00		
To carry out body cavity preservation. (Per panel).	100.00		100.00		
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	(A)	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
Sundries.	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
BOOTLID	1,204.80	1.00		1,204.80	
REAR BUMPER CENTRE GUIDE	32.10	1.00		32.10	
REAR BUMPER CARRIER (ECE)	432.90	1.00		432.90	
REAR BUMPER PANEL PRIMED BASIS	1,100.25	1.00		1,100.25	
# REAR PDC HOLDER SET *	23.10	1.00		23.10	(A)
GROMMET	0.75	2.00		1.50	
PLAQUE 74MM	69.50	1.00		69.50	
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05	(A)

### # SUPPLEMENTARY ITEMS

Total Labour :	5,510.00
Total Parts :	2,917.20
Total Labour & Parts :	8,427.20
Deduction for Excess :	
Total Repair Costs less Excess:	8,427.20
GST @7%:	589.90
Grand Total :	9,017.10



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 47037  
Date Estimated : 22/05/2018  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Kemral Durgadas Shetty  
Blk 305 Bukit Batok Street 31  
#08-89

- ACCOUNT - 148376  
Great American Insurance Company  
3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

Singapore 650305

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SFM7739S	NS37629	30/07/2014	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To remove and install boot compartment carpet and  
garnish to facilitate repairs

231.00 231.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR PDC HOLDER SET *	23.10	1.00		23.10 ✓
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 ✓


Total Labour :	231.00
Total Parts :	76.15
Total Labour & Parts :	307.15

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18009486/R1vbn2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 11-09-2018		
		Code : GAI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YL 2472Z	Veh. Inspected	SFM 7739S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003257	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	23/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	BMW 316I 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBA3A16040NS37629	Colour	WHITE	
Odometer	68671	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/05/2018	Inspection Date	24/05/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFM 7739S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID (SN)	BENT	1,204.80	1,204.80
1	TAIL PANEL (SN)	TO REPAIR SEE LABOUR	592.25	-
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	SERVICEABLE	66.10	-
1	REAR BUMPER CENTRE GUIDE (SN)	CRACKED	32.10	32.10
1	REAR BUMPER CARRIER (ECE)(SN)	BENT	432.90	432.90
1	REAR BUMPER PANEL PRIMED BASIS (SN)	DEFORMED	1,100.25	1,100.25
1	REAR BUMPER LH SIDE GUIDE (SN)	SERVICEABLE	57.05	-
1	REAR BUMPER RH SIDE GUIDE (SN)	SERVICEABLE	57.05	-
1	MODEL LETTERING 316I (SN)	NOT NECESSARY	62.55	-
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	PLAQUE 74MM (SN)	NECESSARY	69.50	69.50
1	TRUNK LID GASKET (SN)	NOT NECESSARY	76.40	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
4	PDC SENSOR MINERALWEISS (A96)(SN)	NOT NECESSARY	1,475.20	-
1	REAR PDC HOLDER SET (SN)(ADDITIONAL)	NECESSARY	23.10	23.10
1	(DG/SL) ADHESIVE SET K6 (SN)(ADDITIONAL)	NECESSARY	53.05	53.05
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			5,474.00	2,997.20
<b>LABOUR</b>				
TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS. (ADDITIONAL)			231.00	231.00
TO REPLACE REAR BUMPER,BOOTLID,TAIL PANEL AND ATTACHMENT KNOCKING CAUSE BY THE ACCIDENT.			5,100.00	2,550.00
PAINTING REAR BUMPER,BOOTLID,TAIL PANEL,TRUNK FLOOR,LEFT REAR FENDER,RIGHT REAR FENDER.			4,967.00	2,399.00
TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).			118.00	100.00
TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).		NOT NECESSARY	531.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			11,124.00	5,430.00
GRAND TOTAL			16,598.00	8,427.20
RECOMMENDED COST OF REPAIRS				8,427.20

Report Ref No. CS/GAI18009486/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.