

2/03/2002

ASS. REC. BY:

REF: CS/SPF18009487/Ssber

Special Instruction:

Surveyor: Sebastian.

ASSIGNMENT (Office)

From (Person): Lim Wei Yee of SPF Date/Time: 28/05/2018 4:41pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QX 683B Insured:

at Workshop m/s SMRT Tel:

of 60 Woodlands Ind Park E4

Policy No: Claim No: HOMSPFETQ17300218.

Sum Insured: Excess:

Make of Veh: D.O.A.
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	QX 683B - X
31/05/18	@ 14:47 p.m revert Wei Yee.
19/06/18	Submit SPF report

REF: SPF

INSURANCE

From	Date: 24052018	Veh No: Qx 683B	Tr Regn:
Estimated Cost		Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or	
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV	To inspect Vehicle No: Qx 683B	Make: Ford Everest	CC:
	at Workshop n/s: SMRT	Colour: Blue	A/C: Insured / Std / NI / NA
of		Sp Reading	T/Radio: Insured / Std / NI / NA
Insured		Eng/No:	
Policy No:		C/No: MNBL5 4090AW 310847	
Claims No:		Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt	
Sum Insured:	Excess:	Steering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or	
(Client's Record)		Brake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or	
Make of Veh:		Modi: ☒ M / ☐ S/Rim / ☐ STD A/Rim or	
(Policy Condition)		Tyre Size F: 245/70R16	
Remark: The veh had commenced its repair at the time of inspection.		R: 1	
		BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken	
Bal. or Market Value:		Front	Rear
IDAC Accident Report:	Consistent?: Yes or No	R/Bal. 6 mm	R/Bal. 6 mm
GIA / PR Seen:	Consistent?: Yes or No	L/Bal. 6 mm	L/Bal. 6 mm
Est. Repairs:	days Res: Yes or No	D.O.A.	D.O.I. 28/5/18
Lump Sum:	% 3 Val: Yes or No	Survey held at: 213 Sy Kadup Dr	
CA / REV / REP. / 24 HRS		Des. of Damages: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☒ Roof top or	
Date:	Person Contacted:	Vehicle: IN / OUT	
The UIC / Chassis frame / Body Structure affected due to collision.			
Date / Time	Action / Instruction		

RECEIVED 19 JUN 2018

Date/Time: File Pass to:

19/06/18
Typist

Date/Time: File Return to:

21

Report Format:

Lump Sum / LB / B

☐ : Preli. Report☒ : Final Report

Days Of Repair: -

Resurvey No. of Trip: -

Survey Fee

Transportation

1. ...

2. ...

3. ...

4. ...

TOTAL

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Diagram (\$)

280

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18009487/Ssb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 24-05-2018



Code : SPF

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 683B
Policy No.	Coverage (\$)	0.00
Claim No. HOMSPFETQ17300218	Excess (\$)	0.00
Assign From LIM WEI YEA	Assign Date	23/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	24/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Shirley Hiew (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Tuesday, 19 June 2018 10:36 AM
To: Shirley Hiew (LKK Auto); 'assignments'
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); 'Shiau Chan (LKKAuto)'; 'Veron Chen (LKKAuto)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Hi Shirley,

Yes, please do.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 19 June 2018 10:32
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Dear Wei Yea,

Please advise whether can we submit our report of QX 683B accordingly.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM Wei Yea@spf.gov.sg]

Sent: Friday, 1 June 2018 9:17 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Hi Shirley,

Thanks for the report.

I will review the report and feedback if any queries.

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Thursday, 31 May 2018 14:47

To: Wei Yea LIM (SPF) <LIM Wei Yea@spf.gov.sg>; 'assignments' <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY Kim Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN Kwee Huat@spf.gov.sg>; Perry HE (SPF) <Perry HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard SEAH@spf.gov.sg>; 'Ai Phing (LKKAuto)' <aiphing@lkkauto.com>; 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>; 'Veron Chen (LKKAuto)' <veronchen@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Dear Wei Yea,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM Wei Yea@spf.gov.sg]

Sent: Wednesday, 23 May 2018 4:41 PM

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 May 2018 2:47 PM
To: 'Wei Yea LIM (SPF)'; 'assignments'
Cc: 'Kim Pang CHAY (SPF)'; 'Kwee Huat TAN (SPF)'; 'Perry HE (SPF)'; 'Bernard SEAH (SPF)'; 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto)'; 'Veron Chen (LKKAuto)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218
Attachments: QX 683B.xls; LKK SURVEYOR PHOTO.pdf

Dear Wei Yea,

Please refer to the attachments.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Wednesday, 23 May 2018 4:41 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 683B

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Do let me know if you have difficulty in arranging a viewing session with SMRT.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 23 May, 2018 4:41 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'; Veron Chen (LKKAuto)
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218
Attachments: QX683B.XLSX

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 683B

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Do let me know if you have difficulty in arranging a viewing session with SMRT.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential Information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ROOF TOP PANEL	1	DENTED	\$ 1,300.00	\$ 1,300.00	
1.2	RH ROOF RAILING	1	BENT	\$ 400.00	\$ 400.00	
1.3	INTERIOR CEILING HOLSTERY	1	DEFORMED	\$ 1,350.00	\$ 1,350.00	
1.4	REAR RH DOOR SHELL	1	DENTED	\$ 1,360.00	\$ 1,360.00	
1.5	FRONT WINDSCREEN	1	CRACKED	\$ 1,400.00	\$ 1,400.00	
1.6	FRONT WINDSCREEN MOULDING	1	NECESSARY	\$ 100.00	\$ 100.00	
1.7	SEALANT FOR FRONT WINDSCREEN	1	NECESSARY	\$ 50.00	\$ 50.00	
1.8	PRIMER FOR FRONT WINDSCREEN	1	NECESSARY	\$ 10.00	\$ 10.00	
1.9	FRONT WINDSCREEN SOLAR FIRM	1	NECESSARY	\$ 180.00	\$ 180.00	
1.10	BONNET COVER	1	DENTED	\$ 1,070.00	\$ 1,070.00	
1.11	FRONT BUMPER LOWER GRILLE	1	DEFORMED	\$ 450.00	\$ 450.00	
1.12	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 1,890.00	\$ 1,890.00	
1	SCOPE OF REPAIRS					
1.1	ROOF TOP PANEL :					38
	REMOVE & RE-INSTALL BAR LIGHT ASSY					
	REMOVE & REPLACE ROOF TOP PANEL (CUT & WELD)					
	REMOVE & REPLACE RH ROOF RAILING					
	PUTTY & SPRAY PAINT FOR ROOF TOP PANEL					
	WATER SEEPAGE TEST FOR ROOF TOP					
1.2	INTERIOR CEILING HOLSTERY :					3
	REMOVE & REPLACE INTERIOR CEILING HOLSTERY					
	REMOVE & RE-INSTALL BACK INTERIOR REAR AIR-CON DUCT & ROOM LIGHT TO FACILITATE THE REMOVAL FOR INTERIOR CEILING HOLSTERY					
1.3	REAR RH DOOR, FRONT LH & RH DOOR :					24
	REMOVE & REPLACE REAR RH DOOR SHELL					

	REMOVE & RE-INSTALL BACK REAR RH DOOR ITEMS (RIOT MESH, WINDOW GLASS, LOCKING MECHANISM, DOOR TRI								
	REPLACE REAR RH DOOR "POLICE" CRESR STICKER (TO BE PROVIDED BY AEMD)								
	ALIGN REAR RH DOOR								
	RE-ALIGN RH DOOR PILLAR								
	RE-ALIGN FRONT LH & RH DOOR								
	PANEL BEATING FOR REAR RH DOOR FRAME								
	PUTTY & SPRAY PAINT FOR REAR RH DOOR FRAME								
	PUTTY & SPRAY PAINT FOR REAR RH DOOR SHELL								6
1.4	FRONT WINDSCREEN :								
	REMOVE & REPLACE FRONT WINDSCREEN								
	REMOVE & REPLACE FRONT WINDSCREEN MOULDING								
	REPLACE FRONT WINDSCREEN SOLAR FIRM								
	WATER SEEPAGE TEST FOR FRONT WINDSCREEN								
1.5	BONNET COVER :								8
	REMOVE & REPLACE FRONT BONNET COVER								
	REMOVE & REPLACE BOTH SIDE BONNET HINGES (LEFT & RIGHT)								
	REPLACE BONNET COVER "POLICE" WORDING STICKER (TO BE PROVIDED BY AEMD)								
	PUTTY & SPRAY PAINT FOR BONNET COVER								
1.6	FRONT BUMPER LOWER GRILLE :								0.5
	REMOVE & REPLACE FRONT BUMPER LOWER GRILL								
1.7	REAR DOOR :								6
	PANEL BEATING FOR REAR DOOR								
	PUTTY & SPRAY PAINT FOR REAR DOOR REPAIRED AREA								
1.8	SPARE TYRE COVER :								1
	REPLACE SPRE TYRE COVER "POLICE" WORDING STICKER (TO BE PROVIDED BY AEMD)								
	PUTTY & SPRAY PAINT FOR SPARE TYRE COVER								
COSTING								TOTAL PARTS COST	\$9,560.00
								TOTAL MAN-HOUR	86.5



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	SUV	UNIT :	HTA
VEH NO :	QX683B	REPAIR TYPE :	ACCIDENT		
VEH MAKE/MODEL :	FORD EVEREST	ODOMETER :	82989		

Reference No.	0683/SPF/4W/18/05/23
iLMS No.	1100004944

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Roof Top Panel <i>✓ DT</i>	\$1,300.00	1		1300.00	1300.00
1.2	RH Roof Railing <i>✓ BT</i>	\$400.00	1		400.00	400.00
1.3	Interior Ceiling Holstery <i>✓ Defcon</i>	\$1,350.00	1		1350.00	1350.00
1.4	Rear RH Door Shell <i>✓ DT</i>	\$1,360.00	1		1360.00	1360.00
1.5	Front Windscreen <i>✓ CRK</i>	\$1,400.00	1		1400.00	1400.00
1.6	Front Windscreen Moulding <i>✓ NCC</i>	\$100.00	1		100.00	100.00
1.7	Sealant for Front Windscreen <i>✓ NCC</i>	\$50.00	1		50.00	50.00
1.8	Primer for Front Windscreen <i>✓ NCC</i>	\$10.00	1		10.00	10.00
1.9	Front Windscreen Solar Firm <i>✓ NCC</i>	\$180.00	1		180.00	180.00
1.10	Bonnet Cover <i>✓ DT</i>	\$1,070.00	1		1070.00	1070.00
1.11	Front Bumper Lower Grille <i>✓ Defcon</i>	\$450.00	1		450.00	450.00
1.12	To Supply Labour & Material To Replace Bar Light Cover	\$1,890.00	1	0%	1890.00	1890.00
2	Additional Services					
2.1	NA	\$0.00	0	0%	0.00	0.00
Remarks:					Parts Total:	\$ 9,560.00

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Roof Top Panel:	38	40	0.00
	Remove & Re-Install Bar Light Assy			
	Remove & Replace Roof Top Panel (Cut & Weld)			
	Remove & Replace RH Roof Railing			
	Putty & Spray Paint for Roof Top Panel			
	Water Seepage Test for Roof Top			
1.2	Interior Ceiling Holstery:	3	4	0.00
	Remove & Replace Interior Ceiling Holstery			
	Remove & Re-Install back Interior Rear Air-Con Duct & Room Light to facilitate the removal for Interior Ceiling Holstery			
1.3	Rear RH Door, Front LH & RH Door:	24	30	0.00
	Remove & Replace Rear RH Door Shell			
	Remove & Re-Install back Rear RH Door Items (Riot Mesh, Window Glass, Locking Mechanism, Door Trim)			
	Replace Rear RH Door "POLICE" Crest Sticker (To be provided by AEMD)			
	Align Rear RH Door			
	Re-Align RH Door Pillar			
	Re-Align Front LH & RH Door			
	Panel Beating for Rear RH Door Frame			
	Putty & Spray Paint for Rear RH Door Frame			
	Putty & Spray Paint for Rear RH Door Shell			
1.4	Front Windscreen:		6	0.00
	Remove & Replace Front Windscreen			
	Remove & Replace Front Windscreen Moulding			
	Replace Front Windscreen Solar Firm			
	Water Seepage Test for Front Windscreen			
1.5	Bonnet Cover:	8	10	0.00
	Remove & Replace Front Bonnet Cover			
	Remove & Replace Both Side Bonnet Hinges (Left & Right)			
	Replace Bonnet Cover "POLICE" Wording Sticker (To be provided by AEMD)			
	Putty & Spray Paint for Bonnet Cover			
1.6	Front Bumper Lower Grille:	0.5	1	0.00
	Remove & Replace Front Bumper Lower Grill			
1.7	Rear Door:	6	8	0.00
	Panel Beating for Rear Door			
	Putty & Spray Paint for Rear Door repaired area			
1.8	Spare Tyre Cover:		1	0.00
	Replace Spare Tyre Cover "POLICE" Wording Sticker (To be provided by AEMD)			
	Putty & Spray Paint for Spare Tyre Cover			
SUB-TOTAL				100 0.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 8)	138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)	44.10	1	44.10

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF18009487/Ssbe2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 26-06-2018



ATTN : LIM WEI YEA

Code : SPF

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	QX 683B
Policy No.		Coverage (\$)	0.00
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00
Assign From	LIM WEI YEA	Assign Date	23/05/2018

2. Vehicle Particulars & Condition

Make & Model	FORD EVEREST	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MNBLS4090AW310847	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/70 R16	FALKEN	6 mm
L/H Front Tyre	245/70 R16	FALKEN	6 mm
R/H Rear Tyre	245/70 R16	FALKEN	6 mm
L/H Rear Tyre	245/70 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND ROOFTOP PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date		Inspection Date	28/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

--



Registration No. QX 383S

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	ROOF TOP PANEL	1	DENTED	\$ 1,300.00	\$ 1,300.00	
1.2	RH ROOF RAILING	1	BENT	\$ 400.00	\$ 400.00	
1.3	INTERIOR CEILING HOLSTERY	1	DEFORMED	\$ 1,350.00	\$ 1,350.00	
1.4	REAR RH DOOR SHELL	1	DENTED	\$ 1,360.00	\$ 1,360.00	
1.5	FRONT WINDSCREEN	1	CRACKED	\$ 1,400.00	\$ 1,400.00	
1.6	FRONT WINDSCREEN MOULDING	1	NECESSARY	\$ 100.00	\$ 100.00	
1.7	SEALANT FOR FRONT WINDSCREEN	1	NECESSARY	\$ 50.00	\$ 50.00	
1.8	PRIMER FOR FRONT WINDSCREEN	1	NECESSARY	\$ 10.00	\$ 10.00	
1.9	FRONT WINDSCREEN SOLAR FIRM	1	NECESSARY	\$ 180.00	\$ 180.00	
1.10	BONNET COVER	1	DENTED	\$ 1,070.00	\$ 1,070.00	
1.11	FRONT BUMPER LOWER GRILLE	1	DEFORMED	\$ 450.00	\$ 450.00	
1.12	TO SUPPLY LABOUR & MATERIAL TO REPLACE BAR LIGHT COVER	1		\$ 1,890.00	\$ 1,890.00	
1	SCOPE OF REPAIRS					
1.1	ROOF TOP PANEL :					38
	REMOVE & RE-INSTALL BAR LIGHT ASSY					
	REMOVE & REPLACE ROOF TOP PANEL (CUT & WELD)					
	REMOVE & REPLACE RH ROOF RAILING					

	PUTTY & SPRAY PAINT FOR ROOF TOP PANEL					
	WATER SEEPAGE TEST FOR ROOF TOP					
1.2	INTERIOR CEILING HOLSTERY :					3
	REMOVE & REPLACE INTERIOR CEILING HOLSTERY					
	REMOVE & RE-INSTALL BACK INTERIOR REAR AIR-CON DUCT & ROOM LIGHT TO FACILITATE THE REMOVAL FOR INTERIOR CEILING HOLSTERY					
1.3	REAR RH DOOR, FRONT LH & RH DOOR :					24
	REMOVE & REPLACE REAR RH DOOR SHELL					
	REMOVE & RE-INSTALL BACK REAR RH DOOR ITEMS (RIOT MESH, WINDOW GLASS, LOCKING MECHANISM, DOOR TRI					
	REPLACE REAR RH DOOR "POLICE" CRESR STICKER (TO BE PROVIDED BY AEMD)					
	ALIGN REAR RH DOOR					
	RE-ALIGN RH DOOR PILLAR					
	RE-ALIGN FRONT LH & RH DOOR					
	PANEL BEATING FOR REAR RH DOOR FRAME					
	PUTTY & SPRAY PAINT FOR REAR RH DOOR FRAME					
	PUTTY & SPRAY PAINT FOR REAR RH DOOR SHELL					
1.4	FRONT WINDSCREEN :					6
	REMOVE & REPLACE FRONT WINDSCREEN					
	REMOVE & REPLACE FRONT WINDSCREEN MOULDING					
	REPLACE FRONT WINDSCREEN SOLAR FIRM					
	WATER SEEPAGE TEST FOR FRONT WINDSCREEN					
1.5	BONNET COVER :					8
	REMOVE & REPLACE FRONT BONNET COVER					
	REMOVE & REPLACE BOTH SIDE BONNET HINGES (LEFT & RIGHT)					
	REPLACE BONNET COVER "POLICE" WORDING STICKER (TO BE PROVIDED BY AEMD)					

	PUTTY & SPRAY PAINT FOR BONNET COVER					
1.6	FRONT BUMPER LOWER GRILLE :					0.5
	REMOVE & REPLACE FRONT BUMPER LOWER GRILL					
1.7	REAR DOOR :					6
	PANEL BEATING FOR REAR DOOR					
	PUTTY & SPRAY PAINT FOR REAR DOOR REPAIRED AREA					
1.8	SPARE TYRE COVER :					1
	REPLACE SPRE TYRE COVER "POLICE" WORDING STICKER (TO BE PROVIDED BY AEMD)					
	PUTTY & SPRAY PAINT FOR SPARE TYRE COVER					
COSTING		TOTAL PARTS COST			\$9,560.00	
		TOTAL MAN-HOUR				86.5

Registration No. QX 383S

Vehicle Inspected By

YWK

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.