

SS. REC. BY:

REF: CS / ICS 18009488 / Sqbn2

Special Instruction:

Survivor

Sebastian

ASSIGNMENT (Office)

From (Person):

Janice Guh

of

ICS

Date/Time:

23052018 545pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHB 5952P

Insured:

Stm 4669E

at Workshop m/s

SMRT

Tel:

of

60 Woodlands Ind Park Et

Policy No:

Claim No:

DMPC1800208H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22052018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Shanti

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 5952P - NS / INC 18006569 / Sqbn2 DdA: 060418
	STM 4669E - CS / AVL08074530 / Rbg DdA: 01092008
	Final Ptg \$ 6756.45, 7 days (Red \$ 12671.29, 65%)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 5485952P

Yr Regn: 17/12/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4.

cc 1798

Colour: Maroon.

A/C: Insured / Std / NI / NA

Sp Reading: 48606

Ti/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU203577416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A. 22/5/18

D.O.I. 24/5/18

Survey held at: SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TA X / 05 / 18 / 2017

Lkr.

ECICS

RECEIVED 29 JUN 2018

SIM 4669E

Date/Time: File Pass to?

☐

Preli. Report

11/29/16 Trans

☐

Final Report

Date/Time: File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + P: \$

Phone

Other

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format: MRP-TP

Lump Sum / I.B.I: (\$ 6756.45)

450
10

460

Catherine Chong (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 23 May, 2018 5:45 PM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); assignments
Cc: Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); ECICS Claims
Subject: RE: shb5952p - Survey (ECICS Limited) - Resend Our ref DMPC1800208H
Attachments: 2097 - 5952.pdf; SHB5952P.PDF

Without Prejudice

Dear Shanti
Thank you for your email.
We will appoint LKK for the survey.

Aside to LKK
Please assist to arrange for TP PRI and our claim no DMPC1800208H.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:BTaiyalN@smrt.com.sg]
Sent: Wednesday, 23 May, 2018 4:45 PM
To: ECICS Claims
Cc: Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: RE: shb5952p - Survey (ECICS Limited) - Resend

Dear Sir/Mdm,

Kindly arrange to survey the vehicle **SHB5952P** within 48 hours according to GIA guide line, involving your insured **SFM4669E**

Insurance Company : ECICS Limited
Vehicle in Woodlands. SMRT Depot


Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5952P
Vehicle to be Exported:	No
Intended De-registration Date:	25 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8267236
Chassis No.:	JTDKB3FU203577416
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$32,289.00
Total Rebate Amount:	\$36,039.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 12:50
Date Of Accident	22/05/2018 17:50
Exact Location Of Accident	LORONG SIREH PINANG TOWARDS TANJONG KATONG COMPLEX
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5952P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	GOH KOK SIONG
NRIC No	S1150234B
Date Of Birth	04/03/1956
Occupation	OUTDOOR
Date Of Driving Pass	18/05/1974
Driving Experience	44 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	06-707
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MUHAMMAD MAHATIR BIN MOHAMED GENDER: : MALE
Passenger 2	NAME: : MASTURA BINTI AWANG GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ORCHARD NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7359999 - FAX NO: 67331934
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180522/2162

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFM4669E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LOH YOON HENG

NRIC/Passport Number

S1351132B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

GOH KOK SIONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHB5952P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?


NO

Address

Postcode

Sketch Plan Pg. 1


SKETCH PLAN



200 Sirih Pinang

A - SHB 5952P

B- SFM4669F



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Service Record

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180522/2162

Police Station Of Origin:

Orchard N.P.C

51 Killiney Road SINGAPORE 239572

Tel: 1900 7350000

1 of 4

Report No. T/20180522/2162

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2018 21:56	Vide Report No.: G/20180522/0151	Station Diary No.: 147
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: GOH KOK SIONG		Address: APT BLK 22 HAVELOCK ROAD #06-707 SINGAPORE 160022	
ID Type / ID No.: NRIC NO / S1150234B		Contact No.: Home/Office: Mobile: 96876749	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 04/03/1956	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Driver		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/05/2018 17:50	Type of Location: Car Park
Location: Along Road 1 LORONG SIREH PINANG				
ALONG LORONG SIREH PINANG				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

No.	Type	Make	Model	Color	Condition	No. of Passenger
9E	Car			Silver	Slightly Damaged	1
SHB6952R	Car			Maroon	Slightly Damaged	4

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180522/2102

2 of 4

Police Station Of Origin:

Orchard N.P.C

51 Killiney Road SINGAPORE 239572

Tel No: 1800-7359999

Report No. T/20180522/2102

CONTINUATION OF REPORT

Passenger			
Name	MASTURA BINTI AWANG	ID No.	G6642382X
Related Vehicle	SHB5952P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	GOH KOK SIONG	ID No.	S1150234B
Related Vehicle	SHB5952P (Car)	Contact No.	96876749
Hospital/Clinic	INTEMEDICAL 24 HR CLINIC	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	22/05/2018	Date Discharge	22/05/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Passenger			
Name	MUHAMMAD MAHATHIR BIN MOHAMED JAFFAR	ID No.	S8821631H
Related Vehicle	SHB5952P (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/05/2018 at about 5.50pm, I was driving straight along Lor Sireh Pinang towards Tanjong Katong Complex drop-off point to drop off my passenger. Suddenly, a silver colour BMW bearing VRN: SFM4669E hit onto the left side of my vehicle, at the front passenger door area. Immediately, I alighted from my vehicle and made a check on the damage on my vehicle and if my passengers are injured. The next moment, the driver of the said BMW then questioned me "how you drive" want tried to start a verbal dispute with me as such I called police for assistance.

The ambulance also came and the paramedic made a check on everyone that was involved in the accident. The paramedic wanted to convey my passengers but they refused and informed that they will seek their own medical treatment should they feel unwell.



**SINGAPORE
POLICE FORCE**



T/20180522/2162

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572

3 of 4

Report No. T/20180522/2162

Tel No. 1800-7339999

CONTINUATION OF REPORT

On the same day at about 8pm, I felt stiffness and soreness at my neck and shoulder area and also pain at the chest area as such I went to seek medical treatment at a private clinic and was given 5 days MC.



**SINGAPORE
POLICE FORCE**



T/20180522/2162

4 of 4

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572

Report No. T/20180522/2162

Tel No. 1800-7333333

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E/

Sgt 2 PANG KUAN HOU

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt ONG YONG HOCK

Contact No. 65476436

POLICE FORCE

SN 172

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

22/05/2018 21:56

Classification Of Case:

SMRT Accident Vehicle Repair Estimates

ECICS

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5952P
 Ref. No : TAX/05/18/2097
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH KOK SIONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 22/05/2018 05:50:00 PM
 Accident Reported Date / Time : 23/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 22/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096223
 Special Instruction to ARC, if any :
 TOWED \$50 / SFM4669E - ECICS LIMITED
 Prepared Date : 23/05/2018 12:47:56 PM



Sebastian.
 24/5/18.
 - Part by part repair
 - Question Mark Item
 Photo
 - Photo Before Paint


 24/5/18

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203577416

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 3,330.00	0.00
Total Material Charges	: 10,089.35	10,089.35
Other Charges	: 1,130.00	0.00
TOTAL	: 15,901.35	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 9.00	0.00
Prepared / Adjusted By	:	6 days
Arc / Surveyor Sign Off Date	: 23/05/2018 03:37:13 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/05/2018 03:37:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,352.00	0.00 500
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X
RESPRAY WHEEL CAP	360.00	0.00 X
TO RESPRAY FRONT PILLAR LH	180.00	0.00 100
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY DOOR HANDLE	180.00	0.00 50
TO RESPRAY VIEW MIRROR	180.00	0.00 X
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY CENTRE PILLAR LH	180.00	0.00 100
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	3,330.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	70.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,130.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5380247100			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace ✓ OT	No
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace ✓ NCC	No
5387647110			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace ✓ Defect	No
42611-47450			WHEEL, DISC FRONT	1	1,555.10	25.00	1,166.32	Replace	Replace X	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace ✓ SCR	No
5382847070			PROTECTOR, FR FENDER LH	1	90.40	25.00	67.80	Replace	Replace X	No
5385712010			RETAINER, FR WHEEL LH	3	3.10	25.00	6.97	Replace	Replace ?	No
6101447010			PILLAR, FRONT BODY, LH	1	339.40	25.00	254.55	Replace	Replace R	No
6762047800C1			PANEL ASSY, FR DOOR LH	1	725.90	25.00	544.42	Replace	Replace ✓ OT	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NCC	No
6874012120			HINGE ASSY, FRONT DOOR, LOWER LH	1	92.10	25.00	69.07	Replace	Replace ✓ BT	No
6872012151			HINGE ASSY, FRONT DOOR, UPPER LH	1	82.10	25.00	61.57	Replace	Replace ✓ BT	No
6861047040			CHECK ASSY, FRONT DOOR	1	153.50	25.00	115.12	Replace	Replace ✓ DMG	No
6786247050			WEATHERSTRIP, FRONT DOOR LH	1	223.80	25.00	167.85	Replace	Replace ✓ NCC	No
6821647010			WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	1	74.30	25.00	55.72	Replace	Replace ✓ NCC	No
6921047051A1			DOOR OUTER HANDLE FRONT, LH	1	378.90	25.00	284.17	Replace	Replace R	No
6904047100			LOCK ASSY, FRONT DOOR LH	1	544.70	10.00	490.23	Replace	Replace ✓ JM	No
8572047140			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, LH	1	768.60	10.00	691.74	Replace	Replace ?	No
6980221010			DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	230.80	25.00	173.10	Replace	Replace ?	No
8794047440			MIRROR ASSY, OUTER REAR VIEW, LH	1	1,283.90	10.00	1,155.51	Replace	Replace X	No
8174047010			LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	1	162.20	10.00	145.98	Replace	Replace X	No
8794847250			COVER, OUTER MIRROR HOLE, LH	1	63.80	25.00	47.85	Replace	Replace X	No
8794547060A1			COVER, OUTER MIRROR, LH	1	89.50	25.00	67.12	Replace	Replace X	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	25.00	432.00	Replace	Replace R	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6140447900			REINFORCE SUB-ASSY, ROCKER, OUTER LH	1	564.80	25.00	423.60	Replace	Replace ?	No
6131247040			PILLAR, CENTER BODY, OUTER LH	1	313.40	25.00	235.05	Replace	Replace R	No
6700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	25.00	932.92	Replace	Replace R	No
6789647010			WEATHERSTRIP, REAR DOOR, NO.2, LH	1	33.20	25.00	24.90	Replace	Replace ?	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace R	No
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace X	No
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace R	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace X	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓	No
TOTAL MATERIALS								10,089.43	10,089.35	
TOTAL MATERIALS(Discounted)								10,089.35	10,089.35	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5952P
 Ref. No : TAX/05/18/2097
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : GOH KOK SIONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 22/05/2018 05:50:00 PM
 Accident Reported Date / Time : 23/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 22/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096223
 Special Instruction to ARC, if any :

TOWED \$50 / SFM4669E - ECICS LIMITED
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianeang @lkkauto.com HP:90036121

Prepared Date : 23/05/2018 12:47:56 PM



Recording Camera

Radio Antenna

1st witness

2nd witness

☐
☐

Date

Date

24-5-18

1-6-18

Vehicle to Wega Date In: 24/5 Towing: Reg

Time In: 1730 Driver: Reg

Wega Job No: 050328

Vehicle sent to SMRT Date In: 1/6/18 Towing: Reg

Time In: 1425 Driver: Reg

Received by (SMRT):

E 1/2 F
KM 48606

Attached Supplementary

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU203577416



Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,352.00	900.00
Total Spray Painting Charges :	3,330.00	1,350.00
Total Material Charges :	4,711.92	4,256.45
Other Charges :	1,130.00	250.00
TOTAL :	10,523.92	6,756.45
Lump Sum Total :	0.00	0.00
No. of Repair Days :	9.00	7.00 ✓
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date :	23/05/2018 03:37:13 PM	24/05/2018 03:48:04 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/05/2018 03:37:13 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1806-0154

Invoice No :

Quotation Date : 7/6

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,352.00	900.00 ✓
Total Labour	1,352.00	900.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	200.00 ✓
TO RESPRAY RIM	180.00	0.00
RESPRAY WHEEL CAP	360.00	0.00
TO RESPRAY FRONT PILLAR LH	180.00	100.00 ✓
TO RESPRAY FRONT DOOR LH	378.00	200.00 ✓
TO RESPRAY DOOR HANDLE	180.00	50.00 ✓
TO RESPRAY VIEW MIRROR	180.00	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00 ✓
TO RESPRAY CENTRE PILLAR LH	180.00	100.00 ✓
TO RESPRAY REAR DOOR LH	378.00	200.00 ✓
TO RESPRAY REAR FENDER LH	378.00	200.00 ✓
TO REPSRAY REAR BUMPER	378.00	200.00 ✓
Total Spray Painting & Panel Beating	3,330.00	1,350.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	70.00	70.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 ✓
TO TRANSFER DOOR MECHANISM	240.00	60.00 ✓
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO REMOVE AND REFIT TYRE	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,130.00	250.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5380247100			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace	No ✓	DT
7537447140			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace	No ✓	NEC
5387647110			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace	No ✓	Deform
42611-47450			WHEEL, DISC FRONT	0	1,555.10	25.00	0.00	Replace	Not given	No X	} NN
			TYRE	0	126.74	0.00	0.00	Replace	Not given	No X	
4260247180			CAP SUB-ASSY, WHEEL	1	175.80	25.00	131.85	Replace	Replace	No ✓	SCR
5382847070			PROTECTOR, FR FENDER LH	0	90.40	25.00	0.00	Replace	Not given	No X	} NN
5385712010			RETAINER, FR WHEEL LH	3	3.10	25.00	6.98	Replace	Check	No X	
6101447010			PILLAR, FRONT BODY, LH	1	339.40	100.00	0.00	Replace	Repair	No R	
6762047800C1			PANEL ASSY, FR DOOR LH	1	725.90	25.00	544.42	Replace	Replace	No ✓	DT
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No ✓	NEC
6874012120			HINGE ASSY, FRONT DOOR, LOWER LH	1	92.10	25.00	69.07	Replace	Replace	No ✓	BT
6872012151			HINGE ASSY, FRONT DOOR, UPPER LH	1	82.10	25.00	61.57	Replace	Replace	No ✓	BT
6861047040			CHECK ASSY, FRONT DOOR	1	153.50	25.00	115.12	Replace	Replace	No ✓	DMG
6786247050			WEATHERSTRIP, FRONT DOOR LH	1	223.80	25.00	167.85	Replace	Replace	No ✓	NEC
6821647010			WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	1	74.30	25.00	55.72	Replace	Replace	No ✓	NEC
6921047051A1			DOOR OUTER HANDLE FRONT, LH	1	378.90	100.00	0.00	Replace	Repair	No R	
6904047100			LOCK ASSY, FRONT DOOR LH	1	544.70	10.00	490.23	Replace	Replace	No ✓	Jm
8572047140			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, LH	1	768.60	10.00	691.74	Replace	Replace S	No ✓	DMG
6980221010			DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	230.80	25.00	173.10	Replace	Replace S	No ✓	DMG
8794047440			MIRROR ASSY, OUTER REAR VIEW, LH	0	1,283.90	10.00	0.00	Replace	Not given	No X	} NN
8174047010			LAMP ASSY, SIDE MIRROR TURN SIGNAL, LH	0	162.20	10.00	0.00	Replace	Not given	No X	
8794847250			COVER, OUTER MIRROR HOLE, LH	0	63.80	25.00	0.00	Replace	Not given	No X	
8794547060A1			COVER, OUTER MIRROR, LH	0	89.50	25.00	0.00	Replace	Not given	No X	
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH	1	576.00	100.00	0.00	Replace	Repair	No R	
6140447900			REINFORCE SUB-ASSY, ROCKER, OUTER LH	1	564.80	25.00	423.60	Replace	Check	No X	NN

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6131247040			PILLAR, CENTER BODY, OUTER LH	1	313.40	100.00	0.00	Replace	Repair	No R
6700447210			PANEL SUB-ASSY, REAR DOOR, LH	1	1,243.90	100.00	0.00	Replace	Repair	No R
6789647010			WEATHERSTRIP, REAR DOOR, NO.2, LH	1	33.20	25.00	24.90	Replace	Check	No X NN
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	100.00	0.00	Replace	Repair	No R
4260247180			CAP SUB-ASSY, WHEEL	0	175.80	25.00	0.00	Replace	Not given	No X NN
5215947913			COVER, RR BUMPER ASSY	1	423.90	100.00	0.00	Replace	Repair	No R
5257647040			RETAINER, RR BUMPER, LH	0	111.50	25.00	0.00	Replace	Not given	No X NN
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No / NEC
861600WX80			FRONT DOOR SPEAKER ASSY, RADIO RH & LH	1	767.30	10.00	690.57	Replace	Replace S	No / CRK
TOTAL MATERIALS							4,711.97	4,256.45		
TOTAL MATERIALS(Discounted)							4,711.92	4,256.45		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
861600WX80		FRONT DOOR SPEAKER ASSY, RADIO RH & LH	1	767.30	10.00	690.57	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						690.57			

$$\begin{array}{r}
 4256.45 \checkmark \\
 + 900.00 \checkmark \\
 + 1600.00 \checkmark \\
 \hline
 6756.45 \checkmark
 \end{array}$$

Part by Part : \$ 6756.45 confirmed

19377.74

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX 105/18/2097	Date of Collection	24/5/18
Vehicle No	CHB 5952 P	Date of Request	25/5/18
Vehicle Model	70307A PRIUS 4	Number of Days to Extend	2 DAYS

REQUEST FOR SUPPLYMENT PARTS

1 day

S/N	Number photos	Part Description	Quantity	Unit Price
1	80521531	Door Fnt Motor Assy Power Window		
2		Regulator LH		# 768.60 ✓ DMG
3	8044145, 49, 50	Door Fnt Window Regulator Sub		
4		Assy LH		# 230.80 ✓ DMG
5	8070, 71, 72, 73	To Repair Rocker Panel LH		# 250.00 100
6		To Respray Rocker Panel LH		# 180.00 100
7	8046, 47, 48	Speaker Fnt Door LH		# 765.40 ✓ CR
8				

<<<Please submit photographs for damaged parts>>>

Sebastian
25/5/18

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18009488/SQBN2

Date: 02/07/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHB5952P	Insured Vehicle No :	SFM4669E
Date of Loss:	22/05/2018	Nature of Claim:	TP
		Claim No:	DMPC1800208H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5952P	Engine No:	2ZR8267236
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU203577416
Reg. Date:	19/12/2017 (Man. Year: 2017)	Odometer:	48606 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,565.74	4,256.45	9,309.29	68.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,812.00	2,500.00	3,312.00	56.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	19,377.74	6,756.45	12,621.29	65.13

INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 24/05/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 7.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB5952P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY FR,LH (DISC 25%)	Dented	933.10 F	*699.82 F
2	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.67 F
3	1		*LINER,FR FENDER LH (DISC 25%)	Deformed	194.30 F	*145.72 F
4	1		*CAP SUB-ASSY WHEEL (DISC 25%)	Scratched	175.80 F	*131.85 F
5	1		*PANEL ASSY,FR DOOR LH (DISC 25%)	Dented	725.90 F	*544.42 F
6	1		*HINGE ASSY,FRONT DOOR,LOWER LH (DISC 25%)	Bent	92.10 F	*69.07 F
7	1		*HINGE ASSY,FRONT DOOR,UPPER LH (DISC 25%)	Bent	82.10 F	*61.57 F
8	1		*CHECK ASSY,FRONT DOOR (DISC 25%)	Damaged	153.50 F	*115.12 F
9	1		*WEATHERSTRIP,FRONT DOOR LH (DISC 25%)	Necessary	223.80 F	*167.85 F
10	1		*WEATHERSTRIP,FRONT DOOR FIX WINDOW,LH (DISC 25%)	Necessary	74.30 F	*55.72 F
11	1		*DOOR FRONT WINDOW REGULATOR SUB-ASSY,LH (DISC 25%)	Damaged	230.80 F	*173.10 F
12	1		*LOCK ASSY,FRONT DOOR LH (DISC 10%)	Jammed	544.70 F	*490.23 F
13	1		*DOOR FRONT MOTOR ASSY,POWER WINDOW REGULATOR LH (DISC 10%)	Damaged	768.60 F	*691.74 F
14	1		*FRONT DOOR SPEAKER ASSY,RADIO RH & LH (DISC 10%)	Cracked	767.30 F	*690.57 F
15	1		*STICKER DECAL SMRT (DOOR)(SN)	Necessary	60.00 F	*60.00 F
16	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
17	1		*WHEEL,DISC FRONT	Not Necessary	1,555.10 F	*- F
18	1		*TYRE	Not Necessary	126.74 F	*- F
19	1		*PROTECTOR,FR FENDER LH	Not Necessary	90.40 F	*- F
20	3		*RETAINER,FR WHEEL LH	Not Necessary	9.30 F	*- F
21	1		*MIRROR ASSY,OUTER REAR VIEW,LH	Not Necessary	1,283.90 F	*- F
22	1		*LAMP ASSY,SIDE MIRROR TURN SIGNAL,LH	Not Necessary	162.20 F	*- F
23	1		*COVER,OUTER MIRROR HOLE,LH	Not Necessary	63.80 F	*- F
24	1		*COVER,OUTER MIRROR,LH	Not Necessary	89.50 F	*- F
25	1		*REINFORCE SUB-ASSY,ROCKER,OUTER LH	Not Necessary	564.80 F	*- F
26	1		*WEATHERSTRIP,REAR DOOR,NO 2,LH	Not Necessary	33.20 F	*- F
27	1		*CAP SUB-ASSY,WHEEL	Not Necessary	175.80 F	*- F
28	1		*PILLAR,FRONT BODY,LH	Repair	339.40 F	*- F
29	1		*DOOR OUTER HANDLE FRONT,LH	Repair	378.90 F	*- F
30	1		*MOULDING ASSY,BODY ROCKER PANEL,LH	Repair	576.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*PILLAR,CENTER BODY,OUTER LH	Repair	313.40 F	*- F
32	1		*PANEL SUB-ASSY,REAR DOOR,LH	Repair	1,243.90 F	*- F
33	1		*PANEL SUB-ASSY,FENDER REAR LH	Repair	824.80 F	*- F
34	1		*COVER,RR BUMPER ASSY	Repair	423.90 F	*- F
35	1		*RETAINER,RR BUMPER,LH	Not Necessary	111.50 F	*- F

F=Franchise part.

Total Parts (S\$) 13,565.74 4,256.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,352.00	900.00
2	SPRAY PAINT	New	3,330.00	1,350.00
3	TOWING CHARGE	New	70.00	70.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
6	TO DO WHEEL ALIGNMENT/TYRE BALANCING	New	120.00	60.00
7	TO TRANSFER DOOR MECHANISM	New	240.00	60.00
8	TO REMOVE AND REFIX WING MIRROR	New	120.00	-
9	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	-
10	TO REMOVE AND REFIT TYRE	New	120.00	-
11	TO REPLACE SUNDRY PARTS	New	100.00	-
12	TO WASH AND VACUUM	New	60.00	-
Gross Labour Cost (\$\$)			5,812.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >