

S-REQ BY:

REF: CS/IAS18009489 / RH622

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person): Anita Guek of Insight Adjusters Date/Time: 20/5/2018 725pm

Estimated Cost: Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 71R Insured: Public Liability

at Workshop m/s Hong Seh Tel: 631259116 • HP: 96302130

of 10 Fourth Lok Yang Rd

Policy No: Claim No: IA2018-37355 / LLY / AQ

Sum Insured: Excess:

Make of Veh: D.O.A. 20/5/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time: Person Contacted: Sam Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 71R - x
	Public Liability - x
	Submit preli report.
	Vehicle not yet start repair.

Ram

Insight Adjuster

08/04/2020/05

Form No: 24052018

Estimated Cost: SKN 71R

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Project Vehicle Tag: SKN 71R

Workshop: Hong Seh

Address: 10 Fourth Lok Yang Rd

Insured: Sam

Policy No: morning

Claims No: 157K

Sum Insured: 157K

Excess: 157K

Remarks: The veh had commenced its repair at the time of inspection.

Diagram: 

Est. Repairs: 157K

CA / REV / REP. / 24 HRS

Date: 24/05/18

Person Contacted: Sam

Vehicle: IN / OUT

Form No: SKN 71R

Year: 2010

Color: WHITE

Sp. Reading: 72402

Engine: 24MHH45C000651288

Gen. Cond: Good

Steering: in order

Brake: in order

Mod: Nil

Tyre Size: 285/352R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIP / SUMI / TOYO / YOKO or

Front: 6

Rear: 6

D.O.A: 20/05/18

Survey taken at: Hong Seh

Des. of Damage: Front

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: 24/05/18

Action / Instruction: estimate not ready yet

516 Typist

Preli. Report: ☒ Final Report: ☒

Days Of Repair: 14

Resurvey No. of Trip: 14

Add Fee: ☐ 1st trip: 15

Report Format: TP

Stamp: TP

Survey Fee: 110 x 15 = 1650

Stamp: 1704 1650

Stamp: 50

Stamp: 119

Stamp: 80

Stamp: 2069

Catherine Chong (LKK Auto)

From: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Sent: Thursday, 24 May, 2018 8:58 AM
To: Anita Quek; assignments
Cc: Liaw Liong Yang
Subject: RE: [IA2018-37355]/LLY/AQ - Insured: Johnson Pacific Pte Ltd - Re: Damage to Third Party Car (SKN 71R) at 137 Serangoon Avenue 3 on 20.05.2018

Dear Assignment Team

Please arrange surveyor to survey this vehicle today morning.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anita Quek [mailto:anitaquek@insightadjusters.com]
Sent: Wednesday, 23 May 2018 7:25 PM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>
Cc: Liaw Liong Yang <LiawLiongYang@insightadjusters.com>
Subject: [IA2018-37355]/LLY/AQ - Insured: Johnson Pacific Pte Ltd - Re: Damage to Third Party Car (SKN 71R) at 137 Serangoon Avenue 3 on 20.05.2018

Dear Mr Ang

Please be advised that we have been appointed by AXA Insurance Pte Ltd.

Best regards,

Anita Quek

E-Mail : anitaquek@insightadjusters.com

From: Anita Quek
Sent: Wednesday, 23 May 2018 7:22 PM
To: 'Bryan Ang (LKKAuto)' <bryanang@lkkauto.com>
Cc: Liaw Liong Yang <LiawLiongYang@insightadjusters.com>
Subject: [IA2018-37355]/LLY/AQ - Insured: Johnson Pacific Pte Ltd - Re: Damage to Third Party Car (SKN 71R) at 137 Serangoon Avenue 3 on 20.05.2018

Dear Mr Bryan,

We are the Loss Adjusters appointed by Liberty Insurance Pte Ltd to look into a Public Liability matter.

This incident involves damage to the Third Party's car.

Below are brief details of the incident:-

➤ Third Party's Car

- Model : Maserati
- Registration no: SKN 71R
- Remarks : Damage to Third Party Car

We require your assistance to provide us with a repair assessment and reasonable quotation on a "Without Prejudice" basis.

Kindly liaise with Mr Sam from Hong Seh Co (Pte) Ltd to make the necessary arrangement on the inspection as soon as possible.

Attached is the photographs taken during our inspection today.

Thank you for your kind assistance and we look forward to receiving the report in due course.

Please do not hesitate to contact us should you have any further enquires. Thank you.

Best regards,
Anita Quek
E-Mail : anitaquek@insightadjusters.com

Insight Adjusters and Surveyors Pte Ltd
133 Cecil Street, #14-02
Keck Seng Tower
Singapore 069535
(65) 6223 2008 • Fax : (65) 6226 2356

<http://www.insightadjusters.com>

- ASIA Regional Office for vrs adjusters
- Loss Adjuster of the Year, Asia Insurance Industry Award
- A Singapore Top 500 SME
- CESAM Average Agents, AIMU Correspondents

*CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law.

If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this message in error, please immediately notify the sender and delete the mail.
Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 14:20
Date Of Accident	20/05/2018 02:50
Exact Location Of Accident	135 SERANGOON AVE 3 CHILTERN PARK S(556114)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN71R
Insured/Policyholder	
Name Of Registered Owner	HO LAN FONG
NRIC No	S2609235C
Email Address	SALES@PETROLOG.COM.SG
Mobile Phone No	(LOCAL) +65-82003136
Alternative Phone No	OTHERS-91110071

Vehicle Particulars

Manufacturer	MASERATI
Model	GRANTURISMO S (MC SPORT LINE)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V09914/VPS/R00
Cover Note Number	

Driver

Name of Driver	WEE CHENG OH
NRIC No	S1538289I
Date Of Birth	08/08/1962
Occupation	INDOOR
Date Of Driving Pass	03/09/1983
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91110071
Fax Number	
Contact Number	
EMail Address	SALES@PETROLOG.COM.SG

Address	71 WESTWOOD AVENUE
Postcode	648393
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TYPE OF ACCIDENT REFER STATEMENT AND SKETCH. NO POLICE REPORT FILED BUT CASE CARD WAS GIVEN TO DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	ROADWORKS (REFER PHOTOS)
Vehicle Category	NA/UNKNOWN
Name of Driver	ALAN HO (PROJECT MANAGER)
NRIC/Passport Number	
Contact Number	62681177 / 81829440
Address	45 DEFU LANE 9
Postcode	539285
Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I drove inside 135 Serangoon Ave 3 Chiltern park. I was driving straight then suddenly I heard a loud thud. I tried to open the door but unable. I wind down the window and look out and saw the right side of my car was in a man hole construction. Please see attached photos. I then climbed out from my car window.

I called the police and told them what happened to come to see the incident scene. I was then given a case card.

The contractor that was doing the road works, did not put any signboard or safety board/barrier. Hence the plank gave way, and put me in a dangerous position.

I am filing this report for insurance claims for my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Common Statement

	
SINGAPORE POLICE FORCE	
CASE CARD	
Report Number:	F/20180510/0049
Classification:	NOD
Actions Taken	
<input type="checkbox"/> For further investigation	
<input type="checkbox"/> Added to the Majorcase's Complaint	
<input type="checkbox"/> Added to seek Community Mediation	
Others:	
Officer Name:	Contact Number:
Sgt S. S. S. S.	6430 999

Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Alan Hon
韓東成
Project Manager
8182 9440

JOHNSON PACIFIC PTE LTD

(A wholly owned subsidiary of Ipimuda Berhad)

45 Defu Lane 9

Singapore 539285

Tel : (65) 6268 1177

Fax : (65) 6264 1331

Email: projects@johnson.com.sg

Website: <http://www.ipmuda.com.my>



ISO 9001:2008 Cert No. 07/008

Accident Photo

PFS

THE MANAGEMENT CORPORATION STRATA TITLE PLANS 2112

c/o PROPERTY FACILITY SERVICES PTE LTD

Leader in International Property & Facility Management Services

51 Cuppage Road #04-08 to #04-11 Singapore 229469

Tel: 65 6221 1313 Fax: 65 6227 3005 Website: www.pfspl.com.sg

Ch

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9235C
Vehicle Details	
Vehicle No.:	SKN71R
Vehicle to be Exported:	No
Intended De-registration Date:	25 May 2018
Vehicle Make:	MASERATI
Vehicle Model:	GRANTURISMO S (MC SPORT LINE)
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	M145156350
Chassis No.:	ZAMHH45C000051288
Maximum Power Output:	323.0 kW (433 bhp)
Open Market Value:	\$120,088.00
Original Registration Date:	10 Oct 2010
First Registration Date:	10 Oct 2010
Transfer Count:	5
Actual ARF Paid:	\$120,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2020
PARF Rebate Amount:	\$72,052.00
Intended COE Rebate Details	
COE Expiry Date:	09 Oct 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$42,901.00
COE Rebate Amount:	\$10,173.00
Total Rebate Amount:	\$82,225.00

The information contained herein is correct as at 25 May 2018

OK

157,000
 82,225

 74,775

 74K



Ms Ho Lan Fong

71 Westwood Avenue

Singapore 648393

Danny Wee sales@petrolog.com.sg

31 May 2018

Mr Sir / Madam

Masarati Granturismo S (4.7) F1 MC Line, Vehicle Reg.No: SKN71R, Chassis No.ZAMHH45C000051288.

are pleased to submit quotation for the repair of the above-mentioned vehicle:

<u>Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Remove, install & renew :- Front bumper, front grill, both headlamp washer system piping, front bumper air conveyor, both headlamp, fender grills, indicator lamp & engine compartment cover air con condenser & radiator, Refill Gas & Coolant.		\$ 5,950.00 5,000
2 Renew right headlamp support bracket include cut & weld		\$ 1,900.00 1,000
3 Remove & renew Rh front fender include cut & weld include remove & reinstall Rh side skirt to facilitate repair.		\$ 3,800.00 2,500
4 Remove & Renew Rh Door include Transfer Internal Accessory.		\$ 1,500.00 3,800.00
5 Remove & renew Front Right Suspension System		? \$ 2,000.00 2,500.00
6 Remove & renew Rear Right Suspension System		? \$ 2,400.00 2,500.00
7 Reset All Wheel Alignment		\$ 900.00 2,200.00
8 Reset all system with computer tester and reset headlight aiming.		\$ 1,000.00 1,200.00
9 Remove & Renew Rh Exhaust System & Center Box.		\$ 750.00 1,200.00
9 Remove, Renew & Alignment Bonnet & Lining.		\$ 950.00 1,200.00
10 Respray premier & paint: Front front bumper, Rh Door, Rh front fender, front bonnet and Bull bar.		\$ 5,800.00 6,400.00

<u>Parts</u>	<u>Qty</u>	<u>Total Price (\$\$)</u>
1 Air-Con Condenser	1	\$ 1,500.00
2 Bracket	1	\$ 50.00
3 Nut	1	\$ 3.20
4 Washer	1	\$ 4.00
5 Bracket	1	\$ 50.00
6 Nut	1	\$ 3.20
7 Washer	1	\$ 4.00

8 Pipe from Condenser to Shield	1	\$	452.50	2
9 Pipe fr compresor to Condense	1	\$	482.90	2
10 OR Gasket fr Pipe (Con to Eva)	2	\$	20.00	} new
11 OR Gasket fr Pipe (Con to Eva)	2	\$	20.00	
12 OR Gasket fr pip (Comp to Con)	1	\$	17.20	
13 OR Gasket fr pip (Comp to Con)	1	\$	6.50	
14 AC Drier	1	\$	380.00	new
15 Dehydrating Filter Kit	1	\$	318.00	new
16 Front Aerodynamic Shield	1	\$	320.00	new
17 Clip	13	\$	234.00	new
18 Screw	16	\$	264.00	new
19 Cpl RH Front Fender	1	\$	8,500.00	BT
20 R.H Connection	1	\$	250.00	BT
21 R.H Headlight Support Bracket	1	\$	600.00	BT
22 Emblem Sport GT	1	\$	280.00	new
23 Oval Emblem, Mgs (Frt Bumper)	1	\$	62.00	new
24 Pininfarina Inscription	1	\$	28.00	new
25 R.H. Air Intake - M145	3	\$	169.20	new
26 LH & RH Side Light	1	\$	30.55	new
27 Water Radiator	1	\$	850.00	BT
28 Screw	1	\$	5.00	new
29 Washer	2	\$	4.00	new
30 Rubber Pad	2	\$	40.40	new
31 Air Conveyor	1	\$	550.00	new
32 Screw	5	\$	10.00	new
33 Washer	5	\$	5.50	new
34 Split Washer D.5.15-15*1.2	5	\$	11.00	new
35 Screw	2	\$	4.40	new
36 Washer	2	\$	4.00	new
37 Bushing	4	\$	40.80	new
38 Rubber Bushing	4	\$	35.20	new
39 Fan Resistor(New)	1	\$	180.00	?
40 Front Bumper Undertray Screw	7	\$	14.00	new
41 LH Lower Radiator Assembly	1	\$	82.00	new
42 Door Striker	1	\$	18.50	Xmm
43 Door Striker Screw	2	\$	11.00	Xmm
44 Front RH Susp Kit M139/M145	1	\$	2,500.00	?
45 RH Air Flow Flap	1	\$	58.00	M13
46 Screw	2	\$	196.00	new
47 NUT	4	\$	40.00	new
48 Washer	4	\$	32.00	new
49 Bolt	2	\$	516.00	?
50 Frt Shock Absorber Ball Joint	1	\$	260.00	?
51 Frnt Rim 20" Neptune Black	1	\$	2,500.00	new
52 Rear Rim 20" Neptune GlossBlack	1	\$	2,800.00	new
53 Tyre Valve	4	\$	70.40	new
54 Complete RH Door	1	\$	9,800.00	Repair

Part Number	Description	Quantity	Unit	Price	Notes
55	RH Door Water Shield	1	\$	120.00	
56	RH Door Wing Mirror Gasket	1	\$	280.00	
57	Rh Inner Door Scraper Gasket	1	\$	382.00	
58	RH Outer Glass Scraper	1	\$	845.00	
59	Under Door Light	1	\$	60.00	
60	Pin	4	\$	4.00	Xnn
61	Block	2	\$	2.40	Xnn
62	R.H Front Wheelhouse	1	\$	150.00	DE
63	Rh Wheel Shield	1	\$	182.00	DE
64	L.H Front Deflector	1	\$	65.00	DE Xnn
65	RH Front Deflector	1	\$	120.00	DE
66	Screw	11	\$	60.50	nn
67	Washer	11	\$	22.00	nn
68	RH Rear Silencer GTS Black	1	\$	3,600.00	PH
69	Central Muffler	1	\$	1,950.00	Xnn
70	Front Cross Member	1	\$	3,800.00	Raw cross member
71	RH Front Headlight	1	\$	4,500.00	CM
72	LH Front Headlight	1	\$	4,500.00	CM
73	Pipes For Headlight Washer Sys	1	\$	680.00	CM
74	R.H Headlight Washer Telescopi	1	\$	460.00	CM
75	Bracket with Sheath	8	\$	20.00	nn
76	Front Bumper (GT Sport)	1	\$	6,800.00	Turn
77	COMPLETE CALENDER Black	1	\$	1,300.00	Fla
78	Undertray Clip	14	\$	42.00	nn
79	Air Conveyor	1	\$	1,050.00	DE
80	Gasket	1	\$	148.00	nn
81	RH Front Grill	1	\$	300.00	nn
82	Lh Front Grill	1	\$	300.00	Xnn
83	LH Front Frame	1	\$	80.00	Xnn
84	RH Front Frame	1	\$	80.00	Xnn
85	Front Spoiler	1	\$	665.00	CM
86	Screw	14	\$	44.80	nn
87	Screw	6	\$	99.00	nn
88	Washer	14	\$	25.20	nn
89	Bracket	14	\$	16.80	nn
90	Front P Sensor Support Kit	1	\$	720.00	CM
91	Cable for Front Parking Sensor	1	\$	202.00	CM
92	Parking Sensor Gasket	4	\$	140.00	nn
93	FRONT PARKING SENSOR	2	\$	960.00	nn
94	Plate	8	\$	32.00	nn
95	R.H Door Upper Gasket	1	\$	535.00	Xnn
96	Door Lower Gasket	1	\$	198.00	Xnn
97	RH Ball Tie Rod	1	\$	160.00	Xnn
98	LH Ball Tie Rod	1	\$	160.00	Xnn
99	Shock Absorber Spring Top pad	2	\$	105.60	Xnn
100	Front Shock Absorber	2	\$	2,400.00	Xnn
101	Absorber Coil Spring Padding	2	\$	96.00	Xnn

Quotation

- 2 Frt Shock Absorber Hyperblock
- 3 Washer
- 4 Screw
- 5 Nut
- 6 Shock Absorber Pad - M145
- 7 Rear Shock Absorber
- 8 Ball Joint 3200Gt
- 9 Absorber Coil Spring Padding
- 10 Rear Shock Absorber Spring Top pad
- 11 Rear Shock Absorber Hyperblock
- 12 Shock Absorber Pad - M145
- 13 Rh Headlight Washer Cover
- 14 Front Hood Bonnet
- 15 Front Hood Bonnet Lining
- 16 Fixing Button
- 17 Small Block
- 18 RH Kickplate
- 19 RH Side Skirt (Primer)
- 20 Radiator Vent Tube
- 21 Clamp - Hose Clip (10-16)
- 22 Water Hose Clamp
- 23 Screw Collar
- 24 Delivery Pipe From Engine
- 25 Return Pipe From Radiator
- 26 Front Reg Plate
- 27 Wheel Bearing With ABS Sensor
- 28 Driver Shaft Lock Nut.
- 29 Engine Coolant

2	\$	216.00	?
2	\$	12.00	✓
2	\$	32.00	✓
2	\$	4.00	✓
2	\$	171.60	?
2	\$	2,256.00	?
2	\$	640.00	?
2	\$	96.00	?
2	\$	105.60	?
2	\$	216.00	?
2	\$	171.60	?
1	\$	185.65	?
1	\$	11,145.85	BT -
1	\$	458.00	X VM
26	\$	98.80	✓
2	\$	2.30	✓
1	\$	780.00	✓
1	\$	680.00	DE -
1	\$	42.00	✓
1	\$	2.20	✓
2	\$	3.60	✓
4	\$	11.20	✓
1	\$	100.00	✓
1	\$	105.00	✓
1	\$	30.00	CRA -
2	\$	3,304.00	?
1	\$	38.00	?
12	\$	240.00	✓

Rasul

hp 90010068

14 days

24/05/18 @ 1035

Rasul & part

TOTAL:

\$ 94,297.15 \$ 3

Total Labour : \$ 3

Total Parts : \$ 9

: \$ 12

Plus 7% GST : \$

Grand Total : \$ 13



Ms Ho Lan Fong

71 Westwood Avenue
Singapore 648393

Danny Wee sales@petrolog.com.sg

31 May 2018

Dear Sir / Madam

RE: Masarati Granturismo S (4.7) F1 MC Line, Vehicle Reg.No: SKN71R , Chassis No.ZAMHH45C000051288.

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) <u>Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Remove, install & renew :- Front bumper, front grill, both headlamp washer system piping, front bumper air conveyor, both headlamp, fender grills, indicator lamp & engine compartment cover air con condenser & radiator , Refill Gas & Coolant.		\$ 5,950.00 5000
2 Renew right headlamp support bracket include cut & weld		\$ 1,900.00
3 Remove & renew Rh front fender include cut & weld include remove & reinstall Rh side skirt to facilitate repair.		\$ 3,000.00
4 Remove & Renew Rh Door Include Transfer Internal Accessory .		\$ 3,000.00
5 Remove & renew Front Right Suspension System		\$ 2,500.00
6 Remove & renew Rear Right Suspension System		\$ 2,500.00
7 Reset All Wheel Alignment		\$ 1,200.00
8 Reset all system with computer tester and reset headlight aiming.		\$ 1,200.00
9 Remove & Renew Rh Exhaust System & Center Box.		\$ 1,200.00
9 Remove, Renew & Alignment Bonnet & Lining.		\$ 1,200.00
10 Respray premier & paint: Front front bumper, Rh Door, Rh front fender, front bonnet and Bull bar.		\$ 6,400.00

B) <u>Parts</u>	<u>Qty</u>	<u>Total Price (\$\$)</u>
1 Air-Con Condenser	1	\$ 1,500.00
2 Bracket	1	\$ 50.00
3 Nut	1	\$ 3.20
4 Washer	1	\$ 4.00
5 Bracket	1	\$ 50.00
6 Nut	1	\$ 3.20
7 Washer	1	\$ 4.00

8 Pipe from Condenser to Shield	1	\$	452.50
9 Pipe from compresor to Condense	1	\$	482.90
10 OR Gasket for Pipe (Con to Eva)	2	\$	20.00
11 OR Gasket for Pipe (Con to Eva)	2	\$	20.00
12 OR Gasket for pip (Comp to Con)	1	\$	17.20
13 OR Gasket for pip (Comp to Con)	1	\$	6.50
14 AC Drier	1	\$	380.00
15 Dehydrating Filter Kit	1	\$	318.00
16 Front Aerodynamic Shield	1	\$	320.00
17 Clip	13	\$	234.00
18 Screw	16	\$	264.00
19 Cpl RH Front Fender	1	\$	8,500.00
20 R.H Connection	1	\$	250.00
21 R.H Headlight Support Bracket	1	\$	600.00
22 Emblem Sport GT	1	\$	280.00
23 Oval Emblem, Mgs (Frt Bumper)	1	\$	62.00
24 Pininfarina Inscription	1	\$	28.00
25 R.H. Air Intake - M145	3	\$	169.20
26 LH & RH Side Light	1	\$	30.55
27 Water Radiator	1	\$	850.00
28 Screw	1	\$	5.00
29 Washer	2	\$	4.00
30 Rubber Pad	2	\$	40.40
31 Air Conveyor	1	\$	550.00
32 Screw	5	\$	10.00
33 Washer	5	\$	5.50
34 Split Washer D.5.15-15*1.2	5	\$	11.00
35 Screw	2	\$	4.40
36 Washer	2	\$	4.00
37 Bushing	4	\$	40.80
38 Rubber Bushing	4	\$	35.20
39 Fan Resistor(New)	1	\$	180.00
40 Front Bumper Undertray Screw	7	\$	14.00
41 LH Lower Radiator Assembly	1	\$	82.00
42 Door Striker	1	\$	18.50
43 Door Striker Screw	2	\$	11.00
44 Front RH Susp Kit M139/M145	1	\$	2,500.00
45 RH Air Flow Flap	1	\$	58.00
46 Screw	2	\$	196.00
47 NUT	4	\$	40.00
48 Washer	4	\$	32.00
49 Bolt	2	\$	516.00
50 Frt Shock Absorber Ball Joint	1	\$	260.00
51 Frnt Rim 20" Neptune Black	1	\$	2,500.00
52 Rear Rim 20" Neptune GlossBlack	1	\$	2,800.00
53 Tyre Valve	4	\$	70.40
54 Complete RH Door	1	\$	9,800.00

55 RH Door Water Shield	1	\$	120.00
56 RH Door Wing Mirror Gasket	1	\$	280.00
57 Rh Inner Door Scrapper Gasket	1	\$	382.00
58 RH Outer Glass Scraper	1	\$	845.00
59 Under Door Light	1	\$	60.00
60 Pin	4	\$	4.00
61 Block	2	\$	2.40
62 R.H Front Wheelhouse	1	\$	150.00
63 Rh Wheel Shield	1	\$	182.00
64 L.H Front Deflector	1	\$	65.00
65 RH Front Deflector	1	\$	120.00
66 Screw	11	\$	60.50
67 Washer	11	\$	22.00
68 RH Rear Silencer GTS Black	1	\$	3,600.00
69 Central Muffler	1	\$	1,950.00
70 Front Cross Member	1	\$	3,800.00
71 RH Front Headlight	1	\$	4,500.00
72 LH Front Headlight	1	\$	4,500.00
73 Pipes For Headlight Washer Sys	1	\$	680.00
74 R.H Headlight Washer Telescopi	1	\$	460.00
75 Bracket with Sheath	8	\$	20.00
76 Front Bumper (GT Sport)	1	\$	6,800.00
77 COMPLETE CALENDER Black	1	\$	1,300.00
78 Undertray Clip	14	\$	42.00
79 Air Conveyor	1	\$	1,050.00
80 Gasket	1	\$	148.00
81 RH Front Grill	1	\$	300.00
82 Lh Front Grill	1	\$	300.00
83 LH Front Frame	1	\$	80.00
84 RH Front Frame	1	\$	80.00
85 Front Spoiler	1	\$	665.00
86 Screw	14	\$	44.80
87 Screw	6	\$	99.00
88 Washer	14	\$	25.20
89 Bracket	14	\$	16.80
90 Front P Sensor Support Kit	1	\$	720.00
91 Cable for Front Parking Sensor	1	\$	202.00
92 Parking Sensor Gasket	4	\$	140.00
93 FRONT PARKING SENSOR	2	\$	960.00
94 Plate	8	\$	32.00
95 R.H Door Upper Gasket	1	\$	535.00
96 Door Lower Gasket	1	\$	198.00
97 RH Ball Tie Rod	1	\$	160.00
98 LH Ball Tie Rod	1	\$	160.00
99 Shock Absorber Spring Top pad	2	\$	105.60
100 Front Shock Absorber	2	\$	2,400.00
101 Absorber Coil Spring Padding	2	\$	96.00

102 Frt Shock Absorber Hyperblock	2	\$	216.00
103 Washer	2	\$	12.00
104 Screw	2	\$	32.00
105 Nut	2	\$	4.00
106 Shock Absorber Pad - M145	2	\$	171.60
107 Rear Shock Absorber	2	\$	2,256.00
108 Ball Joint 3200Gt	2	\$	640.00
109 Absorber Coil Spring Padding	2	\$	96.00
110 Rear Shock Absorber Spring Top pad	2	\$	105.60
111 Rear Shock Absorber Hyperblock	2	\$	216.00
112 Shock Absorber Pad - M145	2	\$	171.60
113 Rh Headlight Washer Cover	1	\$	185.65
114 Front Hood Bonnet	1	\$	11,145.85
115 Front Hood Bonnet Lining	1	\$	458.00
116 Fixing Button	26	\$	98.80
117 Small Block	2	\$	2.30
118 RH Kickplate	1	\$	780.00
119 RH Side Skirt (Primer)	1	\$	680.00
120 Radiator Vent Tube	1	\$	42.00
121 Clamp - Hose Clip (10-16)	1	\$	2.20
122 Water Hose Clamp	2	\$	3.60
123 Screw Collar	4	\$	11.20
124 Delivery Pipe From Engine	1	\$	100.00
125 Return Pipe From Radiator	1	\$	105.00
126 Front Reg Plate	1	\$	30.00
127 Wheel Bearing With ABS Sensor	2	\$	3,304.00
128 Driver Shaft Lock Nut.	1	\$	38.00
129 Engine Coolant	12	\$	240.00

TOTAL:

	\$	94,297.15	\$	30,050.00
Total Labour	:	\$	30,050.00	
Total Parts	:	\$	94,297.15	
	:	\$	124,347.15	
Plus 7% GST	:	\$	8,704.30	
Grand Total	:	\$	133,051.45	

Should this repair job require any additional parts, we will inform you and bill you accordingly.

Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation.

Workshop Department

Signature & Company stamp




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INSIGHT ADJUSTERS AND SURVEYORS PL		Ref : CS/IAS18009489/R1tbe2		
133 CECIL STREET #14-02 KECK SENG TOWER SINGAPORE 069535		Date : 06-06-2018		
		Code : IAS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKN 71R	
Policy No.		Coverage (\$)	0.00	
Claim No.	IA2018-37355/LLY/AQ	Excess (\$)	0.00	
Assign From	ANITA QUEK	Assign Date	23/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	MASERATI GRANTURISMO	c.c	4691	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	ZAMHH45C000051288	Colour	WHITE	
Odometer	72402	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/35Z R18	PIRELLI	6 mm	
L/H Front Tyre	285/35Z R18	PIRELLI	6 mm	
R/H Rear Tyre	285/35Z R18	PIRELLI	6 mm	
L/H Rear Tyre	285/35Z R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/05/2018	Inspection Date	24/05/2018	
Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 71R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	AIR-CON CONDENSER	BENT	1,500.00	1,500.00
1	BRACKET	NECESSARY	50.00	50.00
1	NUT	NECESSARY	3.20	3.20
1	WASHER	NECESSARY	4.00	4.00
1	BRACKET	NECESSARY	50.00	50.00
1	NUT	NECESSARY	3.20	3.20
1	WASHER	NECESSARY	4.00	4.00
1	PIPE FRON CONDENSER TO SHIELD	* CHECK	452.50	-
1	PIPE FR COMPRESOR TO CONDENSE	* CHECK	482.90	-
2	OR GASKET FR PIPE (CON TO EVA)	NECESSARY	20.00	20.00
2	OR GASKET FR PIPE (CON TO EVA)	NECESSARY	20.00	20.00
1	OR GASKET FR PIP (COMP TO CON)	NECESSARY	17.20	17.20
1	OR GASKET FR PIP (COMP TO CON)	NECESSARY	6.50	6.50
1	AC DRIER	NECESSARY	380.00	380.00
1	DEHYDRATING FILTER KIT	NECESSARY	318.00	318.00
1	FRONT AERODYNAMIC SHIELD	MISSING	320.00	320.00
13	CLIP	NECESSARY	234.00	234.00
16	SCREW	NECESSARY	264.00	264.00
1	CPL RH FRONT FENDER	BENT	8,500.00	8,500.00
1	R.H CONNECTION	BENT	250.00	250.00
1	R.H HEADLIGHT SUPPORT BRACKET	BENT	600.00	600.00
1	EMBLEM SPORT GT	NECESSARY	280.00	280.00
1	OVAL EMBLEM, MGS (FRT BUMPER)	NECESSARY	62.00	62.00
1	PININFARINA INSCRIPTION	NECESSARY	28.00	28.00
3	R.H. AIR INTAKE - M145	NECESSARY	169.20	169.20
1	LH & RH SIDE LIGHT	NECESSARY	30.55	30.55
1	WATER RADIATOR	BENT	850.00	850.00
1	SCREW	NECESSARY	5.00	5.00
2	WASHER	NECESSARY	4.00	4.00
2	RUBBER PAD	NECESSARY	40.40	40.40
1	AIR CONVEYOR	CRACKED	550.00	550.00

Report Ref No. CS/IAS18009489/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	SCREW	NECESSARY	10.00	10.00
5	WASHER	NECESSARY	5.50	5.50
5	SPLIT WASHER D.5, 15-15*1.2	NECESSARY	11.00	11.00
2	SCREW	NECESSARY	4.40	4.40
2	WASHER	NECESSARY	4.00	4.00
4	BUSHING	NECESSARY	40.80	40.80
4	RUBBER BUSHING	NECESSARY	35.20	35.20
1	FAN RESISTOR (NEW)	* CHECK	180.00	-
7	FRONT BUMPER UNDERTRAY SCREW	NECESSARY	14.00	14.00
1	LH LOWER RADIATOR ASSEMBLY	NECESSARY	82.00	82.00
1	DOOR STRIKER	NOT NECESSARY	18.50	-
2	DOOR STRIKER SCREW	NOT NECESSARY	11.00	-
1	FRONT RH SUSP KIT M139/M145	* CHECK	2,500.00	-
1	RH AIR FLOW FLAP	MISSING	58.00	58.00
2	SCREW	NECESSARY	196.00	196.00
4	NUT	NECESSARY	40.00	40.00
4	WASHER	NECESSARY	32.00	32.00
2	BOLT	* CHECK	516.00	-
1	FRT SHOCK ABSORBER BALL JOINT	* CHECK	260.00	-
1	FRNT RIM 20" NEPTUNE BLACK	SCRATCHED	2,500.00	2,500.00
1	REAR RIM 20" NEPTUNE GLOSSBLCK	SCRATCHED	2,800.00	2,800.00
4	TYRE VALVE	NECESSARY	70.40	70.40
1	COMPLETE RH DOOR	TO REPAIR SEE LABOUR	9,800.00	-
1	RH DOOR WATER SHIELD	* CHECK	120.00	-
1	RH DOOR WING MIRROR GASKET	* CHECK	280.00	-
1	RH INNER DOOR SCRAPER GASKET	* CHECK	382.00	-
1	RH OUTER GLASS SCRAPER	* CHECK	845.00	-
1	UNDER DOOR LIGHT	* CHECK	60.00	-
4	PIN	NOT NECESSARY	4.00	-
2	BLOCK	NOT NECESSARY	2.40	-
1	R.H FRONT WHEELHOUSE	DEFORMED	150.00	150.00
1	RH WHEEL SHIELD	DEFORMED	182.00	182.00

Report Ref No. CS/IAS18009489/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	L.H FRONT DEFLECTOR	NOT NECESSARY	65.00	-
1	RH FRONT DEFLECTOR	DEFORMED	120.00	120.00
11	SCREW	NECESSARY	60.50	60.50
11	WASHER	NECESSARY	22.00	22.00
1	RH REAR SILENCER GTS BLACK	BENT	3,600.00	3,600.00
1	CENTRAL MUFFLER	NOT NECESSARY	1,950.00	-
1	FRONT CROSS MEMBER	* CHECK	3,800.00	-
1	RH FRONT HEADLIGHT	CRACKED	4,500.00	4,500.00
1	LH FRONT HEADLIGHT	* CHECK	4,500.00	-
1	PIPES FOR HEADLIGHT WASHER SYS	CUT	680.00	680.00
1	R.H HEADLIGHT WASHER TELESCOPI	BROKEN	460.00	460.00
8	BRACKET WITH SHEATH	NECESSARY	20.00	20.00
1	FRONT BUMPER (GT SPORT)	TORN	6,800.00	6,800.00
1	COMPLETE CALENDER BLACK	BROKEN	1,300.00	1,300.00
14	UNDERTRAY CLIP	NECESSARY	42.00	42.00
1	AIR CONVEYOR	DEFORMED	1,050.00	1,050.00
1	GASKET	NECESSARY	148.00	148.00
1	RH FRONT GRILL	MISSING	300.00	300.00
1	LH FRONT GRILL	NOT NECESSARY	300.00	-
1	LH FRONT FRAME	NOT NECESSARY	80.00	-
1	RH FRONT FRAME	* CHECK	80.00	-
1	FRONT SPOILER	CRACKED	665.00	665.00
14	SCREW	NECESSARY	44.80	44.80
6	SCREW	NECESSARY	99.00	99.00
14	WASHER	NECESSARY	25.20	25.20
14	BRACKET	NECESSARY	16.80	16.80
1	FRONT P SENSOR SUPPORT KIT	CRACKED	720.00	720.00
1	CABLE FOR FRONT PARKING SENSOR	CUT	202.00	202.00
4	PARKING SENSOR GASKET	NECESSARY	140.00	140.00
2	FRONT PARKING SENSOR	NECESSARY	960.00	960.00
8	PLATE	NECESSARY	32.00	32.00
1	R.H DOOR UPPER GASKET	NOT NECESSARY	535.00	-
1	DOOR LOWER GASKET	NOT NECESSARY	198.00	-

Report Ref No. CS/IAS18009489/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH BALL TIE ROD	* CHECK	160.00	-
1	LH BALL TIE ROD	* CHECK	160.00	-
2	SHOCK ABSORBER SPRING TOP PAD	* CHECK	105.60	-
2	FRONT SHOCK ABSORBER	* CHECK	2,400.00	-
2	ABSORBER COIL SPRING PADDING	* CHECK	96.00	-
2	FRT SHOCK ABSORBER HYPERBLOCK	* CHECK	216.00	-
2	WASHER	NECESSARY	12.00	12.00
2	SCREW	NECESSARY	32.00	32.00
2	NUT	NECESSARY	4.00	4.00
2	SHOCK ABSORBER PAD - M145	* CHECK	171.60	-
2	REAR SHOCK ABSORBER	* CHECK	2,256.00	-
2	BALL JOINT 3200GT	* CHECK	640.00	-
2	ABSORBER COIL SPRING PADDING	* CHECK	96.00	-
2	REAR SHOCK ABSORBER SPRING TOP PAD	* CHECK	105.60	-
2	REAR SHOCK ABSORBER HYPERBLOCK	* CHECK	216.00	-
2	SHOCK ABSORBER PAD - M145	* CHECK	171.60	-
1	RH HEADLIGHT WASHER COVER	* CHECK	185.65	-
1	FRONT HOOD BONNET	BENT	11,145.85	11,145.85
1	FRONT HOOD BONNET LINING	NOT NECESSARY	458.00	-
26	FIXING BUTTON	NECESSARY	98.80	98.80
2	SMALL BLOCK	NECESSARY	2.30	2.30
1	RH KICKPLATE	NECESSARY	780.00	780.00
1	RH SIDE SKIRT (PRIMER)	DEFORMED	680.00	680.00
1	RADIATOR VENT TUBE	NECESSARY	42.00	42.00
1	CLAMP - HOSE CLIP (10-16)	NECESSARY	2.20	2.20
2	WATER HOSE CLAMP	NECESSARY	3.60	3.60
4	SCREW COLLAR	NECESSARY	11.20	11.20
1	DELIVERY PIPE FROM ENGINE	NECESSARY	100.00	100.00
1	RETURN PIPE FROM RADIATOR	NECESSARY	105.00	105.00
1	FRONT REG PLATE	CRACKED	30.00	30.00
2	WHEEL BEARING WITH ABS SENSOR	* CHECK	3,304.00	-
1	DRIVER SHAFT LOCK NUT	* CHECK	38.00	-

Report Ref No. CS/IAS18009489/R1tbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
12	ENGINE COOLANT	NECESSARY	240.00	240.00
			94,297.15	56,094.80
	LABOUR			
	REMOVE, INSTALL & RENEW :- FRONT BUMPER, FRONT GRILL, BOTH HEADLAMP WASHER SYSTEM PIPING, FRONT BUMPER AIR CONVEYOR, BOTH HEADLAMP, FENDER GRILLS, INDICATOR LAMP & ENGINE COMPARTMENT COVER AIR CON CONDENSER & RADIATOR, REFILL GAS & COOLANT. INCLUSIVE OF THE REPAIR OF COMPLETE RH DOOR.		5,950.00	5,000.00
	RENEW RIGHT HEADLAMP SUPPORT BRACKET INCLUDE CUT & WELD.		1,900.00	1,000.00
	REMOVE & RENEW RH FRONT FENDER INCLUDE CUT & WELD INCLUDE REMOVE & REINSTALL RH SIDE SKIRT TO FACILITATE REPAIR.		3,000.00	2,500.00
	REMOVE & RENEW RH DOOR INCLUDE TRANSFER INTERNAL ACCESSORY.		3,000.00	1,500.00
	REMOVE & RENEW FRONT RIGHT SUSPENSION SYSTEM.	* CHECK	2,500.00	-
	REMOVE & RENEW REAR RIGHT SUSPENSION SYSTEM.	* CHECK	2,500.00	-
	RESET ALL WHEEL ALIGNMENT.		1,200.00	900.00
	RESET ALL SYSTEM WITH COMPUTER TESTER AND RESET HEADLIGHT AIMING.		1,200.00	1,000.00
	REMOVE & RENEW RH EXHAUST SYSTEM & CENTER BOX.		1,200.00	750.00
	REMOVE, RENEW & ALIGNMENT BONNET & LINING.		1,200.00	950.00
	RESPRAY PREMIER & PAINT: FRONT BUMPER, RH DOOR, RH FRONT FENDER, FRONT BONNET AND BULL BAR.		6,400.00	5,800.00
			30,050.00	19,400.00
GRAND TOTAL			124,347.15	75,494.80
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$29,780.45 NETT)				75,494.80

Report Ref No. CS/IAS18009489/R1tbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.