

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019383
Kwok Sai Kual

Page 1 of 1
Your ref. TP-FBE 718M AXA
Job No. 69514
Our ref. 18.05.37
Payment
Date 23/5/2018

Attn

Vehicle No SKK 2188R
Vehicle Model : Infiniti Q50
Accident on ... 20/5/2018

Not at work
Resurvey by paint
2 days

| Quantity | Unit | Description | Unit price | Disc. pct. | Amount |
|------------------|------|--|------------|-----------------|------------|
| Supply of Parts. | | | | | |
| 1.00 | Pc | Front sport rim LH | 1,799.20 | 10.00 <i>OK</i> | 1,619.28 ✓ |
| 1.00 | Pc | Front headamp LH | 2,728.20 | 10.00 <i>OK</i> | 2,455.38 ✓ |
| Labour & Misc. | | | | | |
| 1.00 | | To check wheel alignment (computerised) | 60.00 | | 60.00 ✓ |
| 1.00 | | To renew sport rim + wheel balancing | 20.00 | | 20.00 ✓ |
| 1.00 | | To knock dent on front fender LH and renew parts | 280.00 | <i>2201</i> | 280.00 |
| 1.00 | | To spray paint (Pearl white) | 300.00 | <i>2301</i> | 300.00 |

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$

34.66

331.43

5,066.09

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理，除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."