

VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575656. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	OD/062018/3561
Policy No:	B27247197SMP	Date of Loss:	19/05/2018
Vehicle Reg. No.:	SBU575Z	Driveable?	
Driver Age/Info:	72 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEONG SIEW LOONG	Contact No:	+6596329282
Driver:	LEONG SIEW LOONG		
Make/Model:	BMW 520i, 2.0 (A)	Vehicle Reg. Date:	23/12/2011
Vehicle Colour:	Silver		
Engine No:	A0260054N20B20B	Chassis No:	WBAXG12070DV98946
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	15,328.50
Miscellaneous Items	0.00
Labour	1,680.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	17,008.50
- Excess (S\$)	1,000.00
(S\$)	16,008.50
+ GST 7.00% (S\$)	1,120.60
Nett Amount (S\$)	17,129.10

This claim is handled by: YAP JIN HUI

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2018)
 Parts: 143 BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	R ₁ 0.00	0.00	*1,850.00 F
2	20		*Front bonnet insulator clips @ \$4/pc	R ₁ 0.00	0.00	*80.00 F
3	2		*Front bonnet lock @ \$165/pc	ADP ₁ 0.00	0.00	*330.00 F
4	1		*Front bumper	R ₁ 0.00	0.00	*980.00 F
5	1		*Front bumper reinforcement	R ₁ 0.00	0.00	*510.00 F
6	1		*Front bumper sponge	CM 0.00	0.00	*45.00 F
7	2		*Front bumper fog lamp @ \$190/pc	OLJ CM 0.00	0.00	*380.00 F
8	2		*Front bumper fog lamp cover @ \$50/pc	MS CM 0.00	0.00	*100.00 F
9	2		*Front bumper nozzle cover @ \$30/pc	MS 0.00	0.00	*60.00 F
10	2		*Front bumper nozzle gum @ \$150/pc	SC 0.00	0.00	*300.00 F
11	1		*Front bumper top rubber	MS 0.00	0.00	*30.00 F
12	2		*Front bumper retainer @ \$15/pc	OLJ CM 0.00	0.00	*30.00 F
13	1		*Front bumper emblem	R ₁ 0.00	0.00	*30.00 F
14	2		*Front bumper sensor @ \$190/pc	Shon 0.00	0.00	*380.00 F
15	2		*Front bumper bracket @ \$85/pc	R ₁ 0.00	0.00	*170.00 F
16	2		*Front bumper lower air dust @ \$40/pc	CM 0.00	0.00	*80.00 F
17	1		*Front bumper lower beam	R ₁ 0.00	0.00	*130.00 F
18	1		*Front bumper center lower grille	CR ₁ 0.00	0.00	*50.00 F
19	2		*Front grille @ \$110/pc	CM 0.00	0.00	*220.00 F
20	2		*Front headlamp @ \$1950/pc	MS CM 0.00	0.00	*3,900.00 F
21	2		*Front headlamp HID bulb @ \$250/pc	Phay 0.00	0.00	*500.00 F
22	2		*Front headlamp control unit @ \$610/pc	SC 0.00	0.00	*1,220.00 F
23	2		*Front headlamp lower bracket @ \$110/pc	CM 0.00	0.00	*220.00 F
24	2		*Front RH fender top cover @ \$70/pc	OLJ CM 0.00	0.00	*140.00 F
25	5		*Front RH fender top cover clips @ \$4/pc	R ₁ 0.00	0.00	*20.00 F
26	1		*Front air dust	SC 0.00	0.00	*190.00 F
27	1		*Front air condensor	R ₁ 0.00	0.00	*810.00 F
28	1		*Front radiator	R ₁ 0.00	0.00	*770.00 F
29	1		*Front oil cooler	R ₁ 0.00	0.00	*370.00 F
30	1		*Front number plate	R ₁ 0.00	0.00	*40.00 F

F=Franchise part.

Sub Total (S\$) 13,935.00
 + Margin on L,N Items 10.00% (S\$) 1,393.50
 Total Parts (S\$) 15,328.50

Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants

hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To refill air con gas	New	120.00
2	To repair front damages	New	780.00
3	To spray painting	New	780.00
Gross Labour Cost (S\$)			1,680.00

100L
600L
600L

Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >