

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joslin Lim

Date: 18 Sep 2018

**Preliminary Advice**

Vehicle No	: SBU575Z	Accident Date	: 19/05/2018
Make	: BMW 520I	Policy No.	: B27247197SMP
Assignment Date	: 12/06/2018	Excess	: S\$1,000.00
Date of Inspection	: 12/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,008.50
Revised Amount	:S\$	14,588.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,588.00
Repair Sum Repair	:S\$	13,000.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,740.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,260.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.