

ASS. REC. BY:

REF: CS/MSG18009509/Ked321 Special Instruction:

Surveyor
Meymen

Kenneth

ASSIGNMENT (Office)

From (Person):

Joslin Jim

of

MSG

Date/Time:

12/6/18 @ 3:06pm

Estimated Cost:

Bill to:

☒ OB / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SB4 575Z

Insured:

at Workshop m/s

Vin's Motor

Tel:

6453 2121

of

160 Sin Ming Drive #03-03

Policy No:

B27247197SMP

Claim No:

559120

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

(Client's Record)

D.O.A.

19/05/2018

CA / REV

/

REP.

/

REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13/6/18 @

Person Contacted:

Raymond

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

CC3/AG15021683/Rug352

DOA 16/12/2015

ASS. REC. BY:

REF: MSG /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBU 5752Yr Regn: 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMWColour: M. SilverSp. Reading: 65266

Eng/No: _____

C/No: WBA-XG-120700V98946Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 11/8

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 12/6/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File sent to Kenneth12/09/18 Continued Repair Sum \$13,000/- @ 6 days with Kenneth (\$4,008.50 Red - 24%)19/09/18 @ 08:50 a.m. revised IA to Ong Chin Kiet via merimen19/09/18 @ 08:57 a.m. mandate requested authority finalization to Ong Chin Kiet via merimen

RECEIVED 19 SEP 2018

Date/Time, File Pass to?

19/09/181) Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$Survey Fee: 200

Transportation: _____

S + RS: \$

Fees: _____

Others: 10

TOTAL

210

Report Format :

Lump Sum / I.B.I. (\$) 13,000/- R/S

...CLAIM SUBFOLDER...(Pending Mandate Request)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 13:24	12 Jun 2018 13:32	12 Jun 2018 15:06		Last:IA 19 Sep 2018 08:50		Pending Mandate Request Cancel Case
	Sendback Est	\$17,008.50					

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEONG SIEW LOONG, ID: S0475559F, Tel: +6596329282		
Vehicle Reg. No.:	SBU575Z	Date of Loss:	19/05/2018 15:00 - :59 [76 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 559120	Policy/Cover Note No.:	B27247197SMP (Comprehensive) Coverage: 23/12/2017 - 22/12/2018
		Excess:	S\$1,000.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/07/2018]		
Driver/Custodian:	LEONG SIEW LOONG (71 / Male), NRIC: S0475559F, Tel: +6596329282		
Adj Asg. Remarks:	Vehicle surveyed at Performance Motors by Mohd Taufikh on 25.05.2018.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

BMW Distributor

Performance Motors Limited

A member of the Sime Darby Group

FACSIMILE PAY/FA

24 MAY 2018



Urgent

559120

FACSIMILE MESSAGE

DATE 24/05/18 TIME _____

TO MSIG Ins FAX NO 62257402

ATTENTION Motor Claims NO OF PAGES 13
(INCLUSIVE OF THIS PAGE)

CC _____

ATTENTION _____ FAX NO _____

FROM Han FAX NO 64794601
TEL NO 91165500

If this fax is not received in order, please do call us. Thank you.

Attached is the repair estimate for SBU575Z
(Vehicle Regn. No)

The vehicle is presently IN Not IN our workshop.



This is an Own Damage Claim
Please arrange for a surveyor to inspect the vehicle



This is a 3rd Party Claim.
If we do not hear from you within the next 24 hours, exclude
Saturday and Sunday, we shall proceed with our standard
repair of the vehicle.

CC:

FAX:

Performance Motors
LimitedSales & After-sales
315 Alexandra Road
#01-01
Performance Centre
Singapore 159544Telephone
Sales & Admin:
6319 0100
After-sales: 6319 0111Facsimile
Admin: 6474 7770
Sales: 6474 6003
Parts: 6474 6000
After-sales: 6474 3229896 Dunearn Road
#01-01
Sime Darby Centre
Singapore 585472Telephone
Sales: 6319 0500Facsimile
Sales: 6469 1709260 Kampong Arang Rd
East Coast Centre
Singapore 438190Telephone
Sales: 6319 0800
After-sales: 6319 0808Facsimile
Sales: 6344 1332
Parts: 6344 3182
After-sales: 6344 9773Registered office
896 Dunearn Road
#04-11
Sime Darby Centre
Singapore 585472Co. Reg. No
197401559W



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18009509/T1sd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 25-05-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SBU 575Z
Policy No. B27247197SMP	Coverage (\$)	0.00
Claim No. 559120	Excess (\$)	1,000.00
Assign From MERIMEN (JOSLIN LIM)	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 19/05/2018	Inspection Date 25/05/2018
Survey held at PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2016 Honda Vezel 1.8A 2.

\$2,500 Drive Away! \$1,200
Monthly!

[Browse by Category](#)

Sort by Date Posted 12 results/page

Traveling tips

James 5:20

Advanced Search

from among the

Image	Name	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Wch Type	Status
	Search Selection	BMW 320i	K12	Amort	2011	200	100	100	Available
	BMW 3 Series S20i	\$73,900	\$14,493 /yr	30-Nov-2011	1,997 cc	86,000 km	Luxury	Available	
Only 1 Owner, PPL Unit, Steel Black Complemented With Beautiful Dimension Brown Interior, Genuine Low Mileage, Extremely Well Maintained By Previous Owner, Perfect Inside Out Condition With Daily Maint...									
Posted: 26-Apr-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i Highlighter	\$72,900	\$14,280 /yr	32-Dec-2011	1,997 cc	90,000 km	Luxury	Available	
Complimentary 1 Year Pre-owned Vehicle Warranty! Lowest In The Market! Well Maintained With Major Servicing Done, Wear And Tear Has Been Replaced, Beautiful Metallic Grey With Clean And Neat Interior...									
Posted: 19-May-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i Luxury	\$43,000	\$7,010 /yr	23-Dec-2011	1,997 cc	108,000 km	Luxury	Available	
Upgrade Done Worth \$20k! Stunning Custom Lambo White Firework On Full HD Build Including Items, Producing Up To 300HP With New Front And Rear B&C, 384 With Bluetooth Hi, Metastar Hi, 17A Approved...									
Posted: 10-May-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i	\$73,900	\$14,193 /yr	30-Dec-2011	1,997 cc	138,000 km	Luxury	Available	
Very Well Maintained By A Careful Owner Since Day 1 Sporty Black With Black Leather Interior, Powerful Twin Turbo Engine BMW 320i Power/Luxury Sedan For Your Family, With GPS Navigation, Popular Low Fu...									
Posted: 10-May-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i	\$80,800	\$16,720 /yr	28-Dec-2011	1,997 cc	77,500 km	Luxury	Available	
PPL Unit And Fully Maintained And Serviced At Agent With Low Mileage Done, Last Service At PPL (863270M) On March 2017, 100% Accident Free, Showroom Condition, Call By Appointment Only.									
Sing Auto Trading									
Posted: 04-May-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i	\$76,800	\$15,160 /yr	23-Dec-2011	1,997 cc	90,000 km	Luxury	Available	
Consignment Unit! Very Beautiful Beige On Black S20i F10 Model! Lowest Depreciation In The Market! Very Well Maintained By Owner! Regular Maintenance And Servicing Done At Reputable Workshop! Loan Li...									
At Auction By Ltd									
Posted: 20-Apr-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series S20i	\$73,900	\$14,880 /yr	31-Oct-2011	1,997 cc	85,000 km	Luxury	Available	
Beautiful Black PPL Unit, Well Maintained By Previous Owner, Zero Engine Oil Leakage, All Gaskets And Leaks Have Been Replaced And Serviced With Recent Tyre Press, Low Mileage Done, Call Now To View...									
Posted: 23-Apr-2018 Tag: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									

Save the search criteria, to get email alerts whenever a match is found

Name	Model	Price	Depreciation	Reg. Code	Eng. Cat.	Mileage	Ver. Type	Status
------	-------	-------	--------------	-----------	-----------	---------	-----------	--------

For all advertisements, view Expendable.com

208 www.elsevier.com/locate/jmb[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resource](#)

AGC import is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars & motorcycles, SUV, MPV, hatchback, to CUC cars & CUC cars. You can also buy from a car auction, look up car parts, low mileage cars, car brands, car prices & car insurance. Find the used car, SUV, BMW, Toyota, import, used low \$20 Singapore, used BMW \$20, used vehicles Singapore or even buy a new BMW \$20 Singapore. We have new car dealers coming from all over the world. Authorized car dealers, and used car dealers are all here. Find new car prices, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CUC related.

All prices and other information displayed on agCenter.com are gathered from sources and based on algorithms that are believed by agCenter.com to be reliable, but no assurance can be given that this information is accurate, complete or current. agCenter.com does not assume any responsibility for errors or omissions or warrants the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2018 kgCartNet. All rights reserved.

Campione

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5559F

Vehicle Details

Vehicle No.:	SBU575Z
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	A0260054N20B20B
Chassis No.:	WBAXG12070DV98946
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$44,288.00
Original Registration Date:	23 Dec 2011
First Registration Date:	23 Dec 2011
Transfer Count:	0
Actual ARF Paid:	\$44,288.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2021
PARF Rebate Amount:	\$28,787.00

Intended COE Rebate Details

COE Expiry Date:	22 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$70,003.00
COE Rebate Amount:	\$24,953.00
Total Rebate Amount:	\$53,740.00

The information contained herein is correct as at 28 May 2018

OK

Shirley Hiew (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Wednesday, 19 September 2018 12:57 PM
To: Shirley Hiew (LKK Auto)
Cc: sur@lkkauto.com
Subject: Re: SBU575Z_Finalization

Good afternoon Shirley,

Please proceed with \$13000.

Please make the offer through Merimen.

I will submit the DV to Merimen as well.

Thanks!

Best Regards

Raymond Teo

Vin's

AUTOMOTIVE GROUP
#VAuG

Sin Ming AutoCity
160 Sin Ming Drive
#03-03, #08-08/09
Singapore 575722
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

On 19/09/2018 12:11, Shirley Hiew (LKK Auto) wrote:

Hi Raymond,

Confirmed final fig \$13,000.00 @ 6 days of repairs before excess \$1,000/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG [mailto:admin@vinsautogroup.com.sg]

Sent: Tuesday, 18 September 2018 5:19 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: Re: SBU575Z_Finalization

Good afternoon,

Can we finalize the amount @ \$13000?

Thanks!

Best Regards

Raymond Teo

 **Vin's**
AUTOMOTIVE GROUP
#VAuG

Sin Ming AutoCity

160 Sin Ming Drive

#03-03, #08-08/09

Singapore 575722

Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

On 18/09/2018 15:56, Shirley Hiew (LKK Auto) wrote:

Hi Raymond,

As spoken, enclosed herewith estimate marking by Kenneth.

Please check.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin @ VAuG [<mailto:admin@vinsautogroup.com.sg>]

Sent: Friday, 17 August 2018 3:40 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: sur@lkkauto.com

Subject: Re: SBU575Z_Finalization

Good afternoon,

Is there any update?

Can we confirm the LOR @ \$13000?

Thanks!

Best Regards

Raymond Teo



Sin Ming AutoCity

160 Sin Ming Drive #03-03
Singapore 575722
Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

On 17/07/2018 11:02, Admin @ VAuG wrote:

Good morning Shirley,

This is a limit repair case.

Can we finalize the amount @ \$13000?

Thanks!

Best Regards

Raymond Teo

--



Sin Ming AutoCity

160 Sin Ming Drive #03-03
Singapore 575722
Tel: 64532121 (4 lines)

Fax: 64599795

Website: www.vinsautogroup.com.sg

Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

View Received Message

This mail is associated with :

SBU575Z (559120)

OD

May 19 2018 3:00PM

[LEONG SIEW LOONG]

Vin's Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/09/2018 09:57 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$13000.00) - SBU575Z - Claim Handler: Joslin Lim

Approved:13000.00:Part by part repair not exceeding \$13,000.00 (before excess \$1000). Please take re-survey photos before spray-painting

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 18 Sep 2018

Preliminary Advice

Vehicle No	: SBU575Z	Accident Date	: 19/05/2018
Make	: BMW 520i	Policy No.	: B27247197SMP
Assignment Date	: 12/06/2018	Excess	: S\$1,000.00
Date of Inspection	: 12/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,008.50
Revised Amount	:S\$	14,588.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,588.00
Repair Sum Repair	:S\$	13,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,740.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,260.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 16:38
Date Of Accident	19/05/2018 15:00
Exact Location Of Accident	CHARMICHAEL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBU575Z
Insured/Policyholder	
Name Of Registered Owner	LEONG SIEW LOONG
NRIC No	S0475559F
Email Address	SIEWLOONG.LSL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96329282
Alternative Phone No	OFFICE-96329282

Vehicle Particulars

Manufacturer	BMW
Model	520i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27247197SMP
Cover Note Number	

Driver

Name of Driver	LEONG SIEW LOONG
NRIC No	S0475559F
Date Of Birth	20/07/1946
Occupation	INDOOR
Date Of Driving Pass	07/04/1971
Driving Experience	47 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96329282
Fax Number	
Contact Number	OFFICE-96329282
Email Address	SIEWLOONG.LSL@GMAIL.COM

Address	37 CARMICHAEL RD
Postcode	359822
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFX9199D
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG YET SHIN
NRIC/Passport Number	S1210414F
Contact Number	97925856
Address	23 CARMICHAEL RD
Postcode	359822
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
 Date & Time: 21 May 2018
 3pm.

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 19 May 2018, Time: ~3pm.

I was approaching my home along Commercial Road, and collided with vehicle SFX 9199D. Both vehicles damaged, but no injuries to persons.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

21/05/18
(3.17pm)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575656. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	OD/062018/3561
Policy No:	B27247197SMP	Date of Loss:	19/05/2018
Vehicle Reg. No.:	SBU575Z	Driveable?	
Driver Age/Info:	72 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEONG SIEW LOONG	Contact No:	+6596329282
Driver:	LEONG SIEW LOONG		
Make/Model:	BMW 520I, 2.0 (A)	Vehicle Reg. Date:	23/12/2011
Vehicle Colour:	Silver		
Engine No:	A0260054N20B20B	Chassis No:	WBAXG12070DV98946
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	15,328.50
Miscellaneous Items	0.00
Labour	1,680.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	17,008.50
- Excess (S\$)	1,000.00
(S\$)	16,008.50
+ GST 7.00% (S\$)	1,120.60
Nett Amount (S\$)	17,129.10

This claim is handled by: YAP JIN HUI

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2018)
 Parts: 143 BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	R ₁ 0.00	0.00	*1,850.00 F
2	20		*Front bonnet insulator clips @ \$4/pc	R ₁ 0.00	0.00	*80.00 F
3	2		*Front bonnet lock @ \$165/pc	AA D ₁ 0.00	0.00	*330.00 F
4	1		*Front bumper	R ₁ 0.00	0.00	*980.00 F
5	1		*Front bumper reinforcement	R ₁ 0.00	0.00	*510.00 F
6	1		*Front bumper sponge	CM 0.00	0.00	*45.00 F
7	2		*Front bumper fog lamp @ \$190/pc	MS CM 0.00	0.00	*380.00 F
8	2		*Front bumper fog lamp cover @ \$50/pc	MS 0.00	0.00	*100.00 F
9	2		*Front bumper nozzle cover @ \$30/pc	SN 0.00	0.00	*60.00 F
10	2		*Front bumper nozzle gum @ \$150/pc	SC 0.00	0.00	*300.00 F
11	1		*Front bumper top rubber	MS 0.00	0.00	*30.00 F
12	2		*Front bumper retainer @ \$15/pc	MS CM 0.00	0.00	*30.00 F
13	1		*Front bumper emblem	R ₁ 0.00	0.00	*30.00 F
14	2		*Front bumper sensor @ \$190/pc	Short 0.00	0.00	*380.00 F
15	2		*Front bumper bracket @ \$85/pc	R ₁ 0.00	0.00	*170.00 F
16	2		*Front bumper lower air dust @ \$40/pc	CM 0.00	0.00	*80.00 F
17	1		*Front bumper lower beam	R ₁ 0.00	0.00	*130.00 F
18	1		*Front bumper center lower grille	CR ₁ 0.00	0.00	*50.00 F
19	2		*Front grille @ \$110/pc	CM 0.00	0.00	*220.00 F
20	2		*Front headlamp @ \$1950/pc	MS CM 0.00	0.00	*3,900.00 F
21	2		*Front headlamp HID bulb @ \$250/pc	Short 0.00	0.00	*500.00 F
22	2		*Front headlamp control unit @ \$610/pc	SN 0.00	0.00	*1,220.00 F
23	2		*Front headlamp lower bracket @ \$110/pc	CM 0.00	0.00	*220.00 F
24	2		*Front RH fender top cover @ \$70/pc	MS CM 0.00	0.00	*140.00 F
25	5		*Front RH fender top cover clips @ \$4/pc	R ₁ 0.00	0.00	*20.00 F
26	1		*Front air dust	SN 0.00	0.00	*190.00 F
27	1		*Front air condensor	R ₁ 0.00	0.00	*810.00 F
28	1		*Front radiator	R ₁ 0.00	0.00	*770.00 F
29	1		*Front oil cooler	R ₁ 0.00	0.00	*370.00 F
30	1		*Front number plate	R ₁ 0.00	0.00	*40.00 F

F=Franchise part.

Sub Total (\$\$) 13,935.00
 + Margin on L,N Items 10.00% (\$\$) 1,393.50
 Total Parts (\$\$) 15,328.50

Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To refill air con gas	New	120.00
2	To repair front damages	New	780.00
3	To spray painting	New	780.00
Gross Labour Cost (\$\$)			1,680.00

Vin's Motor Pte Ltd/SBU575Z/12/06/2018 13:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Copy Proposed

Shirley Hiew (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Tuesday, 18 September 2018 1:45 PM
To: Shirley Hiew (LKK Auto)
Subject: Fwd: Re: SBU575Z - DOA: 19/05/18 - OUR REF: 559120 - URGENT
Attachments: 20180607125616.pdf; 20180607125622.pdf

FYI



Sin Ming AutoCity
160 Sin Ming Drive
#03-03, #08-08/09
Singapore 575722
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

----- Original Message -----

Subject: Re: SBU575Z - DOA: 19/05/18 - OUR REF: 559120 - URGENT

Date: 07/06/2018 13:46

From: "Admin @ VAuG" <admin@vinsautogroup.com.sg>

To: Joslin Lim <joslin_lim@sg.msiga-asia.com>



Sin Ming AutoCity
160 Sin Ming Drive #03-03
Singapore 575722
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **
** w.e.f 20th November 2017, we have changed our email address! **

On 07/06/2018 13:16, Admin @ VAuG wrote:

Good afternoon Joslin,

Please check the attachment for the towing letter which is signed and agreed by the owner and letter of undertaking.

How much is the excess for this case?

Can you please send us the official towing letter as well?

Thanks!

Best Regards

Raymond Teo

Sin Ming AutoCity
160 Sin Ming Drive #03-03
Singapore 575722
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :

** w.e.f 15th May 2017, we have shifted location! **
** w.e.f 20th November 2017, we have changed our email address! **

On 06/06/2018 14:19, Joslin Lim wrote:

Hi Vincent

We enclose a copy of the accident report to you.

Please contact OI Mr Leong @ 96329282.

*OI is considering to repair the vehicle.

Thank you.

Regards

Joslin Lim

Senior Admin Officer, Claims Services

D: +65 6643 1327 | F: +65 6225 7402 | joslin_lim@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

From: Admin @ VAuG [<mailto:admin@vinsautogroup.com.sg>]
Sent: Tuesday, 5 June, 2018 9:35 AM
To: Joslin Lim <joslin_lim@sg.msig-asia.com>
Subject: Re: SBU575Z - DOA: 19/05/18 - OUR REF: 559120 - URGENT
Importance: High

Good morning Joslin,

The COR for this vehicle is between 11k - 13k.

Estimate days of repair: 8 days.

We provide 1 year warranty and replacement car during repairing process.

Thanks!

Best Regards

Raymond Teo

Sin Ming AutoCity

16Q Sin Ming Drive #03-03
Singapore 575722
Tel: 64532121 (4 lines)

Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :

** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

On 04/06/2018 17:08, Joslin Lim wrote:

Hi all

Please let us know whether your workshop is able to repair the vehicle within the margin repair amount and also advice your estimate cost of repair.

Attached the damaged photographs and PARF/COE rebate details.

Regards

Joslin Lim

Senior Admin Officer, Claims Services

D: +65 6643 1327 | F: +65 6225 7402 | joslin_lim@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

* Copy Prepared

21/05/2018

ASS. REC. BY:

REF: es/msc1800q50q/T1sd3

Special Instruction:

Surveyor
Menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Joslin Lim

of

M81G

Date/Time:

25/5/18 @ 9.36am

Estimated Cost:

Bill to:

☒ OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBU 5752

Insured:

at Workshop m/s:

Performance Motor Limited

Tel:

9116 5700

of

303 Alexandra Rd

Policy No:

B27247197smp

Claim No:

559120

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

D.O.A.

19/05/2018

(Client's Record)

CA / ☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.55am @ 25/5/18

Person Contacted:

Hein

Vehicle

☒ IN / ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SBU 5752 - cc3/AIG/ISO21683/Fug3s2

DOA: 16/12/15

31/05/18 @ 12:01 p.m. revised IA to Joslin via menmen.

31/05/18 @ 12:03 p.m. mandate request authorise repair to Joslin via menmen.

04/06/18 @ 11:02 a.m. repair cost at part by part not exceeding \$19,000/- offer
by Goh Huey Nin via menmen.

Taylor

MS16

SBU 5752

2011 Dec.

Editorial Note

MD / TP / WS / TR RES / OD RES / EVA / DIV / MV

To assess vehicle for

insurance purposes

if

insured

Policy No.

Class No.

Sum Insured

Vehicle Record

Make Model

(Policy Conditions)

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value

WAC Accidents Report

GLS FR Seen

Est. Future

Loss Limit

CA

Type

Date Time

Action Instruction

Excess \$1000

976K

Consistent? Yes or No

Consistent? Yes or No

Days Res. Yes or No

Val Yes or No

REP.

Person Contacted

Vehicle IN / OUT

Repair Unit



Vehicle IN / OUT

Plan

Unit 53760

Repair Unit 9211C

Truck / Trailer

Make

Model

Year

Engine

Color

Gen. Cond. Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Make Nil / B / R / S / A / R / M

Tyre Size

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R.Bal

L.Bal

D.O.A.

Survey held at

Dis. of Damages

Front

Rear

Q/S

N/S

U/C

Roof top

or

The U/C / Chassis frame / Body Structure affected by collision

BMW 520i

Silver

05258

1997

WBA XG1207 ODV98946

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / B / R / S / A / R / M

275 / 8167

2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R.Bal

L.Bal

D.O.A.

Survey held at

Dis. of Damages

Front

Rear

Q/S

N/S

U/C

Roof top

or

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

The U/C / Chassis frame / Body Structure affected by collision

Print Report

Final Report

Days Of Repair

Resurvey No. of Trip

Add Fee

1st Trip

2nd Trip

3rd Trip

4th Trip

5th Trip

6th Trip

Signature

Date

Time

Place

Remarks

Signature

Date

Time

Place

Remarks

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018		25 May 2018 09:36 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEONG SIEW LOONG, ID: S0475559F, Tel: +6596329282, Email: SIEWLOONG.LSL@GMAIL.COM		[Created by Insurer]
Vehicle Reg. No.:	SBU575Z	Date of Loss:	19/05/2018 15:00 - :59 [76 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 559120	Policy/Cover Note No.:	B27247197SMP (Comprehensive) Coverage: 23/12/2017 - 22/12/2018
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/05/2018]		
Driver/Custodian:	LEONG SIEW LOONG (71 / Male), NRIC: S0475559F, Tel: +6596329282		
Adj Asg. Remarks:	Please survey and revert.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Assigned On	Created On	Complete
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 28 May 2018

Preliminary Advice

Vehicle No	: SBU575Z	Accident Date	: 19/05/2018
Make	: BMW 520i	Policy No.	: B27247197SMP
Assignment Date	: 25/05/2018	Excess	: S\$1,000.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 9 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,135.00
Revised Amount	:S\$	13,941.70
Check Items (Estimated)	:S\$	12,782.85
Total	:S\$	26,724.55

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	53,740.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,260.00

Remarks

- (X) The vehicle is not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comment : Repairer propose repair cost \$ 27,000.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190300 (Sales & Admin)
63190311 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64736601 (AfterSales)
64736624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47014
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Leong Siew Loong
37 Carmichael Road

Singapore 359822

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

DESCRIPTION

VALUE

To tow accident vehicle to PML workshop.

195.00

To replace front bumper & attachments, bonnet, front inner support panel including to pull & straighten both front chassis, to knock out both front fender and dented area caused by the accident

3400 5,100.00

To respray front bumper, front left fender, front right fender and bonnet

2898 4,106.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To replace radiator assembly including pressure test, bleed cooling system and conduct checks for leak. (For all models except 7 series).

photo? 702 826.00

To replace charge air cooler including conduct checks for leak and proper function.

photo? 451 531.00

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

852 1,003.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To supply front emboss number plate.

61- 83.00

Sundries.

? 150.00

Total Labour 1: 12,289.00

DESCRIPTION

QTY PRIC

VALUE

PLASTIC NUT

10 0.90

9.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No. M2-0020081-s



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/538 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47014
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
PLUG	2	5.10	10.20
CLIP	2	2.15	4.30
MODULE BUSHING	2	14.45	28.90
# CHARGE AIR COOLER	1	609.75	609.75
MODULE MOUNT LH	1	75.70	75.70
MODULE MOUNT RH	1	75.70	75.70
COVER	1	52.30	52.30
RADIATOR	1	967.35	967.35
BLIND RIVET FLAT HEADED 6.5X14.3	4	4.30	17.20
LH ENGINE HOOD HINGE	1	88.70	88.70
RH ENGINE HOOD HINGE	1	88.70	88.70
BONNET	1	2,224.70	2,224.70
RIVET	10	0.50	5.00
# FRT LH BOTTOM DEFORMATION EL	1	101.70	101.70
# FRT RH BOTTOM DEFORMATION EL	1	101.70	101.70
FRT BUMPER LH CONNECTOR	1	57.95	57.95
FRT BUMPER RH CONNECTOR	1	54.75	54.75
FRT BUMPER LH ADAPTER PLATE	1	52.35	52.35
FRT BUMPER RH ADAPTER PLATE	1	53.65	53.65
GRILLE AIR INLET OPEN RH	1	71.80	71.80
LH GRILLE AIR INLET PARTLY CLOSED	1	72.20	72.20
FRT BUMPER CARRIER	1	684.75	684.75
FRT BUMPER TOP IMPACT ABSORBER	1	48.00	48.00
LEVER RH	1	5.95	5.95
FRT BUMPER BOTTOM MOUNT	1	157.50	157.50
FRT BUMPER LH FINISHER ROD	1	34.45	34.45
FRT BUMPER RH FINISHER ROD	1	34.45	34.45
FRT BUMPER TOW HOOK COVER PRIMED	1	46.45	46.45
COVERING PRIMEND RH	1	46.45	46.45
GRILLE AIR INLET MIDDLE	1	68.80	68.80
FRT BUMPER TRIM PRIMED (PDC)	1	1,277.55	1,277.55
BUMPER RIVET	10	0.50	5.00
LH GRILLE CHROME	1	120.50	120.50
RH GRILLE CHROME	1	120.50	120.50
EMBLEM GROMMET	2	0.80	1.60
BMW EMBLEM	1	69.50	69.50
RIVET	10	0.45	4.50
RIVET	2	0.70	1.40
STOP BUFFER	2	12.20	24.40
RH LOCK BONNET PASSIVE	1	184.00	184.00
LH UPPER LOCK SECTION	1	66.90	66.90
RH UPPER LOCK SECTION	1	66.90	66.90
BONNET CATCH OPERATOR	1	39.65	39.65
LH LOCK BONNET PASSIVE	1	184.00	184.00
SUPPORT LH	1	18.40	18.40
SUPPORT RH	1	18.40	18.40
CONNECTION TOP FRT	1	155.35	155.35
LH HEADLAMP SUPPORT	1	126.10	126.10
RH HEADLAMP SUPPORT	1	128.45	128.45

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47014
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
CLIP	10	1.30	13.00
# FRT LH WHEEL ARCH COVER	1	127.15	127.15
FRT RH WHEEL ARCH COVER	1	127.15	127.15
AIR DUCT	1	308.95	308.95
FRT RH AIR DUCT ENGINE OIL COOLER	1	51.50	51.50
LH AIR DUCT BRAKE	1	51.50	51.50
RH AIR DUCT BRAKE	1	51.50	51.50
# ENGINE COMP. SHIELD UNDERRID	1	202.15	202.15
COVER BOTTOM LEFT	1	71.30	71.30
COVER BOTTOM RIGHT	1	71.30	71.30
FRT LH LOCATOR SEAL	1	55.80	55.80
FRT RH LOCATOR SEAL	1	56.80	56.80
COVER	4	6.70	26.80
SEAL ENGINE BONNET FRT	1	42.30	42.30
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	47.50	47.50
LH HIGH PRESSURE NOZZLE	1	179.30	179.30
RH HIGH PRESSURE NOZZLE	1	179.30	179.30
LH BI-XENON HEADLIGHT	1	2,631.15	2,631.15
RH BI-XENON HEADLIGHT	1	2,631.15	2,631.15
LH FOG LIGHT	1	260.75	260.75
RH FOG LIGHT	1	260.75	260.75
CONDENSER AIR CONDITIONING	1	1,028.45	1,028.45
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	10.10
BUMPER PDC SENSOR (354 TITANSILBER)	2	368.80	737.60
ANTI-FREEZE 1.5 LITRES	3	19.75	59.25

UKX Auto Consultance to notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

17,846.00

Claimed by / 3rd Party / Uninsured Inmate / Direct Settlement

Reg No.

Claim No.

Date/Time

Excess \$

Damage's Name

Sign

Amount

Amount

Authorized Date

Time

RECEIVED WITHIN 10 DAYS BY INSURER

No

Yes

Service's Date

No. of Working Days Promised

Labour 1	:	12,289.00
Parts	:	17,846.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,109.45
Grand Total	:	32,244.45

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 191401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 43190100 (Sales & Admin)
43190111 (AfterSales)
Fax: 44747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel: 43190888 (AfterSales)
Fax: 43449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 43190528 (AfterSales)
43190533/538 (Motorrad)
44796501 (AfterSales)
44796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47014
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 4 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. NO. 197401559W GST Reg. NO M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47014**
Date Estimated : **21/05/2018**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales/
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales/
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47014
Date Estimated : 21/05/2018
Prepared By : Han Kwan Yong

Page No. : 6 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU575Z	DV98946	23/12/2011	520iA	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pmi.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 13:24 Sendback Est	12 Jun 2018 13:32 S\$17,008.50	12 Jun 2018 15:06 Edit Adj Rpt	S\$13,000.00 Edit Estimates	S\$13,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: LEONG SIEW LOONG , ID: S0475559F, Tel: +6596329282									
Vehicle Reg. No.: SBU575Z		Date of Loss: 19/05/2018 15:00 - :59 [76 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 559120		Policy/Cover Note No.: B27247197SMP (Comprehensive) Coverage: 23/12/2017 - 22/12/2018							
		Excess: S\$1,000.00							
Repairer: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/07/2018]									
Driver/Custodian: LEONG SIEW LOONG (71 / Male), NRIC: S0475559F, Tel: +6596329282									
Adj Asg. Remarks: Vehicle surveyed at Performance Motors by Mohd Taufikh on 25.05.2018.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (19/09/2018): Alert - Adj Mandate Approved (S\$13000.00) - SBU575Z - Claim Handler: Joslin Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SBU575Z (559120)
OD
May 19 2018 3:00PM
[LEONG SIEW LOONG]
Vin's Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	25/06/18 08:46	Video - Other - conditions of car						Load MP4		
2	25/06/18 08:47	Video - Other - conditions of car						Load MP4		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)						Thumbnail	Print	
1	12/06/18 13:32	Repairer Estimates						Load HTM		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	12/06/18 15:01	Accident Statement <small>From: OD - Reg. No: SBU575Z, Claimant: LEONG SIEW LOONG</small>						Load HTM		
2	12/06/18 15:02	Adjuster Immediate Advice <small>From: OD - Reg. No: SBU575Z, Claimant: LEONG SIEW LOONG</small>						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/09/18 08:50	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
2	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
3	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
4	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
5	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
6	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
7	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
8	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
9	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
10	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
11	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
12	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
13	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
14	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
15	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
16	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
17	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
18	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
19	18/09/18 16:06	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
20	18/09/18 16:06	General View						Load JPG	<input checked="" type="checkbox"/>	
21	18/09/18 16:06	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
22	18/09/18 16:10	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
23	18/09/18 16:10	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
24	18/09/18 16:10	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
25	18/09/18 16:10	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
26	18/09/18 16:10	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
27	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	18/09/18 16:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/18 16:14	TOW.pdf	 Load PDF	
2	19/09/18 09:09	UNDERTAKING LETTER.pdf	 Load PDF	
3	19/09/18 09:20	ESTIMATE MARKED.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009509/KSD3E2

Date: 19/09/2018

REFERENCE

Insured/Claimant:	LEONG SIEW LOONG	Policy No:	B27247197SMP	
Date of Loss:	19/05/2018	Nature of Claim:	OD	Claim No: 559120

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBU575Z		
Make & Model:	BMW 520i, 2.0 (A)	Engine No:	A0260054N20B20B
Reg. Date:	23/12/2011 (Man. Year: 2011)	Chassis No:	WBAXG12070DV98946
Colour:	Metallic Silver	Odometer:	65266 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,328.50	13,288.00	2,040.50	13.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,300.00	380.00	22.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,008.50	14,588.00	2,420.50	14.23
Approved Total (Overridden) (S\$)		13,000.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	16,008.50	12,000.00	4,008.50	25.04
+ GST 7.00/7.00% (S\$)	1,120.60	840.00	280.60	25.04
Nett Amount (S\$)	17,129.10	12,840.00	4,289.10	25.04

INSPECTION

Date of Assignment:	12/06/2018 Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	12/06/2018 Inspected At:	Vin's Motor Pte Ltd (Sin Ming)
		160 Sin Ming Drive, #03-03, Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2018)
Parts: 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBU575Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet	Bent	1,850.00 F	*1,850.00 F
2	20		*Front bonnet insulator clips @ \$4/pc	Necessary	80.00 F	*80.00 F
3	2		*Front bonnet lock @ \$165/pc	Bent / Distorted	330.00 F	*330.00 F
4	1		*Front bumper	Bent	980.00 F	*980.00 F
5	1		*Front bumper reinforcement	Bent	510.00 F	*510.00 F
6	1		*Front bumper sponge	Cracked	45.00 F	*45.00 F
7	2		*Front bumper fog lamp @ \$190/pc	O/S Cut / N/S Cracked	380.00 F	*380.00 F
8	2		*Front bumper fog lamp cover @ \$50/pc	Missing	100.00 F	*100.00 F
9	2		*Front bumper nozzle cover @ \$30/pc	Serviceable	60.00 F	*- F
10	2		*Front bumper nozzle gum @ \$150/pc	Serviceable	300.00 F	*- F
11	1		*Front bumper top rubber	Missing	30.00 F	*30.00 F
12	1		*Front bumper retainer @ \$15/pc	O/S Cracked	30.00 F	*15.00 F
13	1		*Front bumper emblem	Dented	30.00 F	*30.00 F
14	2		*Front bumper sensor @ \$190/pc	Shorted	380.00 F	*380.00 F
15	2		*Front bumper bracket @ \$85/pc	Bent	170.00 F	*170.00 F
16	2		*Front bumper lower air dust @ \$40/pc	Cracked	80.00 F	*80.00 F
17	1		*Front bumper lower beam	Bent	130.00 F	*130.00 F
18	1		*Front bumper center lower grille	Cracked	50.00 F	*50.00 F
19	2		*Front grille @ \$110/pc	Cracked	220.00 F	*220.00 F
20	2		*Front headlamp @ \$1950/pc	MTG Cracked	3,900.00 F	*3,900.00 F
21	2		*Front headlamp HID bulb @ \$250/pc	Shorted	500.00 F	*500.00 F
22	2		*Front headlamp control unit @ \$610/pc	Serviceable	1,220.00 F	*- F
23	2		*Front headlamp lower bracket @ \$110/pc	Cracked	220.00 F	*220.00 F
24	1		*Front RH fender top cover @ \$70/pc	O/S Cracked	140.00 F	*70.00 F
25	5		*Front RH fender top cover clips @ \$4/pc	Necessary	20.00 F	*20.00 F
26	1		*Front air dust	Serviceable	190.00 F	*- F
27	1		*Front air condensor	Bent	810.00 F	*810.00 F
28	1		*Front radiator	Punctured	770.00 F	*770.00 F
29	1		*Front oil cooler	Bent	370.00 F	*370.00 F
30	1		*Front number plate	Bent	40.00 F	*40.00 F

F=Franchise part.

Sub Total (\$\$)	13,935.00	12,080.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,393.50	1,208.00
Total Parts (\$\$)	15,328.50	13,288.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To refill air con gas	New	120.00	100.00
2	To repair front damages	New	780.00	600.00
3	To spray painting	New	780.00	600.00
Gross Labour Cost (S\$)			1,680.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >