

ASS. REC. BY:

REF: 08/MSG18009529 / Gsd3

Special Instruction:

Surveyor  
Meimen

Guo Qiang  
Winnie Chua

ASSIGNMENT (Office)

of MSIG

Date/Time: 25/5/18 @ 9:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLV 583B

Insured:

at Workshop m/s: Jack Cars

Tel: 67488824

of Blk 3007 ubi Rd 1 # 01-450

Policy No: 29065410 MCX

Claim No: 559135

Sun Insured:

Excess: \$500.00

Make of Veh:

(Client's Record)

D.O.A. 22/05/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11am @ 25/5/18

Person Contacted:

Therna

Vehicle: IN / OUT


Date/Time	Action/Instruction	Estimate
	SLV 583B - CVI / VAL 18009439 / B5	DIA: 22/5/2018
28/05/18 @ 17:43 p.m.	revised <del>FA</del> <sup>IA</sup> to Winnie Chua Ping Ping via meimen.	
28/05/18 @ 17:50 p.m.	revised Authorization to Winnie Chua Ping Ping via meimen.	
01/06/18 @ 17:32 p.m.	revised autodax to Winnie Chua Ping Ping via meimen.	
04/06/18 @ 11:55 a.m.	revised autodax to Winnie Chua Ping Ping via meimen.	

ASSIGNMENT

From: \_\_\_\_\_ Date: 25/5/18  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SLV 583B  
 at Workshop m/s: Jack Car  
 of: Blk 3007, Ubi Rd 1 # 01-450  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLV 583 B Yr Regn: 2017 / Dec 21  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota CHR Hybrid cc 1797  
 Colour: Metallic brown A/C: Insured / Std / NI / NA  
 Sp. Reading: 3960 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZYX102078200  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Harder / Jammed / Leaked / Burnt or  
 Brake:  Harder / Jammed / Leaked / Burnt or  
 Modi: Nil (S/Rim) / STD A/Rim or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$96K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA /  RE / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Tyre Size: F: 225 / 50 R18  
 R: 225 / 50 R18  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front Rear  
 R/Bal. 7 mm R/Bal. 7 mm  
 L/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 25/5/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages  Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
07/06/18 @ 12:06 p.m. revert authorized repair to Thana (operator) via email.  
18/06/18 @ 11:55 a.m. revised IA (include Supplementary) to Winnie Chua Ping Ping via messenger.  
13/06/18 @ 11:58 a.m. mandate requested authorization of Supplementary to Winnie Chua Ping Ping via messenger.  
20/06/18 @ 20:47 p.m. mandate approved by Eng Huey Ni. via messenger. (Supplementary)  
21/06/18 @ 17:00 p.m. revert authorized repair of Supplementary to Thana (operator) via email.

RECEIVED 21 OCT 2018

Date/Time: File Pass to?  : Prell. Report  
24/10/18  : Final Report  
 Typist  
 Date/Time: File Return to?  
 Report Format :  
 Lump Sum / I.B.I: (\$) 11,323.54 P/P

Days Of Repair: 8  
 Resurvey No. of Trip: 2  
 Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)  
 Survey Fee: 200  
 Transportation: \_\_\_\_\_  
 Others: 10  
 TOTAL: 210

*Amn 18*  
*18/10/2018*

200
10
<b>210</b>

13/10/18 P/P \$ 11,323.57 @ 8 days.

( \$ 3,688.26 Red - 25% )

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Action	Status
Main	22 May 2018 <a href="#">Sendback Est</a>	24 May 2018 17:00 <b>S\$13,692.50</b>	25 May 2018 09:28 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	NEW REZKI RESTAURANT PTE LTD, Co. Reg. No.: 19960601K, Tel: +6592314006								
Vehicle Reg. No.:	SLV583B	Date of Loss:	22/05/2018 12:00 - :59 [5 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 559135	Policy/Cover Note No.:	29065410MCX (Comprehensive) Coverage: 21/12/2017 - 20/12/2018						
		Excess:	S\$500.00						
Repairer:	Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart, 408898 Singapore - Tel: 67441900								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/05/2018]								
Driver/Custodian:	KAKKAT MOHAMMAD RAOOF (33 / Male), NRIC: G1059612U, Tel: +6592314006								
Adj Asg. Remarks:	Survey TODAY and REVERT. Car at Blk 3007 Ubi Rd 1 #01-450 S408701.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed	Created On	Done?
No results.									



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD      Ref : CS/MSG18009529/Gsd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581      Date : 25-05-2018  
Code : MSG



### 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLV 583B
Policy No.	29065410MCX	Coverage (\$)	0.00
Claim No.	559135	Excess (\$)	0.00
Assign From	MERIMEN (WINNI CHUA)	Assign Date	25/05/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	22/05/2018	Inspection Date	
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

### 5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	----------------------------------------------------------------------------------------------------------------------------------------

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6061K
Vehicle Details	
Vehicle No.:	SLV583B
Vehicle to be Exported:	No
Intended De-registration Date:	24 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.85 CVT
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	22R8202510
Chassis No.:	ZYX10207B200
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,447.00
Original Registration Date:	21 Dec 2017
First Registration Date:	21 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$51,403.00
Total Rebate Amount:	\$55,153.00

The information contained herein is correct as at 23 May 2018

OK

Dep - 10010/yr  
834/mth

93800  
6004  
98804

MV 96-97k

doi

23/5/18

## CHEAPEST CAR INSURANCE RENEWAL



Compare  
10+ Insurers

**GET A CHEAPER QUOTE NOW!**

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

2016 Honda Vezel:



\$2,200 Down (RM 33,000)  
Monthly  
Urban Motors Pte Ltd



**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997**

[View our Cars](#)

100% SATISFACTION GUARANTEE

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Browse by Category

• Back ( 1 2 3 ) Next •

Sort by Date Posted 20 results/page

48 vehicles

Toyota HYBRID

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota HYBRID	Any	Any	2017	Any	Any	Any	Available



**Toyota Sienta Hybrid 1.5A G \$103,988 \$10,500 /yr 22-Dec-2017 1,456 cc 12 km MPV Available**

**Fuel Type:** Petrol-Electric

Two Automatic Power Door, 2018 New Facelift, No-Need Wait for COE Bidding, High Loan Available Up To 95% From 7-10 Years Loan, Flood Recording Camera, Welcome Trade In For Your Existing Car, Warranty 3...

Posted: 22-May-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota



**Toyota Prius Hybrid 1.8A S \$95,000 \$10,570 /yr 23-Jan-2017 1,797 cc 26,000 km Hatchback Available**

**Fuel Type:** Petrol-Electric

Single Owner Unit! Come With 5 Years Warranty & Warranty On Hybrid Battery Till End Of Drive With Free Change Of Hybrid Battery Twice. Added On Servicing Package, Smooth & Comfortable Drive Pulling 95...

Posted: 21-May-2018 Tags: 2017 Toyota Prius, Toyota Prius, Toyota, Prius, Used Toyota



**Toyota C-HR Hybrid 1.8A G \$104,800 \$10,633 /yr 29-Dec-2017 1,797 cc 28 km SUV Available**

**Fuel Type:** Petrol-Electric

New Registered Vehicle. In House Flexible Loan Available. Make And Assemble In Japan. 8 Years Warranty! View To Appreciate. Call Now.

Tai Hwat Automobile

Posted: 23-May-2018 Tags: 2017 Toyota C-HR, 2017 Toyota C-HR, Toyota C-HR, Toyota C-HR, Toyota, C-HR, C-HR, Used Toyota



**Toyota Sienta Hybrid 1.5A G \$118,800 \$12,110 /yr 29-Dec-2017 1,486 cc 3,000 km MPV Available**

**Fuel Type:** Petrol-Electric

Pre-Owned Unit, Bidded Number To Go Along With The Car, Test Drive Available, 5 Year/100,000km Warranty, 1 Owner, Early/In-House Finance Available, Trade-In Available, Call To View This Beast Now, Etc...

Tan Wei Auto Pte Ltd

Posted: 20-May-2018 Tags: 2017 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



**Toyota C-HR Hybrid 1.8A S \$93,800 \$10,010 /yr 05-Jul-2017 1,797 cc 5,000 km SUV Available**

**Fuel Type:** Petrol-Electric

Almost New Toyota C-HR S Hybrid With Toyota C Sensing, Lane Departure, Pre-Collision Sensing, New Facelift Pearl White, 10% Down Payment 10 Years Repayment, In House Loan Or Balloon Scheme Available! ...

Trust Motoring

Posted: 20-May-2018 Tags: 2017 Toyota C-HR, 2017 Toyota C-HR, Toyota C-HR, Toyota C-HR, Toyota, C-HR, C-HR, Used Toyota



**Toyota C-HR Hybrid 1.8A G \$111,800 \$11,940 /yr 14-Jun-2017 1,797 cc 8,000 km SUV Available**

**Fuel Type:** Petrol-Electric

Almost New Toyota C-HR G Hybrid With C Sensing, Lane Departure, Pre-Collision Sensing, Paddle Shifters, New Facelift Pearl White, 10% Down Payment, 10 Years Repayment, In House Loan Or Balloon Scheme A...

Trust Motoring

Posted: 20-May-2018 Tags: 2017 Toyota C-HR, 2017 Toyota C-HR, Toyota C-HR, Toyota C-HR, Toyota, C-HR, C-HR, Used Toyota

**Toyota C-HR Hybrid 1.8A G \$105,800 \$11,240 /yr 23-Jun-2017 1,797 cc 15 km SUV Available**

**Fuel Type:** Petrol-Electric

LEU Version, Immediate Delivery, Special Promo, Various Color Available, Bank Loan In House Loan Available, Trade In Welcome.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 24 October 2018 10:14 AM  
**To:** 'Thanaletchumi Santerashigaram'  
**Cc:** SUR  
**Subject:** RE: SLV 583B OD (MSIG)

Dear Thana,

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Thanaletchumi Santerashigaram [mailto:[thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)]  
**Sent:** Tuesday, 23 October 2018 5:44 PM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** Re: SLV 583B OD (MSIG)

Greetings Ms. Shirley ,

Would accept the offer of \$11,323.54 before excess & GST @ 8 days.

Kindly revert.

*Thank You.*

*Best Regards ,  
S.Thanaletchumi (Ms)  
JACK CARS ENTERPRISE PTE LTD  
Office : 67488824  
Mobile : 92206746  
Fax : 67488834  
Email : [thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)*

On Mon, Oct 22, 2018 at 10:24 AM, Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)> wrote:

Hi Thana,

Please confirm final fig of \$11,323.54 (part by part) @ 8 days of repairs before excess \$ 500/- & GST.



Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]  
**Sent:** Monday, 4 June 2018 12:06 PM  
**To:** 'Thanaletchumi Santerashigaram' <[thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)>  
**Cc:** 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SLV 583B OD (MSIG)

Dear Thana,

As instructed by our client, please proceed to repair the insured vehicle **SLV 583B (Excess S 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel. 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 21 June 2018 5:00 PM  
**To:** 'Thanaletchumi Santerashigaram'  
**Cc:** "SUR"  
**Subject:** SLV 583B OD (MSG)  
**Attachments:** SUPPLEMENTARY 1.pdf; SUPPLEMENTARY 2.pdf

Dear Thana,

Supplementary approved, please proceed to repair the vehicle.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Thanaletchumi Santerashigaram <thana@jackcars.com.sg>  
**Sent:** Thursday, 7 June 2018 6:51 PM  
**To:** Shirley Hiew (LKK Auto); guoqiang@lkkauto.com  
**Cc:** SUR  
**Subject:** Re: SLV583B (SUPPLEMENTARY 2)  
**Attachments:** IMG-20180605-WA0004.jpg; IMG-20180605-WA0005.jpg; IMG-20180606-WA0012.jpg; IMG-20180606-WA0016.jpg; IMG-20180606-WA0017.jpg; IMG-20180606-WA0018.jpg; IMG-20180607-WA0007.jpg; IMG-20180607-WA0008.jpg; IMG-20180607-WA0009.jpg; IMG-20180607-WA0022.jpg; IMG-20180607-WA0023.jpg; IMG-20180607-WA0024.jpg; IMG-20180607-WA0025.jpg; IMG-20180607-WA0028.jpg; MARKED ESTIMATE.pdf

Greetings Ms. Shirley ,

Attached are the available photos from my end.

Kindly revert.

*Thank You.*

*Best Regards ,  
S.Thanaletchumi (Ms)  
JACK CARS ENTERPRISE PTE LTD  
Office : 67488824  
Mobile : 92206746  
Fax : 67488834  
Email : [thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)*

On Thu, Jun 7, 2018 at 4:53 PM, Thanaletchumi Santerashigaram <[thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)> wrote:  
Greetings Ms. Shirley ,

Attached would be the supplementary of SLV583B as requested.

Kindly revert.

*Thank You.*

*Best Regards ,  
S.Thanaletchumi (Ms)  
JACK CARS ENTERPRISE PTE LTD  
Office : 67488824  
Mobile : 92206746  
Fax : 67488834  
Email : [thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)*

On Thu, Jun 7, 2018 at 4:45 PM, Thanaletchumi Santerashigaram <[thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)> wrote:  
Greetings Ms. Shirley ,

Attached would be the before paint photos of SLV583B for your kind perusal.

Kindly revert.

**Thank You.**

**Best Regards ,  
S.Thanaletchumi (Ms)  
JACK CARS ENTERPRISE PTE LTD  
Office : 67488824  
Mobile : 92206746  
Fax : 67488834  
Email : [thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)**

On Thu, Jun 7, 2018 at 2:08 PM, Thanaletchumi Santerashigaram <[thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)> wrote:  
Greetings Ms. Shirley ,

Attached would be the supplementary for your kind perusal.

Kindly revert.

**Thank You.**

**Best Regards ,  
S.Thanaletchumi (Ms)  
JACK CARS ENTERPRISE PTE LTD  
Office : 67488824  
Mobile : 92206746  
Fax : 67488834  
Email : [thana@jackcars.com.sg](mailto:thana@jackcars.com.sg)**

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 4 June 2018 12:06 PM  
**To:** 'Thanaletchumi Santerashigaram'  
**Cc:** 'SUR'  
**Subject:** SLV 583B OD (MSIG)

Dear Thana,

As instructed by our client, please proceed to repair the insured vehicle **SLV 583B (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### View Received Message

This mail is associated with :

**SLV583B (559135)**  
OD  
May 22 2018 12:00PM  
[NEW REZKI RESTAURANT PTE LTD]  
Jack Cars Enterprise Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 19/10/2018 14:27 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11323.54) - SLV583B - Claim Handler: Winnie Chua Ping Ping

Approved:11323.54:a if c

#### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 19 Oct 2018

**Preliminary Advice**

Vehicle No	: SLV583B	Accident Date	: 22/05/2018
Make	: TOYOTA C-HR HYBRID	Policy No.	: 29065410MCX
Assignment Date	: 25/05/2018	Excess	: S\$500.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart Singapore 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,011.80
Revised Amount	:S\$	11,323.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,323.54
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,847.00

**Remarks**

- ( X ) The vehicle is economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.



## View Received Message

This mail is associated with :

**SLV583B (559135)**

OD

May 22 2018 12:00PM

[NEW REZKI RESTAURANT PTE LTD]

Jack Cars Enterprise Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 20/06/2018 20:47 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$12277.24) - SLV583B - Claim Handler: Winnie Chua Ping Ping

Approved:12277.24;a if c; check items to be confirmed

### DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 18 Jun 2018

**Preliminary Advice**

Vehicle No	: SLV583B	Accident Date	: 22/05/2018
Make	: TOYOTA C-HR HYBRID	Policy No.	: 29065410MCX
Assignment Date	: 25/05/2018	Excess	: S\$500.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart Singapore 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,692.50
Revised Amount	:S\$	11,232.24
Check Items (Estimated)	:S\$	1,045.00
Total	:S\$	12,277.24

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,847.00

**Remarks**

- ( X ) The vehicle is economical/not economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

## View Received Message

This mail is associated with :

**SLV583B (559135)**  
OD  
May 22 2018 12:00PM  
[NEW REZKI RESTAURANT PTE LTD]  
Jack Cars Enterprise Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 04/06/2018 11:55 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (5\$11231.24) - SLV583B - Claim Handler: Winnie Chua Ping Ping

Approved:11231.24:a if c; check items to be confirmed

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 01 Jun 2018

**Preliminary Advice**

Vehicle No	: SLV583B	Accident Date	: 22/05/2018
Make	: TOYOTA C-HR HYBRID	Policy No.	: 29065410MCX
Assignment Date	: 25/05/2018	Excess	: S\$500.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart Singapore 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,692.50
Revised Amount	:S\$	10,186.24
Check Items (Estimated)	:S\$	1,045.00
Total	:S\$	11,231.24

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,847.00

**Remarks**

- ( X ) The vehicle is economical/not economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No.199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 28 May 2018

**Preliminary Advice**

Vehicle No	: SLV583B	Accident Date	: 22/05/2018
Make	: TOYOTA C-HR HYBRID	Policy No.	: 29065410MCX
Assignment Date	: 25/05/2018	Excess	: S\$500.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart Singapore 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,692.50
Revised Amount	:S\$	11,310.50
Check Items (Estimated)	:S\$	594.00
Total	:S\$	11,904.50

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,847.00

**Remarks**

- ( X ) The vehicle is economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/05/2018 18:38
Date Of Accident	22/05/2018 12:00
Exact Location Of Accident	SEERVICE ROAD OF BAYSHORE PARK CONDO
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV583B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NEW REZKI RESTAURANT PTE LTD
Co Reg No	19960601K <b>604K</b>
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92314006
Alternative Phone No	OFFICE-92314006

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	51000918

### Driver

Name of Driver	KAKKAT MOHAMMAD RAOOF
Passport No/FIN	G1059612U
Date Of Birth	24/05/1984
Occupation	INDOOR
Date Of Driving Pass	19/08/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92314006
Fax Number	
Contact Number	
Email Address	RAOOF.KAKKAT@GMAIL.COM

Address	203 BEDOK NORTH STREET 1 #01-469
Postcode	460203
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

-----REFER TO ATTACHMENT -----

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC7843Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repealate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the receipt of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Singapore Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:



  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

**JACK CARS ENTERPRISE PTE LTD**  
 BLK 3007 UBI ROAD 1  
 #01-448 / 450 / 452  
 SINGAPORE 408701  
 TEL: 6746 8824 FAX: 6746 8834  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:





\* for record Purpose

JackCars Enterprise Pte Ltd

Claim Reference: JC / 2018 / SLV583B

Full Report - V1

Assessment Number: JC SLV583

Registration: SLV583B

Version: JACKCARS/3

Printed: 16/10/2018 09:22

Date Calculated: 31/05/2018 09:12

28	8402	1	AIR FILTER LWR HSG	17701 OT140	0%	180.00*
28	8401	1	AIR FILTER UPPER HSG	17705 OT170	0%	100.00*
25	8375	1	AIR INTAKE HOSE	17751 OT190	0%	160.00*
35	8405	1	AIR INTAKE PIPE	17752 OT060	0%	60.00*
11	471	1	BONNET	53301 F4010	0%	460.00*
16	481	1	BONNET INSULATION	53341 F4010	0%	210.00*
30	493	1	BONNET LOCK	53510 F4010	0%	180.00*
15	281	1	FRONT BUMPER	52119 F4900	0%	400.00*
16	375	1	FRONT LWR AIR GRILLE	52129 F4010	0%	260.00*
17	417	1	FRONT LWR ENGINE CVR	51420 F4010	0%	120.00*
30	1000	1	FRONT RIGHT TYRE	Renew	0%	220.00*
	350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS *	0%	50.00*
18	340	1	FRT BUMPER REINF	52131 F4020	0%	280.00*
4	1017	1	FRT LOCK CARRIER	53205 F4010	0%	180.00*
19	339	1	FRT LWR BUMPER REINF	52132 F4010	0%	160.00*
20	260	1	FRT NO PLATE REINF	52114 F4010	0%	70.00*
	41922	1	FRT UPP BUMPER REINF	52029 F4010	0%	160.00*
	1421	1	GRILLE	53114 F4010	0%	210.00*
	411g remove	1	GRILLE BADGE BRACKET	53112 F4010 *	0%	180.00*
36	9645	1	HORN	86520 02140	0%	120.00*
29	1000	1	HYBRID SPARE TANK	Renew	0%	160.00*
26	1029	1	INN REAR PANEL TRIM	53141 F4021	0%	110.00*
7	7793	1	L/BLOWER FAN	16361 OT180	0%	110.00*
23	351	1	L/F BUMPER COVER	52128 F4020	0%	70.00*
	34329	1	L/F BUMPER COVER	81482 F4020 € (1700 PROX. (D/WL))	0%	30.00*
34	475	1	L/F HINGE	53420 F4010	0%	80.00*
*	12 841	1	L/F WHEELHOUSE COVER	53876 F4021	0%	130.00*
*	13 741	1	L/F WING	53802 F4010	0%	290.00*
6	7797 remove	1	L/FAN MOTOR	16363 OT200 *	0%	200.00*
8	561	1	LEFT HEADLAMP ASSY	81170 F4010	0%	900.00*
3	431	1	MANUFACTURER BADGE	53141 47030	0%	330.00*
7	7794	1	R/BLOWER FAN	16361 OT190	0%	110.00*
33	352 remove	1	R/F BUMPER COVER	52127 F4020	0%	70.00*
34	476	1	R/F HINGE	53410 F4020	0%	80.00*
37	7202	1	R/F WHEEL	42611 F4020	0%	200.00*
*	12 842	1	R/F WHEELHOUSE COVER	53875 F4021	0%	130.00*
*	14 742	1	R/F WING	53801 F4010	0%	290.00*
	7776 remove	1	R/RADIATOR HOSE	16572 OT050 *	0%	160.00*
24	7761	1	RADIATOR CPL	16400 OT370	0%	650.00*
9	562	1	RIGHT HEADLAMP ASSY	81130 F4010	0%	900.00*
2	527	1	UPP RAD GRILLE SEAL	53395 F4010	0%	35.00*
31	410	1	UPP RADIATOR GRILLE	53111 F4901	0%	80.00*
11	1014	1	UPPER AIR GUIDE	16561 OT210	0%	150.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

(10 %)

Total Parts

\$9,025.00

\$902.50

\$9,927.50

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation

Total Parts

\$9,927.50

# For record  
Purpose

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: JC / 2018 / SLV583B  
Assessment Number: JC SLV583  
Version: LKKAUTOC/5

Full Report - V1  
Registration: SLV583B  
Printed: 01/06/2018 16:57

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	JC / 2018 / SLV583B	Estimated Repair Time:	
Policy Number:	51000918	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	TOYOTA
Model:	C-HR
Sub Model:	BASE MODEL
Model Sheet Number:	YCH 01
Registration:	SLV583B
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



#### Model Specs

1.8 LTR 100KW HYBRID	6-SPEED GEARBOX
WHEELS 6.5J X 16 ALU	


### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition: Steering:	Severity of Impact: Vehicle Status on Inspection:
Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:	Date of Inspection: 23/05/2018
Tyres Condition: Tread Depth LHF: Tread Depth LHR:	Tread Depth RHF: Tread Depth RHR:
Damage Areas:	Direction of Impact:



Primary Impact  
Secondary Impact



## Addresses

### Cost Summary

Total Labour	\$610.00
Total Paint/Material	\$115.74
Total Parts	\$10,455.50
Total of Additional Costs	\$50.00
Repair Cost Exc GST:	\$11,231.24
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	
Grand Total Exc GST:	\$10,731.24
7 % GST:	\$751.19
Grand Total Inc GST:	\$11,482.43

### Repair Information

#### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
Price/Dent = \$50.00/HR

#### Repair /

#### Guide Number Repair Details

		WU	Cost Price (\$)
B020)	R + R FRONT BUMPER UPP REINF	1.0	5.00
B020	RENEW COMPLETE FRONT BUMPER	20.0	100.00
	INCLUDES: FRONT BUMPER, RADIATOR GRILLE		
	LOWER GRILLE AND REQUIRED ATTACHED		
	PARTS		
	REMOVE AND REFIT		
B040	RENEW BOTH HEADLAMPS	5.0	25.00
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS		
B020)	RENEW FRONT BUMPER LOWER TRIM	2.0	10.00
	(BUMPER REMOVED)		
	INCLUDES: LWR ABSORBER REMOVE AND REFIT		
B020)	RENEW FRONT BUMPER REINFORCEMENT	3.0	15.00
	(BUMPER REMOVED)		
	INCLUDES: FRONT BUMPER ABSORBER		
	REMOVE AND REFIT		
B100	R + R LEFT FRONT WING	6.0	30.00
	INCLUDES: WHEELHOUSE LINER AND REQUIRED		
	ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLAMP AND		
	R + R BUMPER		
B100	R + R RIGHT FRONT WING	6.0	30.00
	INCLUDES: WHEELHOUSE LINER AND REQUIRED		
	ATTACHED PARTS R + R		
	NOT INCLUDED: HEADLAMP AND		

B070	R + R BUMPER RENEW BONNET	5.0	25.00
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW		
B080	R + R BONNET HINGE/S	1.0	5.00
B125	R + R FRONT LOCK CARRIER	2.0	10.00
B100	R + R L/SILL MOULDING	3.0	15.00
B100	R + R R/SILL MOULDING	3.0	15.00
M020	RENEW RADIATOR (BUMPER REMOVED)	19.0	95.00
	INCLUDES: HOSE, FAN HOUSING AND REQUIRED ATTACHED PARTS R + R. COOLING SYSTEM DRAIN/REFILL AND BLEED.		
420018)	R + R RIGHT FRONT WHEEL	1.0	5.00
420091)	R + R R/F TYRE AND WHEEL	2.0	10.00
042214)	BALANCE WHEEL/S	4.0	20.00
<b>LABOUR COST</b>			
	<b>Total Work Units</b>	<b>83.0</b>	
	<b>Sub Total</b>	<b>8.3HRS</b>	<b>\$415.00</b>
	<b>Paint Labour</b>	<b>3.9HRS</b>	<b>195.00</b>
	<b>Total Labour</b>	<b>12.2HRS</b>	<b>\$610.00</b>

<b>PAINT WORK</b>		Time Basis 10 WU = 1 HR. Price = \$0.00/HR	
Guide Number	Description	WU	Cost Price (\$)
471	BONNET NEW PART PAINTING	21.0	
281	FRONT BUMPER NEW PART PAINT K1R	8.0	
<b>LABOUR COST - PAINT</b>			
	<b>TIME(PAINT)</b>	<b>29.0</b>	
	Preparation Main Work Metal	7.0	
	Preparation Comp. Work Plastic	3.0	
	Preparation Work Multi Layer Paint	0.0	
	<b>Total Work Units (10WU/HR)</b>	<b>39.0</b>	
	<b>Total Paintwork Labour</b>	<b>3.9HRS</b>	<b>\$195.00</b>
<b>MATERIAL COST - PAINT</b>			<b>Cost Price</b>
	New Part Painting		\$57.23
	New Part Painting - Plastic K1R		\$31.41
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	<b>Total Excluding Pearlescent Uplift</b>		<b>\$115.74</b>
	<b>Pearlescent Uplift @ 0.0%</b>		<b>\$0.00</b>
	<b>Total Paint Material Cost</b>		<b>\$115.74</b>

**PARTS**

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
8402	1	AIR FILTER LWR HSG	17701 0T140		0%	180.00* CRA
1000	1	AIR FILTER PIPE	Renew		0%	160.00* CR
8401	1	AIR FILTER UPPER HSG	17705 0T170		0%	100.00* CRA
8375	1	AIR INTAKE HOSE	17751 0T190		0%	160.00* BT
8405	1	AIR INTAKE PIPE	17752 0T060		0%	60.00* DM
1000	1	AIRCON CONDENSOR	Renew		0%	650.00* BT
471	1	BONNET	53301 F4010		0%	460.00* BUC

QTY	DESCRIPTION	PART NO	UNIT	PRICE	REMARKS
481	BONNET INSULATION	53341 F4010		210.00*	BT
493	BONNET LOCK	53510 F4010		180.00*	DM
281	FRONT BUMPER	52119 F4900		400.00*	DD
1000	FRONT BUMPER SPONGE	Renew		180.00*	DM
375	FRONT LWR AIR GRILLE	52129 F4010		260.00*	CRA
417	FRONT LWR ENGINE CVR	51420 F4010		120.00*	CUT
1000	FRONT RIGHT TYRE	Renew		220.00*	TN
340	FRT BUMPER REINF	52131 F4020		280.00*	BT
1000	FRT GRILLE SUPPORT P	Renew		180.00*	BT
339	FRT LWR BUMPER REINF	52132 F4010		160.00*	BT
260	FRT NO PLATE REINF	52114 F4010		70.00*	DIS
1000	FRT PARKING SENSOR	Renew		120.00*	DM
419	FRT UPP BUMPER REINF	52029 F4010		160.00*	BT
421	GRILLE	53114 F4010		210.00*	CRA
411	GRILLE BADGE BRACKET	53112 F4010		180.00*	?
9645	HORN	86520 02140		120.00*	?
1000	HYBRID SPARE TANK	Renew	nr photo to be provided	160.00*	?
1029	INN REAR PANEL TRIM	53141 F4021		110.00*	BT
7793	L/BLOWER FAN	16361 0T180		110.00*	CUT
351	L/F BUMPER COVER	52128 F4020		70.00*	CUT
343	L/F BUMPER COVER	81482 F4020		30.00*	CRA
475	L/F HINGE	53420 F4010		80.00*	DM
841	L/F WHEELHOUSE COVER	Renew		130.00*	?
561	LEFT HEADLAMP ASSY	81170 F4010		900.00*	CRA
431	MANUFACTURER BADGE	53141 47030		330.00*	CUT
7794	R/BLOWER FAN	16361 0T190		110.00*	CUT
352	R/F BUMPER COVER	52127 F4020		70.00*	?
476	R/F HINGE	53410 F4020		80.00*	DM
7202	R/F WHEEL	42611 F4020		200.00*	CUT
842	R/F WHEELHOUSE COVER	Renew		130.00*	?
7776	R/RADIATOR HOSE	16572 0T050		160.00*	?
7761	RADIATOR CPL	16400 0T370		650.00*	DD
1000	RADIATOR FAN COVER	Renew		200.00*	CRA
562	RIGHT HEADLAMP ASSY	81130 F4010		900.00*	CRA
527	UPP RAD GRILLE SEAL	53395 F4010		35.00*	BT
410	UPP RADIATOR GRILLE	53111 F4901		80.00*	BR
1014	UPPER AIR GUIDE	16561 0T210		150.00*	DIS
f: OEM Parts			Sub Total	\$9,505.00	
g: Original			<b>Total Parts</b>	<b>\$10,455.50</b>	
h: Secondhand					
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
FRT BUMPER CLAMP SPECIALIST KIT	0%	\$50.00
<b>Total Extras</b>		<b>\$50.00</b>

**Final Calculation**

<b>Total Parts</b>	<b>\$10,455.50</b>
<b>Labour</b>	
Total Panel/Mechanical	\$415.00
Total Paintwork	\$195.00

<b>Total Labour</b>		<b>\$610.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$50.00	
<b>Total of Additional Costs</b>		<b>\$50.00</b>
<b>Total Paint/Material Costs</b>		<b>\$115.74</b>
<b>Repair Costs Excludes GST</b>		<b>\$11,231.24</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$500.00	
<b>Total Deductions</b>		<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$10,731.24</b>
GST @ 7 %		<b>\$751.19</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$11,482.43</b>

### Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attr: Winnie Chua Ping Ping

Date: 18 Jun 2018

**Preliminary Advice**

Vehicle No	: SLV583B	Accident Date	: 22/05/2018
Make	: TOYOTA C-HR HYBRID	Policy No.	: 29065410MCX
Assignment Date	: 25/05/2018	Excess	: S\$500.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 8 days
Inspection At	: Jack Cars Enterprise Pte Ltd (HQ) 61 Ubi Avenue 2, #01-20 Automobile Megamart Singapore 408898		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,692.50
Revised Amount	:S\$	11,232.24
Check Items (Estimated)	:S\$	1,045.00
Total	:S\$	12,277.24

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,153.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,847.00

**Remarks**

( X ) The vehicle is economical/not economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.



67441900 88200

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	JC.2018.SLV583B
Policy No:	29065410MCX	Date of Loss:	22/05/2018
Vehicle Reg. No.:	SLV583B	Driveable?	NO
Driver Age/Info:	33 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NEW REZKI RESTAURANT PTE LTD	Contact No:	+6592314006
Driver:	KAKKAT MOHAMMAD RAOOF		

Make/Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Vehicle Reg. Date:	21/12/2017
Vehicle Colour:	Brown		
Engine No:	2ZR8202510	Chassis No:	ZYX102078200
Odometer:	3000 KM		

Paint Type:  
 Total Loss? **NO**  
 Est. Duration of Repair (day) 12

Description of Accident/Loss -----REFER TO ATTACHMENT -----  
 Present Location: JACK CARS ENTERPRISE PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	10,642.50
Miscellaneous Items	50.00
Labour	3,000.00
Paintwork Labour	0.00
Towing	0.00
	Calculated Gross Total (S\$) <b>13,692.50</b>
	- Excess (S\$) 500.00
	(S\$) 13,192.50
	+ GST 7.00% (S\$) 923.48
	Nett Amount (S\$) <b>14,115.98</b>

15011.31

This claim is handled by: **THANALETCHUMI SANTERASHIGARM**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DOI 25/5/18

1730 hr

Surveyed by Simon & TG Lim LKK

Not authorized w/s

Resurvey before paint

Repair 8 days

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 May 2018)  
 Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Jack Cars Enterprise Pte Ltd/SLV583B/23/05/2018 16:06  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT GRILLE	0.00	0.00	*210.00 F	CRA
2	1		*FRONT GRILLE WEATHERSTRIP	0.00	0.00	*35.00 F	BT
3	1		*FRONT TOYOTA EMBLEM	0.00	0.00	*330.00 F	MCV
4	1		*FRONT GRILLE SUPPORT PANEL	0.00	0.00	*180.00 F	BT
5	1		*AIRCON CONDENSOR	0.00	0.00	*650.00 F	BT
6	1		*RADIATOR FAN COVER	0.00	0.00	*200.00 F	CRA
7	1		*RADIATOR FAN FIN x 2	0.00	0.00	*220.00 F	CNT
8	1		*HEADLAMP LEFT	0.00	0.00	*900.00 F	CRA
9	1		*HEADLAMP RIGHT	0.00	0.00	*900.00 F	CRA
10	1		*BONNET INNER COVER <i>with subloter</i>	0.00	0.00	*210.00 F	BT
11	1		*BONNET	0.00	0.00	*460.00 F	BUC
12	1		*LEFT & RIGHT MUDGUARD	0.00	0.00	*260.00 F	BSVC
13	1		*FRONT LEFT FENDER	0.00	0.00	*290.00 F	R
14	1		*FRONT RIGHT FENDER	0.00	0.00	*290.00 F	R
15	1		*FRONT BUMPER	0.00	0.00	*400.00 F	DD
16	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*260.00 F	CRA
17	1		*FRONT BUMPER LOWER GRILLE COVER	0.00	0.00	*120.00 F	CNT
18	1		*TOP SUPPORT BEAM	0.00	0.00	*280.00 F	BT
19	1		*LOWER SUPPORT BEAM	0.00	0.00	*160.00 F	BT
20	1		*FRONT NUMBER PLATE BRACKET <i>Garrigh</i>	0.00	0.00	*70.00 F	DIS
21	1		*FRONT BUMPER TOP COVER	0.00	0.00	*150.00 F	DIS
22	1		*FRONT TOP SUPPORT PANEL	0.00	0.00	*160.00 F	BT
23	1		*FRONT LOWER PANEL COVER	0.00	0.00	*70.00 F	CRA
24	1		*RADIATOR	0.00	0.00	*650.00 F	DD
25	1		*AIRCON PIPE	0.00	0.00	*160.00 F	BT
26	1		*TOP REINFORCEMENT PANEL	0.00	0.00	*110.00 F	BT
27	1		*TOW HOOK COVER	0.00	0.00	*30.00 F	CNT
28	1		*AIR FILTER HOUSING	0.00	0.00	*280.00 F	CRA
29	1		*AIR FILTER PIPE x 2	0.00	0.00	*160.00 F	CRA
30	1		*BONNET LOCK	0.00	0.00	*180.00 F	DM
31	1		*BUMPER GRILLE	0.00	0.00	*80.00 F	BT
32	1		*FRONT PARKING SENSOR <i>x 2</i>	0.00	0.00	*120.00 F	dm
33	1		*FRONT BUMPER SPONGE x 2	0.00	0.00	*180.00 F	dm
34	1		*BONNET HINGE x 2	0.00	0.00	*160.00 F	dm
35	1		*AIR BOX INTAKE	0.00	0.00	*60.00 F	dm
36	1		*HORN	0.00	0.00	*120.00 F	dm
37	1		*FRONT RIGHT RIM	0.00	0.00	*200.00 F	BT
38	1		*FRONT RIGHT TYRE	0.00	0.00	*220.00 F	BT
39	1		*HYBRID SPARE TANK <i>photo to be provided</i>	0.00	0.00	*160.00 F	BT
						F=Franchise part.	
						Sub Total (\$\$)	9,675.00
						+ Margin on L,N Items 10.00% (\$\$)	967.50
						Total Parts (\$\$)	10,642.50

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	CLIPS ✓	50.00 <i>nee</i>
Sub Total (S\$)			<u>50.00</u>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	195 ✓ 1,300.00 <i>1000</i>
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	415 / 1,600.00 <i>800</i>
3	TO CHECK WIRING & REWIRE	New	- 80.00 <i>50 x</i>
4	TO CHECK LIGHTING SYSTEM & WATER TEST FOR ANY LEAKAGE	New	420.00 <i>x</i>
Gross Labour Cost (S\$)			<u>3,000.00</u> <i>1850</i>

Jack Cars Enterprise Pte Ltd/SLV583B/23/05/2018 16:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Paint/material costs*

*\$ 115.74*


**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~ is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SUPPLEMENTARY

DATE OF ACCIDENT : 22/05/2018
VEHICLE : SLV583B
MAKE & MODEL : TOYOTA CHR
INSURANCE : MSIG
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	LEFT WHEEL ARCH		\$ 120
2.	AIR GUIDE		\$ 90
3.	RADIATOR SEAL		\$ 100
4.	FRONT SUPPORT BEAM BRACKET - LEFT		\$ 150
5.	FRONT SUPPORT BEAM BRACKET - RIGHT		\$ 150
SPECIAL NETT			
1.	AIRCON GAS / Sale		<del>\$ 80</del>
2.	COOLANT / Sale		<del>\$ 50</del>
	<b>PARTS :</b>	\$ 610	
	<b>SPECIAL NETT :</b>	\$ 130	
	<b>7% GST :</b>	\$ 51.80	
	<b>GRAND TOTAL :</b>	\$ 791.80	

DM  
X(NC)  
TV  
CMT  
DD  
DD  
30  
30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# SUPPLEMENTARY

<b>DATE OF ACCIDENT :</b> 22/05/2018
<b>VEHICLE :</b> SLV583B
<b>MAKE &amp; MODEL :</b> TOYOTA CHR
<b>INSURANCE :</b> MSIG
<b>SURVEYOR :</b> LKK AUTO

PARTS		CONDITION	COST
1.	AIRBOX LOWER BRACKET / BT		\$ 78
2.	OUTSIDE TEMP SENSOR / DM		\$ 65
3.	CENTRE SUPPORT BEAM / BT		\$ 280
4.	AIR FILTER / RE.		\$ 28
5.	Front number plate / BT	<b>PARTS :</b>	\$ 423
		<b>7% GST :</b>	\$ 29.61
		<b>GRAND TOTAL :</b>	\$ 452.61

32/W

*Gano Q.M.P.*

*LKK  
05/6/18*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject in confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

51 Ubi Avenue 1, #01-25  
Paya Ubi Industrial Park  
Singapore  
408933

Claim Reference: JC / 2018 / SLV583B  
Assessment Number: JC SLV583  
Version: LKKAUTO/9  
Date Calculated: 17/10/2018 04:41

Full Report - V1  
Registration: SLV583B  
Printed: 17/10/2018 11:46

## Summary Information

### Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	JC / 2018 / SLV583B	Estimated Repair Time:	
Policy Number:	51000918	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

### Vehicle Details

#### Vehicle

Manufacturer:	TOYOTA
Model:	C-HR
Sub Model:	BASE MODEL
Model Sheet Number:	YCH 01
Registration:	SLV583B
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



#### Model Specs

1.8 LTR 100KW HYBRID	6-SPEED GEARBOX
WHEELS 6.5J X 16 ALU	

### Vehicle Condition

#### Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Primary Impact →  
Secondary Impact - - - - - →

**Addresses**

**Cost Summary**

Total Labour	\$610.00
Total Paint/Material	\$115.74
Total Parts	\$10,414.80
Total of Additional Costs	\$183.00
Repair Cost Exc GST:	\$11,323.54
Overall Discount (0.0%):	- \$0.00
Excess:	-\$500.00
After Deduction -	Grand Total Exc GST: \$10,823.54
	7 % GST: \$757.65
	Grand Total Inc GST: \$11,581.19

**Repair Information**

**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR  
Price/Dent = \$50.00/HR

**Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
B020)	R + R FRONT BUMPER UPP REINF	1.0	5.00
B020	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, RADIATOR GRILLE LOWER GRILLE AND REQUIRED ATTACHED PARTS	20.0	100.00
B040	REMOVE AND REFIT RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	5.0	25.00
B020)	RENEW FRONT BUMPER LOWER TRIM (BUMPER REMOVED) INCLUDES: LWR ABSORBER REMOVE AND REFIT	2.0	10.00
B020)	RENEW FRONT BUMPER REINFORCEMENT (BUMPER REMOVED) INCLUDES: FRONT BUMPER ABSORBER REMOVE AND REFIT	3.0	15.00
B100	R + R LEFT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	6.0	30.00
B100	R + R RIGHT FRONT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R	6.0	30.00

	NOT INCLUDED: HEADLAMP AND R + R BUMPER		
B070	RENEW BONNET	5.0	25.00
	INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW		
B080	R + R BONNET HINGE/S	1.0	5.00
B125	R + R FRONT LOCK CARRIER	2.0	10.00
B100	R + R L/SILL MOULDING	3.0	15.00
B100	R + R R/SILL MOULDING	3.0	15.00
M020	RENEW RADIATOR (BUMPER REMOVED)	19.0	95.00
	INCLUDES: HOSE, FAN HOUSING AND REQUIRED ATTACHED PARTS R + R. COOLING SYSTEM DRAIN/REFILL AND BLEED.		
420018)	R + R RIGHT FRONT WHEEL	1.0	5.00
420091)	R + R R/F TYRE AND WHEEL	2.0	10.00
042214)	BALANCE WHEEL/S	4.0	20.00
	<b>LABOUR COST</b>		
	<b>Total Work Units</b>	83.0	
	<b>Corrosion Protection External Labour</b>	0.0HRS	0.00
	<b>Corrosion Protection Internal Labour</b>	0.0HRS	0.00
	<b>Sub Total</b>	8.3HRS	\$415.00
	<b>Paint Labour</b>	3.9HRS	\$195.00
	<b>Total Labour</b>	12.2HRS	\$610.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$0.00/HR	
Guide Number	Description	WU	Cost Price (\$)
471	BONNET NEW PART PAINTING	21.0	
281	FRONT BUMPER NEW PART PAINT K1R	8.0	
	<b>LABOUR COST - PAINT</b>		
	<b>TIME(PAINT)</b>	29.0	
	Preparation Main Work Metal	7.0	
	Preparation Comp. Work Plastic	3.0	
	Preparation Work Multi Layer Paint	0.0	
	<b>Total Work Units (10WU/HR)</b>	39.0	
	<b>Total Paintwork Labour</b>	3.9HRS	\$195.00
	<b>MATERIAL COST - PAINT</b>		Cost Price
	New Part Painting		\$57.23
	New Part Painting - Plastic K1R		\$31.41
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	<b>Total Excluding Pearlescent Uplift</b>		\$115.74
	Pearlescent Uplift @ 0.0%		\$0.00
	<b>Total Paint Material Cost</b>		\$115.74

**PARTS**

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
8402	1	AIR FILTER LWR HSG	17701 0T140			0%	180.00*
1000	1	AIR FILTER PIPE	Renew			0%	160.00*
8401	1	AIR FILTER UPPER HSG	17705 0T170			0%	100.00*



51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: JC / 2018 / SLV583B

Full Report - V1

Assessment Number: JC SLV583

Registration: SLV583B

Version: LKKAUTOC/9

Printed: 17/10/2018 11:46

Date Calculated: 17/10/2018 04:41

1000	1	AIR GUIDE	Renew	0%	90.00*
8375	1	AIR INTAKE HOSE	17751 0T190	0%	160.00*
8405	1	AIR INTAKE PIPE	17752 0T060	0%	60.00*
1000	1	AIRBOX LOWER BRACKET	Renew	0%	78.00*
1000	1	AIRCON CONDENSOR	Renew	0%	650.00*
471	1	BONNET	53301 F4010	0%	460.00*
481	1	BONNET INSULATION	53341 F4010	0%	210.00*
493	1	BONNET LOCK	53510 F4010	0%	180.00*
1000	1	CENTRE SUPPORT BEAM	Renew	0%	280.00*
281	1	FRONT BUMPER	52119 F4900	0%	400.00*
1000	1	FRONT BUMPER SPONGE	Renew	0%	180.00*
375	1	FRONT LWR AIR GRILLE	52129 F4010	0%	260.00*
417	1	FRONT LWR ENGINE CVR	51420 F4010	0%	120.00*
1000	1	FRONT RIGHT TYRE	Renew	0%	220.00*
340	1	FRT BUMPER REINF	52131 F4020	0%	280.00*
1000	1	FRT GRILLE SUPPORT P	Renew	0%	180.00*
339	1	FRT LWR BUMPER REINF	52132 F4010	0%	160.00*
260	1	FRT NO PLATE REINF	52114 F4010	0%	70.00*
1000	1	FRT PARKING SENSOR	Renew	0%	120.00*
1000	1	FRT SUPP BEAM BRK LF	Renew	0%	150.00*
1000	1	FRT SUPP BEAM BRK RF	Renew	0%	150.00*
419	1	FRT UPP BUMPER REINF	52029 F4010	0%	160.00*
421	1	GRILLE	53114 F4010	0%	210.00*
1029	1	INN REAR PANEL TRIM	53141 F4021	0%	110.00*
7793	1	L/BLOWER FAN	16361 0T180	0%	110.00*
351	1	L/F BUMPER COVER	52128 F4020	0%	70.00*
475	1	L/F HINGE	53420 F4010	0%	80.00*
561	1	LEFT HEADLAMP ASSY	81170 F4010	0%	900.00*
431	1	MANUFACTURER BADGE	53141 47030	0%	330.00*
1000	1	OUTSIDE TEMP SENSOR	Renew	0%	65.00*
7794	1	R/BLOWER FAN	16361 0T190	0%	110.00*
476	1	R/F HINGE	53410 F4020	0%	80.00*
7202	1	R/F WHEEL	42611 F4020	0%	200.00*
7761	1	RADIATOR CPL	16400 0T370	0%	650.00*
1000	1	RADIATOR FAN COVER	Renew	0%	200.00*
1000	1	RADIATOR SEAL	Renew	0%	100.00*
562	1	RIGHT HEADLAMP ASSY	81130 F4010	0%	900.00*
1000	1	TOW HOOK COVER	Renew	0%	30.00*
527	1	UPP RAD GRILLE SEAL	53395 F4010	0%	35.00*
410	1	UPP RADIATOR GRILLE	53111 F4901	0%	80.00*
1014	1	UPPER AIR GUIDE	16561 0T210	0%	150.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

\$9,468.00

Mark Up From Cost (10 %)

\$946.80

**Total Parts**

**\$10,414.80**

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Extras**

Description	Betterment	Price
FRT BUMPER CLAMP SPECIALIST KIT	0%	\$50.00
AIR FILTER SPECIALIST		\$28.00

FRONT NUMBER	SPECIALIST	0%	\$25.00
PLATE			
AIRCON GAS	SPECIALIST		\$50.00
COOLANT	SPECIALIST	0%	\$30.00
<b>Total Extras</b>			<b>\$183.00</b>

**Final Calculation**

<b>Total Parts</b>		<b>\$10,414.80</b>
<b>Labour</b>		
Total Panel/Mechanical	\$415.00	
Total Paintwork	\$195.00	
<b>Total Labour</b>		<b>\$610.00</b>
<b>Additional Costs</b>		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$183.00	
<b>Total of Additional Costs</b>		<b>\$183.00</b>
<b>Total Paint/Material Costs</b>		<b>\$115.74</b>
<b>Repair Costs Excludes GST</b>		<b>\$11,323.54</b>
<b>Deductions</b>		
Deduction for Excess ( Fixed )	-\$500.00	
<b>Total Deductions</b>		<b>-\$500.00</b>
<b>Grand Total Excludes GST (After Deduction)</b>		<b>\$10,823.54</b>
GST @ 7 %		<b>\$757.65</b>
<b>Grand Total Includes GST (After Deduction)</b>		<b>\$11,581.19</b>

**Assessment Notes**

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 May 2018 <a href="#">Sendback Est</a>	18 Oct 2018 11:58 <b>S\$15,011.80</b>	25 May 2018 09:28 <a href="#">Edit Adj Rpt</a>	<b>S\$11,323.54</b> <a href="#">Edit Estimates</a>	<b>S\$11,323.54</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

















































  

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>NEW REZKI RESTAURANT PTE LTD.</b> Co. Reg. No.: 19960601K, Tel: +6592314006								
Vehicle Reg. No.:	<b>SLV583B</b>	Date of Loss:	22/05/2018 12:00 - :59 [5 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 559135</b>	Policy/Cover Note No.:	29065410MCX (Comprehensive) Coverage: 21/12/2017 - 20/12/2018						
		Excess:	S\$500.00						
Repairer:	<b>Jack Cars Enterprise Pte Ltd (HQ)</b> 61 Ubi Avenue 2, #01-20 Automobile Megamart, 408898 Ubi - Tel: 67441900								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Winnie Chua Ping Ping</b> - 6594 2556]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 24/06/2018]								
Driver/Custodian:	KAKKAT MOHAMMAD RAOOF (33 / Male), NRIC: G10S9612U, Tel: +6592314006								
Adj Asg. Remarks:	Survey TODAY and REVERT. Car at Blk 3007 Ubi Rd 1 #01-450 S408701.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>• MSIG_SG (19/10/2018): <b>Alert - Adj Mandate Approved (S\$11323.54) - SLV583B - Claim Handler: Winnie Chua...</b></li> <li>• MSIG_SG (20/06/2018): <b>Alert - Adj Mandate Approved (S\$12277.24) - SLV583B - Claim Handler: Winnie Chua...</b></li> <li>• MSIG_SG (04/06/2018): <b>Alert - Adj Mandate Approved (S\$11231.24) - SLV583B - Claim Handler: Winnie Chua...</b></li> <li>• MSIG_SG (30/05/2018): <b>Alert - Adj Mandate Approved (S\$0.00) - SLV583B - Claim Handler: Winnie Chua Pin...</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SLV583B (559135)  
OD  
May 22 2018 12:00PM  
[NEW REZKI RESTAURANT PTE LTD]  
Jack Cars Enterprise Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser <input type="button" value="v"/>
<b>Assessment Reports</b>			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)		Thumbnail Print
1	22/05/18 18:47	<b>Accident Statement</b>	1	Load HTM <input type="checkbox"/>
2	18/10/18 11:58	<b>Repairer Estimates</b>	1	Load HTM <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/05/18 17:43	<b>Adjuster Immediate Advice</b>	1	Load HTM <input type="checkbox"/>
2	01/06/18 17:32	<b>Adjuster Immediate Advice</b>	1	Load HTM <input type="checkbox"/>
3	18/06/18 11:55	<b>Adjuster Immediate Advice</b>	1	Load HTM <input type="checkbox"/>
4	19/10/18 10:02	<b>Adjuster Immediate Advice</b>	1	Load HTM <input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)		Thumbnail Print
1	22/05/18 18:46	<b>Accident Photo 1</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
2	22/05/18 18:46	<b>Accident Photo 2</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
3	22/05/18 18:46	<b>Accident Photo 3</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
4	22/05/18 18:46	<b>Accident Photo 4</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
5	22/05/18 18:46	<b>Accident Photo 5</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
6	22/05/18 18:46	<b>Accident Photo 6</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
7	22/05/18 18:46	<b>Accident Photo 7</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
8	22/05/18 18:46	<b>Accident Photo 8</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
9	22/05/18 18:46	<b>Accident Photo 9</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
10	22/05/18 18:46	<b>Accident Photo 10</b> [Linked Accident Report Documents]	1	Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
2	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
3	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
4	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
5	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
6	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
7	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
8	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
9	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
10	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
11	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
12	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
13	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
14	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
15	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>
16	28/05/18 17:48	<b>General View</b>	1	Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
17	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/05/18 17:48	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
43	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/05/18 17:48	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
52	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
61	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
62	28/05/18 17:48	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/06/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/06/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/06/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/06/18 11:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
67	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
68	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
69	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
70	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
71	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
72	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
73	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
74	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
75	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
76	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
77	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
78	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
79	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
80	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
81	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
82	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
83	18/06/18 11:46	Dismantled Parts		<input checked="" type="checkbox"/>
84	18/10/18 15:36	Dismantled Parts		<input checked="" type="checkbox"/>
85	18/10/18 15:36	Dismantled Parts		<input checked="" type="checkbox"/>
86	18/10/18 15:36	Dismantled Parts		<input checked="" type="checkbox"/>
87	18/10/18 15:36	Dismantled Parts		<input checked="" type="checkbox"/>
88	18/10/18 15:36	Dismantled Parts		<input checked="" type="checkbox"/>
89	18/10/18 15:37	Reinspection Photo		<input checked="" type="checkbox"/>
90	18/10/18 15:37	Reinspection Photo		<input checked="" type="checkbox"/>
91	18/10/18 15:37	Reinspection Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 17:00	AUDATEX ESTIMATE		<input type="checkbox"/>
2	31/05/18 16:25	AUDATEX AMENDED ESTIMATE		<input type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 16:50	SUPPLEMENTARY 1		<input type="checkbox"/>
2	21/06/18 16:50	SUPPLEMENTARY 2		<input type="checkbox"/>
3	19/10/18 09:56	ESTIMATE MARKED.pdf		<input type="checkbox"/>
4	19/10/18 09:56	JCSLV583.AudatexMS.pdf		<input type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 18:47	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 18:46	Accident Photo 1		<input checked="" type="checkbox"/>
2	22/05/18 18:46	Accident Photo 2		<input checked="" type="checkbox"/>
3	22/05/18 18:46	Accident Photo 3		<input checked="" type="checkbox"/>
4	22/05/18 18:46	Accident Photo 4		<input checked="" type="checkbox"/>
5	22/05/18 18:46	Accident Photo 5		<input checked="" type="checkbox"/>
6	22/05/18 18:46	Accident Photo 6		<input checked="" type="checkbox"/>
7	22/05/18 18:46	Accident Photo 7		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
8	22/05/18 18:46	<b>Accident Photo 8</b>	 Load JPG	<input checked="" type="checkbox"/>
9	22/05/18 18:46	<b>Accident Photo 9</b>	 Load JPG	<input checked="" type="checkbox"/>
10	22/05/18 18:46	<b>Accident Photo 10</b>	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jack Cars Enterprise Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 18:47	<b>Sketch Plan</b>	 Load TIFF	
2	22/05/18 18:47	<b>Sketch Plan #2</b>	 Load TIFF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="text-align: right;"> <span>^</span>  <span>v</span> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG18009529/GSD3E2

**Date:** 24/10/2018

#### REFERENCE

Insured/Claimant:	NEW REZKI RESTAURANT PTE LTD	Policy No:	29065410MCX
Date of Loss:	22/05/2018	Nature of Claim:	OD
			Claim No: 559135

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV583B	Engine No:	2ZR8202510
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102078200
Reg. Date:	21/12/2017 (Man. Year: 2017)	Odometer:	3960 km
Colour:	Metallic Brown		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$96,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,778.80	10,414.80	1,364.00	11.58
Miscellaneous Items	233.00	183.00	50.00	21.46
Labour	3,000.00	725.74	2,274.26	75.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,011.80</b>	<b>11,323.54</b>	<b>3,688.26</b>	<b>24.57</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	14,511.80	10,823.54	3,688.26	25.42
<b>+ GST 7.00/7.00% (S\$)</b>	1,015.83	757.65	258.18	25.42
<b>Nett Amount (S\$)</b>	<b>15,527.63</b>	<b>11,581.19</b>	<b>3,946.44</b>	<b>25.42</b>

#### INSPECTION

Date of Assignment:	25/05/2018	Present Location:	Jack Cars Enterprise Pte Ltd (HQ)
Date Inspected:	25/05/2018	Inspected At:	Jack Cars Enterprise Pte Ltd (HQ) BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700
Estimated Period of Repair:	8.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** Hiew May Fung



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2018)
<b>Parts:</b> M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV583B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE (WCP)	Cracked	210.00 F	*210.00 F
2	1		*FRONT GRILLE WEATHERSTRIP (WCP)	Bent	35.00 F	*35.00 F
3	1		*FRONT TOYOTA EMBLEM (WCP)	Cut	330.00 F	*330.00 F
4	1		*FRONT GRILLE SUPPORT PANEL (WCP)	Bent	180.00 F	*180.00 F
5	1		*AIRCON CONDENSOR (WCP)	Bent	650.00 F	*650.00 F
6	1		*RADIATOR FAN COVER (WCP)	Cracked	200.00 F	*200.00 F
7	1		*RADIATOR FAN FIN x 2 (WCP)	Cut	220.00 F	*220.00 F
8	1		*HEADLAMP LEFT (WCP)	Cracked	900.00 F	*900.00 F
9	1		*HEADLAMP RIGHT (WCP)	Cracked	900.00 F	*900.00 F
10	1		*BONNET INNER COVER (WCP)	Bent	210.00 F	*210.00 F
11	1		*BONNET (WCP)	Buckled	460.00 F	*460.00 F
12	1		*LEFT & RIGHT MUDGUARD (WCP)	Serviceable	260.00 F	*- F
13	1		*FRONT LEFT FENDER (WCP)	Repair	290.00 F	*- F
14	1		*FRONT RIGHT FENDER (WCP)	Repair	290.00 F	*- F
15	1		*FRONT BUMPER (WCP)	Dented	400.00 F	*400.00 F
16	1		*FRONT BUMPER LOWER GRILLE (WCP)	Cracked	260.00 F	*260.00 F
17	1		*FRONT BUMPER LOWER GRILLE COVER (WCP)	Cut	120.00 F	*120.00 F
18	1		*TOP SUPPORT BEAM (WCP)	Bent	280.00 F	*280.00 F
19	1		*LOWER SUPPORT BEAM (WCP)	Bent	160.00 F	*160.00 F
20	1		*FRONT NUMBER PLATE BRACKET (WCP)	Distorted	70.00 F	*70.00 F
21	1		*FRONT BUMPER TOP COVER (WCP)	Distorted	150.00 F	*150.00 F
22	1		*FRONT TOP SUPPORT PANEL (WCP)	Bent	160.00 F	*160.00 F
23	1		*FRONT LOWER PANEL COVER (WCP)	Cracked	70.00 F	*70.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*RADIATOR (WCP)	Dented	650.00 F	*650.00 F
25	1		*AIRCON PIPE (WCP)	Bent	160.00 F	*160.00 F
26	1		*TOP REINFORCEMENT PANEL (WCP)	Bent	110.00 F	*110.00 F
27	1		*TOW HOOK COVER (WCP)	Cut	30.00 F	*30.00 F
28	1		*AIR FILTER HOUSING (WCP)	Cracked	280.00 F	*280.00 F
29	1		*AIR FILTER PIPE x 2 (WCP)	Cracked	160.00 F	*160.00 F
30	1		*BONNET LOCK (WCP)	Damaged	180.00 F	*180.00 F
31	1		*BUMPER GRILLE (WCP)	Bent	80.00 F	*80.00 F
32	1		*FRONT PARKING SENSOR (WCP)	Damaged	120.00 F	*120.00 F
33	1		*FRONT BUMPER SPONGE x 2 (WCP)	Damaged	180.00 F	*180.00 F
34	1		*BONNET HINGE x 2 (WCP)	Damaged	160.00 F	*160.00 F
35	1		*AIR BOX INTAKE (WCP)	Damaged	60.00 F	*60.00 F
36	1		*HORN (WCP)	Serviceable	120.00 F	*- F
37	1		*FRONT RIGHT RIM (WCP)	Cut	200.00 F	*200.00 F
38	1		*FRONT RIGHT TYRE (WCP)	Torn	220.00 F	*220.00 F
39	1		*HYBRID SPARE TANK (WCP)	Not Necessary	160.00 F	*- F
40	1		*LEFT WHEEL ARCH (DAMAGED)(WCP)	Not Consistent With The Impact	120.00 F	*- F
41	1		*AIR GUIDE (WCP)	Torn	90.00 F	*90.00 F
42	1		*RADIATOR SEAL (WCP)	Cut	100.00 F	*100.00 F
43	1		*FRONT SUPPORT BEAM BRACKET - LEFT (WCP)	Dented	150.00 F	*150.00 F
44	1		*FRONT SUPPORT BEAM BRACKET - RIGHT (WCP)	Dented	150.00 F	*150.00 F
45	1		*AIRBOX LOWER BRACKET (WCP)	Bent	78.00 F	*78.00 F
46	1		*OUTSIDE TEMP SENSOR (WCP)	Damaged	65.00 F	*65.00 F
47	1		*CENTER SUPPORT BEAM (WCP)	Bent	280.00 F	*280.00 F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>10,708.00</b>	<b>9,468.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	<b>1,070.80</b>	<b>946.80</b>
<b>Total Parts (S\$)</b>	<b>11,778.80</b>	<b>10,414.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	AIR FILTER (DEFORMED)	28.00	28.00
2	1	AIRCON GAS (NECESSARY)	80.00	50.00
3	1	CLIPS (NECESSARY)	50.00	50.00
4	1	COOLANT (NECESSARY)	50.00	30.00
5	1	FRONT NUMBER PLATE (BENT)	25.00	25.00
<b>Sub Total (S\$)</b>			<b>233.00</b>	<b>183.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY & SPRAY PAINT ON AFFECTED AREA	New	1,300.00	195.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED PARTS	New	1,500.00	415.00
3	TO CHECK WIRING & REWIRE	New	80.00	0.00
4	TO CHECK LIGHTING SYSTEM & WATER TEST FOR ANY LEAKAGE	New	120.00	0.00
5	PAINT / MATERIAL COSTS	New	-	115.74
<b>Gross Labour Cost (S\$)</b>			<b>3,000.00</b>	<b>725.74</b>

Report was unsubmitted during this print-out.
-----------------------------------------------

< END OF ESTIMATES >