

## **ESTIMATE FOR SKQ1420U**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

Vehicle & Document Information WIP No

23889

SKQ1420U Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

30/05/2018/256584 WDD2050402F044099

27491030208540

10.00

4.00

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A 021 149 Polar White/ 041 101 ARTICO Blac

/ 04/11/2014

Date/Time Printed CSE Operator Terms Account No 356 / Vincent Seah WC000668 Credit 29/06/2018/ 15:41 VS Description of Goods / Services Unit Price Disc% Qty Amount

M BPNSUN
POLICY NO ACC DATE
DRIVE IN EXCESS : DMPCSN1438041708 : 23.05.18 // \$10 \$1000

DATE IN/DATE SURVEY:23.05.18 // 25.05.18 TAUFIKH-LKK 12:30PM :DENISE TAY -LKK // 30.05.18 BY/AUTHRIZED ON

STOP

SERVO U-SHAPED STRIKER

62222366

X NUT

SEAM SEAL BLIND RIVET

RIVET

X BLIND RIVET

X WASHER

4.55 00.00 2.00 1.00 458.89 00.00 4.00 4.86 00.00 1.00 97.68 00.00 0,00

1.27 00.00 2.29 00.00 1.27 00.00 4.10 00.00 bt \_ 458.89 me 19.44 Nu 97.68 ml / 12.70 nu 22.90 nu 5.08

Me 8.20

iver 9.10

SUPPLEMENTAR

Confirmed & accepted by

35061.44

Nett 633.99

633.99

7% GST on

44.38

**Total Payable** 

678.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

the removal of the windscreen.