

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0298/18

DATE : 16-MAY-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

#04-05 IOB BUILDING

S(049711)

TEL : 63476100

FAX : 62244174

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR CHIA SOO ON

ADDRESS : BLK 374 TAMPINES STREET 34

#07-48

S(520374)

TELEPHONE NO : 96629842

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SLL5189B

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2398302A

CHASSIS NO : SJNFEAJ11U1902411

MILEAGE : 36676 KM

DATE IN : 16/05/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 16/05/2018

96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL5189B

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR LH SIDE SILL, RENEW LH FRONT FENDER AND LH FRONT DOOR.	850.00	
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	750.00	
3 ZZ/003	REMOVE AND INSTALL LH FRONT DOOR MECHANISM.	80.00	
	TOTAL LABOUR CHARGES	1680.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL5189B

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN				60.00
2	LH WHEEL ARC MLDG FRT	63811-4EA0A	483.00			
3	LH FRT FENDER	F3101-4EAMB	622.70			
4	FRT DOOR LOWER PVC MLDG	80871-4EA0A	323.60			
5	L/F DOOR TAPE	80813-4EA0A	29.90			
6	FRT LH DOOR	H0101-PVOMA	1104.80			
SUB TOTAL			2564.00	0.00		60.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)			512.80	0.00		0.00
GRAND TOTAL			2051.20	0.00		60.00
OVERALL TOTAL			2111.20			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL5189B

TOTAL LABOUR CHARGES	1680.00
TOTAL SPARE PARTS CHARGES	2111.20

GRAND TOTAL	3791.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.