

Attm Kenneth

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKW 1683X

TP/ER

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 10/05/2018
TP Veh Reg No: SJM4183S

Claim No: ES1890585
Estimate No: ES1890585/YISHUN
Date: 24 May 2018
Policy No: D17MTPV01014279
Veh Reg No: SKW1683X
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11103058
Engine No: L15B4023059
Reg. Date: 20/10/2015

Not Authorised

Henry B & pain

81116-30

Estimate Repair Cost to Vehicle No : SKW1683X

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	220.00	1 PC	220.00	✓
2 FRONT BUMPER REINFORCEMENT	210.00	1 PC	210.00	✓
3 FRONT BUMPER CLIPS	1.50	6 PCS	9.00	✓
4 RH HEADLAMP BRACKET	23.00	1 PC	23.00	✓
			462.00	
	Add 15%		69.30	531.30
Special Net				
5 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
				35.00
Labour				
6 REMOVE & REFIX FRT BUMPER ASSY.HEADLAMP,REINFORCEMENT,TO KNOCK & REPAIR FRT BUMPER BRACKET & REALIGN THE SAME	450.00	1 LA	450.00	250
7 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT	400.00	1 LA	400.00	300
				850.00

Total S\$ 1,416.30

Add GST @ 7% 99.14

Total Amount payable S\$ 1,515.44

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Final #1116.30