

22/03/2002

ASS. REC. BY:

REF:

CS/EGT/18009555 / Utbet

Special Instruction:

Surveyor

Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGT

Date/Time:

29052018 11:44am

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EX 1000H

Insured:

XD 1135H

at Workshop m/s

Autolulution

Tel:

9645 0079

of

19 Ubi Rd 4

Policy No:

Claim No:

XD1135H/SL/pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18052018

(Client's Record)

CA / REV / REP. / REV 24 HRS D91

H.O.D. Endorsement:

Date/Time:

29052018 12pm

Person Contacted:

Hamzah

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

EX 1000H - X

XD 1135H - X

Surveyor

REF: EGI

ASSIGNMENT

From: Date: 31/05/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Ex1000H
at Workshop m/s Autolution (ubi)

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 9am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IBAC Accident Report: Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: EX1000H Yr Regn: 12/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Nissan X-trail C.C. 1997

Colour: S. / wh A/C: Insured / Std / NI / NA

Sp. Reading: 46841 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1JANT3220001238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 60R18
R:

BS / DUNTEXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYOT YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/5/18 D.O.I. 31/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 60567

18/18 cont. mt. fuel by 5977.12 with hanzoh.
(Red: 2630-16, 25%)

RECEIVED 02 JUN 2018

Date/Time. File Pass to?

☐ : Preli. Report1) 318 Typist
Date/Time. File Return to?☒ : Final Report

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) 5977.12

250

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 25 May, 2018 11:44 AM
To: 'admin-d@lkkauto.com'
Subject: OI : XD1135H / TP : EX1000H/LKK / DOA : 18/05/2018
Attachments: XD1135H - SAS.pdf; EX1000H - SAS.pdf; EX1000H - ESTIMATE.pdf; EX1000H - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AUTOLUTION INDUSTRIAL PTE LTD**,

ADDRESS : 19 UBI ROAD 4
SINGAPORE 408623

PERSON TO CONTACT : HAMZAH SA'AD @ 6703 8690 / 9645 0079

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 25.05.2018

Our Reference: XD 1135H/SL/pl

Your Reference: EX 1000H

Sent via Fax

or

Email

hamzah_saad@tanchong.com

To: AUTOLUTION INDUSTRIAL PTE. LTD.

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: EX 1000H

Insured's Vehicle: XD 1135H

Date Of Accident: 18.05.2018

We acknowledge receipt of your request for PRS on: 24.05.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from

the list below and indicate your selection in the box marked *.


* LKK Auto Consultants

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us to date.

☒ Others: We write to confirm our agreement to have a direct settlement of this claim with

quantum to be agreed. OFFICER-IN-CHARGE STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____

Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____

Time: _____

Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18009555/Utb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 25-05-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1135H	Veh. Inspected	EX 1000H
Policy No.		Coverage (\$)	0.00
Claim No.	XD1135H/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/05/2018	Inspection Date
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/05/2018 08:39
Date Of Accident	18/05/2018 15:10
Exact Location Of Accident	OUTSIDE GATE(23 JOON KOON RD - LAND EQUIPMENT BLD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EX1000H
Insured/Policyholder	
Name Of Registered Owner	WA SOCK YIN (HE SHUYAN)
NRIC No	S7315605Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96874773
Alternative Phone No	OTHERS-96874773

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY


Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700081331
Cover Note Number	

Driver

Name of Driver	JEREMIAH PANGIHUTAN TAMPU BOLON
NRIC No	S1537934J
Date Of Birth	07/11/1962
Occupation	INDOOR
Date Of Driving Pass	31/07/1998
Driving Experience	19 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96874773
Fax Number	
Contact Number	
Email Address	JBOLE009@GMAIL.COM



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

There was space constraint at 23 Joo Koon Rd Land Equipment Bldg S(628980) and there were a number of cars and trucks at the said building. As I had driven head in first into the facility, I had to reverse my car (EX1000H) to allow a black SUV SLT 1888D to get onto the road named Joo Koon Rd. I came to a total stop after reversing enough to allow the black SUV to exit the premises. That's when the truck XD 1135H rear-ended my car at 3.11 pm as shown in the video clip. My client, Mr David Fong Hong Wai, was with me in my car & he confirms that I had sounded my car horn to warn the truck driver. Incidentally, he (Mr Ah Yu - a Chinese driver) looked drowsy during the time of the accident. He stepped out of the truck & my client & I confirm that he did look drowsy even soon after 3.11 pm (Time of accident).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Sat, May 19 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Friday, May 18 2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 808623
TEL: 6490 9886 FAX: 6846 7483

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5605Z
Vehicle Details	
Vehicle No.:	EX1000H
Vehicle to be Exported:	No
Intended De-registration Date:	31 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	MR20790807B
Chassis No.:	JN1JANT32Z0001238
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,714.00
Original Registration Date:	09 Dec 2015
First Registration Date:	09 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$22,400.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2025
PARF Rebate Amount:	\$16,800.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$43,767.00
Total Rebate Amount:	\$60,567.00

The information contained herein is correct as at 31 May 2018

OK

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0301/18
DATE : 19-MAY-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9665 FAX: 6846 7492

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : WA SOCK YIN (HE SHUYAN)
ADDRESS : BLK 765 PASIR RIS ST 71
#07-104
S(510765)
TELEPHONE NO : 96874773

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : EX1000H
MODEL CODE : JDRNRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20790807B
CHASSIS NO : JN1JANT32Z000123B
MILEAGE : 46052 KM
DATE IN : 19/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 18/05/2018

Not Acknowledged
with
the 3rd. Behn. Party.
31/5/18
the 5 day.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EX1000H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		380		
1	ZZ/001	LABOUR CHARGES TO REPAIR REAR END PANEL,RENEW REAR BUMPER & H/BACK DOOR.	1200.00	780
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	850.00	750
3	ZZ/003	REMOVE AND INSTALL REAR W/SCREEN GLASS.	240.00	✓
4	ZZ/004	REMOVE AND INSTALL H/BACK DOOR MECHANISM.	80.00	✓
5	ZZ/005	APPLY SEALANT TO REAR H/BACK DOOR.	100.00	✓
6	ZZ/006	REMOVE AND INSTALL REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT SETTING AND FUNCTION TEST.	150.00	✓
7	ZZ/007	SUPPLY REAR LICENCE PLATE.		
		TOTAL LABOUR CHARGES	2620.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EX1000H

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN		11	60.00 X
2 REAR W/SCREEN SEALANT	SEALANT - 4		ner	80.00 —
3 REAR W/SCREEN MOULDING	90352-4CC0A	ner 65.70	—	
4 REAR LICENCE PLATE	RLP X		11	80.00 X
5 REVERSE SENSOR	SENSOR X		11	250.00 X
6 CLIP REAR BUMPER @1.20 EACH	01553-10501	ner 7.20	—	
7 EMBLEM REAR-X-TRAIL	84890-4CLOA	ner 59.70	—	
8 EMBLEM REAR-NISSAN	84895-4CLOA	ner 101.30	—	
9 WEATHER STRIP REAR H/BACK DOOR	90830-4CC0B X	11 133.80	X	
10 REAR H/BACK DOOR	9001A-4CC5C	ner 4200.00	—	
11 STAY-REAR BUMPER LH	H5210-4CCMA	11 174.80	X	
12 STAY-REAR BUMPER RH	H5211-4CCMA	11 174.80	X	
13 REINFORCEMENT BUMPER REAR	85032-4CC0A X	11 533.80	X	
14 RH BRACKET REAR BUMPER	85221-4CE0A X	11 35.80	X	
15 LH BRACKET REAR BUMPER	85220-4CE0A X	11 35.90	X	
16 REAR BUMPER FASCIA	85022-4CE0H X	ner 623.80	X	
SUB TOTAL		6146.60	0.00	470.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1229.32	0.00	0.00
GRAND TOTAL		4917.28	0.00	470.00
OVERALL TOTAL		5387.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO EX1000H

TOTAL LABOUR CHARGES	2620.00
TOTAL SPARE PARTS CHARGES	5387.28

GRAND TOTAL	8007.28 *

8257.28

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Marcus

AUTOLUTON INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0301/18

DATE : 19-MAY-2018

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD

#04-01 SUNTEC TOWER FIVE

S(038985)

TEL : 68299199

FAX : 68299247/9248

ATTN : CLAIM MANAGER

OWNER'S NAME : WA SOCK YIN (HE SHUYAN)

ADDRESS : BLK 765 PASIR RIS ST 71

#07-104

S(510765)

TELEPHONE NO : 96874773

5 days e.

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : EX1000H

MODEL CODE : JORNRRZT32EWA-----

MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I

ENGINE NO : MR20790807B

CHASSIS NO : JN1JANT32Z0001238

MILEAGE : 47654 KM

DATE IN : 19/05/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 18/05/2018

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EX1000H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR REAR ENG PANEL, REAR BUMPER & RENEW REAR H/BACK DOOR.	1200.00	700.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	850.00	750.00
3 ZZ/003	REMOVE AND INSTALL REAR W/SCREEN GLASS.	240.00	240.00
4 ZZ/004	REMOVE AND INSTALL H/BACK DOOR MECHANISM.	80.00	80.00
5 ZZ/005	APPLY SEALANT TO REAR H/BACK DOOR.	100.00	100.00
6 ZZ/006	REMOVE AND INSTALL REVERSE CAMERA, FINTSHER MOUNTING, ALIGNMENT SETTING AND FUNCTION TEST.	150.00	150.00
7 ZZ/007	SUPPLY REAR LICENCE PLATE.		
8 ZZ/008	REMOVE AND INSTALL REAR INTERIOR FINISHER.	250.00	250.00 (A)
TOTAL LABOUR CHARGES		2870.00	2350.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EX1000H

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	WEATHER STRIP REAR H/BACK DOOR	90830-4CC0B	133.80			X
2	REAR LICENCE PLATE	RLP			60.00	X
3	SUNDRIES	NPN			60.00	X
4	REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
5	REVERSE SENSOR	SENSOR			250.00	X
6	CLIP REAR BUMPER Ø1.20 EACH	01553-10501	7.20			OK
7	EMBLEM REAR-X-TRAIL	84890-4CLOA	59.70			OK
8	EMBLEM REAR-NISSAN	84895-4CLOA	101.30			OK
9	STAY-REAR BUMPER RH	H5211-4CCMA	174.80			X
10	REINFORCEMENT BUMPER REAR	85032-4CCDA	533.60			X
11	RH BRACKET REAR BUMPER	85221-4CEDA	35.80			X
12	REAR W/SCREEN MOULDING	90352-4CCDA	65.70			OK
13	REAR H/BACK DOOR	9001A-4CC5C	4200.00			OK
14	STAY-REAR BUMPER LH	H5210-4CCMA	174.80			X
15	LH BRACKET REAR BUMPER	85220-4CEDA	35.90			X
16	REAR BUMPER FASCIA	85022-4CE0H	623.80			X
SUB TOTAL			4433.90	0.00	80.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			886.78	0.00	0.00	
GRAND TOTAL			3547.12	0.00	80.00	
OVERALL TOTAL			3627.12			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO EX1000H

NETT ITEM	4433.90
LESS 20.00%	-886.78
NETT AMOUNT	3547.12

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	80.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	80.00

TOTAL LABOUR CHARGES	2350.00
TOTAL SPARE PARTS CHARGES	3627.12

TOTAL CHARGES	5977.12
ADD 7 % GST	418.40

GRAND TOTAL	6395.52
-------------	---------



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorised Dealer
19 Ubi Road 4
Singapore 408623
Tel (65) 64909666 / 67038680
Fax (65) 68467483
Business Reg. No.: 199500871W

31-July-2018

INS/SC/H/0424/18

ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Sunctec Tower Five
Singapore 038985

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : EX1000H
CLAIM NO: XD 1135H/SL/pl


Further to our claim INS/IC/EA/0301/18 we are submitting a supplementary claim for the below mentioned labour and part for the above mentioned case.

Labour charges

1 Remove and install rear interior finisher. *ADD* \$ 250.00

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
AUTOLUTION INDUSTRIAL PTE LTD


Hamzah Sa'ad
Insurance Claim Dept

Cc: Surveyor-Mr. Marcus – LKK



www.tanchong.com




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18009555/Utbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 23-08-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 1135H	Veh. Inspected	EX 1000H	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD1135H/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	25/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1JANT32Z0001238	Colour	SILVER	
Odometer	46841	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	DUNLOP	6 mm	
L/H Front Tyre	225/60 R18	DUNLOP	6 mm	
R/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
L/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/05/2018	Inspection Date	31/05/2018	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EX 1000H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR W/SCREEN MOULDING (N)	NECESSARY	65.70	65.70
6	CLIP REAR BUMPER @\$1.20 (N)	NECESSARY	7.20	7.20
1	EMBLEM REAR X-TRAIL (N)	NECESSARY	59.70	59.70
1	EMBLEM REAR - NISSAN (N)	NECESSARY	101.30	101.30
1	WEATHERSTRIP REAR H/BACK DOOR (N)	NOT NECESSARY	133.80	-
1	REAR H/BACK DOOR (N)	DENTED / CRACKED	4,200.00	4,200.00
1	STAY-REAR BUMPER LH (N)	NOT NECESSARY	174.80	-
1	STAY-REAR BUMPER RH (N)	NOT NECESSARY	174.80	-
1	REINFORCEMENT BUMPER REAR (N)	NOT NECESSARY	533.80	-
1	RH BRACKET REAR BUMPER (N)	NOT NECESSARY	35.80	-
1	LH BRACKET REAR BUMPER (N)	NOT NECESSARY	35.90	-
1	REAR BUMPER FASCIA (N)	TO REPAIR SEE LABOUR	623.80	-
	LESS 20% DISCOUNT		-1,229.32	-886.78
			4,917.28	3,547.12
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	REAR W/SCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
			470.00	80.00
<u>LABOUR</u>				
	LABOUR CHARGE TO REPAIR REAR END PANEL, RENEW REAR BUMPER & H/BACK DOOR. INCLUSIVE OF THE REPAIR OF REAR BUMPER FASCIA.		1,200.00	780.00
	CHARGES TO SPRAY PAINTING SAME.		850.00	750.00
	REMOVE AND INSTALL REAR W/SCREEN GLASS.		240.00	240.00
	REMOVE & INSTALL H/BACK DOOR MECHANISM.		80.00	80.00
	APPLY SEALANT TO REAR H/BACK DOOR.		100.00	100.00
	REMOVE AND INSTALL REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT SETTING AND FUNCTION TEST.		150.00	150.00

Report Ref No. CS/EGI18009555/Utb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY REAR LICENCE PLATE (NPA).		-	-
	REMOVE AND INSTALL REAR INTERIOR FINISHER. (ADDITIONAL)		250.00	250.00
			2,870.00	2,350.00
GRAND TOTAL			8,257.28	5,977.12
RECOMMENDED COST OF REPAIRS				5,977.12

Report Ref No. CS/EGI18009555/Utbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.