

ASS. REC. BY:

REF:

CS / CNB / 8009556 / R19022

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Muhammad Asyraf

of

CNB

Date/Time:

24 05 2018 4:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 9162B

Insured:

at Workshop m/s

SMRT

Tel:

98576861 - Kong

of

60 Woodlands Ind Park E4

Policy No:

H01CNBEC118300468

Claim No:

H01CNBEP018300474

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

28/05/2018
31

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (

✓) Estimate

SLB 9162B - X

18/9/18 @ 1.29pm revert to Sherhane Yeo by email.

Material = # 6577 ; man hrs = # 6 hrs


0001-17

REF:

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OB / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLL 9162B
 at Workshop m/s: SMART
 of: 60, mmmmm (incl PK 04)
 Insured: CNB
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL 9162B Yr Regn: _____
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: CHEVROLET C.C.
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 010969 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KL13A69E9GK 351372
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 31/05/18

Survey held at SMART
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) 04/10 14:00
 Date/Time, File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

☐ Photos

☐ Others

☐

TOTAL

280

280

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Catherine Chong (LKK Auto)

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Sent: Friday, 25 May, 2018 9:39 AM
To: Muhammad Asyraf ANUAR (CNB); assignments
Cc: Shirlene YEO (CNB); Sylvester QUAH (CNB); Celine Fong (LKKAuto)
Subject: [CNB]: Engage for Assessment SLL9162B

Hi Mr. Asyraf,

Thank you for the email.

Catherine / Nivitha - please register case.

Best Regards,
Olivia Lau
LKK Auto Consultants Pte Ltd

From: Muhammad Asyraf ANUAR (CNB) <muhammad_asyraf_anuar@cnb.gov.sg>
Sent: Thursday, May 24, 2018 4:09 PM
Subject: Engage for Assessment SLL9162B
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Cc: Shirlene YEO (CNB) <shirlene_yeo@cnb.gov.sg>, Sylvester QUAH (CNB) <sylvester_quah@cnb.gov.sg>

Hi Olivia

I would like to engage LKK to assess on the vehicle repair for CNB. The quote of the assess is still \$280.

Here are the details of the Vehicle and attached is the quote given by contractor.

Vehicle Number : SLB9162B
Make & Model : CHEVROLET CRUZE NB 1.6D AT
Location of vehicle : SMRT

Thank you.

Muhammad Asyraf Bin Anuar
Logistics, Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6627 | FAX: (65) 6224 3204



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB fb.com/CNB.DrugFreeSG IG Instagram.com/cnb.drugfreesg

Shiau Chan (LKKAUTO)

From: Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>
Sent: Thursday, 4 October 2018 1:13 PM
To: Shiau Chan (LKKAUTO); Olivia Lau (LKKAUTO); Rasul (LKKAUTO)
Cc: Muhammad Hafiz ABDUL HASSAN from.TP (CNB); SUR
Subject: RE: [CNB]: List - status on vehicle report and e-invoice // LKK Ref: CS/CNB18009556/R1qb

Message Classification: Restricted

Hi Shiau

Yes, pls submit the report. Thanks.

Shirlene Yeo (Ms)
Manager, Logistics Unit
Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6626



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Keeping Singapore Drug-Free

Central Narcotics Bureau W cnb.gov.sg FB [fb.com/CNB.DrugFreeSG](https://www.facebook.com/CNB.DrugFreeSG) IG [Instagram.com/cnb.drugfreesg](https://www.instagram.com/cnb.drugfreesg)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 4 October 2018 11:20 AM
To: Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Muhammad Asyraf ANUAR (CNB) <Muhammad_Asyraf_ANUAR@cnb.gov.sg>; Muhammad Hafiz ABDUL HASSAN from.TP (CNB) <Muhammad_Hafiz_ABDUL_HASSAN_from.TP@cnb.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: [CNB]: List - status on vehicle report and e-invoice // LKK Ref: CS/CNB18009556/R1qb

Dear Sir/Madam,

Kindly advise whether we can submit our report accordingly to your good office.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 18 September 2018 1:29 PM
To: Shirlene YEO (CNB); Olivia Lau (LKKAuto); Rasul (LKKAuto)
Cc: Muhammad Asyraf ANUAR (CNB); Muhammad Hafiz ABDUL HASSAN from.TP (CNB); SUR
Subject: RE: [CNB]: List - status on vehicle report and e-invoice // LKK Ref: CS/CNB18009556/R1qb
Attachments: SLL9162 Photo.pdf; SLL 9162B.xls

Dear Shirlene,

Please find the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirlene YEO (CNB) <Shirlene_YEO@cnb.gov.sg>
Sent: Tuesday, 18 September 2018 8:46 AM
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Muhammad Asyraf ANUAR (CNB) <Muhammad_Asyraf_ANUAR@cnb.gov.sg>; Muhammad Hafiz ABDUL HASSAN from.TP (CNB) <Muhammad_Hafiz_ABDUL_HASSAN_from.TP@cnb.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: [CNB]: List - status on vehicle report and e-invoice // LKK Ref: CS/CNB18009556/R1qb

Message Classification: Restricted

Hi Olivia

Any updates, pls? Please reply asap as we need to send our vehicle for repair.

Thanks.

Shirlene Yeo (Ms)
Manager, Logistics Unit
Corporate Services Division
Central Narcotics Bureau
DID: (65) 6325 6626



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 1 June 2018 2:51 PM
To: 'muhammad_asyraf_anuar@cnb.gov.sg'; assignments
Cc: SUR
Subject: RE: [CNB]: Engage for Assessment SLL9162B

Dear Mr Asyraf,

Please be informed that we have inspected the vehicle SLL 9162B on 31/05/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto)
Sent: Friday, 25 May, 2018 9:39 AM
To: Muhammad Asyraf ANUAR (CNB) <muhammad_asyraf_anuar@cnb.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Shirlene YEO (CNB) <shirlene_yeo@cnb.gov.sg>; Sylvester QUAH (CNB) <sylvester_quah@cnb.gov.sg>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: [CNB]: Engage for Assessment SLL9162B

Hi Mr. Asyraf,

Thank you for the email.

Catherine / Nivitha - please register case.

Best Regards,

Olivia Lau

LKK Auto Consultants Pte Ltd

From: Muhammad Asyraf ANUAR (CNB) <muhammad_asyraf_anuar@cnb.gov.sg>
Sent: Thursday, May 24, 2018 4:09 PM
Subject: Engage for Assessment SLL9162B
To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Cc: Shirlene YEO (CNB) <shirlene_yeo@cnb.gov.sg>; Sylvester QUAH (CNB) <sylvester_quah@cnb.gov.sg>

Hi Olivia

I would like to engage LKK to assess on the vehicle repair for CNB. The quote of the assess is still \$280.

Here are the details of the Vehicle and attached is the quote given by contractor.



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	UNMARKED	UNIT :	CNB	Reference No. 1320/CNB/4W/18/03/02
VEH NO :	QX1320S / SLL9162B	REPAIR TYPE:	ACCIDENT			
VEH MAKE/MODEL:	CHEROULET CRUZE	ODOMETER :	10954			

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)	
1	Scope Of Repairs						
1.1	Boot Lid Cover	\$1,230.00	1		1230.00	1230.00	BT ✓
1.2	Boot Lid Hinges LH & RH	\$50.00	2		50.00	100.00	X 4% ✓
1.3	RHS Boot Lamp	\$310.00	1		310.00	310.00	Pro ✓
1.4	RHS Tail Lamp	\$310.00	1		310.00	310.00	CAQ ✓
1.5	LHS Tail Lamp	\$310.00	1		310.00	310.00	Pro ✓
1.6	Boot Lid Emblem	\$85.00	1		85.00	85.00	new ✓
1.7	"CHEVROLET" Emblem	\$25.00	1		25.00	25.00	new ✓
1.8	"CRUZE IS" Emblem	\$25.00	1		25.00	25.00	new ✓
1.9	Car Boot Inner Lock	\$85.00	1		85.00	85.00	BT ✓
1.10	Car Boot Rubber Seal	\$200.00	1		200.00	200.00	cut ✓
1.11	Rear Bumper	\$1,050.00	1		1050.00	1050.00	DE ✓
1.12	Rear Bumper Retainers (Side)	\$15.00	2		15.00	30.00	new ✓
1.13	Rear Bumper Retainers (Centre)	\$52.00	1		52.00	52.00	Pro ✓
1.14	Rear Bumper Retainers (Below Tail Lamp)	\$28.00	2		28.00	56.00	X 4% ✓
1.15	Rear Bumper Centre Garnish	\$105.00	1		105.00	105.00	DE ✓
1.16	Rear Bumper Side Garnish	\$55.00	2		55.00	110.00	DE ✓
1.17	Rear End Panel	\$805.00	1		805.00	805.00	BT ✓
1.18	Rear End Panel Garnish	\$60.00	1		60.00	60.00	DE ✓
1.19	Reverse Sensor	\$200.00	1		200.00	200.00	new ✓ s/n
1.20	Rear RHS Tow Eye Cover	\$10.00	1		10.00	10.00	mis ✓
1.21	Rear Bumper Reinforcement	\$260.00	1		260.00	260.00	BT ✓
1.22	Luggage Cover	\$280.00	1		280.00	280.00	X 4% ✓
1.23	Rear Number Plate & Casing	\$50.00	1		50.00	50.00	mis ✓
1.24	Front Bumper	\$1,205.00	1		1205.00	1205.00	DE ✓
1.25	Front RH Bumper Retainer	\$10.00	1		10.00	10.00	new ✓
1.26	Front Number Plate & Casing	\$50.00	1		50.00	50.00	BT ✓
1.27	Spare Tyre Panel	\$1,110.00	1		1110.00	1110.00	repair ✓
2	Additional Services						
2.1	NA			0%	0.00	0.00	
Remarks:					Parts Total:	\$ 8,123.00	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Car Boot:	12	16	0.00
	Remove & Replace Boot Lid Cover			
	Remove & Replace Boot Lid Cover Hinges			
	Remove & Replace Boot Lid Emblem			
	Remove & Replace "CHEROULET" Emblem			
	Remove & Replace "CRUZE IS" Emblem			
	Remove & Replace Car Boot Inner Lock			
	Remove & Replace Car Boot Rubber Seal			
	Remove & Replace Luggage Cover			
	Putty & Spray Paint for Boot Lid Cover			
1.2	Rear Boot Lamp & Tail Lamp:	3	1	0.00
	Remove & Replace RHS Boot Lamp & Tail Lamp			
	Remove & Replace LHS Tail Lamp			
	Wiring for Replaced Boot & Tail Lamp			
1.3	Rear Bumper:	no charge	12	0.00
	Remove & Replace Rear Bumper			
	Remove & Replace Both Side Rear Bumper Retainers (Side, Centre & Below Tail Lamp)			
	Remove & Replace Rear Bumper Centre Garnish			
	Remove & Replace Rear Bumper Side Garnish			
	Remove & Replace Rear Bumper Reinforcement			
	Remove & Replace Rear RHS Tow Eye Cover			
	Remove & Replace Reverse Sensor			
	Wiring for Reverse Sensor			
	Putty & Spray Paint for Rear Complete Bumper			
1.4	Rear End Panel:	12	16	0.00
	Remove & Replace Rear End Panel			
	Remove & Replace Rear End Panel Garnish			

1.5	Front Bumper:	<i>KASU</i>	<i>no charge</i>	6	<i>0.00</i>
	Remove & Replace Front Bumper	<i>#p 90010068</i>			<i>0.00</i>
	Remove & Replace Front RH Bumper Retainer				<i>0.00</i>
	Putty & Spray Paint for Front Complete Bumper				<i>0.00</i>
1.6	Number Plates:	<i>12 days</i>	<i>no charge</i>	1	<i>0.00</i>
	Remove & Replace Front & Rear Number Plate				<i>0.00</i>
1.7	Rear RH & LH Panel:	<i>4/3</i>		6	<i>0.00</i>
	Panel Beating for Rear RH & LH Panel				<i>0.00</i>
	Putty & Spray Paint for Rear RH & LH Panel	<i>31/05/18 @ 1600</i>			<i>0.00</i>
1.8	Spare Tyre Panel:	<i>Repair after repair</i>		10	<i>0.00</i>
	Remove & Replace Sprare Tyre Panel				<i>0.00</i>
	Putty & Spray Paint for Spare Tyre Panel				<i>0.00</i>
SUB-TOTAL				75	0.00
2	Additional Services				
2.1	Towing Service From Station to Workshop (SOR 8)		138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)		44.10	1	44.10
SUB-TOTAL				2	182.70
				Labour Total:	\$ 182.70
				GRAND TOTAL :	\$ 8,305.70
				Total sum billed under SOR only :	\$ 182.70
				Total sum billed under CVR only :	\$ 8,123.00
Contractor shall complete the entire repair within <u>40</u> working days upon quotation approval date . (Include parts awaiting time)					

Verification of Scope of Work					
Contractor QC		Vetted By:		Approved By:	
Name:	KONG SEW KUI	Name:		Name:	
Date:	15.03.2018	Date:		Date:	
Sign:		Sign:		Sign:	
Verification of Completed Repairs					
Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager	
Name:		Name:		Name:	
Date:		Date:		Date:	
Sign:		Sign:		Sign:	
All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made					

Registration No. SLL 9162B

S/N	ITEM DESCRIPTION	PARTS			MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP
1	MATERIALS				
1.1	Boot Lid Cover	1	Bent	\$1,230.00	\$1,230.00
1.2	Boot Lid Hinges LH & RH	2	Servicable	\$50.00	\$0.00
1.3	RHS Boot Lamp	1	Broken	\$310.00	\$310.00
1.4	RHS Tail Lamp	1	Cracked	\$310.00	\$310.00
1.5	LHS Tail Lamp	1	Broken	\$310.00	\$310.00
1.6	Boot Lid Emblem	1	Necessary	\$85.00	\$85.00
1.7	"CHEVROLET" Emblem	1	Necessary	\$25.00	\$25.00
1.8	"CRUZE IS" Emblem	1	Necessary	\$25.00	\$25.00
1.9	Car Boot Inner Lock	1	Bent	\$85.00	\$85.00
1.10	Car Boot Rubber Seal	1	Cut	\$200.00	\$200.00
1.11	Rear Bumper	1	Deformed	\$1,050.00	\$1,050.00
1.12	Rear Bumper Retainers (Side)	2	Necessary	\$15.00	\$30.00
1.13	Rear Bumper Retainers (Centre)	1	Necessary	\$52.00	\$52.00
1.14	Rear Bumper Retainers (Below Tail Lamp)	2	Servicable	\$28.00	\$0.00
1.15	Rear Bumper Centre Garnish	1	Deformed	\$105.00	\$105.00
1.16	Rear Bumper Side Garnish	2	Deformed	\$55.00	\$110.00
1.17	Rear End Panel	1	Bent	\$805.00	\$805.00
1.18	Rear End Panel Garnish	1	Deformed	\$60.00	\$60.00
1.19	Reverse Sensor	1	Necessary	\$200.00	\$200.00
1.20	Rear RHS Tow Eye Cover	1	Missing	\$10.00	\$10.00
1.21	Rear Bumper Reinforcement	1	Bent	\$260.00	\$260.00
1.22	Luggage Cover	1	Servicable	\$280.00	\$0.00

1.23	Rear Number Plate & Casing	1	Missing	\$50.00	\$50.00
1.24	Front Bumper	1	Deformed	\$1,205.00	\$1,205.00
1.25	Front RH Bumper Retainer	1	Necessary	\$10.00	\$10.00
1.26	Front Number Plate & Casing	1	Bent	\$50.00	\$50.00
1.27	Spare Tyre Panel	1	Repair	\$1,110.00	\$0.00
	SCOPE OF REPAIRS				
1.1	Car Boot:				12
	Remove & Replace Boot Lid Cover				
	Remove & Replace Boot Lid Cover Hinges				
	Remove & Replace Boot Lid Emblem				
	Remove & Replace "CHEVROLET" Emblem				
	Remove & Replace "CRUZE IS" Emblem				
	Remove & Replace Car Boot Inner Lock				
	Remove & Replace Car Boot Rubber Seal				
	Remove & Replace Luggage Cover				
	Putty & Spray Paint for Boot Lid Cover				
1.2	Rear Boot Lamp & Tail Lamp:				3
	Remove & Replace RHS Boot Lamp & Tail Lamp				
	Remove & Replace LHS Tail Lamp				
	Wiring for Replaced Boot & Tail Lamp				
1.3	Rear Bumper:				12
	Remove & Replace Rear Bumper				
	Remove & Replace Both Side Rear Bumper Retainers (Side, Centre & Below Tail Lamp)				
	Remove & Replace Rear Bumper Centre Garnish				
	Remove & Replace Rear Bumper Side Garnish				
	Remove & Replace Rear Bumper Reinforcement				
	Remove & Replace Rear RHS Tow Eye Cover				
	Remove & Replace Reverse Sensor				

	Wiring for Reverse Sensor								
	Putty & Spray Paint for Rear Complete Bumper								
1.4	Rear End Panel:								12
	Remove & Replace Rear End Panel								
	Remove & Replace Rear End Panel Garnish								
1.5	Front Bumper:								6
	Remove & Replace Front Bumper								
	Remove & Replace Front RH Bumper Retainer								
	Putty & Spray Paint for Front Complete Bumper								
1.6	Number Plates:								1
	Remove & Replace Front & Rear Number Plate								
1.7	Rear RH & LH Panel:								6
	Panel Beating for Rear RH & LH Panel								
	Putty & Spray Paint for Rear RH & LH Panel								
1.8	Spare Tyre Panel:								10
	Remove & Replace Spare Tyre Panel								
	Putty & Spray Paint for Spare Tyre Panel								
COSTING			TOTAL PARTS COST			\$6,577.00			
			TOTAL MAN-HOUR						62



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CENTRAL NARCOTICS BUREAU			Ref : CS/CNB18009556/R1qbe2	
CORPORATE SERVICES DIVISION BLK B POLICE CANTONMENT COMPLEX 393 NEW BRIDGE ROAD SINGAPORE 088763 ATTN : MUHAMMAD ASYRAF			Date : 01-11-2018	
Code : CNB				
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	SLL 9162B
Policy No.	HOMCNBECI18300468		Coverage (\$)	0.00
Claim No.	HOMCNBEPO18300474		Excess (\$)	0.00
Assign From	MUHAMMAD ASYRAF		Assign Date	24/05/2018
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	KL1JA69E9GK351372	Colour	BLACK	
Odometer	10969	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	KUMHO	6 mm	
L/H Front Tyre	205/60 R16	KUMHO	6 mm	
R/H Rear Tyre	205/60 R16	KUMHO	6 mm	
L/H Rear Tyre	205/60 R16	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date			Inspection Date	31/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				



Registration No. SLL 9162B

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Boot Lid Cover	1	Bent	\$1,230.00	\$1,230.00	
1.2	Boot Lid Hinges LH & RH	2	Servicable	\$50.00	\$0.00	
1.3	RHS Boot Lamp	1	Broken	\$310.00	\$310.00	
1.4	RHS Tail Lamp	1	Cracked	\$310.00	\$310.00	
1.5	LHS Tail Lamp	1	Broken	\$310.00	\$310.00	
1.6	Boot Lid Emblem	1	Necessary	\$85.00	\$85.00	
1.7	"CHEVROLET" Emblem	1	Necessary	\$25.00	\$25.00	
1.8	"CRUZE IS" Emblem	1	Necessary	\$25.00	\$25.00	
1.9	Car Boot Inner Lock	1	Bent	\$85.00	\$85.00	
1.10	Car Boot Rubber Seal	1	Cut	\$200.00	\$200.00	
1.11	Rear Bumper	1	Deformed	\$1,050.00	\$1,050.00	
1.12	Rear Bumper Retainers (Side)	2	Necessary	\$15.00	\$30.00	
1.13	Rear Bumper Retainers (Centre)	1	Necessary	\$52.00	\$52.00	
1.14	Rear Bumper Retainers (Below Tail Lamp)	2	Servicable	\$28.00	\$0.00	
1.15	Rear Bumper Centre Garnish	1	Deformed	\$105.00	\$105.00	
1.16	Rear Bumper Side Garnish	2	Deformed	\$55.00	\$110.00	
1.17	Rear End Panel	1	Bent	\$805.00	\$805.00	
1.18	Rear End Panel Garnish	1	Deformed	\$60.00	\$60.00	
1.19	Reverse Sensor	1	Not Working	\$200.00	\$200.00	
1.20	Rear RHS Tow Eye Cover	1	Missing	\$10.00	\$10.00	
1.21	Rear Bumper Reinforcement	1	Bent	\$260.00	\$260.00	
1.22	Luggage Cover	1	Servicable	\$280.00	\$0.00	
1.23	Rear Number Plate & Casing	1	Missing	\$50.00	\$50.00	
1.24	Front Bumper	1	Deformed	\$1,205.00	\$1,205.00	
1.25	Front RH Bumper Retainer	1	Necessary	\$10.00	\$10.00	
1.26	Front Number Plate & Casing	1	Bent	\$50.00	\$50.00	
1.27	Spare Tyre Panel	1	Repair	\$1,110.00	\$0.00	

	SCOPE OF REPAIRS					
1.1	Car Boot:					12
	Remove & Replace Boot Lid Cover					
	Remove & Replace Boot Lid Cover Hinges					
	Remove & Replace Boot Lid Emblem					
	Remove & Replace "CHEVROLET" Emblem					
	Remove & Replace "CRUZE IS" Emblem					
	Remove & Replace Car Boot Inner Lock					
	Remove & Replace Car Boot Rubber Seal					
	Remove & Replace Luggage Cover					
	Putty & Spray Paint for Boot Lid Cover					
1.2	Rear Boot Lamp & Tail Lamp:					3
	Remove & Replace RHS Boot Lamp & Tail Lamp					
	Remove & Replace LHS Tail Lamp					
	Wiring for Replaced Boot & Tail Lamp					
1.3	Rear Bumper:					12
	Remove & Replace Rear Bumper					
	Remove & Replace Both Side Rear Bumper Retainers (Side, Centre & Below Tail Lamp)					
	Remove & Replace Rear Bumper Centre Garnish					
	Remove & Replace Rear Bumper Side Garnish					
	Remove & Replace Rear Bumper Reinforcement					
	Remove & Replace Rear RHS Tow Eye Cover					
	Remove & Replace Reverse Sensor					
	Wiring for Reverse Sensor					
	Putty & Spray Paint for Rear Complete Bumper					
1.4	Rear End Panel:					12
	Remove & Replace Rear End Panel					
	Remove & Replace Rear End Panel Garnish					
1.5	Front Bumper:					6
	Remove & Replace Front Bumper					
	Remove & Replace Front RH Bumper Retainer					
	Putty & Spray Paint for Front Complete Bumper					
1.6	Number Plates:					1
	Remove & Replace Front & Rear Number Plate					
1.7	Rear RH & LH Panel:					6
	Panel Beating for Rear RH & LH Panel					
	Putty & Spray Paint for Rear RH & LH Panel					
1.8	Spare Tyre Panel:					10
	Remove & Replace Spare Tyre Panel					

	Putty & Spray Paint for Spare Tyre Panel					
COSTING		TOTAL PARTS COST		\$6,577.00		
		TOTAL MAN-HOUR				62

Registration No. SLL 9162B

Vehicle Inspected By

MOHD RASUL BIN MOHD YUNUS
AMSOE,AMIRTE,AMSAE-A,M.MATAI
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.