

ASS. REC. BY:

REF:

C33/AIG18009560/G24d3

Special Instruction:

Surveyor

Name

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

25/5/18 @ 1.04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 7865B

Insured:

SLP 6681T

at Workshop m/s

Hup Lee Huat Motor

Tel:

9677 3832

of

Blk 1, Kaki Bukit Ave 6 # 01-35

Policy No:

0999994784

Claim No:

6984467098SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/05/2018

CA / REV / REP. / REV 24 HRS

Wp

H.O.D. Endorsement:

Date/Time:

2.01pm @ 25/5/18

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	SKM 7865B - C06 / AIG 1402 / 219 / M / ry 3w2
	SLP 6681 T-X

D.O.A. 10/11/2014

PRs
Karl

REF:

ALG.

3887i

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKM 7865B
 at Workshop m/s Hup Ley Huat
 of Blk 1 Kaki Bukit Ave 6 #01-35
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$60K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKM 7865B Yr Regn: 10 Apr 2014
 Type: Truck / Trailer or
 Make: Nissan Sylphy 1.6 C.C. 1598
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 139511 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MNTBBA B 1780018072
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 30-05-18
 Survey held at W/S 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/8	Submit DAR report.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format : DAR

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: 180

Transportation: _____ \$ + RS. _____ \$

Photos _____

Others _____

TOTAL

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLP6681T AND SKM7865B ON 20/5/2018 (Our ref:
2KB02.ACC.LCH.80462.18.ct)**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 25/5/2018 1:04:34 PM

Attachments:  80462.list of surveyor.pdf  SLP6681T--PRI.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cheonghoh Law Corporation

(Incorporated with limited liability)
Co. Reg No. 2011080703

Blk 53 Chin Swee Road #03-05 Singapore 160053
Tel: 63373700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number
Our Ref: LCH.d/2KB02-80482.18

24.05.18

BY FAX NO. 88367416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Robinson Road #07-18
Singapore 078920

BY CERTIFICATE OF POSTING
LCR Pte Ltd
80 Anson Road #11-01
Singapore 078914

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Tan Mui Lee to notify you of a road traffic accident on 20.05.18 at about 11:45 am at Geylang Road involving our client's vehicle registration number SKM 7885 B and vehicle registration number SLP 6681 T driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encls:

This is a computer-generated document and requires no signature
cc: client (via e-mail/fax only) - SKM 7885 B

Cheonghoh

Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ct/2KB02-80462.18
Your Ref: SLP 6681 T

24 May 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120
Attn: MOTOR CLAIMS DEPARTMENT

BY EMAIL ONLY
Fax No: 68357416

Dear Sirs

ACCIDENT INVOLVING VEHICLES NO SKM 7865 B AND SLP 6681 T ON 20 MAY 2018 AT/ALONG GEYLANG ROAD -

We refer to the above matter and to your email of 24 May 2018.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your said email.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- 1) Fong Kok Heng
- 2) Danny Yap
- 3) Willy Goh
- 4) Francis Ng
- 5) Dennis Yap
- 6) Louis Ng
- 7) Michael Yap
- 8) LimYong Tian
- 9) Patrick Ng
- 10) Philip Foo

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle at our client's repairer workshop as follows :-

Hup Ley Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Thank you.

Yours faithfully



Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (SKM 7865 B)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish	CRA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	OUT	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	R	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock		2	
1178	990377	Bootlid Rubber	DD	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SKM7865B

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	DDR		
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018 Edit Reg		25 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]		
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K					
Main Claimant:	-					
Vehicle Reg. No.:	SKM7865B	Date of Loss:	20/05/2018 11:00 - :59 [49 Months and 10 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 6984467098SG	Policy/Cover Note No.:	0999994784 (Comprehensive)			
Vehicle Reg. No. (Insured):	SLP6681T	Policy No. (Claimant):				
		Excess:				
Repairer:	Hup Ley Huat Motor Spray Painting Services () BLK 1 KAKI BUKIT AVE 6 #01-35, 409793 Kaki Bukit - Tel:					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/07/2018]					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
AIG_SG (17/07/2018): Request To Upload TP GIA Report			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKM7865B (6984467098SG)**
[SLP6681T]

TP

-

May 20 2018 11:00AM

[LCRF PTE LTD]

Hup Ley Huat Motor Spray Painting Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	06/08/18 15:34	General View														Load JPG				
2	06/08/18 15:34	General View														Load JPG				
3	06/08/18 15:34	General View														Load JPG				
4	06/08/18 15:34	General View														Load JPG				
5	06/08/18 15:34	General View														Load JPG				
6	06/08/18 15:34	General View														Load JPG				
7	06/08/18 15:34	General View														Load JPG				
8	06/08/18 15:34	General View														Load JPG				
9	06/08/18 15:34	General View														Load JPG				
10	06/08/18 15:34	General View														Load JPG				
11	06/08/18 15:34	General View														Load JPG				
12	06/08/18 15:34	General View														Load JPG				
13	06/08/18 15:34	General View														Load JPG				
14	06/08/18 15:34	General View														Load JPG				
15	06/08/18 15:34	General View														Load JPG				
16	06/08/18 15:34	General View														Load JPG				
17	06/08/18 15:34	General View														Load JPG				
18	06/08/18 15:34	General View														Load JPG				
19	06/08/18 15:34	General View														Load JPG				
20	06/08/18 15:34	General View														Load JPG				
21	06/08/18 15:34	General View														Load JPG				
22	06/08/18 15:34	General View														Load JPG				
23	06/08/18 15:34	General View														Load JPG				
24	06/08/18 15:34	General View														Load JPG				
25	06/08/18 15:34	General View														Load JPG				
26	06/08/18 15:34	General View														Load JPG				
27	06/08/18 15:34	General View														Load JPG				
28	06/08/18 15:34	General View														Load JPG				
29	06/08/18 15:34	General View														Load JPG				
30	06/08/18 15:34	General View														Load JPG				
31	06/08/18 15:34	General View														Load JPG				
32	06/08/18 15:34	General View														Load JPG				
33	06/08/18 15:34	General View														Load JPG				
34	06/08/18 15:34	General View														Load JPG				
35	06/08/18 15:34	General View														Load JPG				
36	06/08/18 15:34	General View														Load JPG				
37	06/08/18 15:34	General View														Load JPG				

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/08/18 15:34	General View	 Load JPG	☒
39	06/08/18 15:34	General View	 Load JPG	☒
40	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
41	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
42	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
43	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
44	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
45	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
46	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
47	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
48	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
49	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
50	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
51	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
52	06/08/18 15:36	Photographs of Damaged Parts	 Load JPG	☒
53	06/08/18 15:38	Photo After Spray	 Load JPG	☒
54	06/08/18 15:38	Photo After Spray	 Load JPG	☒
55	06/08/18 15:38	Photo After Spray	 Load JPG	☒
56	06/08/18 15:38	Photo After Spray	 Load JPG	☒
57	06/08/18 15:38	Photo After Spray	 Load JPG	☒
58	06/08/18 15:38	Photo After Spray	 Load JPG	☒
59	06/08/18 15:38	Photo After Spray	 Load JPG	☒
60	06/08/18 15:38	Photo After Spray	 Load JPG	☒
61	06/08/18 15:38	Photo After Spray	 Load JPG	☒
62	06/08/18 15:38	Photo After Spray	 Load JPG	☒
63	06/08/18 15:38	Photo After Spray	 Load JPG	☒
64	06/08/18 15:38	Photo After Spray	 Load JPG	☒
65	06/08/18 15:38	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/07/18 10:18	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009560/GZ4D3E2

Date: 13/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994784

Claimant Vehicle
No : SKM7865B

Insured Vehicle No : SLP6681T

Date of Loss: 20/05/2018

Nature of Claim:

TP

Claim No: 6984467098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM7865B

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 10/04/2014 (Man. Year: 2014)

Chassis No: MNTBBAB17Z0018072

Colour: Grey

Odometer: 139511 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2018

Date Inspected: 30/05/2018 Inspected At:

Hup Ley Huat Motor Spray Painting
Services
BLK 1 KAKI BUKIT AVE 6 #01-35
Singapore 409793

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
9	1		*BOOTLID	Repair	0.00 F	*- F
10	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
11	1		*BOOTLID LOCK	* Check	0.00 F	*- F
12	1		*BOOTLID RUBBER	Dented	0.00 F	*- F
13	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >