

REF: CS1/LAW18009584/u qbsz

Special Instruction:

YS: \$24,000.00

ASSIGNMENT (Office)

From (Person): Sarjeet Singh of Alan Shunkar Date/Time: 24/05/2018

Estimated Cost: 9.00 Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SDS 182K Insured: GBC 279BL

at Workshop m/s K-Auto Care Tel: 109 Kaki Bukit Ave 1 #01-00
of

Policy No: 2015.3537.mlk.ua Claim No: S3/10289/17

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24.11.2015

(Client's Record)

SIF

H.O.D. Enforcement/Date

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 1/12 Confirmed with 1 Final Fig 10, 10 days (Red \$ 1 / 10 %; Original 10 days)

Date/Time: 9/6/18 Submit Final Fig 4/5 8000, 7 days (Red \$ 16000, 17%; Original 10 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add	
Transport	
Photos	
Others	
Total	

Date: _____

1) Date/Time 19/6/18 File Pass to typist

2) Date/Time File Return to

3) Date/Time _____ File Pass to _____

4) Date/Time File Return to

5) Date/Time _____ File Pass to _____

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 24 May, 2018 2:19 PM
To: Sarjeet Singh; assignments
Cc: SUR; Reports (LKKAuto)
Subject: RE: Part 1 of 2 - Appointment of LKK Auto Consultants as SJE in MC Suit No. 12869/2017 Alan Shankar & Lim LLC Ref: SS/10289/117 East Asia Law Corporation ref: 2015.3537.MK.ya
Attachments: D [GBC 2795L] GIA.pdf; P [SDS 182K] GIA.pdf; SDS 182K Survey Photos.pdf; SDS 182K Survey Report.pdf

Dear Sarjeet,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sarjeet Singh [mailto:sarjeet@asllaw.com.sg]
Sent: Thursday, 24 May 2018 2:15 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Reports (LKKAuto) <report@lkkauto.com>
Subject: Part 1 of 2 - Appointment of LKK Auto Consultants as SJE in MC Suit No. 12869/2017 Alan Shankar & Lim LLC Ref: SS/10289/117 East Asia Law Corporation ref: 2015.3537.MK.ya

Dear Veron,

LKK Auto Consultants have been agreed by both parties as the SJE for the above matter.

We act for Sompo Insurance Singapore Pte Ltd for the Defendant driving GBC 2995L and East Asia Law Corporation acts for the Plaintiff driving SDS 182K at the time of the accident.

We attach the following documents:

- 1) Accident statement by Plaintiff [SDS 182K];
- 2) Accident statement by Defendant [GBC 2795L];
- 3) Survey report by Delta V Consultant on SDS 182K;
- 4) Photos by Delta V Consultant on SDS 182K
- 5) PRI by Priority Services on SDS 182K;
- 6) Re-inspection report by Priority Services on SDS 182K

We will be grateful for the SJE report b and the invoice. Thank you.

Best regards,

Sarjeet Singh
Alan Shankar & Lim LLC
151 Chin Swee Road
#09-16 Manhattan House
Singapore 169876
Tel: 6538 1044
Fax: 6538 5231
Website: www.alanshankar-lim.com

Statement of Confidentiality

The contents of this e-mail message and any attachments are confidential and are intended solely for the addressee. The information may also be legally privileged solicitor and client information and is sent in trust, for the sole purpose of delivery to the intended recipient. If you have received this transmission in error, any use, reproduction or dissemination of this transmission is strictly prohibited and may be unlawful. If you are not the intended recipient, please immediately notify the sender by reply e-mail or phone and delete this message and its attachments, if any.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2015 10:53
Date Of Accident	24/11/2015 10:45
Exact Location Of Accident	ALONG PIE WESTBOUND BEFORE TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDS182K
Insured/Policyholder	
Name Of Registered Owner	TAN TIAN SIM
NRIC No	S1708985D
Email Address	TAN.TS@ONYO.COM.SG
Mobile Phone No	(LOCAL) +65-97846351
Alternative Phone No	OFFICE-67770785

Vehicle Particulars

Manufacturer	BMW
Model	BMW 523I 2.5AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1411681501
Cover Note Number	

Driver

Name of Driver	TAN TIAN SIM
NRIC No	S1708985D
Date Of Birth	12/09/1965
Occupation	INDOOR
Date Of Driving Pass	24/02/1993
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97846351
Fax Number	(LOCAL) +65-7732358
Contact Number	OFFICE-67770785
Email Address	TAN.TS@ONYO.COM.SG

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO REAR (TP HIT INSURED)

Weather Conditions RAINING

Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number GBC2795L (COMMERCIAL VEHICLE)

Was any body injured in the Accident? NO

Was any other material or property damaged? NO

Was there any video captured by Car Camera? NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

on the 24th Nov around 10.45am, I was driving along PIE westbound before the toa payoh exit just before ERP gantry. It was raining heavily. Suddenly I noticed something hit me from behind. I got a knock on my left forehead. I stopped my vehicle and I noticed that a Nissan van has hit my rear. The car plate no is GBC2795L. The driver Mr EU apologised for hitting the rear of my car. We exchanged particulars and left the scene. The rear side of my car was dented, the under carriage protection cover drop off. My car restrain system has activated. The alarm came out but air bag was not activated

Are accident photos available for attachment? YES

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) Investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

On the 24th November around 10-45am, I was driving along PIE westbound before the Taa Payoh exit just before ERP gantry. It was raining heavily. Suddenly I noticed something hit me from behind. I got a knocked on my left forehead. I stopped my vehicle, and I noticed that a Nissan Van has hit my rear. The car plate is GSC 295L. The driver Mr. Ngene An Chiang Meng apologise for hitting the rear of my car. We exchange particulars and left the scene. The back rear side of my car was dented the under carriage protection corner drop off. My car restraint system has activated. The alarm came out but Air bag was not activated.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre
Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2015 09:42
Date Of Accident	24/11/2015 10:30
Exact Location Of Accident	ALONG PIE TOWARDS JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2795L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	ETHOZ GROUP LTD
Co Reg No	198104531H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66547777

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TENET SOMPO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	D15MTHCVE000045
Cover Note Number	01/01/2015 - 31/12/2015

Driver

Name of Driver	GN CHIANG MENG EUGENE
NRIC No	S7830967I
Date Of Birth	22/10/1978
Occupation	OUTDOOR
Date Of Driving Pass	02/11/2004
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97493594
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 128 BUKIT MERAH VIEW 16-20
Postcode	150128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- HEAD TO REAR (INSURED HIT TP)
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Was there any video captured by Car Camera?	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN

Are accident photos available for attachment?	YES
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDS182K
Vehicle Make/Model/Colour	B
Details Of Properties	
Name of Driver	TAN TIAN SIM
NRIC/Passport Number	
Contact Number	97846351
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A - GBC2795L
B - SDS182K

A B

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On 24/11/15, 1030 am. I am driving my ~~vehicle~~
Vehicle GBC 279SL along PIE towards Jurong.
At The front vehicle suddenly jam brake.
I manage to jam brake but my vehicle
move forward and touch SDS 182K
rear bumper. There was no injury ~~is~~
involved.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

KENNETH

Sketch Plan Pg. 3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S78309671



GN CHIANG MENG, EUGENE

鄭昌銘

RACE

CHINESE

Date of birth:

22-10-1978

Country of birth:

SINGAPORE

Sex

M

0006567068

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S78309671

Name

GN CHIANG MENG, EUGENE

Birth Date: 22 Oct 1978

Issue Date: 14 Jul 2003



#311036



NRIC No: S78309671

Date of issue:

24-11-2008

APT BLK 129 DUKIT MERAH VIEW #18-20
SINGAPORE 150128

NRIC No: S78309671

Date: 03/05/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 2B Motorcycles <= 200 CC

12 Jul 1999

Class 2A Motorcycles between 201 CC and 400 CC

14 Dec 2001

Class 3 Motor cars <= 3000 kg with <= 9 passengers, excluding of the driver, and motor tractors/vehicles <= 2500 kg

03 Nov 2014

S78309671

S / No: 5000016506



NP 426A

DELTA-V CONSULTANT

Motor Vehicle Appraisal & Inspection Services, Accident Collision Investigation & Reconstruction Consultant

Reg. No: 52954213K

Our Reference: 0H2711 - K-AUTO

04 February 2016

3537

Tan Tian Sim
C/o K-Auto Care
109 Kaki Bukit Avenue 1
#01-00 Shun Li Industrial Park
Singapore 415989

INVOICE No. 0H2711 - 1608

Vehicle No. SDS 182 K

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, photographs, transport and miscellaneous	\$741.00
Total amount payable		\$741.00

Kindly cross your cheque in favour of "DELTA V Consultant".

We thank you in anticipation for your prompt payment.



Manager

DELTA-V CONSULTANT

Motor Vehicle Appraisal & Inspection Services, Accident Collision Investigation & Reconstruction Consultant

Reg. No: 52954213K

Our Reference: 0H2711 - K-AUTO

04 February 2016

APPRAISAL REPORT

Tan Tian Sim
C/o K-Auto Care
109 Kaki Bukit Avenue 1
#01-00 Shun Li Industrial Park
Singapore 415989

GENERAL INFORMATION

Vehicle Reg No.	SDS 182 K	Year of Reg.	2011
Make & Model	BMW 523i	Colour	Brown
Chassis Number	WBAFP32000C864286	Speedo Reading	140133 km
Assigned by	Owner Request	Type Of Survey	Third Party
Date Of Accident	24 Nov 2015	Date Inspected	27 Nov 2015
Workshop	K-Auto Care 109 Kaki Bukit Avenue 1 #01-00 Shun Li Industrial Park Singapore 415989		

MECHANICAL CHECKS

Steering	Serviceable	Paintwork	Good
Footbrake	Serviceable	Gen. condition	Good
Handbrake	Serviceable		

TYRE CONDITION

	Size	Left Tread / Make	Right Tread / Make
Front	225/55R17	60%/Dunlop	60%/Dunlop
Rear	225/55R17	60%/Dunlop	60%/Dunlop

DESCRIPTION OF IMPACT AND DAMAGE

The vehicle sustained damages to its rear portion.
Details are as described in the attached Annex for parts and labour

SUMMARY

As assigned by your goodself, the above-mentioned vehicle has been inspected on a "Without Prejudice" basis
Appraised repairs cost is **\$24,000.00** and **10** days is required for the repairs.

DELTA-V CONSULTANT

Reg. No: 52954213K

Motor Vehicle Appraisal & Inspection Services, Accident Collision Investigation & Reconstruction Consultant

Spare Parts And Labour Assessment

Our reference : 0H2711 - K-AUTO

Vehicle No: SDS 182 K

Results of my inspection of the said accident vehicle are as shown below.

Parts Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
Bootlid	1460	1 distorted <i>DD/bul</i>	2,572.50	2,572.50 ✓
Bootlid top lock	1	1 jammed <i>twl</i>	373.80	373.80 ✓
Bootlid weatherstrip	1	1 necessary <i>nu</i>	220.50	220.50 ✓
Bootlid stopper	1	1 necessary <i>11</i>	52.50	52.50 X
Bootlid lamp lh	1	1 cracked <i>11</i>	719.25	719.25 X
Bootlid lamp rh	338.50	1 cracked <i>CAR</i>	719.25	719.25 ✓
Bootlid BMW logo	6325	1 necessary <i>nu</i>	131.25	131.25 ✓
Bootlid 523i emblem	74.00	1 necessary <i>nu</i>	100.80	100.80 ✓
Rear bumper	1397.00	1 deformed <i>de/fo.1</i>	2,047.50	2,047.50 ✓
Rear bumper center guide *	1	1 necessary <i>nu</i>	73.29	73.29 ✓
Rear bumper towing cover	1	1 deformed <i>de</i>	61.43	61.43 ✓
Rear bumper reflector lh	1	1 cracked <i>11</i>	71.40	71.40 X
Rear bumper reflector rh	1	1 cracked <i>11</i>	71.40	71.40 X
Rear bumper beam	1	1 bent <i>NS</i>	367.50	367.50 X
Rear bumper top garnish	1	1 not necessary <i>11</i>	236.25	0.00 X
Rear bumper corner bracket plastic @ \$153.09	2	2 not necessary <i>11</i>	306.18	0.00 X
Rear bumper bottom garnish	82	1 deformed/torn <i>de</i>	142.28	142.28 ✓
Rear bumper bottom garnish side @ \$112.82	2	2 deformed/torn <i>de</i>	225.64	225.64 ✓
Rear bumper side retainer @ \$104.79	2	2 necessary <i>nu</i>	209.58	209.58 ✓
Rear bumper reinforcement	684	1 bent <i>DD</i>	895.13	895.13 ✓
Rear bumper sensor	980	1 set malfunctioned <i>shut</i>	1,113.00	1,113.00 ✓
Rear bumper sensor holder	16.60	1 necessary <i>nu</i>	126.00	126.00 ✓
Rear bumper wire harness set	1	1 malfunctioned <i>11</i>	2,184.00	2,184.00 X
Rear end panel	804.10	1 distorted <i>DD</i>	1,312.50	1,312.50 ✓
Taillamp lh	1	1 cracked <i>11</i>	984.90	984.90 X
Taillamp rh	1	1 cracked <i>11</i>	984.90	984.90 X
Rear exhaust pipe	1	1 distorted <i>de</i>	2,588.25	2,588.25 X
Rear exhaust chrome @ \$236.25	2	2 distorted <i>bul</i>	472.50	472.50 ✓
Airbag control module	1	1 malfunctioned <i>11</i>	2,526.30	2,526.30 X
Front headrest and sensor @\$1,149.96	304.20	2 deployed (<i>Repair</i>) <i>Appl</i>	2,299.92	2,299.92 ✓
Front seatbelt tensioner @ \$866.46	(No evidence show damage)	2 deployed (<i>only</i>) <i>11</i>	1,732.92	1,732.92 X
Sub-total before discount			25,922.62	25,380.19
Percentage discount 5% and 5%			1,296.13	1,269.01
Sub-total			24,626.49	24,111.18

786057
7448.53

DELTA-V CONSULTANT

Reg. No: 52954213K

Motor Vehicle Appraisal & Inspection Services, Accident Collision Investigation & Reconstruction Consultant

Rear number plate	1 grazed	50.00	50.00	40
	Sub-total before discount	50.00	50.00	
Percentage discount	0% and 0%	0.00	0.00	
	Sub-total	50.00	50.00	
	Parts-total	24,676.49	24,161.18	

Labour Description

1. Remove and replace damaged portion	1,400.00	1,000.00	950
2. Check wiring	200.00	150.00	30
3. Remove/refix reverse sensor	150.00	120.00	50
4. Remove/refix exhaust pipe	180.00	120.00	✓
5. Remove/refix rear upholstery	180.00	150.00	80
6. Remove and replace seatbelt & headrest	450.00	400.00	180
7. Remove/refix rear fuse box & rear wire harness	500.00	300.00	X
8. Reprogramme ECU	500.00	400.00	250
9. Spray painting	1,400.00	800.00	✓
10. Tuff Kote	200.00	150.00	60
Labour total	5,160.00	3,590.00	
Parts & Labour total	29,836.49	27,751.18	

The vehicle has been inspected thoroughly on the actual damages found, the age and pre-accident condition has been taken into consideration during my inspection.

Hence, I recommend that the vehicle be repaired base on a lump sum of:

\$24,000.00

Commended number of days for the repairs is :

10

1000f23

Only

Joshua Ong
Motor Appraiser
B.Eng (Mech)(Hons)



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Your Ref. : CMTD01503223
Our Ref. : TP-0143/11/15

Date : 03-Dec-2015

Tenet Somp Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attn. : Ms. Irene Henry

Dear Sirs/Madam,

Pre-Repair Inspection

Vehicle No.: SDS 182 K

Date Of Accident: 24-Nov-2015



Date and Time of Request : 26-Nov-2015 / 12.40pm

Date and Time of Inspection : 27-Nov-2015 / 12pm
@ K-Auto Garage Pte Ltd

Particulars of Vehicle

Registration No. : SDS 182 K
Make / Model : B.M.W / 523i (A)
Year : 2011
Colour : Met. Brown
Odometer : 140133 km
Engine Capacity : 2497 cc
Carrying Capacity : 04
Engine No. : -
Chassis / Body Frame : WBAFP32000C864286
Radio / CD Player : Yes
Air-Con Conditioner : Yes
Other Apparent Accessories: No
Spare Tyre : Intact
Jack / Tools : Intact

(51) Photographs of vehicle taken.

Visual Damages

At the rear portion.

Damages subject to consistency.

Remarks

Despite our request, the repairer would not provide:-

- 1) Repairer estimate
- 2) SAS for Third Party driver

Damages at the front portion might not be related to this accident.

Estimated period of repair: 5 days

Estimated repair cost: About \$4k



Yours Very Truly
PRIORITY SERVICES


Jeffrey Ong
Motor Appraiser



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 29 July 2016

Your Ref: CMTD1503223

Our Ref: TP-0087/07/16

Motor Claims Department
M/s. Sompoo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Ms. Agnes Chan

Madam,

Re-inspection of 2011 BMW 523i (A)
Registration No.: SDS 182 K
Odometer Reading: 156240 km
Chassis No.: WBAFP32000C864286

We refer to your instructions to us to conduct a re-survey of the above vehicle. A pre-repair inspection was conducted by us on 27-11-2015.

The following documents were received: -

- 1) Copy of survey report by M/s. Delta-V Consultant
- 2) 56 copies of photos depicting damages sustained by SDS 182 K
- 3) Accident reports by drivers of SDS 182 K and GBC 2795 L
- 4) 4 copies of photos showing condition of GBC 2795 L and 4 copies of scene photos

On 22-07-2016, we conducted a re-inspection of the above @ M/s. K-Auto Garage Pte Ltd, 109 Kaki Bukit Ave 1 #01-00 Shun Li Industrial Park, Singapore 415989.

The vehicle sustained rear damages during an accident on 24-11-2015.

Repair cost submitted was \$24,000.00 lump-sum.

We append below our findings: -

Replacement of Parts		Revised Amount	Our Recommendation
1pc.	Boot lid	\$ 2,572.50	\$ 1,460.00
1pc.	Boot lid top lock – refitted	373.80	-
1pc.	Boot lid weatherstrip – visually intact/not necessary	220.50	-
1pc.	Boot lid stopper – visually intact/not necessary	52.50	-

1pc.	Boot lid lamp LH – visually intact	\$ 719.25	\$ -
1pc.	Boot lid lamp RH	719.25	338.50
1pc.	Boot lid BMW logo	131.25	63.25
1pc.	Boot lid 523i emblem	100.80	74.00
1pc.	Rear bumper	2,047.50	1,397.00
1pc.	Rear bumper centre guide	73.29	73.29
1pc.	Rear bumper towing cover	61.43	66.00
1pc.	Rear bumper reflector LH – visually intact	71.40	-
1pc.	Rear bumper reflector RH – visually intact	71.40	-
1pc.	Rear bumper beam – not in use	367.50	-
1pc.	Rear bumper bottom garnish	142.28	82.00
2pcs.	Rear bumper bottom garnish side – no evidence of damage	225.64	-
2pcs.	Rear bumper side retainer	209.58	238.00
1pc.	Rear bumper reinforcement	895.13	684.00
1set	Rear bumper sensor	1,113.00	980.00
1pc.	Rear bumper sensor holder	126.00	16.80
1pc.	Rear bumper wire harness set – no evidence of damage	2,184.00	-
1pc.	Rear end panel – slightly dented/repairable	1,312.50	-
1pc.	Tail lamp LH – refitted	984.90	-
1pc.	Tail lamp RH – refitted	984.90	-
1pc.	Rear exhaust pipe	2,588.25	1,306.00
2pcs.	Rear exhaust chrome	472.50	228.90
1pc.	Airbag control module – not necessary	2,526.30	-
2pcs.	Front headrest crash repair kit	2,299.92	304.20
2pcs.	Front seatbelt tensioner – no evidence of damage	1,732.92	-
		<u>\$ 25,380.19</u>	<u>\$ 7,311.94</u>
	Less 5%	<u>1,269.01</u>	<u>365.60</u>
		<u>\$ 24,111.18</u>	<u>\$ 6,946.34</u>

Special Nett Items:-

1pc.	Rear number plate	\$ 50.00	\$ 35.00
	Total For Parts:-	<u>\$ 24,161.18</u>	<u>\$ 6,981.34</u>

Labour Charges:-

Remove and replace damaged portions.	\$ 1,000.00	\$ 750.00
Check wiring.	150.00	150.00
Remove/refit reverse sensor.	120.00	120.00
Remove/refit exhaust silencer.	120.00	120.00
Remove/refix rear upholstery.	150.00	150.00
Remove and replace headrest crash repair kit.	400.00	180.00

Remove/refix rear fuse box and rear wire harness.	\$ 300.00	\$ -
Reprogramme ECU.	400.00	250.00
Spray painting.	800.00	600.00
Tuff kote.	150.00	30.00
Total:-	<u>\$ 27,751.18</u>	<u>\$ 9,331.34</u>
Lump-sum repairs:	\$ 24,000.00	\$ 7,450.00

1) Parts price have been checked and amended.

Estimated period of repairs: 7 working days

Photos of the present condition of the vehicle taken by us are enclosed.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully
PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser

Surveyed by:


LAWRENCE NG
Motor Appraiser

Encl.



Your Ref: SS/10289/117

Date: 27th June 2018

Our Ref: CS1/LAW18009584/Uqbs2

M/s Alan Shankar & Lim LLC

151 Chin Swee Road

#09-16 Manhattan House

Singapore 169876

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SDS 182K INSURED VEHICLE: GBC 2795L ACCIDENT DATE: 24/11/2015**

We thank you for your instruction on 24/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDS 182K from M/s Priority Services.
- b) Survey report by Delta-V Consultant with colour photographs.
- c) Singapore Accident Statement of Vehicles SDS 182K and SGC 2795L.
- d) Colour damaged vehicle photographs of SDS 182K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDS 182K
Make & Model	: BMW 523I
Year of Registration	: 2011
Chassis Number	: WBAFP32000C864286
Engine Capacity	: 2497 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDS 182K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BENT	2,572.50	1,460.00
1	BOOTLID TOP LOCK	TWISTED	373.80	373.80
1	BOOTLID WEATHERSTRIP	NECESSARY	220.50	220.50
1	BOOTLID STOPPER	NOT NECESSARY	52.50	-
1	BOOTLID LAMP LH	NOT NECESSARY	719.25	-
1	BOOTLID LAMP RH	CRACKED	719.25	338.50
1	BOOTLID BMW LOGO	NECESSARY	131.25	63.25
1	BOOTLID 523I EMBLEM	NECESSARY	100.80	74.00
1	REAR BUMPER	DEFORMED / TORN	2,047.50	1,397.00
1	REAR BUMPER CENTER GUIDE	CRACKED	73.29	73.29
1	REAR BUMPER TOWING COVER	DEFORMED	61.43	61.43
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	71.40	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	71.40	-
1	REAR BUMPER BEAM	NO SUCH PARTS	367.50	-
1	REAR BUMPER TOP GARNISH	NOT NECESSARY	236.25	-
2	REAR BUMPER CORNER BRACKET PLASTIC @ \$153.09	NOT NECESSARY	306.18	-
1	REAR BUMPER BOTTOM GARNISH	DEFORMED	142.28	82.00
2	REAR BUMPER BOTTOM GARNISH SIDE @ \$112.82	DEFORMED	225.64	225.64
2	REAR BUMPER SIDE RETAINER @ \$104.79	NECESSARY	209.58	209.58
1	REAR BUMPER REINFORCEMENT	DENTED	895.13	684.00
1	SET REAR BUMPER SENSOR	SHORTED	1,113.00	980.00
1	REAR BUMPER SENSOR HOLDER	NECESSARY	126.00	16.80
1	SET REAR BUMPER WIRE HARNESS	NOT NECESSARY	2,184.00	-
1	REAR END PANEL	DENTED	1,312.50	804.10
1	TAILLAMP LH	NOT NECESSARY	984.90	-
1	TAILLAMP RH	NOT NECESSARY	984.90	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	2,588.25	-
2	REAR EXHAUST CHROME @ \$236.25	BENT	472.50	472.50
1	AIRBAG CONTROL MODULE	NOT NECESSARY	2,526.30	-
2	FRONT HEADREST AND SENSOR @ \$1149.96	ACTIVATED	2,299.92	304.20

Report Ref No. CS1/LAW18009584/Uqbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SEATBELT TENSIONER @\$866.46 LESS 5% DISCOUNT	NOT NECESSARY	1,732.92 -1,296.13 24,626.49	- -392.03 7,448.56
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	GRAZED	50.00 50.00	40.00 40.00
	<u>LABOUR</u>			
	REMOVE AND REPLACE DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE. CHECK WIRING.		1,400.00 200.00	950.00 30.00
	REMOVE / REFIX REVERSE SENSOR.		150.00	50.00
	REMOVE / REFIX EXHAUST PIPE.		180.00	120.00
	REMOVE / REFIX REAR UPHOLSTERY.		180.00	80.00
	REMOVE AND REPLACE SEATBELT & HEADREST.		450.00	180.00
	REMOVE / REFIX REAR FUSE BOX & REAR WIRE HARNES.	NOT NECESSARY	500.00	-
	REPROGRAMME ECU.		500.00	250.00
	SPRAY PAINTING.		1,400.00	800.00
	TUFF KOTE.		200.00	60.00
			5,160.00	2,520.00
GRAND TOTAL			29,836.49	10,008.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CS1/LAW18009584/Uqbs2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.