

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGH3433p

at Workshop m/s BMW

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 20

IDAC Accident Report Consistent?: Yes or No

G/A / PR Seen: 9 Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 31/5/2014

Date: _____ Person Contacted: _____

Veh No: SGH3433p Yr Regn: 6,06

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: M.F Lence G.C. 1584

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 241022 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCS3A64009880

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodyear

Front R/Bal. 5 mm Rear R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/5/18 D.O.I. 28/5/18

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision: Rear

Date / Time	Action / Instruction
	LTA 13710 3yrs net 6290
	45 @ 5200
08/06/18	(£ 11,121.00 - £ 5,200) - Reduction = 53%

RECEIVED 08 JUN 2018

Date/Time, File Pass to? 08/06/18

1) Final : Prel. Report : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ 5,200/45)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Survey Fee: 170+15

Transportation: 50

Photo: 66

Others: 80

TOTAL: 481

1x15=15

Ref. No :	CS/TP18009605/usb ⁿ²	Res. Date:	28/5/18	Date Received:	
Veh. No :	SAM34337	SP:		WKSP:	<i>[Signature]</i>
C/No :					
Action/Instruction:					
1.File	2.Submit Photo?	YES / NO			
3.Indicate Res. Date On Photo Page?		YES / NO		Message:	
If No, due to	a) No authorisation	b) Days of repair			
others:					
Final Re-inspection	or	Progress Photos		Inspected By:	<i>[Signature]</i>

COME VOLUNTEER WITH US!

Sharing & Serving

If you are 40 years old and above and are able to spend half a day every mo to contribute your talents and skills in many meaningful ways, we want you

Home » Used Cars » Auto Quest Singapore » Mitsubishi Lancer 1.6M GLX Sports (COE till 01/2021)

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)




Mitsubishi Lancer 1.6M GLX Sports (COE till 01/2021)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#)

Car Details

Price	\$21,900	?
Depreciation	\$8,410 /yr	?
Reg Date	03-Jan-2006 (2yrs 7mths 5days COE left)	
Manufactured	2005	?
Mileage	-	
Transmission	Manual	
Engine Cap	1,584 cc	?
Road Tax	\$881 /yr	
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)	
Features	Powerful And Fuel Efficient 1.6L Inline 4 Cylinders 16 Valves SOHC Engine, Smooth 5 Speed Manual Transmission, ABS.	
Accessories	Solar Film, Reverse Sensors, Audio System, Spoiler, Bodykit.	
Description	Beautifully Done Up Sports Model! Save Thousands Of Dollars For Those Who Appreciated! Frozen Matt Black With Carbon Fibre Roof & Rear Bumper Vertex! Matching Bronze Sports Rims That Make The Whole Car Very Sporty Yet Classy! Very Good Running Condition! Must Really View And Test It Yourself To Be Convince! Scrap Now Coming To \$16K Already! Safe Buy! \$2K Downpayment Will Do! Grab Before Others Do!	
COE	\$28,317	?
OMV	\$11,349	?



Seller Infor

Company

Address

Location

Office No

[Compare](#)

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Mitsubishi Lancer Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » SG Car Consign Pte Ltd » Mitsubishi Lancer 1.6M GLX (COE till 07/2021)

Resources

[Car Buying](#)

[Car Selling](#)

[Car Ownership](#)

[Car Aftermarket](#)

[On The Move](#)

[Lifestyle](#)

Vehicle Number Plates

Mitsubishi Lancer 1.6M GLX (COE till 07/2021)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#)

Car Details

Price	\$22,900	
Depreciation	\$7,240 /yr	?
Reg Date	26-Jul-2006 (3yrs 1mth 27days COE left)	
Manufactured	2006	?
Mileage	-	
Transmission	Manual	
Engine Cap	1,584 cc	
Road Tax	\$881 /yr	?
Power	79.0 kW (105 bhp) View specs of the Mitsubishi Lancer (2006-2008)	
Curb Weight	1,162 kg	?
Features	-	
Accessories	-	
Description	The Most Reliable And Fuel Efficient Red Sedan. Well Maintained. Well Taken Care By Owner. Low Maintenance. Easy To Maintain. Suitable For Any Driver. Flexible Loan Available, Trade In Welcome. No Obligation. Please Call To Arrange For Viewing!	
COE	\$24,760	?
OMV	\$11,595	?
ARF	\$12,755	?
Dereg Value	\$15,656 as of today (change)	?
No. of Owners	4	?
Type of Veh	Mid-Sized Sedan	



Seller Infor

Company

Address

Location

Office No

Contact Perso

[Compare](#)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5358E
Vehicle Details	
Vehicle No.:	SGH3433P
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	MINISUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	4G18HJ0096
Chassis No.:	JMYSTCS3A6U009880
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,603.00
Original Registration Date:	08 Jun 2006
First Registration Date:	08 Jun 2006
Transfer Count:	0
Actual ARF Paid:	\$13,864.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$13,710.00
Total Rebate Amount:	\$13,710.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 May 2018

OK

https://www.giamc.org.sg/claims/index.cfm?fusebox=MTTRclaim&fuseaction=gen_doc... 2/5/2018

MSME18057831 / SME Motor Pte Ltd - Mail Built
 ENTRY DATE & TIME: 24/05/2018 15:18
 SUBMITTED BY: Chio Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 15:15
Date Of Accident	23/05/2018 23:15
Exact Location Of Accident	UPP SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH3433P
Insured/Policyholder	
Name Of Registered Owner	YIP PEK KHUAN
NRIC No	S1435358E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96389136
Alternative Phone No	OFFICE-96389136
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC17S006164
Cover Note Number	
Driver	
Name of Driver	YIP PEK KHUAN
NRIC No	S1435358E
Date Of Birth	05/08/1960
Occupation	INDOOR
Date Of Driving Pass	07/04/1979
Driving Experience	39 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96389136
Fax Number	
Contact Number	OFFICE-96389136
Email Address	NOEMAIL

Address BLK 91 DAWSON ROAD #17-24
 Postcode 144091
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 23/05/2018 AT ABOUT 11.15PM, I WAS DRIVING ALONG UPP SERANGOON ROAD ON THE MOST OUTER RIGHT LANE. VEHICLE IN FRONT SLOWED DOWN AND I FOLLOWED. SUDDENLY, VEHICLE B HIT THE REAR OF MY VEHICLE. I DID NOT HIT THE VEHICLE IN FRONT OF MINE.

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF7695T
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver GOH KAI HOO
 NRIC/Passport Number S1779597Z
 Contact Number 96706435
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/5/18 at about 11:15pm, I was driving along Upper Serangoon Road on the most outer right lane. Vehicle in front slowed down and I followed. Suddenly vehicle B hit the rear of my vehicle. I did not hit the vehicle in front of mine.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature

Date & Time: 24/5/18, 11:30 am

[Signature]
 Driver's Signature


(If driver is not the policyholder)
 Date & Time: 24/5/18, 11:30 am

Reporting Centre Personnel's Signature

Name:
 NRIC/FIN No.:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation



Acknowledged by Repairer

Signature:

Nett iter

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 KAKI BUKIT AVE B (UNIT B) #01-28

(Unit C) #01-28-53/55 Singapore 417883

Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088

Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg

Co. Reg. No.: 200704951N

GST Reg. No.: 200704951N

not added
 2/585200
 6h.

SGH3433P

	Boothlid	body	645.00	N	/
	Boothlid outer garnish	body	197.00	N	/
	Boothlid Rear logo	acc	38.00	N	/
	Boothlid 'Lancer' emblem	acc	39.00	N	/
2 pcs	Boothlid hinges @ 75.00	N	150.00	N	X
	Boothlid inner lock	tool	85.00	N	/
	Boothlid weatherstrip	tool	171.00	N	/
2 pcs	tailamps @ 384.00	acc	768.00	N	/
2 pc	tailamp housing panels @ 162.00	N	324.00	N	X
	Rear bumper	dis	681.00	N	/
	Rear bumper beam	body	174.00	N	/
2 pcs	Rear bumper side retainers @ 46.00	body	92.00	N	/
1 set	Rear bumper clips	acc	50.00	N	/
	Rear end panel	body	442.00	N	/
	Rear end panel top garnish	tool	168.00	N	/
2 pc	Rear fenders @ 671.00	N	1342.00	N	X
2 pcs	Rear fender inner trims @ 242.00	tool	484.00	N	/
	Rear floor panel	N	911.00	N	X
	Rear floor panel top board	tool	164.00	N	/
	Rear exhaust silencer	N	454.00	N	X
1 set	Rear bumper reverse sensor	slut	220.00	N	/
	Rear licence plate w/holder	body	42.00	N	/
			7641.00		4460
	To check wiring		50.00		30
	To Dismantle & replacing reverse sensor		80.00		50
	To spray rust proofing		100.00		80
	To Dismantle & refix seat cushion upholstery		150.00		100
	labour for panel beating & replacing parts		1500.00		950
	To putty & spray painting		1500.00		1280
	To transfer Boothlid components		100.00		60 6354

TOTAL = 11121.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18009605/Usbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 11-06-2018



ON BEHALF OF YIP PEK KHUAN

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SGH 3433P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER (A)	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JMYSTCS3A6U009880	Colour	SILVER
Odometer	241022	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/60 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/60 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/60 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/05/2018	Inspection Date	28/05/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 3433P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID (N)	BADLY DENTED	645.00	645.00
1	BOOTLID OUTER GARNISH (N)	BENT / CRACKED	197.00	197.00
1	BOOTLID REAR LOGO (N)	NECESSARY	38.00	38.00
1	BOOTLID "LANCER" EMBLEM (N)	NECESSARY	39.00	39.00
2	BOOTLID HINGES @\$75.00 (N)	TO REPAIR SEE LABOUR	150.00	-
1	BOOTLID INNER LOCK (N)	TWISTED	85.00	85.00
1	BOOTLID WEATHERSTRIP (N)	TWISTED	171.00	171.00
2	TAILLAMPS @\$384.00 (N)	CRACKED	768.00	768.00
2	TAILLAMP HOUSING PANELS @\$162.00 (N)	TO REPAIR SEE LABOUR	324.00	-
1	REAR BUMPER (N)	DISTORTED	681.00	681.00
1	REAR BUMPER BEAM (N)	BENT	174.00	174.00
2	REAR BUMPER SIDE RETAINER S@\$46.00 (N)	BENT	92.00	92.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	50.00	50.00
1	REAR END PANEL (N)	BADLY DENTED	442.00	442.00
1	REAR END PANEL TOP GARNISH (N)	TWISTED	168.00	168.00
2	REAR FENDERS @\$671.00 (N)	TO REPAIR SEE LABOUR	1,342.00	-
2	REAR FENDER INNER TRIMS @\$242.00 (N)	TORN	484.00	484.00
1	REAR FLOOR PANEL (N)	TO REPAIR SEE LABOUR	911.00	-
1	REAR FLOOR PANEL TOP BOARD (N)	TORN	164.00	164.00
1	REAR EXHAUST SILENCER (N)	TO REPAIR SEE LABOUR	454.00	-
1	SET REAR BUMPER REVERSE SENSOR (N)	SHORTED	220.00	220.00
1	REAR LICENCE PLATE W/HOLDER (N)	BENT	42.00	42.00
	LESS 10% DISCOUNT		-	-446.00
			7,641.00	4,014.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO SPRAY RUST PROOFING.		100.00	80.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00

Report Ref No. CS/TP18009605/Usbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID HINGES,TAILLAMP HOUSING PANELS,REAR FENDERS,REAR FLOOR PANEL AND REAR EXHAUST SILENCER.		1,500.00	950.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,280.00
	TO TRANSFER BOOTLID COMPONENTS.		100.00	60.00
			3,480.00	2,550.00
	GRAND TOTAL		11,121.00	6,564.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00

Report Ref No. CS/TP18009605/Usbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.