

ASS. REC. BY:

REF:

CS/MSH 18009609 / Tlsb 94

Special Instruction:

SURVEYOR

malim

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSH

Date/Time:

25/05/2018 4:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 8913A

Insured:

SJV 673Z

at Workshop m/s

Borneo Motor

Tel:

9847 6178

of

2 Pandan Crescent

Policy No:

A2781-7272 QMY

Claim No:

559350

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/05/2018

CA / REV / REP. / REV 24 HRS WPI

3:30pm

H.O.D. Endorsement:

Date/Time:

25/05/2018 1:39pm

Person Contacted:

Wally

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 8913A - X

SJV 673Z - X

20/05/18 @ 17:48 p.m. revised IA to Katherine Wong Chew Sheng vic marine

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	25 May 2018		25 May 2018 16:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LOO CHEONG FOOK, ID: S0179903G, Tel: +6597370380, Email: NOEMAIL								
Main Claimant:	TAY LIM HENG, ID: S1600469C								
Vehicle Reg. No.:	SLW8913A	Date of Loss:	24/05/2018 07:00 - :59 [2 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559350	Policy/Cover Note No.:	A27817272QMY (Comprehensive) Coverage: 09/01/2018 - 08/01/2019						
Vehicle Reg. No. (Insured):	SJV673Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/05/2018]								
Driver/Custodian (Insured):	LOO CHEONG FOOK (68 / Male), NRIC: S0179903G, Tel: +6597370380								
Adj. Asg. Remarks:	on WP. Survey on 28/05/18, 3.30pm. Owner waiting. Please contact us ASAP if you cannot attend this assignment. Liability : 100%. Contact person : Wally Tan @9847 6178 / 6631 1506. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Wally Tan TCBC <wally.tan@borneomotors.com.sg>
Sent: Thursday, 28 June 2018 3:14 PM
To: Shirley Hiew (LKK Auto)
Subject: RE: Final bill for SLW8913A

Hi Shirley,

Yes confirmed.

Regards
Wally

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 25 June 2018 4:58 PM
To: Wally Tan TCBC
Cc: 'SUR'
Subject: FW: Final bill for SLW8913A

Hi Wally,

kindly confirmed finalised P/P amount \$ 16,520.58 and 9 repair days.

Thank you.
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Wally Tan TCBC [mailto:wally.tan@borneomotors.com.sg]
Sent: Saturday, 23 June 2018 10:31 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>
Subject: RE: Final bill for SLW8913A

Hi Taufikh/Catherine,

Please find attached final bill of SLW8913A for your kind perusal.

Regards
Wally TCBC

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited.

Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose. This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited.

Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose. This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 30 May 2018

Preliminary Advice

Insured Vehicle No	: SJV673Z	Accident Date	: 24/05/2018
TP Vehicle No	: SLW8913A	Assignment Date	: 25/05/2018
Make	: TOYOTA LEXUS	Est. Duration of Repair	: 9 days
Date of Inspection	: 28/05/2018		
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,062.00
Revised Amount	:S\$	17,391.20
Check Items (Estimated)	:S\$	291.80
Total	:S\$	17,683.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 14:04
Date Of Accident	24/05/2018 07:15
Exact Location Of Accident	PIE BFR BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW8913A
Insured/Policyholder	
Name Of Registered Owner	TAY LIM HENG
NRIC No	S1600469C
Email Address	LIMNLYN@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98183877
Alternative Phone No	OFFICE-96972731
Vehicle Particulars	
Manufacturer	LEXUS
Model	ES300H-2.5 EXECUTIVE (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2087737
Cover Note Number	
Driver	
Name of Driver	TEOW WEILING LYNETTE
NRIC No	S1828083C
Date Of Birth	03/02/1967
Occupation	INDOOR
Date Of Driving Pass	18/03/1993
Driving Experience	25 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96972731
Fax Number	
Contact Number	
EMail Address	LIMNLYN@YAHOO.COM

	4 JALAN BINCHANG
Postcode	578582
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV673Z
Vehicle Make/Model/Colour	HYUNDAI/GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOO CHEONG FOOK
NRIC/Passport Number	S0179903G
Contact Number	97897591
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: ;
	GENDER: ;

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
24/5/18
10:30am
Policyholder's Signature / Date & Time

[Signature]
24/5/18
10:30am
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Please see video.

Turn along P/E - Car SJU 6732 cut into my lane & hit my car on the back right

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

24/5/18
10.30 am



Driver's Signature (If driver is not the policyholder) / Date & Time

24/5/18
10.30 am

Witnessed by Reporting Centre Personnel



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Account Detail

Account No

Customer Detail

THIRD PARTY CLAIM

S1000020/TPCLAIM

Mr Tay Lim Heng
4 Jalan Binchang

Document No

0

Singapore 578582

Document Date

24/05/2018

Mobile: 96972731

Year Make Model Reg Date Veh Reg No Kilometers WIP No Order No/Remarks

18 BEXGB S5 AVV60R 08/03/2018 SLW8913A 0 15422 4TP/SLW8913A/24051:

Chassis No Engine No TWC No Terms Lexus Consultant Vehicle In Collected On

JTHBW1GG702183349 2AR1893490 60 Wally Tan G H 24/05/2018 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80 100.00
2	B	BP-WS REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				✓ 816.00
3	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)				✓ 420.00
4	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 204.00
5	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)				✓ 204.00
6	B	BP-LAB REMOVE/REFIX RHS ROCKER MLDG TO ASSIST REPAIR. (NETT)				✓ 204.00
7	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.				612 816.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of **LK Auto Consultants** Customer's Signature
Borneo Motors

Change Summary

Total

Less

Amount Due

Acknowledged by Repairer

PLEASE TEAR ALONG PERFORATED LINE

Signature

Date

DATE 24/05/2018

TIME 14:32

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000020 / TPCLAIM		Customer Detail				
THIRD PARTY CLAIM		Document No 0		Mr Tay Lim Heng 4 Jalan Binchang				
		Document Date 24/05/2018		Singapore 578582 Mobile: 96972731				
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
18	BEXGB	S5	08/03/2018	SLW8913A	0	15422	4TP/SLW8913A/24051	
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBW1GG702183349		2AR1893490	60	Wally Tan G H	24/05/2018	0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
8	B	BP-LAB REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHS, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)						✓ 816.00 4080
9	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN, R/R DOOR, R/R WHEEL ARCH PANEL, R/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS.						4896.00 2100
10	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.						2450.00
11	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)						✓ 816.00
12	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)						✓ 612.00
13	S	BP-SUBLET TRANSFER R/R TYRE TO NEW WHEEL RIM AND BALANCING. (NETT)						✓ 102.00
14	1	L67857-33040	PROTECTOR, RR DOOR		1.00	10.80		Net 10.80 9.18
15	2	L75473-33060	PLATE, BODY SIDE		1.00	76.80		Net 76.80 65.2
16	3	L61611-33250	PANEL, QUARTER RH		1.00	1449.90		Net 1449.90 1252
17	4	L58747-33071	PROTECTOR, QUART		1.00	27.70		Net 27.70 23.89
18	5	L64801-33905	GLASS, BACK WINDOW		1.00	1571.60		Net 1571.60 1330
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less		
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 24/05/2018
TIME 14:32

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020/TPCLAIM	Mr Tay Lim Heng 4 Jalan Binchang Singapore 578582 Mobile: 96972731
	Document No 0	
	Document Date 24/05/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	BEXGB	S5	08/03/2018	SLW8913A	0	15422	4TP/SLW8913A/24051:

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG702183349	2AR1893490	60	Wally Tan G H	24/05/2018	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
19	6	L75573-33080 MOULDING, BACK WINDOW	1.00	58.40		net 58.40 49.6
20	7	L56117-50140 DAM, WINDOW GLASS	1.00	27.90		net 27.90 23.4
21	8	L56115-30100 STOPPER, WINDSHIELD	2.00	4.40		net 8.80 7.48
22	9	T56116-22050 STOPPER, WINDSHIE	2.00	4.30		net 8.60 7.32
23	0	T04562-12010 W/SCREEN DAM KIT,	1.00	101.00		net 101.00 85.8
24	1	T08826-08682 SINGLE STEP PRIMER	1.00	173.44	200	net 173.44 170
25	2	T08826-08609 SUPER FAST URETHANE BLACK	2.00	90.08	108	net 180.16 165.6
26	3	T08826-08115 PANEL BONDING AD	1.00	237.60	267-20	net 237.60 224.7
27	4	L52157-33030 SUPPORT, RR BUMPER RH	1.00	97.50		net 97.50 83.6
28	5	L52155-33010 SUPPORT, RR BUMPER RH	1.00	186.70		net 186.70 160.4
29	6	L52462-33030 PAD RR BUMPER RH	1.00	7.60		net 7.60 6.5
30	7	L52159-33951 COVER, RR BUMPER Repair	1.00	989.00		net 989.00 840.0
31	8	S52161-OK040 BUMPER CLIPS	2.00	3.90		net 7.80 6.63
32	9	L89348-78020 RETAINER, ULTRASONIC	4.00	16.00		net 64.00 54.4
33	0	L89348-35030 CLIP, ULTRASONIC	4.00	3.60		net 14.40 12.29
34	1	L89348-50050 CLIP, ULTRASONIC	1.00	11.30		net 11.30 9.60
35	2	L42611-33B61 WHEEL, DISC	1.00	2295.00		net 2295.00 1950

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 7,606.00	20,062.00
		Labour 11,934.00	GST 7.00%
		Materials 522.00	1,404.34
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 21,466.34

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 24/05/2018
TIME 14:32

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Attn: Taufik
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP 8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tay Lim Heng 4 Jalan Binchang Singapore 578582 Mobile: 96972731
	Document No 0	
	Document Date 23/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	BEXGB	S5	AVV60R	08/03/2018	SLW8913A	5093	15422 :4DS/SLW8913A/24051:

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG702183349	2AR1893490	60	Wally Tan G H	24/05/2018	0.00	14/06/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS.:MSIG ACC DATE:24.05.18 T/P VEHICLE NO.:SJV0673Z DATE-IN:06.06.18 DATE SURVEY:28.05.18 NO OF REPAIR DAYS:9 DAYS BY:TAUFIKH (LKK) *DIRECT SETTLEMENT*				80.00
2	B	BP-WS REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)	*			816.00
3	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT) PO#3428	M30			420.00
4	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)	*			204.00
5	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)	*			204.00
6	B	BP-LAB REMOVE/REFIX RHS ROCKER MLDG TO ASSIST REPAIR. (NETT)	*			204.00
7	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.	*			612.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/06/2018
TIME 10:12

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : 196700000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail				Account No S1000004 / ICCUA1		Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				Document No: 0		Mr Tay Lim Heng 4 Jalan Binchang		
				Document Date 23/06/2018		Singapore 578582 Mobile: 96972731		
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
18	BEXGB S5	AVV60R	08/03/2018	SLW8913A	5093	15422	4DS/SLW8913A/24051	
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBWIGG702183349		ZAR1893490	60	Wally Tan G H	24/05/2018	0.00	14/06/2018 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
8	B	BP-LAB REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHS, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)			*			816.00
9	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN, R/R DOOR, R/R WHEEL ARCH PANEL, R/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS.			*			4080.00
10	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.			*			2100.00
11	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)			18			816.00
12	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)			18			612.00
13	S	BP-SUBLET TRANSFER R/R TYRE TO NEW WHEEL RIM AND BALANCING. (NETT)						102.00
14	1	L67857-33040 PROTECTOR, RR DOOR			1.00	10.80	15.00	9.18
15	2	L75473-33060 PLATE, BODY SIDE			1.00	76.80	15.00	65.28
16	3	L61611-33250 PANEL, QUARTER RH			1.00	1449.90	15.00	1232.41
17	4	L58747-33071 PROTECTOR, QUARTER			1.00	27.70	15.00	23.54
18	5	L75573-33080 MOULDING, BACK WINDOW			1.00	58.40	15.00	49.64
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors			Customer's Signature		Change Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less	
							Amount Due	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 23/06/2018
TIME 10:12

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : 196700000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Account No S1000004 / ICCUA1		Customer Detail Mr Tay Lim Heng 4 Jalan Binchang Singapore 578582 Mobile: 96972731	
		Document No 0			
		Document Date 23/06/2018			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	BEUGB S5	AVV60R	08/03/2018	SLW8913A	5093	15422	4DS/SLW8913A/24051

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG702183349	2AR1893490	60	Wally Tan G H	24/05/2018	0.00	14/06/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
19	6	L56117-50140 DAM, WINDOW GLASS	1.00	27.90	15.00	23.71
20	7	L56115-30100 STOPPER, WINDSHIELD	2.00	4.40	15.00	7.48
21	8	T56116-22050 STOPPER, WINDSHIELD	2.00	4.30	15.00	7.30
22	9	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00	15.00	85.85
23	0	T08826-08682 SINGLE STEP PRIMER	1.00	200.00	15.00	170.00
24	1	T08826-08609 SUPER FAST URETHANE BLACK	1.00	108.00	15.00	91.80
25	2	T08826-08115 PANEL BONDING AD	1.00	267.20	15.00	227.12
26	3	S52161-0K040 PIECE, RR BUMPER	2.00	3.90	15.00	6.62
27	4	L89348-78020 RETAINER, ULTRASONIC	4.00	16.00	15.00	54.40
28	5	L89348-35030 CLIP, ULTRASONIC	4.00	3.60	15.00	12.24
29	6	L89348-50050 CLIP, ULTRASONIC	1.00	11.30	15.00	9.60
30	7	L42611-33B61 WHEEL, DISC	1.00	2295.00	15.00	1950.75
31	8	T08826-08609 SUPER FAST URETHANE BLACK	1.00	108.00	15.00	91.80
32	9	L64801-33905 GLASS, BACK WINDOW	1.00	1571.60	15.00	1335.86

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary 5,454.58 Parts 10,544.00 Labour 522.00 Materials 0.00 Lubrication/Fluid 0.00 Others	Total GST 7.00%	1,156.44
			Less	0.00
			Amount Due	17,677.02

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 23/06/2018
TIME 10:12

VEHICLE NO SLW8913A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

...CLAIM SUBFOLDER...(Pending for Survey Report)




















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018		25 May 2018 16:27 Edit Adj Rpt	S\$16,520.58 Edit Estimates	S\$16,520.58 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LOO CHEONG FOOK, ID: S0179903G, Tel: +6597370380, Email: NOEMAIL								
Main Claimant:	TAY LIM HENG, ID: S1600469C								
Vehicle Reg. No.:	SLW8913A	Date of Loss:	24/05/2018 07:00 - :59 [2 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559350	Policy/Cover Note No.:	A27817272QMY (Comprehensive) Coverage: 09/01/2018 - 08/01/2019						
Vehicle Reg. No. (Insured):	SJV673Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/06/2018]								
Driver/Custodian (Insured):	LOO CHEONG FOOK (68 / Male), NRIC: S0179903G, Tel: +6597370380								
Adj Asg. Remarks:	on WP. Survey on 28/05/18, 3.30pm. Owner waiting. Please contact us ASAP if you cannot attend this assignment. Liability : 100%. Contact person : Wally Tan @9847 6178 / 6631 1506. Thanks.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW8913A (559350)
[SJV673Z]
TP
TAY LIM HENG
May 24 2018 7:00AM
[LOO CHEONG FOOK]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser			
Video												1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)										Thumbnail		Print	
1	25/05/18 14:38	Video - Accident (TP CAM) From: SC - Reg. No: SJV673Z, Claimant: LOO CHEONG FOOK												Load AVI	
Assessment Reports												1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)										Thumbnail		Print	
1	25/05/18 12:04	Accident Statement From: SC - Reg. No: SJV673Z, Claimant: LOO CHEONG FOOK												Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print	
1	30/05/18 17:48	Adjuster Immediate Advice												Load HTM	
Photos/Images												3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print	
1	30/05/18 17:49	Odometer Reading												Load JPG <input checked="" type="checkbox"/>	
2	30/05/18 17:49	Chassis Number												Load JPG <input checked="" type="checkbox"/>	
3	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
4	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
5	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
6	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
7	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
8	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
9	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
10	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
11	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
12	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
13	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
14	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
15	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
16	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
17	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
18	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
19	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
20	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
21	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
22	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
23	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
24	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
25	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
26	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
27	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	
28	30/05/18 17:49	General View												Load JPG <input checked="" type="checkbox"/>	

Video			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
29	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/05/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	28/06/18 15:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/05/18 12:04	SLW8913A E FILE REPORT From: SC - Reg. No: SJV673Z, Claimant: LOO CHEONG FOOK	 Load PDF	
2	25/05/18 12:05	Estimate	 Load PDF	
3	25/05/18 12:05	PRI notice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009609/T1SBQ2

Date: 02/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A27817272QMY
Claimant Vehicle No : SLW8913A **Insured Vehicle No :** SJV673Z
 Date of Loss: 24/05/2018 Nature of Claim: TP Claim No: 559350

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW8913A**
 Make & Model: TOYOTA LEXUS, 2.5 ES300H CVT (A) Engine No: 2AR1893490
 Reg. Date: 08/03/2018 (Man. Year: 2018) Chassis No: JTHBW1GG702183349
 Colour: White Odometer: 4501 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,705.90	5,534.58	2,171.32	28.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,356.00	10,986.00	1,370.00	11.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,061.90	16,520.58	3,541.32	17.65
+ GST 7.00/7.00% (S\$)	1,404.33	1,156.44	247.89	17.65
Nett Amount (S\$)	21,466.23	17,677.02	3,789.21	17.65

INSPECTION

Date of Assignment: 25/05/2018
 Date Inspected: 28/05/2018 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
 2 Pandan Crescent
 Singapore 128462
 Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2018)
Parts:	143	TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW8913A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*80.00 FS
2	1		*PROTECTOR ,RR DOOR	Necessary	10.80 FS	*9.18 FS
3	1		*PLATE,BODY SIDE	Necessary	76.80 FS	*65.28 FS
4	1		*PANEL ,QUARTER RH	Bent	1,449.80 FS	*1,232.41 FS
5	1		*PROTECTOR ,QUART	Necessary	27.70 FS	*23.54 FS
6	1		*GLASS ,BACK WINDOW	Necessary	1,571.60 FS	*1,335.86 FS
7	1		*MOULDING ,BACK WINDOW	Necessary	58.40 FS	*49.64 FS
8	1		*DAM ,WINDOW GLASS	Necessary	27.90 FS	*23.71 FS
9	2		*STOPPER ,WINDSHIELD	Necessary	8.80 FS	*7.48 FS
10	2		*STOPPER ,WINDSHIE	Necessary	8.60 FS	*7.30 FS
11	1		*W/SCREEN DAM KIT	Necessary	101.00 FS	*85.85 FS
12	1		*SINGLE STEP PRIMER	Necessary	173.44 FS	*170.00 FS
13	2		*SUPER FAST URETHANE BLACK	Necessary	180.16 FS	*183.60 FS
14	1		*PANEL BONDING AD	Necessary	237.60 FS	*227.12 FS
15	1		*SUPPORT ,RR BUMPER RH	Not Necessary	97.50 FS	*- FS
16	1		*SUPPORT ,RR BUMPER RH	Not Necessary	186.70 FS	*- FS
17	1		*PAD RR BUMPER RH	Not Necessary	7.60 FS	*- FS
18	1		*COVER,RR BUMPER	Repair	989.00 FS	*- FS
19	2		*BUMPER CLIPS	Necessary	7.80 FS	*6.62 FS
20	4		*RETAINER ,ULTRASONIC	Necessary	64.00 FS	*54.40 FS
21	4		*CLIP,ULTRASONIC	Necessary	14.40 FS	*12.24 FS
22	1		*CLIP,ULTRASONIC	Necessary	11.30 FS	*9.60 FS
23	1		*WHEEL ,DISC	Cut	2,295.00 FS	*1,950.75 FS
					Total Parts (\$\$)	7,705.90 5,534.58

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE /REFIX REAR WINDSHIELD TO ASSIT REPAIR	New	816.00	816.00
2	INSTALLING SOLAR FILM FOR REAR WINDSHIELD	New	420.00	420.00
3	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE	New	204.00	204.00
4	REMOVE/REFIX REVERSE SENSORS	New	204.00	204.00
5	REMOVE/REFIX RHS ROCKER MLDG TO ASSSIT REPAIR	New	204.00	204.00
6	REMOVE/REFIX REAR LUGGAGE COMPARTMENT,INTERIOR TRIM GARNISH TO ASSIST REPAIR	New	816.00	612.00
7	REMOVE/REFIX INTERIOR UPHOLSTERY ,ROOF LINING ,REAR SPEAKER BOARD ,TRIMMINGS ,GARNISHES ,FRONT AND REAR SEATS ,SEAT BELTS ,FLOOR CARPETS IN ORDER TO FACILITATE REPAIR	New	816.00	816.00
8	REMOVE ALL NECESSARY PARTS ,TO ENABLE REPAIRING AND STRAIGHTEN ,R/R DOOR ,R/R WHEEL ARC PANEL ,R/R BODY PANEL ,CUT AND WELD PANEL AND FIT NEW PARTS	New	4,896.00	4,080.00
9	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR	New	2,450.00	2,100.00
10	TO CARRY OUT WHEEL ALIGNMENT	New	816.00	816.00
11	TO RESET R/R TYRE TO NEW WHEEL RIM AND BALANCING	New	-	-
12	TO RESET ECU AND REPORGRAMME	New	612.00	612.00
13	TRANFER R/R TYRE TO NEW WHEEL RIM AND BALANCING	New	102.00	102.00
Gross Labour Cost (\$\$)			12,356.00	10,986.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >