



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SGT1313C

Date of Accident : 18 May 2018

Messrs Ten Dollar Salon Hub

Date : 23 May 2018

Estimate To Repair GBF8866K - NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6

Chassis No : VSKYBAM20Z0135771

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>deformed</i>	\$ 450.00 ✓
02	1 pc	n/s rear bumper reflector <i>NH</i>	\$ 45.00 X
			\$ 495.00
		Less 30 %	\$ 148.50
			\$ 346.50
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00 300/-
02		Putty and spray painting of the affected portion.	\$ 500.00 200/-
			\$ 950.00
		Total	\$ 1,296.50

25/05/2018 @ 1100am
Not Actual
L/Smm
2 days.
LKK Ando

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed ~~and~~ is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: