

ASS. REC. BY:

REF: CSLMSC18009619 / T19d3et

Special Instructions:

Surveyor
Memmen

- Ian Fick

ASSIGNMENT (Office)

From (Person):

Jaelyn Ng

of

MSIG

Date/Time:

28/5/18 @ 10:08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDK 12724

Insured:

at Workshop no/s

Sng Ah Tee

Tel:

6268 6183

of Blk 3 Pioneer Rd North # 01-18

Policy No:

A804 31961 QMX

Claim No:

5593 02

Sum Insured:

Excess:

\$600.00

Make of Veh:

(Client's Record)

D.O.A.

22/05/2018

CA (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:03am @ 28/5/18

Person Contacted:

Janice

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SDK 12724-X
30/5/18 @ 5.15pm	Spk went to Jaelyn Ng via Memmen.
31/5/18 @ 10.05am	Kenly Ong informed C/A of ex \$600 via Memmen.
31/5/18 @ 10.11am	Uninformed Joyce C/A of ex \$600 by email.
30/10/18 @ 7.20pm	2nd revert to Jaelyn Ng via Memmen. (Supplementary).
31/10/18 @ 1.54pm	Kenly Ong informed C/A at \$5430.69 via Memmen.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018 Sendback Est	25 May 2018 18:04 S\$12,685.29	28 May 2018 10:08 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GOH KIM SENG, ID: S1121272G, Tel: +6597847481, Email: KSGOH10@HOTMAIL.COM		
Vehicle Reg. No.:	SDK1272U	Date of Loss:	22/05/2018 16:00 - :59 [46 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 559302	Policy/Cover Note No.:	A80431961QMY (Comprehensive) Coverage: 23/06/2017 - 22/06/2018
		Excess:	S\$600.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]		
Driver/Custodian:	GOH KIM SENG (63 / Male), NRIC: S1121272G, Tel: +6597847481		
Adj Asg. Remarks:	Car in, request survey by today. Survey & revert. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 5 December 2018 1:18 PM
To: Shiau Chan (LKKAuto); SUR; Taufikh (LKKAuto)
Subject: RE: SDK1272U - FINALISE

Hi Shiau chan

confirm. thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, December 5, 2018 11:41 AM
To: Sharon Sng <sharon@sngahtee.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SDK1272U - FINALISE

Dear Sharon,

Re-send with attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 5 December 2018 11:16 AM
To: 'Sharon Sng' <sharon@sngahtee.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SDK1272U - FINALISE

Dear Sharon,

WITHOUT PREJUDICE

Offer final fig \$5,953.34 before excess \$600.00 & GST and 8 repair days.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	24 May 2018 16:50	Cim Veh Model Changed	(202780) TOYOTA CAMRY 2.5 (A).	[I] Jocelyn Ng Shin Bun
2	24 May 2018 16:50	Cim Created	Reg No: SDK1272U, Policy No: AB0431961QMY, Acct Date: 2018/05/22, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MSAT18067012	[I] Jocelyn Ng Shin Bun
3	25 May 2018 17:38	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] Samantha Tan Yong Sing (R)
4	25 May 2018 18:04	Cim Submitted	12685.29.	Samantha Tan Yong Sing
5	28 May 2018 09:24	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Jocelyn Ng Shin Bun
6	28 May 2018 09:24	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2018/05/29	[I] Jocelyn Ng Shin Bun
7	28 May 2018 09:24	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
8	28 May 2018 09:33	Assignment 1st Accessed		[A] Crystal Lee
9	28 May 2018 10:07	Adj Assignment Cancelled	Car in, request survey by today. IHS unable to attend (AL & KL-Appt Full, ET-MC).	[I] Crystal Lee
10	28 May 2018 10:07	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Crystal Lee
11	28 May 2018 10:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, request survey by today, Survey & revert. Please contact us ASAP if you cannot attend this assignment.	[I] Crystal Lee
12	28 May 2018 10:08	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2018/05/29	[I] Crystal Lee
13	28 May 2018 10:08	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Crystal Lee
14	28 May 2018 10:53	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	28 May 2018 14:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
16	30 May 2018 16:51	Adj Rpt Initiated		[A] SHIAU CHAN
17	30 May 2018 17:12	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
18	30 May 2018 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
19	30 May 2018 17:15	Adj Mandate Request	Cur.Req:9951.69:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	31 May 2018 10:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27, Mandate Remarks: a if c, excess \$600	[I] Keny Ong Thiam Beng
21	31 May 2018 10:05	Adj Mandate Set	Approved:3967.69;a if c, excess \$600	[I] Keny Ong Thiam Beng
22	26 Oct 2018 14:21	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
23	26 Oct 2018 14:21	Adj Mandate Request	Cur.Req:10248.69:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	31 Oct 2018 13:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27, Mandate Remarks: a if c, to include supp parts	[I] Keny Ong Thiam Beng
25	31 Oct 2018 13:54	Adj Mandate Set	Approved:5430.69;a if c, to include supp parts	[I] Keny Ong Thiam Beng
26	14 Nov 2018 17:10	Cim Supp Created (S:762574)		[R] Sharon Sng May Yuen
27	14 Nov 2018 17:28	Cim Submitted (S:762574)	1457.50.	[R] Sharon Sng May Yuen
28	14 Nov 2018 17:28	Adj Co Assigned (S:762574)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merimen Administrator
29	15 Nov 2018 17:18	Supp Combined (S:762574)		[A] SHIAU CHAN
30	23 Nov 2018 17:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
31	23 Nov 2018 17:41	Adj Mandate Request	Cur.Req:5953.34:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, KINDLY APPROVE ON CHECK ITEMS & SUPPLEMENTARY.	[A] SHIAU CHAN
32	04 Dec 2018 17:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27, Mandate Remarks: a if c, to include supp parts	[I] Eng Huey Ni
33	04 Dec 2018 17:02	Adj Mandate Set	Approved:5953.34;a if c, to include supp parts	[I] Eng Huey Ni

Date From



Date To



Audit Type None

Go

ACTIVITY

[28/05/2018 10:05] Crystal Lee:

IHS unable to attend (AL & KL-Appt Full, ET-MC).

[28/05/2018 09:34] Crystal Lee:

Samantha informed car in since last Thur, request urgent survey by today.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1815375	25/05/2018 17:38	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	SDK1272U		XX.XX
1818474	30/05/2018 16:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDK1272U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 23 Nov 2018

Preliminary Advice

Vehicle No	: SDK1272U	Accident Date	: 22/05/2018
Make	: TOYOTA CAMRY	Policy No.	: A80431961QMY
Assignment Date	: 28/05/2018	Excess	: S\$600.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 8.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,181.29	(ESTIMATE \$12,982.29 + SUPPLEMENTARY 2 \$1,199.00)
Revised Amount	:S\$	5,953.34	(INCLUSIVE OF CHECK ITEMS & SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	5,953.34	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	64,239.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,761.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVAL ON CHECK ITEMS & SUPPLEMENTARY.

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	24 May 2018 16:50	Cim Veh Model Changed	(202780) TOYOTA CAMRY 2.5 (A).	[I] Jocelyn Ng Shin Bun
2	24 May 2018 16:50	Cim Created	Reg No: SDK1272U, Policy No: A80431961QMY, Acct Date: 2018/05/22, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MSAT18067012	[I] Jocelyn Ng Shin Bun
3	25 May 2018 17:38	Cim Registration Modified	Settl.Type:3->0, Claim Type:SC->OD.	[I] Samantha Tan Yong Sing
4	25 May 2018 18:04	Cim Submitted	12685.29.	[R] Samantha Tan Yong Sing
5	28 May 2018 09:24	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Jocelyn Ng Shin Bun
6	28 May 2018 09:24	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/29	[I] Jocelyn Ng Shin Bun
7	28 May 2018 09:24	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
8	28 May 2018 09:33	Assignment 1st Accessed		[A] Crystal Lee
9	28 May 2018 10:07	Adj Assignment Cancelled	Car in, request survey by today, IHS unable to attend (AL & KL-Appet Full, ET-MC).	[I] Crystal Lee
10	28 May 2018 10:07	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Crystal Lee
11	28 May 2018 10:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, request survey by today, Survey & revert. Please contact us ASAP if you cannot attend this assignment.	[I] Crystal Lee
12	28 May 2018 10:08	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/29	[I] Crystal Lee
13	28 May 2018 10:08	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Crystal Lee
14	28 May 2018 10:53	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	28 May 2018 14:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
16	30 May 2018 16:51	Adj Rpt Initiated		[A] SHIAU CHAN
17	30 May 2018 17:12	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
18	30 May 2018 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
19	30 May 2018 17:15	Adj Mandate Request	Cur.Req:9951.69:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	31 May 2018 10:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27, Mandate Remarks: a if c. excess \$600	[I] Keny Ong Thiam Beng
21	31 May 2018 10:05	Adj Mandate Set	Approved:3967.69:a if c. excess \$600	[I] Keny Ong Thiam Beng
22	26 Oct 2018 14:21	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27	[A] SHIAU CHAN
23	26 Oct 2018 14:21	Adj Mandate Request	Cur.Req:10248.69:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	31 Oct 2018 13:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27, Mandate Remarks: a if c. to include supplementary parts	[I] Keny Ong Thiam Beng
25	31 Oct 2018 13:54	Adj Mandate Set	Approved:5430.69:a if c. to include supplementary parts	[I] Keny Ong Thiam Beng

Date From



Date To



Audit Type None

Go

ACTIVITY

[28/05/2018 10:05] Crystal Lee:

IHS unable to attend (AL & KL-Appet Full, ET-MC).

[28/05/2018 09:34] Crystal Lee:

Samantha informed car in since last Thur, request urgent survey by today.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1815375	25/05/2018 17:38	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	SDK1272U		XX.XX
1818474	30/05/2018 16:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDK1272U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 26 Oct 2018

Preliminary Advice

Vehicle No	: SDK1272U	Accident Date	: 22/05/2018
Make	: TOYOTA CAMRY	Policy No.	: A80431961QMY
Assignment Date	: 28/05/2018	Excess	: S\$600.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 8.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,982.29	(ESTIMATE \$12,685.29 + SUPPLEMENTARY \$297.00)
Revised Amount	:S\$	5,430.69	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	4,818.00	
Total	:S\$	10,248.69	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	64,239.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,761.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 31 May 2018 10:11 AM
To: admin@sngahtee.com
Cc: SUR
Subject: VEHICLE SDK 1272U (DOA: 22/05/2018)

Dear Joyce,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SDK 1272U (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	24 May 2018 16:50	Cim Veh Model Changed	(202780) TOYOTA CAMRY 2.5 (A).		[I] Jocelyn Ng Shin Bun
2	24 May 2018 16:50	Cim Created	Reg No: SDK1272U. Policy No: A80431961QMY. Acct Date: 2018/05/22. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSAT18067012		[I] Jocelyn Ng Shin Bun
3	25 May 2018 17:38	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[I] Samantha Tan Yong Sing
4	25 May 2018 18:04	Cim Submitted	12685.29.		[R] Samantha Tan Yong Sing
5	28 May 2018 09:24	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c		[I] Jocelyn Ng Shin Bun
6	28 May 2018 09:24	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/29		[I] Jocelyn Ng Shin Bun
7	28 May 2018 09:24	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Jocelyn Ng Shin Bun
8	28 May 2018 09:33	Assignment 1st Accessed			[A] Crystal Lee
9	28 May 2018 10:07	Adj Assignment Cancelled	Car in, request survey by today. IHS unable to attend (AL & KL-Appr Full, ET-MC).		[I] Crystal Lee
10	28 May 2018 10:07	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Crystal Lee
11	28 May 2018 10:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, request survey by today. Survey & revert. Please contact us ASAP if you cannot attend this assignment.		[I] Crystal Lee
12	28 May 2018 10:08	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/05/29		[I] Crystal Lee
13	28 May 2018 10:08	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Crystal Lee
14	28 May 2018 10:53	Assignment 1st Accessed			[A] Nivitha Govindasamy
15	28 May 2018 14:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] Nivitha Govindasamy
16	30 May 2018 16:51	Adj Rpt Initiated			[A] SHIAU CHAN
17	30 May 2018 17:12	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/27		[A] SHIAU CHAN
18	30 May 2018 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27		[A] SHIAU CHAN
19	30 May 2018 17:15	Adj Mandate Request	Cur.Req:9951.69:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
20	31 May 2018 10:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/27. Mandate Remarks: a if c. excess \$600		[I] Keny Ong Thiam Beng
21	31 May 2018 10:05	Adj Mandate Set	Approved:3967.69:a if c. excess \$600		[I] Keny Ong Thiam Beng

Date From



Date To



Audit Type None

Go

ACTIVITY

[28/05/2018 10:05] Crystal Lee:
IHS unable to attend (AL & KL-Appr Full, ET-MC).
[28/05/2018 09:34] Crystal Lee:
Samantha informed car in since last Thur, request urgent survey by today.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1815375	25/05/2018 17:38	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	SDK1272U		xx.xx
1818474	30/05/2018 16:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SDK1272U		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 30 May 2018

Preliminary Advice

Vehicle No	: SDK1272U	Accident Date	: 22/05/2018
Make	: TOYOTA CAMRY	Policy No.	: A80431961QMY
Assignment Date	: 28/05/2018	Excess	: S\$600.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 8.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,685.29
Revised Amount	:S\$	3,967.69
Check Items (Estimated)	:S\$	5,984.00
Total	:S\$	9,951.69

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	86,000.00
COE / PARF Rebate	:S\$	64,239.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,761.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1272G
Vehicle Details	
Vehicle No.:	SDK1272U
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	2ARU143768
Chassis No.:	MR053AK5004007792
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$28,027.00
Original Registration Date:	23 Jun 2014
First Registration Date:	23 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$31,238.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2024
PARF Rebate Amount:	\$23,428.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,304.00
COE Rebate Amount:	\$40,811.00
Total Rebate Amount:	\$64,239.00

The information contained herein is correct as at 30 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/05/2018 12:21
Date Of Accident	22/05/2018 16:35
Exact Location Of Accident	ADMIRATLY WEST RD & WOODLANDS AVE 8
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDK1272U
Insured/Policyholder	
Name Of Registered Owner	GOH KIM SENG
NRIC No	S1121272G
Email Address	KSGOH10@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97847481
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CAMRY-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80431961QMY
Cover Note Number	
Driver	
Name of Driver	GOH KIM SENG
NRIC No	S1121272G
Date Of Birth	13/09/1954
Occupation	INDOOR
Date Of Driving Pass	30/07/1975
Driving Experience	42 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97847481
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	KSGOH10@HOTMAIL.COM

Address	520 SERANGOON NORTH AVE 4 #06-186
Postcode	550520
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 22/05/2018 AT AROUND 1635HRS, I WAS TRAVELLING ALONG ADMIRATLY RD WEST TO WOODLANDS AVE 8. WHEN I WAS AT THE JUNCTION TO MAKE MY TURN TO RIGHT INTO WOODLANDS AVE 8, I SAW MY TRAFFIC LIGHT IS GREEN AND RIGHT TURN ARROW AND I PROCEED TO MAKE MY TURN. WHEN I WAS ON THE MID OF TURNING TO THE RIGHT, SUDDENLY I SAW VEHICLE B OUT OF SUDDEN DRIVE TOWARDS MY VEHICLE ON MY LEFT AND COLLIDED ONTO MY VEHICLE FROM FRONT LEFT PORTION TO REAR LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGT9214C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG MUN LAI
NRIC/Passport Number	S6905923F
Contact Number	97599847
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAY TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to accident circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☒ Claim own policy *Refer.*
☐ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose
 Policy No. *A 8431961 Army*
 Insurer *WTA* Veh. No. *SK12724*

SRP/SC 10/10/2017/1/1/1/1/1

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000478
Version: SNGAHTEE/1

Full Report - V1
Registration: SDK1272U
Printed: 25/05/2018 17:35

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	A80431961QMY	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YA7 01
Registration:	SDK1272U
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 05/2014	MIRROR W/INDICATOR
MULTIFUNCTION MIRROR	CHROME DOOR HANDLES
PACK RZ	2.5 LTR 133 KW
FRT/RR DOOR PROT MLD	SILL MOULDING CHROME
TWO COAT METALLIC	PREPARE OFF VEHICLE

Tan Jia 97495749
Ex \$600
Not Authorise
28/5/18 @ 1730
** Resurvey before paint*

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	24/05/2018
Pre-Accident Damage:	

Tyres Condition:

Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000478
Version: SNGAHTTE/1

Full Report - V1
Registration: SDK1272U
Printed: 25/05/2018 17:35



Addresses

Cost Summary

Total Labour	\$2,415.00
Total Paint/Material	\$221.29
Total Parts	\$8,569.00
Total of Additional Costs	\$1,480.00
Excess:	TBA
Grand Total Exc GST:	\$12,685.29
7 % GST:	\$887.97
Grand Total Inc GST:	\$13,573.26

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B125	R + R LOCK INSERT	3.0	15.00
B163)	RENEW L/F WHEELHOUSE FRONT SECTION	17.0	85.00
B100	R + R LEFT SILL RAIL	3.0	15.00
NO NUMBER	R + R L/INNER SILL COVER	2.0	10.00
B110	RENEW LEFT FRONT WING	6.0	30.00
	INCLUDES: TRANSFER ATTACHED PARTS		
B010	R + R FRONT BUMPER	6.0	30.00
B010)	R + R FRONT BUMPER CARRIER (BUMPER REM)	2.0	10.00
B030	R + R RADIATOR GRILLE	3.0	15.00
B040	R + R LEFT HEADLAMP	4.0	20.00
NO NUMBER	R + R LEFT DOOR SILL TRIM	1.0	5.00
B060	R + R BONNET	3.0	15.00
743261	R + R L/F WEATHERSTRIP	2.0	10.00
743261	R + R R/F WEATHERSTRIP	2.0	10.00
743011	R + R L/LOWER A-PILLAR TRIM	2.0	10.00
743011	R + R R/LOWER A-PILLAR TRIM	2.0	10.00
G010	R + R LEFT UPPER A-PILLAR TRIM	1.0	5.00
G010	R + R RIGHT UPPER A-PILLAR TRIM	1.0	5.00
B210)	RENEW L/F DOOR	28.0	140.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
B210	RENEW L/R DOOR	26.0	130.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
B270)	RENEW L/R SIDE PANEL	66.0	330.00
G020	R + R REAR SCREEN	33.0	165.00
	INCLUDES: R + R REAR PARCEL SHELF AND		

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000478

Version: SNGAHTEE/1

Full Report - V1

Registration: SDK1272U

Printed: 25/05/2018 17:35

	ADDITIONAL BRAKE LAMP		
B410	R + R REAR BUMPER	7.0	35.00
640301	R + R BOOT LID WEATHERSTRIP	2.0	10.00
812011	R + R FRONT INNER LAMP	2.0	10.00
B430)	R + R HEADLINING	1.0	5.00
752101	R + R SUN VISORS	2.0	10.00
752021	R + R REAR VIEW MIRROR	2.0	10.00
B430)	ADD/WORK R + R ROOF LINING	7.0	35.00
M230)	R + R INSTRUMENT PANEL	15.0	75.00
M230)	R + R CENTRE CONSOLE INSERT	3.0	15.00
B440	R + R LEFT FRONT SEAT	2.0	10.00
B440	R + R RIGHT FRONT SEAT	2.0	10.00
B450)	R + R SEAT CUSHION	1.0	5.00
B450)	R + R REAR SEAT BACKREST	2.0	10.00
M010	R + R CONDENSER	12.0	60.00
M020	R + R RADIATOR	4.0	20.00
	INCLUDES: BLEED COOLING SYSTEM		
NO NUMBER	R + R R/UPPER ENGINE STRUT	1.0	5.00
420091)	R + R L/F WHEEL/TYRE	2.0	10.00
473101A)	DETACH + REFIT FRONT BRAKE CALIPER	5.0	25.00
896081)	R + R R/F ABS SENSOR	2.0	10.00
431151A)	R + R FRONT SUSPENSION STRUT/S	2.0	10.00
431151)	R + R LEFT FRONT SPRING/SHOCK ABSORBER	6.0	30.00
431011)	R + R LEFT FRONT CONTROL ARM	1.0	5.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
434211)	RENEW LEFT FRONT STEERING KNUCKLE	7.0	35.00
	DOES NOT INCLUDE: VEHICLE ALIGNMENT		
434021A	R + R FRONT WHEEL HUB (COMPOSITE WORK)	3.0	15.00
431011A)	R + R L + R LWR STEERING AXLE	11.0	55.00
420018)	R + R LEFT REAR WHEEL	1.0	5.00
420091)	R + R LEFT REAR TYRE/WHEEL	2.0	10.00
042214)	BALANCE WHEEL/S	1.0	5.00
473061A)	R + R REAR BRAKE DISC/S	4.0	20.00
422041)	RENEW L/R WHEEL HUB	1.0	5.00
422041A)	RENEW REAR WHEEL HUBS	1.0	5.00
2277	REPAIR B-PILLAR L/SILL PNL	10.0*	50.00
1000	CHECK WIRING	10.0*	50.00

LABOUR COST

Total Work Units

347.0

Sub Total

34.7HRS

\$1,735.00

Paint Labour

13.6HRS

680.00

Total Labour

48.3HRS

\$2,415.00

PAINT WORK

Guide Number Description

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

WU

Cost Price (\$)

- TWO COAT METALLIC

- PREPARE OFF VEHICLE

741	L/F WING NEW PART PAINTING	10.0
1123	L/F WHEELHOUSE SURFACE PAINT	6.0
1481	LEFT FRONT DOOR NEW PART PAINTING	17.0
1781	L/R DOOR NEW PART PAINTING	15.0
3481	L/R SIDE PANEL NEW PART PAINTING	29.0

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000478

Version: SNGAHTEE/1

Full Report - V1

Registration: SDK1272U

Printed: 25/05/2018 17:35

7201	L/F WHEEL NEW PART PAINTING	7.0	
9551	L/R WHEEL NEW PART PAINTING	7.0	
2101	L/OUTER SILL PANEL REPAIR PAINTING <50%	10.0	
2277	B-PILLAR L/SILL PNL REPAIR PAINTING <50%	10.0	
LABOUR COST - PAINT			
	TIME(PAINT)	111.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	136.0	
	Total Paintwork Labour	13.6HRS	\$680.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$161.38
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$10.96
	Repair Painting		\$20.35
	Total Excluding Pearlescent Uplift		\$221.29
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$221.29

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	DUAL VVTI LOGO	Renew		0% 25.00*
1505	1	L/F DOOR CHECK	68610 06101		0% 135.00* X m
1777	1	L/F DOOR FRAME SEAL	62312 06140A0		0% 200.00* X m
1567	1	L/F DOOR OUT HANDLE	69210 06936		0% 75.00*
1509	1	L/F DOOR SEAL	67862 06100		0% 65.00*
1711	1	L/F DOOR TRIM	67620 06J00C1		0% 1,060.00*
1495	1	L/F LOWER DOOR HINGE	68740 06060		0% 35.00*
1625	1	L/F OUT WINDOW SEAL	75720 06140		0% 50.00*
7081	1	L/F STEERING KNUCKLE	43212 06220		0% 140.00*
7077	1	L/F STRUT	48520 09V80		0% 505.00*
7227	1	L/F TYRE	215/60 R 16 .. Y		0% 0.00F
1699	1	L/F UPP DOOR MLDG	75754 06090		0% 50.00*
1487	1	L/F UPPER DOOR HINGE	68720 06030		0% 35.00*
7201	1	L/F WHEEL	42611 06454		0% 0.00
7117	1	L/F WHEEL BEARING	90369 T0007		0% 80.00*
7131	1	L/F WHEEL HUB	43502 06100		0% 395.00*
1123	1	L/F WHEELHOUSE	53712 06090		0% 180.00*
841	1	L/F WHEELHOUSE COVER	53876 06130		0% 70.00*
1597	1	L/F WINDOW CHANNEL	68151 06100		0% 55.00*
1551	1	L/F WINDOW MOTOR	85720 35140		0% 280.00*
741	1	L/F WING	53812 06160		0% 180.00*
789	9	L/F WING CLAMP KIT	91631 B0610		0% 25.00*
4203	4	L/FASTENING CLIP	90467 06169		0% 25.00*
2187	1	L/INNER SILL MLDG	75864 06160		0% 200.00*
4337	1	L/INSTR PANEL COVER	55318 06110C0		0% 30.00* X m
1795	1	L/LOWER DOOR HINGE	68780 06010		0% 35.00*
7053	1	L/LWR AXLE STEERING	48069 33070		0% 130.00*
1781	1	L/R DOOR	67004 06160		0% 480.00*
1805	1	L/R DOOR CHECK	68630 06091		0% 75.00* X m
2063	1	L/R DOOR FRAME SEAL	62332 06130A0		0% 295.00*
1809	1	L/R DOOR SEAL	67872 06100		0% 75.00*
2011	1	L/R DOOR TRIM	67640 06E70C1		0% 1,060.00*
3481	1	L/R SIDE PANEL	61602 06190		0% 450.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000478
Version: SNGAHTEE/1

Full Report - V1
Registration: SDK1272U
Printed: 25/05/2018 17:35

9565	1	L/R TYRE	215/60 R 16 .. Y	0%	X	0.00F	X
1787	1	L/R UPPER DOOR HINGE	68760 06020	0%	?	35.00*	X
9551	1	L/R WHEEL	42611 06454	0%	?	0.00	X
9181	1	L/R WHEEL HUB CPL	42460 06090	0%	?	535.00*	X
4201	1	L/R WHEELHOUSE COVER	65638 06071	0%		100.00*	X
2189	1	L/SILL PANEL COVER	75858 33030	✓0%	de	70.00*	=
1547	1	L/WINDOW REGULATOR	69802 52130	0%	?	75.00*	X
1481	1	LEFT FRONT DOOR	67002 06180	0%	by	480.00*	=
3160	1	REAR SCREEN BOND KIT	PZ49I 00C1131	0%		0.00F	X
3171	1	REAR SCREEN CLIP SET	56115 30120	0%		0.00F	X
3173	1	REAR SCREEN CLIP SET	56116 22050	0%	max	0.00F	X
3163	1	REAR SCREEN FIX SET	USE SINGLE PARTS	0%		0.00	
3161	1	REAR WINDOW MOULDING	75573 06090	0%		0.00	
f: OEM Parts				Saving		\$328.54	
g: Original				Sub Total		\$7,790.00	
h: Secondhand				Total Parts		\$8,569.00	
p: Parallel							
x: Exchange							

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
L/F RIM 17" SPECIALIST	0%	\$300.00
L/F TYRE 215/55R17 SPECIALIST		\$400.00
L/R RIM 17" SPECIALIST	0%	\$300.00
L/R TYRE 215/55R17 SPECIALIST		\$400.00
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
Total Extras		\$1,480.00

Final Calculation

Total Parts	\$8,569.00
Labour	
Total Panel/Mechanical	\$1,735.00
Total Paintwork	\$680.00
Total Labour	\$2,415.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$1,480.00
Total of Additional Costs	\$1,480.00
Total Paint/Material Costs	\$221.29
Grand Total Excludes GST	\$12,685.29
GST @ 7 %	\$887.97
Grand Total Includes GST	\$13,573.26

Assessment Notes

Sng Ah Tee Motor&Panel Service Pte Ltd

Tel:62686183 (4 lines) Fax:62681429

SUPPLEMENTARY ITEM

VEHICLE NO	SDK1272U	COST PRICE
VEHICLE TYPE	TOYOTA CAMRY	
ACCIDENT DATE	22/5/2018	
INSURANCE	OD MSIG P/P	
CHASSIS	MR053AK5004007792	
SURVEYOR	TAUFIQ	

ITEM DESCRIPTION	QTY	AMOUNT
SIDE SKIRT (LH)	1	\$ 200.00 <i>de</i>
FRT DOOR FRAME COVER (LH)	1	\$ 35.00 <i>nee</i>
RR DOOR FRAME COVER (LH)	1	\$ 35.00 <i>nee</i>
CHECK ITEM		
FRT DOOR INNERTRIM BOARD (LH)	1	\$ 1,060.00 <i>de</i>

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000478
Version: SNGAHT/3
Date Calculated: 14/11/2018 09:25

Full Report - V1
Registration: SDK1272U
Printed: 14/11/2018 17:27

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	A80431961QMY	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	TOYOTA	FROM 05/2014	MIRROR W/INDICATOR
Model:	Camry	MULTIFUNCTION MIRROR	CHROME DOOR HANDLES
Sub Model:	BASE MODEL	PACK RZ	2.5 LTR 133 KW
Model Sheet Number:	YA7 01	FRT/RR DOOR PROT MLD	SILL MOULDING CHROME
Registration:	SDK1272U	TWO COAT METALLIC	PREPARE OFF VEHICLE
Registration Month:			
Registration Year:			
VIN Number:			
Odometer:	Not Known		
Colour:			
Engine Number:			
Fuel Level:	%		

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	24/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000478



Version: SNGAHTTE/3

Date Calculated: 14/11/2018 09:25

Full Report - V1

Registration: SDK1272U

Printed: 14/11/2018 17:27



Addresses

Cost Summary

Total Labour	\$1,440.00
Total Paint/Material	\$198.84
Total Parts	\$3,954.50
Total of Additional Costs	\$380.00
Excess:	TBA
Grand Total Exc GST:	\$5,973.34
7 % GST:	\$418.13
Grand Total Inc GST:	\$6,391.47

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	R + R L/INNER SILL COVER	2.0	10.00
B110	RENEW LEFT FRONT WING	6.0	30.00
	INCLUDES: TRANSFER ATTACHED PARTS		
B100	RENEW L/SILL MOULDING	4.0	20.00
B010	R + R FRONT BUMPER	6.0	30.00
B030	R + R RADIATOR GRILLE	3.0	15.00
B040	RENEW LEFT HEADLAMP	4.0	20.00
743261	R + R L/F WEATHERSTRIP	2.0	10.00
743261	R + R R/F WEATHERSTRIP	2.0	10.00
743011	R + R L/LOWER A-PILLAR TRIM	2.0	10.00
743011	R + R R/LOWER A-PILLAR TRIM	2.0	10.00
G010	R + R LEFT UPPER A-PILLAR TRIM	1.0	5.00
G010	R + R RIGHT UPPER A-PILLAR TRIM	1.0	5.00
B210)	RENEW L/F DOOR	28.0	140.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
B210	RENEW L/R DOOR	26.0	130.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
M230)	R + R INSTRUMENT PANEL	15.0	75.00
NO NUMBER	RENEW INSTRUMENT PANEL (REMOVED)	3.0	15.00
M230)	R + R CENTRE CONSOLE INSERT	3.0	15.00
420018)	R + R LEFT REAR WHEEL	1.0	5.00
420091)	R + R LEFT REAR TYRE/WHEEL	2.0	10.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000478

Version: SNGAHTTE/3

Date Calculated: 14/11/2018 09:25

Full Report - V1

Registration: SDK1272U

Printed: 14/11/2018 17:27

042214)	BALANCE WHEEL/S	1.0	5.00
2227	REPAIR LEFT A-PILLAR	15.0*	75.00
2277	REPAIR B-PILLAR L/SILL PNL	10.0*	50.00
3481	REPAIR L/R SIDE PANEL	20.0*	100.00
1000	CHECK WIRING	10.0*	50.00
		6	30.
LABOUR COST			
	Total Work Units	169.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	16.9HRS	\$845.00
	Paint Labour	11.9HRS	\$595.00
	Total Labour	28.8HRS	\$1,440.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	10.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	17.0	
1781	L/R DOOR NEW PART PAINTING	15.0	
9551	L/R WHEEL NEW PART PAINTING	7.0	
2101	L/OUTER SILL PANEL REPAIR PAINTING <50%	10.0	
2227	LEFT A-PILLAR REPAIR PAINTING <50%	10.0	
2277	B-PILLAR L/SILL PNL REPAIR PAINTING <50%	10.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
LABOUR COST - PAINT			
	TIME(PAINT)	94.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	119.0	
	Total Paintwork Labour	11.9HRS	\$595.00
MATERIAL COST - PAINT			
	New Part Painting		\$116.62
	Material-Constant Main Work Metal		\$28.60
	Repair Painting		\$53.62
	Total Excluding Pearlescent Uplift		\$198.84
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$198.84

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
561	1	LEFT HEADLAMP ASSY	81170 06811		0%	380.00*
741	1	L/F WING	53812 06160		0%	180.00*
789	9	L/F WING CLAMP KIT	91631 B0610		0%	15.00*
841	1	L/F WHEELHOUSE COVER	53876 06130		0%	55.00*
843	1	L/F WING INSULATOR	53883 06100		0%	35.00*
1481	1	LEFT FRONT DOOR	67002 06180		0%	480.00*
1487	1	L/F UPPER DOOR HINGE	68720 06030		0%	35.00*
1495	1	L/F LOWER DOOR HINGE	68740 06060		0%	35.00*
1509	1	L/F DOOR SEAL	67862 06100		0%	75.00*
1695	1	L/F DOOR REAR STRIP	75976 06060		0%	35.00*
1711	1	L/F DOOR TRIM	67620 06J00C1		0%	550.00*
1781	1	L/R DOOR	67004 06160		0%	480.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000478

Version: SNGAHTTE/3

Date Calculated: 14/11/2018 09:25

Full Report - V1

Registration: SDK1272U

Printed: 14/11/2018 17:27

1809	1	L/R DOOR SEAL	67872 06100	0%	75.00*
1955	1	L/R DOOR FRAME MLDG	75762 33060	0%	35.00*
2185	1	L/SILL MOULDING	75852 06917	0%	200.00*
2187	1	L/INNER SILL MLDG	75864 06160	0%	200.00*
2189	1	L/SILL PANEL COVER	75858 33030	0%	70.00*
3160	1	REAR SCREEN BOND KIT	PZ49I 00C1131	0%	0.00F
3171	1	REAR SCREEN CLIP SET	56115 30120	0%	0.00F
3173	1	REAR SCREEN CLIP SET	56116 22050	0%	0.00F
4203	4	L/FASTENING CLIP	90467 06169	0%	15.00*
4331	1	INSTRUMENT PNL TRIM	55301 06290C0	0%	550.00*
4337	1	L/INSTR PANEL COVER	55318 06110C0	0%	70.00*
9551	1	L/R WHEEL	42611 06454	0%	0.00
9565	1	L/R TYRE	215/60 R 16 .. Y	0%	0.00F
1000	1	DUAL VVTI LOGO	Renew	0%	25.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Saving

Sub Total

Mark Up From Cost (10 %)

Total Parts

\$185.54

\$3,595.00

\$359.50

\$3,954.50

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
L/F RIM 17" SPECIALIST	0%	\$300.00
WHEEL ALIGNMENT SPECIALIST		\$80.00
Total Extras		\$380.00

Final Calculation

Total Parts	\$3,954.50
Labour	
Total Panel/Mechanical	\$845.00
Total Paintwork	\$595.00
Total Labour	\$1,440.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$380.00
Total of Additional Costs	\$380.00
Total Paint/Material Costs	\$198.84
Grand Total Excludes GST	\$5,973.34
GST @ 7 %	\$418.13
Grand Total Includes GST	\$6,391.47

Assessment Notes



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 PRONTER ROAD NORTH

#01-18

SINGAPORE 228475

CAMRY

YAO SHENG

NO: DL09204229

DATE: 1

TIME: 12:00:2018

AMOUNT: 1335.95

TERMS: 1/10

VALUE: 518.95

Part No	Description	Location	Qty	Unit Price	Amount
1	T75756-33080 #1695 RR WIND MILDING LH FRONT	DD1E7	1	35.00	35.00
2	T75762-33080 #1465 RR WIND MILDING LH REAR	DUT240	1	35.00	35.00
3	T53883-06130 #843 RR FENDER SEAL LH VERTICAL	DUTAB25	1	35.00	35.00
4	T81185-00700 #156 HEADLAMP HID-LH	DB2S	1	350.00	350.00
TOTAL QUANTITY			4	518.95	518.95
			ADDITIONAL 7%		33.95
			GRAND TOTAL		SIN 518.95

total \$518.95

Printed by: SINGAPORE MOTOR PARTS LTD

SALES TAX: 7%

This document is computer generated. No signature required.

GOODS RECEIVED BY: [Signature]



GOODS RECEIVED BY



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

ALST SNG AH TEH MOTOR & PANEL SERVICE PTE LTD

BLK 3 DELOS PUE ROAD SINGAPORE

#01-18

SINGAPORE 629403

CAMRY

YAO SHENG

NO. D119204288


PAGE 1

DATE 12/06/2018

ITEM GROUP 10000000

TERMS C/D

Part No.	Description	Location	Qty	Unit Price	Amount
1 15340140370000	DASH BOARD	DB2D	1	588.50	588.50
#4331 TOTAL QUANTITY			1	TOTAL	588.50
				AMOUNT IN SGD	588.50
				GRAND TOTAL	SIN 588.50



Reprint: LSK 17/6/2018 5:36:20 PM

SALESMAN: LSK

This document is computer generated. No signature is needed

GOODS RECEIVED BY: [Signature]



GOODS RECEIVED BY

[Signature]





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

US: SING AI TEE MOTOR & PANEL SERVICE PTE LTD

BLK 3 HOUSHEK ROAD SINGAPORE

#01-18

SINGAPORE 209403

CAMRY

YAO SHENG

NO: DL19266289

PAGE: 1

DATE: 08/08/2018

AMOUNT: 1100.00

TAX: 0.00

Part No	Description	Location	Qty	Unit Price	Amount
	4537			SIN	SIN
155318-00180-00	DASHBOARD SIDE LH	DDS	1	70.00	70.00
167620-00P90-00	FRONT DOOR TRIM LH	DDS	1	550.00	550.00
	1711	TOTAL QUANTITY	2	TOTAL	SIN 620.00
				ADDITIONAL	43.40
				GRAND TOTAL	SIN 663.40

print: LSK 08/08/2018 9:28:53 AM

ALOSMAN: LSK

no document is computer generated. No signatures required.

08/08/2018 09:28:53 AM

08/08/2018

GOODS RECEIVED BY

08/08/2018



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

MS: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

101, 3, PIONEER ROAD NORTH

401-18

SINGAPORE 4201

CASH

YAO SHENG

NO: 10104448

DATE:

10/06/2018

AMOUNT: 133.75

TAX: 0.00

TOTAL: 133.75

10/06/2018

Part No.	Description	Quantity	Unit Price	Amount
101700200170	FRONT WIPER BLADE	1	20.00	20.00
153006000000	FRONT WIPER BLADE	1	113.75	113.75
TOTAL QUANTITY				133.75
ADJUST 0.00				0.00
GRAND TOTAL				SIN 133.75



Page 1 of 1

SALES TAX: 133.75

This document is computer generated. No signature required.

10/06/2018 10:00:00 AM

[Handwritten signature]

GOODS RECEIVED





日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9938



Dept Direct: 6365 9610

Dept Direct: 6365 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201805-16041
DATE : 31/05/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SDK1272U
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T90467-07166 JB33/ACV30/31R	CLIP FOR SHIELD #789	PA PL2-K1-06J	10	1.50	15.00
2.	T68720-0D050/06030/12151 NCP93 ZRE171	FRT DR HINGE LH (UP) X12151 #1487	PA PL2-K1-03E	1	35.00	35.00
3.	T68740-02100 ZZE141 ZRE171	FRT DR HINGE LH (LWR) #1495	PA PL2-K1-03D	1	35.00	35.00
4.	T61412-06180 ASV51	CENTER PILLAR LH #2187	PA PL2-C1-03A	1	200.00	200.00
5.	T75858-33030 CAMRY-AVV50	ROCKER GARNISH MLDG LH 12" #2189	PA PL2-B1-020	1	70.00	70.00
6.	T67872-06130 ACV51	RR DR RUBBER LH #1809	PA PL1-A1-164	1	75.00	75.00

SUB-TOTAL : 430.00
ADD GST 7.00 % 30.10

E. & O.E

TOTAL AMOUNT SGD : 460.10

[P] 31/05/2018 1:31:22PM

[E] 31/05/2018 1:13:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LAI

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

SING AH TEL MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

S'PORE 628457

CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

WINDSCREEN GLASS
Dept Direct: 8417 8781 / 8745 9528



Dept Direct: 8305 9610

Dept Direct: 8300 9611

Dept Direct: 8417 8782



Dept Direct: 8417 8783

Dept Direct: 8417 8785

Dept Direct: 8417 8786

Dept Direct: 8417 8783

Wiper blade: NWB (Nippon Wiper blade), Simper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso (Nippon Made in Japan)

TAX INVOICE : AR201805-16059

DATE : 31/05/2018

CUSTOMER ID : SNG001

VEH REG. NO. : SDK1272U

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	T53812-06190 ASV51	#741 FRT FENDER LH 12"	U1 SUPPLIER	1	180.00	180.00
2.	T75443-06A70 ASV50	#1000 FRT FENDER "DUAL VVTI" LOGO	U1 SUPPLIER	1	25.00	25.00
3.	T67002-06210 ASV51	#1481 FRT DOOR LH	U1 SUPPLIER	1	480.00	480.00
4.	T67004-06190 ACV51	#480 RR DOOR LH	U1 SUPPLIER	1	480.00	480.00
5.	T90467-07166 JB33/ACV30/31R	#4203 CLIP FOR SHIELD	U1 L2-T10	10	1.50	15.00

SUB-TOTAL : 1,180.00

ADD GST 7.00 % 82.60

E. & O.E

TOTAL AMOUNT SGD : 1,262.60

PJ 31/05/2018 13:31:44

[E] 31/05/2018 1:30:47PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : LAI



AR201805-16059

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8781 / 6745 9638



Dept Direct: 6306 9610

Dept Direct: 6306 9611

Dept Direct: 6417 8780



Dept Direct: 6417 8784

Dept Direct: 6417 8785

Dept Direct: 6417 8786

Dept Direct: 6417 8787

Wiper blade: NWB (Nippon Wiper blades, Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN / SHARON / BERTHA / JANICE / SAMANTHA

TAX INVOICE : AR201806-02379
DATE : 05/06/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SDK1272U
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T75852-06925 CAMRY-AVV50	ROCKER GARNISH LH 12" #2185	PA PL2-G1-050	1	200.00	200.00

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E & O E TOTAL AMOUNT SGD : 214.00

[P] 05/06/2018 11:49:45AM

[E] 05/06/2018 11:47:40AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: LA1

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 9417 9791 / 9745 9833



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201806-02531
DATE : 05/06/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SDK1272U
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
T67862-06130 ACV51	FRT DR RUBBER LH #1509	PA PL1-A1-15N	1	75.00	75.00

SUB-TOTAL : 75.00
ADD GST 7.00 % 5.25

E & O E TOTAL AMOUNT SGD : 80.25

[F] 05/06/2018 2:18:19PM

[E] 05/06/2018 2:16:25PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : LAI

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

(SUPPLEMENTARY)

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80431961QMY	Date of Loss:	22/05/2018
Vehicle Reg. No.:	SDK1272U	Driveable?	
Driver Age/Info:	63 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH KIM SENG	Contact No:	+6597847481
Driver:	GOH KIM SENG		
Make/Model:	TOYOTA CAMRY, 2.5 (A)	Vehicle Reg. Date:	23/06/2014
Vehicle Colour:	GREY		
Engine No:	2ARU143768	Chassis No:	MR053AK5004007792
Odometer:	115294 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	13		
Description of Accident/Loss	ON 22/05/2018 AT AROUND 1635HRS, I WAS TRAVELLING ALONG ADMIRATLY RD WEST TO WOODLANDS AVE 8. WHEN I WAS AT THE JUNCTION TO MAKE MY TURN TO RIGHT INTI WOODLANDS AVE 8, I SAW MY TRAFFIC LIGHT IS GREEN AND RIGHT TURN ARROW AND I PROCEED TO MAKE MY TURN. WHEN I WAS ON THE MID OF TURNING TO THE RIGHT, SUDDENLY I SAW VEHICLE B OUT OF SUDDEN DRIVE TOWARDS MY VEHICLE ON MY LEFT AND COLLIDED ONTO MY VEHICLE FROM FRONT LEFT PORTION TO REAR LEFT PORTION.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	1,457.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,457.50
+ GST 7.00% (S\$)	102.03
Nett Amount (S\$)	1,559.53
+ Previous Estimates (S\$)	12,931.26
Claim Total (S\$)	14,490.79

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 25 May 2018)**Parts:** 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/25/05/2018 18:04**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SPARE PART	0.00	0.00	2790 *7,790.00 F
2	1		*SPARE PART	0	0.00	330 *1,480.00 FS
Sub Total (S\$)						9,270.00
+ Margin on L,N Items 10.00% (S\$)						779.00
Total Parts (S\$)						10,049.00

F=Franchise part, S=SpcNett.

Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/25/05/2018 18:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	TOTAL PAINT/MATERIAL COST	198.84 221.29
Sub Total (S\$)			221.29

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOTAL PANEL/MECHANICAL LABOUR	New	825 1,735.00
2	TOTAL PAINTWORK LABOUR	New	595 680.00
Gross Labour Cost (S\$)			2,415.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/25/05/2018 18:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: A80431961QMY
 Vehicle Reg. No.: SDK1272U
 Driver Age/Info: 63 / MALE
 TP Injury Involved? NO
 Insured/Claimant: GOH KIM SENG
 Driver: GOH KIM SENG

Ref. No:
 Date of Loss: 22/05/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES
 Contact No: +6597847481

Make/Model: TOYOTA CAMRY, 2.5 (A)
 Vehicle Colour: GREY
 Engine No: 2ARU143768
 Odometer: 5 KM

Vehicle Reg. Date: 23/06/2014
 Chassis No: MR053AK5004007792

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 13

Description of Accident/Loss

ON 22/05/2018 AT AROUND 1635HRS, I WAS TRAVELLING ALONG ADMIRATLY RD WEST TO WOODLANDS AVE 8. WHEN I WAS AT THE JUNCTION TO MAKE MY TURN TO RIGHT INTI WOODLANDS AVE 8, I SAW MY TRAFFIC LIGHT IS GREEN AND RIGHT TURN ARROW AND I PROCEED TO MAKE MY TURN. WHEN I WAS ON THE MID OF TURNING TO THE RIGHT, SUDDENLY I SAW VEHICLE B OUT OF SUDDEN DRIVE TOWARDS MY VEHICLE ON MY LEFT AND COLLIDED ONTO MY VEHICLE FROM FRONT LEFT PORTION TO REAR LEFT PORTION.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	10,049.00
Miscellaneous Items	221.29
Labour	2,415.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	12,685.29
- Excess (S\$)	600.00
(S\$)	12,085.29
+ GST 7.00% (S\$)	845.97
Nett Amount (S\$)	12,931.26

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Nov 2018)

Parts: 143 TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/14/11/2018 17:28

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LEFT HEADLAMP ASSY *	0.00	0.00	crn / *380.00 F
2	1		*L/F WHEELHOUSE COVER	0.00	0.00	de / *55.00 F
3	1		*L/F DOOR REAR STRIP	0.00	0.00	ra / *35.00 F
4	1		*L/R DOOR FRAME MLDG	0.00	0.00	ra / *35.00 F
5	1		*L/SILL MOULDING	0.00	0.00	crn / *200.00 F
6	1		*INSTRUMENT PNL TRIM	0.00	0.00	de / *550.00 F
7	1		*L/INSTR PANEL COVER	0.00	0.00	de / *70.00 F
F=Franchise part.			1/F USING INSULATOR			
			JE			
			Sub Total (S\$)			1360 1,325.00
			+ Margin on L,N Items 10.00% (S\$)			136 132.50
			Total Parts (S\$)			1496 1,457.50

Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/14/11/2018 17:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/SDK1272U/14/11/2018 17:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: DS000478
Version: SNGAHTTE/3
Date Calculated: 23/11/2018 09:24

Full Report - V1
Registration: SDK1272U
Printed: 23/11/2018 17:26

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	22/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	A80431961QMY	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YA7 01
Registration:	SDK1272U
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 05/2014	MIRROR W/NDICATOR
MULTIFUNCTION MIRROR	CHROME DOOR HANDLES
PACK RZ	2.5 LTR 133 KW
FRT/RR DOOR PROT MLD	SILL MOULDING CHROME
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	24/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: DS000478

Registration: SDK1272U

Version: SNGAHTTE/3

Printed: 23/11/2018 17:26

Date Calculated: 23/11/2018 09:24



Addresses

Cost Summary

Total Labour	\$1,420.00
Total Paint/Material	\$198.84
Total Parts	\$3,954.50
Total of Additional Costs	\$380.00
Repair Cost Exc GST:	\$5,953.34
Overall Discount (0.0%):	- \$0.00
Excess:	-\$600.00
After Deduction -	
Grand Total Exc GST:	\$5,353.34
7 % GST:	\$374.73
Grand Total Inc GST:	\$5,728.07

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	R + R L/INNER SILL COVER	2.0	10.00
B110	RENEW LEFT FRONT WING	6.0	30.00
	INCLUDES: TRANSFER ATTACHED PARTS		
B100	RENEW L/SILL MOULDING	4.0	20.00
B010	R + R FRONT BUMPER	6.0	30.00
B030	R + R RADIATOR GRILLE	3.0	15.00
B040	RENEW LEFT HEADLAMP	4.0	20.00
743261	R + R L/F WEATHERSTRIP	2.0	10.00
743261	R + R R/F WEATHERSTRIP	2.0	10.00
743011	R + R L/LOWER A-PILLAR TRIM	2.0	10.00
743011	R + R R/LOWER A-PILLAR TRIM	2.0	10.00
G010	R + R LEFT UPPER A-PILLAR TRIM	1.0	5.00
G010	R + R RIGHT UPPER A-PILLAR TRIM	1.0	5.00
B210)	RENEW L/F DOOR	28.0	140.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
B210	RENEW L/R DOOR	26.0	130.00
	INCLUDES: R + R AND ALIGN DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
M230)	R + R INSTRUMENT PANEL	15.0	75.00
NO NUMBER	RENEW INSTRUMENT PANEL (REMOVED)	3.0	15.00
M230)	R + R CENTRE CONSOLE INSERT	3.0	15.00
420018)	R + R LEFT REAR WHEEL	1.0	5.00
420091)	R + R LEFT REAR TYRE/WHEEL	2.0	10.00

Claim Reference:

Full Report - V1

Assessment Number: DS000478

Registration: SDK1272U

Version: SNGAHTTE/3

Printed: 23/11/2018 17:26

Date Calculated: 23/11/2018 09:24

042214)	BALANCE WHEEL/S	1.0	5.00
2227	REPAIR LEFT A-PILLAR	15.0*	75.00
2277	REPAIR B-PILLAR L/SILL PNL	10.0*	50.00
3481	REPAIR L/R SIDE PANEL	20.0*	100.00
1000	CHECK WIRING	6.0*	30.00

LABOUR COST

Total Work Units	165.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	16.5HRS	\$825.00
Paint Labour	11.9HRS	\$595.00
Total Labour	28.4HRS	\$1,420.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	10.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	17.0	
1781	L/R DOOR NEW PART PAINTING	15.0	
9551	L/R WHEEL NEW PART PAINTING	7.0	
2101	L/OUTER SILL PANEL REPAIR PAINTING <50%	10.0	
2227	LEFT A-PILLAR REPAIR PAINTING <50%	10.0	
2277	B-PILLAR L/SILL PNL REPAIR PAINTING <50%	10.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	

LABOUR COST - PAINT

TIME(PAINT)	94.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	119.0	
Total Paintwork Labour	11.9HRS	\$595.00

MATERIAL COST - PAINT

New Part Painting	\$116.62
Material-Constant Main Work Metal	\$28.60
Repair Painting	\$53.62
Total Excluding Pearlescent Uplift	\$198.84
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$198.84

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
561	1	LEFT HEADLAMP ASSY	81170 06811		0%	380.00*
741	1	L/F WING	53812 06160		0%	180.00*
789	9	L/F WING CLAMP KIT	91631 B0610		0%	15.00*
841	1	L/F WHEELHOUSE COVER	53876 06130		0%	55.00*
843	1	L/F WING INSULATOR	53883 06100		0%	35.00*
1481	1	LEFT FRONT DOOR	67002 06180		0%	480.00*
1487	1	L/F UPPER DOOR HINGE	68720 06030		0%	35.00*
1495	1	L/F LOWER DOOR HINGE	68740 06060		0%	35.00*
1509	1	L/F DOOR SEAL	67862 06100		0%	75.00*
1695	1	L/F DOOR REAR STRIP	75976 06060		0%	35.00*
1711	1	L/F DOOR TRIM	67620 06J00C1		0%	550.00*

Claim Reference:

Full Report - V1

Assessment Number: DS000478

Registration: SDK1272U

Version: SNGAHTTE/3

Printed: 23/11/2018 17:26

Date Calculated: 23/11/2018 09:24

1781	1	L/R DOOR	67004 06160	0%	480.00*
1809	1	L/R DOOR SEAL	67872 06100	0%	75.00*
1955	1	L/R DOOR FRAME MLDG	75762 33060	0%	35.00*
2185	1	L/SILL MOULDING	75852 06917	0%	200.00*
2187	1	L/INNER SILL MLDG	75864 06160	0%	200.00*
2189	1	L/SILL PANEL COVER	75858 33030	0%	70.00*
3160	1	REAR SCREEN BOND KIT	PZ49I 00C1131	0%	0.00F
3171	1	REAR SCREEN CLIP SET	56115 30120	0%	0.00F
3173	1	REAR SCREEN CLIP SET	56116 22050	0%	0.00F
4203	4	L/FASTENING CLIP	90467 06169	0%	15.00*
4331	1	INSTRUMENT PNL TRIM	55301 06290C0	0%	550.00*
4337	1	L/INSTR PANEL COVER	55318 06110C0	0%	70.00*
9551	1	L/R WHEEL	42611 06454	0%	0.00
9565	1	L/R TYRE	215/60 R 16 .. Y	0%	0.00F
1000	1	DUAL VVTI LOGO	Renew	0%	25.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Saving

Sub Total

Mark Up From Cost (10 %)

Total Parts

\$185.54

\$3,595.00

\$359.50

\$3,954.50

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
L/F RIM 17" SPECIALIST	0%	\$300.00
WHEEL ALIGNMENT SPECIALIST		\$80.00
Total Extras		\$380.00

Final Calculation

Total Parts	\$3,954.50
--------------------	-------------------

Labour

Total Panel/Mechanical	\$825.00
Total Paintwork	\$595.00

Total Labour	\$1,420.00
---------------------	-------------------

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$380.00

Total of Additional Costs	\$380.00
----------------------------------	-----------------

Total Paint/Material Costs	\$198.84
-----------------------------------	-----------------

Repair Costs Excludes GST	\$5,953.34
----------------------------------	-------------------

Deductions

Deduction for Excess (Fixed)	-\$600.00
--------------------------------	-----------

Total Deductions	-\$600.00
-------------------------	------------------

Grand Total Excludes GST (After Deduction)	\$5,353.34
---	-------------------

GST @ 7 %	\$374.73
-----------	----------

Grand Total Includes GST (After Deduction)	\$5,728.07
---	-------------------

Assessment Notes

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: DS000478

Registration: SDK1272U

Version: SNGAHTTE/3

Printed: 23/11/2018 17:26

Date Calculated: 23/11/2018 09:24

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018 Sendback Est	25 May 2018 18:04 S\$12,685.29	28 May 2018 10:08 Edit Adj Rpt	S\$5,953.34 Edit Estimates	S\$5,953.34 View Rpt		Pending for Survey Report Cancel Case
Supp #1	14 Nov 2018 17:10	14 Nov 2018 17:28 S\$1,457.50	14 Nov 2018 17:28			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	GOH KIM SENG, ID: S1121272G, Tel: +6597847481, Email: KSGOH10@HOTMAIL.COM			
Vehicle Reg. No.:	SDK1272U	Date of Loss:	22/05/2018 16:00 - :59 [46 Months and 29 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 559302	Policy/Cover Note No.:	A80431961QMY (Comprehensive) Coverage: 23/06/2017 - 22/06/2018	
		Excess:	S\$600.00	
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/06/2018]			
Driver/Custodian:	GOH KIM SENG (63 / Male), NRIC: S1121272G, Tel: +6597847481			
Adj Asg. Remarks:	Car in, request survey by today. Survey & revert. Please contact us ASAP if you cannot attend this assignment.			

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- MSIG_SG (04/12/2018): Alert - Adj Mandate Approved (S\$5953.34) - SDK1272U - Claim Handler: Jocelyn Ng ...
- MSIG_SG (31/10/2018): Alert - Adj Mandate Approved (S\$5430.69) - SDK1272U - Claim Handler: Jocelyn Ng ...
- MSIG_SG (31/05/2018): Alert - Adj Mandate Approved (S\$3967.69) - SDK1272U - Claim Handler: Jocelyn Ng ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SDK1272U (559302)
 OD
 May 22 2018 4:00PM
 [GOH KIM SENG]
 Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/05/18 15:20	Accident Statement	 Load HTM	☐
2	25/05/18 18:04	Repairer Estimates	 Load HTM	☐
3	14/11/18 17:28	Repairer Estimates Suppl. #1	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 17:12	Adjuster Immediate Advice	 Load HTM	☐
2	26/10/18 14:21	Adjuster Immediate Advice	 Load HTM	☐
3	23/11/18 17:40	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 17:13	Odometer Reading	 Load JPG ☒	☒
2	30/05/18 17:13	General View	 Load JPG ☒	☒
3	30/05/18 17:13	General View	 Load JPG ☒	☒
4	30/05/18 17:13	General View	 Load JPG ☒	☒
5	30/05/18 17:13	General View	 Load JPG ☒	☒
6	30/05/18 17:13	General View	 Load JPG ☒	☒
7	30/05/18 17:13	General View	 Load JPG ☒	☒
8	30/05/18 17:13	General View	 Load JPG ☒	☒
9	30/05/18 17:13	General View	 Load JPG ☒	☒
10	30/05/18 17:13	General View	 Load JPG ☒	☒
11	30/05/18 17:13	General View	 Load JPG ☒	☒
12	30/05/18 17:13	General View	 Load JPG ☒	☒
13	30/05/18 17:13	General View	 Load JPG ☒	☒
14	30/05/18 17:13	General View	 Load JPG ☒	☒
15	30/05/18 17:13	General View	 Load JPG ☒	☒
16	30/05/18 17:13	General View	 Load JPG ☒	☒
17	30/05/18 17:13	General View	 Load JPG ☒	☒
18	30/05/18 17:13	General View	 Load JPG ☒	☒
19	30/05/18 17:13	General View	 Load JPG ☒	☒
20	30/05/18 17:13	General View	 Load JPG ☒	☒
21	30/05/18 17:13	General View	 Load JPG ☒	☒
22	30/05/18 17:13	General View	 Load JPG ☒	☒
23	30/05/18 17:13	General View	 Load JPG ☒	☒
24	30/05/18 17:13	General View	 Load JPG ☒	☒
25	30/05/18 17:13	General View	 Load JPG ☒	☒
26	30/05/18 17:13	General View	 Load JPG ☒	☒
27	30/05/18 17:13	General View	 Load JPG ☒	☒
28	30/05/18 17:13	General View	 Load JPG ☒	☒
29	30/05/18 17:13	General View	 Load JPG ☒	☒
30	30/05/18 17:13	General View	 Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
31	30/05/18 17:13	General View	 Load JPG	☒
32	30/05/18 17:13	General View	 Load JPG	☒
33	30/05/18 17:13	General View	 Load JPG	☒
34	30/05/18 17:13	General View	 Load JPG	☒
35	30/05/18 17:13	General View	 Load JPG	☒
36	30/05/18 17:13	General View	 Load JPG	☒
37	30/05/18 17:13	General View	 Load JPG	☒
38	30/05/18 17:13	General View	 Load JPG	☒
39	30/05/18 17:13	General View	 Load JPG	☒
40	30/05/18 17:13	General View	 Load JPG	☒
41	30/05/18 17:13	General View	 Load JPG	☒
42	30/05/18 17:13	General View	 Load JPG	☒
43	30/05/18 17:13	General View	 Load JPG	☒
44	30/05/18 17:13	General View	 Load JPG	☒
45	30/05/18 17:13	General View	 Load JPG	☒
46	30/05/18 17:13	Chassis Number	 Load JPG	☒
47	30/05/18 17:13	General View	 Load JPG	☒
48	30/05/18 17:13	General View	 Load JPG	☒
49	30/05/18 17:13	General View	 Load JPG	☒
50	30/05/18 17:13	General View	 Load JPG	☒
51	30/05/18 17:13	General View	 Load JPG	☒
52	30/05/18 17:13	General View	 Load JPG	☒
53	30/05/18 17:13	General View	 Load JPG	☒
54	30/05/18 17:13	General View	 Load JPG	☒
55	30/05/18 17:13	General View	 Load JPG	☒
56	30/05/18 17:13	General View	 Load JPG	☒
57	30/05/18 17:13	General View	 Load JPG	☒
58	30/05/18 17:13	General View	 Load JPG	☒
59	30/05/18 17:13	General View	 Load JPG	☒
60	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
61	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
62	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
63	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
64	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
65	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
66	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
67	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
68	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
69	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
70	31/10/18 11:03	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/18 16:59	PARF COE	 Load PDF	
2	24/05/18 16:59	Transfer Fee Details	 Load PDF	
3	24/05/18 16:59	TP GIA Report - SGT9214C	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	25/05/18 17:47	IC,DL,CI	 Load TIF	
2	25/05/18 17:47	AUDATEX REPORT	 Load PDF	
3	25/05/18 17:47	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 17:12	ESTIMATE	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
2	30/05/18 17:12	ADJUSTED AUDATEX	 Load PDF	
3	26/10/18 14:30	SUPPLEMENTARY LIST	 Load PDF	
4	03/12/18 17:21	SUPPLEMENTARY LIST 2	 Load PDF	
5	03/12/18 17:22	REVISED AUDATEX	 Load PDF	
6	12/12/18 14:22	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/05/18 15:20	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/05/18 15:20	Accident Photo	 Load JPG	☒
2	23/05/18 15:20	Accident Photo	 Load JPG	☒
3	23/05/18 15:20	Accident Photo	 Load JPG	☒
4	23/05/18 15:20	Accident Photo	 Load JPG	☒
5	23/05/18 15:20	Accident Photo	 Load JPG	☒
6	23/05/18 15:20	Accident Photo	 Load JPG	☒
7	23/05/18 15:20	Accident Photo	 Load JPG	☒
8	23/05/18 15:20	Accident Photo	 Load JPG	☒
9	23/05/18 15:20	Accident Photo	 Load JPG	☒
10	23/05/18 15:20	Accident Photo	 Load JPG	☒
11	23/05/18 15:20	Accident Photo	 Load JPG	☒
12	23/05/18 15:20	Accident Photo	 Load JPG	☒
13	23/05/18 15:20	Accident Photo	 Load JPG	☒
14	23/05/18 15:20	Accident Photo	 Load JPG	☒
15	23/05/18 15:20	Accident Photo	 Load JPG	☒
16	23/05/18 15:20	Accident Photo	 Load JPG	☒
17	23/05/18 15:20	Accident Photo	 Load JPG	☒
18	23/05/18 15:20	Accident Photo	 Load JPG	☒
19	23/05/18 15:20	Accident Photo	 Load JPG	☒
20	23/05/18 15:20	Accident Photo	 Load JPG	☒
21	23/05/18 15:20	Accident Photo	 Load JPG	☒
22	23/05/18 15:20	Accident Photo	 Load JPG	☒
23	23/05/18 15:20	Accident Photo	 Load JPG	☒
24	23/05/18 15:20	Accident Photo	 Load JPG	☒
25	23/05/18 15:20	Accident Photo	 Load JPG	☒
26	23/05/18 15:20	Accident Photo	 Load JPG	☒
27	23/05/18 15:20	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	23/05/18 15:20	Sketch Plan	 Load TIF	
2	23/05/18 15:20	CI,IC,DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18009619/T1QD3E2

Date: 12/12/2018

REFERENCE

Insured/Claimant:	GOH KIM SENG	Policy No:	A80431961QMY	Claim No:	559302
Date of Loss:	22/05/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK1272U	Engine No:	2ARU143768
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004007792
Reg. Date:	23/06/2014 (Man. Year: 2014)	Odometer:	115294 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,506.50	4,334.50	7,172.00	62.33
Miscellaneous Items	221.29	198.84	22.45	10.15
Labour	2,415.00	1,420.00	995.00	41.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,142.79	5,953.34	8,189.45	57.91
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	13,542.79	5,353.34	8,189.45	60.47
+ GST 7.00/7.00% (S\$)	948.00	374.73	573.27	60.47
Nett Amount (S\$)	14,490.79	5,728.07	8,762.72	60.47

INSPECTION

Date of Assignment:	28/05/2018 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	28/05/2018 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2018)
Parts: 143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDK1272U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PART (WCP)		7,790.00 F	*2,290.00 F
2	1		*SPARE PART		1,480.00 FS	*380.00 FS
3	1		*L/F WING INSULATOR	Deformed	-	*35.00 F
Supplementary #1						
4	1		*LEFT HEADLAMP ASSY (WCP)	Cracked	380.00 F	*380.00 F
5	1		*L/F WHEELHOUSE COVER (WCP)	Repeated	55.00 F	*. F
6	1		*L/F DOOR REAR STRIP (WCP)	Necessary	35.00 F	*35.00 F
7	1		*L/R DOOR FRAME MLDG (WCP)	Necessary	35.00 F	*35.00 F
8	1		*L/SILL MOULDING (WCP)	Cracked	200.00 F	*200.00 F
9	1		*INSTRUMENT PNL TRIM (WCP)	Deformed	550.00 F	*550.00 F
10	1		*L/INSTR PANEL COVER (WCP)	Deformed	70.00 F	*70.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	10,595.00	3,975.00
+ Margin on L,N Items 10.00/10.00% (S\$)	911.50	359.50
Total Parts (S\$)	11,506.50	4,334.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	TOTAL PAINT/MATERIAL COST	221.29	198.84
Sub Total (S\$)			221.29	198.84

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL PANEL/MECHANICAL LABOUR	New	1,735.00	825.00
2	TOTAL PAINTWORK LABOUR	New	680.00	595.00
Gross Labour Cost (S\$)			2,415.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >